

**Customer Information Notification**

2020020031

**Issue Date:** 02-Aug-2020  
**Effective Date:** 17-Aug-2020



**Management Summary**

Introduction of Nexperia new outer box label

**Change Category**

- |  |   |  |   |   |
|--|---|--|---|---|
| <input type="checkbox"/> Wafer Fab Process   | <input type="checkbox"/> Assembly Process             | <input type="checkbox"/> Product Marking           | <input type="checkbox"/> Test Location  | <input type="checkbox"/> Design                         |
| <input type="checkbox"/> Wafer Fab Materials | <input type="checkbox"/> Assembly Materials           | <input type="checkbox"/> Mechanical Specification  | <input type="checkbox"/> Test Process   | <input type="checkbox"/> Errata                         |
| <input type="checkbox"/> Wafer Fab Location  | <input checked="" type="checkbox"/> Assembly Location | <input type="checkbox"/> Packing/Shipping/Labeling | <input type="checkbox"/> Test Equipment | <input type="checkbox"/> Electrical spec./Test coverage |

Introduction of Nexperia New Outer Box Label

**Information Notification**

Introduction of Nexperia new outer box label

- To achieve quality and operation efficiency improvement

**Why do we issue this Information Notification**

Nexperia will change Nexperia outer box label to achieve:

- Compliancy to ECIA (Electronics Component Industry Association) label standardization
- Quality and operation efficiency improvement
- Environmentally friendly reduce material use and waste

**Identification of Affected Products**

Packing labels

Details and identification of current and new label can be found in the attached slides

## Impact

No impact on other product labeling only the outer box label will be changed

### Data Sheet Revision

No impact to existing datasheet

### Disposition of Old Products

Not applicable, change of outer box label only

## Additional information

Affected products and sales history information: see attached file

Additional documents: [view online](#)

## Remarks

Effective date 17th August 2020

## Contact and Support

For all inquiries regarding the ePCN tool application or access issues, please [contact Nexperia "Global Quality Support Team"](#).

For all Quality Notification content inquiries, please contact your local Nexperia Sales Support team.

For specific questions on this notice or the products affected please contact our specialist directly:

**e-mail address** [PCN-Logic@nexperia.com](mailto:PCN-Logic@nexperia.com)

At Nexperia B.V. we are constantly striving to improve our product and processes to ensure they reach the highest possible Quality Standards.

## About Nexperia B.V.

We at Nexperia are the efficiency semiconductor company. We deliver over 90 billion products a year and as such service thousands of global customers, both directly and through our extensive network of channel partners. We are at the heart of billions of electronic devices in the Automotive, Mobile, Industrial, Consumer, Computing, and Communication Infrastructure segments.

You have received this email because you are a designated contact or subscribed to Nexperia Quality Notifications. Nexperia shall not be held liable if this Notification is not correctly distributed within your organization.

This message has been automatically distributed. Please do not reply.

[View Notification](#)

[Subscription](#)

[Support](#)

[Nexperia](#) |

Nexperia B.V.  
Jonkerbosplein 52 6534 AB Nijmegen, The Netherlands

© 2017 Nexperia. All rights reserved.

| Changed Orderable Part# | Changed Part 12NC | Changed Part Number |
|-------------------------|-------------------|---------------------|
| BC846AW,135             | 934021730135      | BC846AW             |
| HEF4543BT,653           | 933373300653      | HEF4543BT           |
| PMEG4002EL,315          | 934058009315      | PMEG4002EL          |
| PBSS4112PANP,115        | 934066895115      | PBSS4112PANP        |
| "HEF4002BT,652"         | 933372600652      | HEF4002BT           |
| "74AHC86PW,118"         | 935263564118      | 74AHC86PW           |
| BZX84J-C2V4,115         | 934060994115      | BZX84J-C2V4         |
| PDZ5.1BGWX              | 934071088115      | PDZ5.1BGW           |
| BZA856A,115             | 934056032115      | BZA856A             |
| NZX8V2B,133             | 934062045133      | NZX8V2B             |
| 74LVT162244BDGG:11      | 935204090118      | 74LVT162244BDGG     |
| BUK962R5-60E,118        | 934066501118      | BUK962R5-60E        |
| "74LVC02APW,118"        | 935250010118      | 74LVC02APW          |
| "74HC373PW,112"         | 935165240112      | 74HC373PW           |
| "74HCT74PW,112"         | 935175150112      | 74HCT74PW           |
| BAS516,115              | 934055217115      | BAS516              |
| 74LVC244APW,112         | 935210420112      | 74LVC244APW         |
| "74HC02PW,118"          | 935174150118      | 74HC02PW            |
| "74AHC164PW,118"        | 935265466118      | 74AHC164PW          |
| PMEG050T150EPDAZ        | 934069826139      | PMEG050T150EPD      |
| BF620,115               | 933659260115      | BF620               |
| 74AUP1G34GX4Z           | 935340118147      | 74AUP1G34GX4        |
| BST52,115               | 933644270115      | BST52               |
| PEMH13,115              | 934056872115      | PEMH13              |
| PUMD2,125               | 934049950125      | PUMD2               |
| "74VHCT14PW,118"        | 935289535118      | 74VHCT14PW          |
| 74HC597PW,118           | 935189150118      | 74HC597PW           |
| 74HCT273D,653           | 933715550653      | 74HCT273D           |
| PDTB114EUF              | 934068339135      | PDTB114EU           |
| 74HC2G02DC,125          | 935274814125      | 74HC2G02DC          |
| BC847BW,115             | 934021770115      | BC847BW             |
| BZT52H-B68,115          | 934064816115      | BZT52H-B68          |
| BZX384-C3V9,115         | 934057630115      | BZX384-C3V9         |
| PSMN6R0-30YLB,115       | 934066006115      | PSMN6R0-30YLB       |
| 74HCT4511D,653          | 933715360653      | 74HCT4511D          |
| BUK9M11-40HX            | 934660797115      | BUK9M11-40H         |
| PUMD12,115              | 934055432115      | PUMD12              |
| TDZ3V9J,115             | 934065706115      | TDZ3V9J             |
| BZX585-B22,115          | 934057407115      | BZX585-B22          |
| BAS32L,115              | 933913910115      | BAS32L              |
| BZX79-C15,133           | 933117830133      | BZX79-C15           |
| BZT52-B10J              | 934071159118      | BZT52-B10           |
| BZT52-C30X              | 934071142115      | BZT52-C30           |
| 1PS70SB82,115           | 934056488115      | 1PS70SB82           |
| 74LVC2T45GN,115         | 935292251115      | 74LVC2T45GN         |

|                      |              |                    |
|----------------------|--------------|--------------------|
| BUK9K25-40EX         | 934067814115 | BUK9K25-40E        |
| PESD5V0U1UT,215      | 934059103215 | PESD5V0U1UT        |
| PMEG045T100EPDZ      | 934068776146 | PMEG045T100EPD     |
| PSMN008-75B,118      | 934056399118 | PSMN008-75B        |
| BC56PASX             | 934068131115 | BC56PAS            |
| PEMX1,315            | 934056704315 | PEMX1              |
| PESD1LVDS,115        | 934065905115 | PESD1LVDS          |
| BUK9M28-80EX         | 934070063115 | BUK9M28-80E        |
| 74HCT175D,653        | 933715060653 | 74HCT175D          |
| BZV55-B12,115        | 933827770115 | BZV55-B12          |
| PBSS305NZ,135        | 934059046135 | PBSS305NZ          |
| BZX84J-C24,115       | 934060992115 | BZX84J-C24         |
| 74LVT241PW,118       | 935210110118 | 74LVT241PW         |
| CBT3253APW,118       | 935275887118 | CBT3253APW         |
| PMDPB58UPE,115       | 934066845115 | PMDPB58UPE         |
| BZX384-C22,115       | 934057648115 | BZX384-C22         |
| PESD5VOL1BA,115      | 934058421115 | PESD5VOL1BA        |
| PMDPB30XN,115        | 934066581115 | PMDPB30XN          |
| PMEG4010ER,115       | 934061465115 | PMEG4010ER         |
| BC846A,215           | 933589550215 | BC846A             |
| 74LV164PW,118        | 935175240118 | 74LV164PW          |
| 74CBTLV3126BQ-Q10X   | 935300957115 | 74CBTLV3126BQ-Q100 |
| "74LVC1G80GW-Q100,1" | 935299033125 | 74LVC1G80GW-Q100   |
| BZX884-B13,315       | 934057207315 | BZX884-B13         |
| PHP18NQ10T,127       | 934055698127 | PHP18NQ10T         |
| 74VHCT244PW,118      | 935289614118 | 74VHCT244PW        |
| 74LVC06ABQ,115       | 935274344115 | 74LVC06ABQ         |
| 74LVC595AD,118       | 935282469118 | 74LVC595AD         |
| 74HC2G08DP,125       | 935271870125 | 74HC2G08DP         |
| 74LVC125AD-Q100J     | 935300916118 | 74LVC125AD-Q100    |
| PESD18VV1BBSFYL      | 934660067315 | PESD18VV1BBSF      |
| BUK9K6R2-40E,115     | 934066976115 | BUK9K6R2-40E       |
| PDTC123TM,315        | 934059931315 | PDTC123TM          |
| BUK9Y12-40E,115      | 934067047115 | BUK9Y12-40E        |
| PESD3V3X1BL,315      | 934063265315 | PESD3V3X1BL        |
| 74AUP1T04GWH         | 935690087125 | 74AUP1T04GW        |
| PHPT610035PKX        | 934068172115 | PHPT610035PK       |
| PHB110NQ08T,118      | 934058279118 | PHB110NQ08T        |
| HEF4053BTT-Q100J     | 935300214118 | HEF4053BTT-Q100    |
| PMEG100V060ELPDZ     | 934069522146 | PMEG100V060ELPD    |
| 74AHCT1G125GM,115    | 935285525115 | 74AHCT1G125GM      |
| BUK9K13-60EX         | 934067951115 | BUK9K13-60E        |
| 74AHC574PW,118       | 935263081118 | 74AHC574PW         |
| 74LVC86ABQ,115       | 935274925115 | 74LVC86ABQ         |
| BZX79-B30,143        | 933166980143 | BZX79-B30          |
| 74AHC594PW,118       | 935282021118 | 74AHC594PW         |

|                      |              |                  |
|----------------------|--------------|------------------|
| 74HC153PW,118        | 935174480118 | 74HC153PW        |
| 1PS79SB70,315        | 934054924315 | 1PS79SB70        |
| 2PC4081R,135         | 934031760135 | 2PC4081R         |
| 74HC244DB,118        | 935166890118 | 74HC244DB        |
| BZV55-C20,115        | 933699590115 | BZV55-C20        |
| PCMF3USB30Z          | 934069585087 | PCMF3USB30       |
| BZV90-C5V6,115       | 934014700115 | BZV90-C5V6       |
| 74HC27PW,118         | 935189010118 | 74HC27PW         |
| BZV85-C8V2,133       | 933500630133 | BZV85-C8V2       |
| MJD44H11J            | 934660546118 | MJD44H11         |
| PTVS64VS1UR,115      | 934061375115 | PTVS64VS1UR      |
| 74LVC1G332GM,115     | 935282686115 | 74LVC1G332GM     |
| 74LV1T00GWH          | 935690114125 | 74LV1T00GW       |
| BUK7Y102-100B,115    | 934063321115 | BUK7Y102-100B    |
| "74LV4066PW,112"     | 935175010112 | 74LV4066PW       |
| PBSS4540X,135        | 934057105135 | PBSS4540X        |
| "HEF4528BT,652"      | 933373260652 | HEF4528BT        |
| "74LVC74AD,112"      | 935260734112 | 74LVC74AD        |
| PM CXB900UELZ        | 934070417147 | PM CXB900UEL     |
| 74HC165PW,118        | 935174530118 | 74HC165PW        |
| BC847C/DG/B4R        | 934068362215 | BC847C/DG/B4     |
| PBSS302ND,115        | 934059129115 | PBSS302ND        |
| "74AHC08D,112"       | 935262678112 | 74AHC08D         |
| PUMB11,135           | 934056289135 | PUMB11           |
| PSMN8R0-40BS,118     | 934066198118 | PSMN8R0-40BS     |
| 74HC27D-Q100J        | 935300791118 | 74HC27D-Q100     |
| PMXB65UPEZ           | 934067151147 | PMXB65UPE        |
| 74LVC1G02GW-Q100H    | 935300241125 | 74LVC1G02GW-Q100 |
| 74LVCH162373ADGG:1   | 935238750118 | 74LVCH162373ADGG |
| 74HC166PW,112        | 935188960112 | 74HC166PW        |
| 74AHC2G126DC,125     | 935275134125 | 74AHC2G126DC     |
| PZU14B2,115          | 934059831115 | PZU14B2          |
| "74LVC16244ADGG,112" | 935235150112 | 74LVC16244ADGG   |
| HEF4557BT,653        | 933373330653 | HEF4557BT        |
| PMD3001D,115         | 934059685115 | PMD3001D         |
| "74LVC1G14GW,125"    | 935268595125 | 74LVC1G14GW      |
| BUK9M20-40HX         | 934660799115 | BUK9M20-40H      |
| PMEG3010CEH,115      | 934061054115 | PMEG3010CEH      |
| BAT54A,215           | 933976360215 | BAT54A           |
| 74AHC3G04DP,125      | 935274681125 | 74AHC3G04DP      |
| BAV70S,115           | 934045740115 | BAV70S           |
| BZX585-B43,115       | 934057414115 | BZX585-B43       |
| "74HC1G02GW,125"     | 935245630125 | 74HC1G02GW       |
| PBLS4002Y,115        | 934058645115 | PBLS4002Y        |
| 74HCT574DB,118       | 935175110118 | 74HCT574DB       |
| BZT52-C2V4J          | 934071097118 | BZT52-C2V4       |

|                    |              |                  |
|--------------------|--------------|------------------|
| "74LVT125PW,118"   | 935197940118 | 74LVT125PW       |
| PSMN1R4-30YLDX     | 934068236115 | PSMN1R4-30YLD    |
| BZX585-C15,115     | 934055855115 | BZX585-C15       |
| BZX884-B4V3,315    | 934057190315 | BZX884-B4V3      |
| "74HC138D,652"     | 933713400652 | 74HC138D         |
| BAS70VV,115        | 934058742115 | BAS70VV          |
| BZT52-C3V6J        | 934071104118 | BZT52-C3V6       |
| NCR401UX           | 934067775115 | NCR401U          |
| PESD12VL1BA,115    | 934058422115 | PESD12VL1BA      |
| 1N4742A,113        | 933931680113 | 1N4742A          |
| 74AHCT123APW,118   | 935265562118 | 74AHCT123APW     |
| 74AHC132BQ,115     | 935278794115 | 74AHC132BQ       |
| 74HCT112D,653      | 933714970653 | 74HCT112D        |
| BSP122,115         | 934019820115 | BSP122           |
| "74AHCT139PW,112"  | 935263568112 | 74AHCT139PW      |
| BZX585-B3V0,115    | 934055858115 | BZX585-B3V0      |
| 74AVC16244DGG,118  | 935264443118 | 74AVC16244DGG    |
| BAT54L,315         | 934057248315 | BAT54L           |
| BZX585-B75,115     | 934057420115 | BZX585-B75       |
| BZT52-C6V8J        | 934071112118 | BZT52-C6V8       |
| NX3008PBK,215      | 934065642215 | NX3008PBK        |
| 74LVC16373ADGG,118 | 935235170118 | 74LVC16373ADGG   |
| BCM857BS,115       | 934058729115 | BCM857BS         |
| PESD1IVN24-AX      | 934070275115 | PESD1IVN24-A     |
| 74HCT4052PW,118    | 935290849118 | 74HCT4052PW      |
| PTVS26VP1UP,115    | 934064176115 | PTVS26VP1UP      |
| BZX585-B15,115     | 934055875115 | BZX585-B15       |
| 74AHC595BQ,115     | 935281621115 | 74AHC595BQ       |
| 74HC5555D,118      | 933998590118 | 74HC5555D        |
| 74LVC00ADB,118     | 935249970118 | 74LVC00ADB       |
| BZT52-C3V0X        | 934071101115 | BZT52-C3V0       |
| PHPT60606PYX       | 934068573115 | PHPT60606PY      |
| PCMF1USB3SZ        | 934069594087 | PCMF1USB3S       |
| PCMF2HDMI14SZ      | 934070708087 | PCMF2HDMI14S     |
| PSMN6R0-30YL,115   | 934063076115 | PSMN6R0-30YL     |
| "74AUP1G79GX,125"  | 935298365125 | 74AUP1G79GX      |
| BAT46WJ,115        | 934064494115 | BAT46WJ          |
| PMZB670UPE,315     | 934065872315 | PMZB670UPE       |
| BZV55-B5V6,115     | 933827690115 | BZV55-B5V6       |
| 74LVC2G32DC,125    | 935274976125 | 74LVC2G32DC      |
| PUSB3FR4Z          | 934068419471 | PUSB3FR4         |
| 74HCT4067PW-Q100J  | 935306644118 | 74HCT4067PW-Q100 |
| 74HCT9046AD,118    | 935044180118 | 74HCT9046AD      |
| BUK9Y58-75B,115    | 934063306115 | BUK9Y58-75B      |
| 74AUP1G175GF,132   | 935281334132 | 74AUP1G175GF     |
| BUK9Y14-40B,115    | 934060172115 | BUK9Y14-40B      |

|                     |              |                  |
|---------------------|--------------|------------------|
| "74AHC1G86GV,125"   | 935271673125 | 74AHC1G86GV      |
| "74ABT16244ADL,112" | 935183120112 | 74ABT16244ADL    |
| PMEG4010ESBYL       | 934068754315 | PMEG4010ESB      |
| 74LVC1G18GW,125     | 935273781125 | 74LVC1G18GW      |
| BZV49-C3V3,115      | 933605840115 | BZV49-C3V3       |
| BZX884-B16,315      | 934057438315 | BZX884-B16       |
| 74LVT162245BDL,118  | 935204100118 | 74LVT162245BDL   |
| BC817-16,235        | 933628620235 | BC817-16         |
| PSMN2R8-40PS,127    | 934063986127 | PSMN2R8-40PS     |
| 74LVT126PW,118      | 935209470118 | 74LVT126PW       |
| 74LVC1G57GF,132     | 935282423132 | 74LVC1G57GF      |
| 74HC245PW,118       | 935183570118 | 74HC245PW        |
| PMEG3010BER,115     | 934061459115 | PMEG3010BER      |
| BAT54S,215          | 933976380215 | BAT54S           |
| BZV55-B2V4,115      | 933931760115 | BZV55-B2V4       |
| PSMN7R0-30YLC,115   | 934066007115 | PSMN7R0-30YLC    |
| BZX84J-B4V7,115     | 934060966115 | BZX84J-B4V7      |
| PSMN5R6-100PS,127   | 934064274127 | PSMN5R6-100PS    |
| PSMN017-60YS,115    | 934064399115 | PSMN017-60YS     |
| 74LVC257AD,118      | 935260678118 | 74LVC257AD       |
| BAS116GWJ           | 934070361118 | BAS116GW         |
| 74AUP2G86DC,125     | 935280724125 | 74AUP2G86DC      |
| "CBT3306PW,118"     | 935270498118 | CBT3306PW        |
| BZT52H-C68,115      | 934059424115 | BZT52H-C68       |
| 74HC4067BQ-Q100J    | 935306681118 | 74HC4067BQ-Q100  |
| 2PC4081S,115        | 934031770115 | 2PC4081S         |
| PSMN013-30MLC,115   | 934066943115 | PSMN013-30MLC    |
| BZT52H-C5V6,115     | 934059394115 | BZT52H-C5V6      |
| BZT52H-C51,115      | 934059421115 | BZT52H-C51       |
| BZT52-C13J          | 934071128118 | BZT52-C13        |
| PESD5V0L2UMB,315    | 934065861315 | PESD5V0L2UMB     |
| 74HCT164BQ,115      | 935279166115 | 74HCT164BQ       |
| BZT52-C4V3X         | 934071106115 | BZT52-C4V3       |
| "74AUP1G09GW,125"   | 935288302125 | 74AUP1G09GW      |
| 74HC154DB,118       | 935182570118 | 74HC154DB        |
| BZV55-B3V3,115      | 933827630115 | BZV55-B3V3       |
| PESD5V0L1BSF,315    | 934064606315 | PESD5V0L1BSF     |
| 74AUP1G08GM,115     | 935279021115 | 74AUP1G08GM      |
| BZX384-B3V9,115     | 934057362115 | BZX384-B3V9      |
| "74LVC541AD,112"    | 935260901112 | 74LVC541AD       |
| PDZ5.1BGWJ          | 934071088118 | PDZ5.1BGW        |
| 74HCT573DB,112      | 935186980112 | 74HCT573DB       |
| MMBTA42,215         | 933818950215 | MMBTA42          |
| 74LVC1G00GW-Q100H   | 935299284125 | 74LVC1G00GW-Q100 |
| PUMH18,115          | 934057899115 | PUMH18           |
| 74LVC2G74DC-Q100H   | 935300077125 | 74LVC2G74DC-Q100 |

|                   |              |                 |
|-------------------|--------------|-----------------|
| 74AHCT02PW,112    | 935262691112 | 74AHCT02PW      |
| 74LV245APWJ       | 935307852118 | 74LV245APW      |
| BC847CW,135       | 934021780135 | BC847CW         |
| PDZ3.0BGWJ        | 934071058118 | PDZ3.0BGW       |
| PSMN3R0-30YL,115  | 934063072115 | PSMN3R0-30YL    |
| "74HCT1G00GV,125" | 935272012125 | 74HCT1G00GV     |
| BZV85-C16,113     | 933500700113 | BZV85-C16       |
| BC857AMB,315      | 934065888315 | BC857AMB        |
| 74HCT126D,653     | 933757050653 | 74HCT126D       |
| 74AUP1T08GXH      | 935690049125 | 74AUP1T08GX     |
| BZX79-C2V7,113    | 933298820113 | BZX79-C2V7      |
| HEF4016BT,653     | 933372690653 | HEF4016BT       |
| NX3020NAKV,115    | 934067068115 | NX3020NAKV      |
| 74LVC1G66GM,115   | 935284306115 | 74LVC1G66GM     |
| MMBZ33VAL,215     | 934061802215 | MMBZ33VAL       |
| 74LV00D,112       | 935063080112 | 74LV00D         |
| BZX884-B2V7,315   | 934057185315 | BZX884-B2V7     |
| BZV90-C4V7,115    | 934014680115 | BZV90-C4V7      |
| PMEG4005EH,115    | 934059025115 | PMEG4005EH      |
| BUK9K6R8-40EX     | 934067809115 | BUK9K6R8-40E    |
| 74LVC574AD,118    | 935219030118 | 74LVC574AD      |
| 74AHC541PW-Q100J  | 935300706118 | 74AHC541PW-Q100 |
| MMBZ12VAL,215     | 934061796215 | MMBZ12VAL       |
| PMEG4010AESBYL    | 934068755315 | PMEG4010AESB    |
| BCP53-16,135      | 933917350135 | BCP53-16        |
| BZV55-C16,135     | 933699570135 | BZV55-C16       |
| PMEG1020EJ,115    | 934058255115 | PMEG1020EJ      |
| "74AVC1T45GM,132" | 935284154132 | 74AVC1T45GM     |
| PRMH2Z            | 934070177147 | PRMH2           |
| PMBT3946YPN,115   | 934061453115 | PMBT3946YPN     |
| BZT52-C2V4X       | 934071097115 | BZT52-C2V4      |
| "74HC238D,652"    | 933714640652 | 74HC238D        |
| MMBZ9V1AL,215     | 934063466215 | MMBZ9V1AL       |
| PMBT4403,215      | 933821340215 | PMBT4403        |
| PESD3V3X1BCSFYL   | 934069674315 | PESD3V3X1BCSF   |
| BAS40-05V,115     | 934056716115 | BAS40-05V       |
| BZA420A,115       | 934045750115 | BZA420A         |
| BC847AQA          | 934069066147 | BC847AQA        |
| PTVS26VS1UR,115   | 934061361115 | PTVS26VS1UR     |
| PMBD7000,215      | 933859210215 | PMBD7000        |
| PUMH9,125         | 934055557125 | PUMH9           |
| PMPB50ENEX        | 934660354115 | PMPB50ENE       |
| BZT52H-B51,115    | 934064813115 | BZT52H-B51      |
| "74AHC02D,112"    | 935262692112 | 74AHC02D        |
| 74LV4060PW,112    | 935174990112 | 74LV4060PW      |
| 74HCT4053BQ,115   | 935277428115 | 74HCT4053BQ     |



|                      |              |                  |
|----------------------|--------------|------------------|
| "74ALVT16244DGG,112" | 935209570112 | 74ALVT16244DGG   |
| NX3008CBKS,115       | 934065639115 | NX3008CBKS       |
| PZU4.3BA,115         | 934062485115 | PZU4.3BA         |
| 74HCT244D,653        | 933713430653 | 74HCT244D        |
| BAT54,215            | 933742280215 | BAT54            |
| BZX585-C3V6,115      | 934055840115 | BZX585-C3V6      |
| PBHV9040T,215        | 934061415215 | PBHV9040T        |
| PDTA123YU,115        | 934058792115 | PDTA123YU        |
| 74HCT85D,653         | 933715430653 | 74HCT85D         |
| 74AXP1T32GXZ         | 935308977147 | 74AXP1T32GX      |
| BCP69-25,115         | 933969390115 | BCP69-25         |
| BC850C,235           | 933589700235 | BC850C           |
| BUK7880-55A/CUX      | 934068288115 | BUK7880-55A/CU   |
| PHPT61003NYX         | 934067881115 | PHPT61003NY      |
| BZX84-C6V8,235       | 933137420235 | BZX84-C6V8       |
| PZU16B1A,115         | 934062352115 | PZU16B1A         |
| PESD3V3MS-SFYL       | 934660875315 | PESD3V3MS-SF     |
| PTVS5V0P1UTP,115     | 934065528115 | PTVS5V0P1UTP     |
| 74HCT4052BQ,115      | 935273617115 | 74HCT4052BQ      |
| BUK9612-55B,118      | 934057705118 | BUK9612-55B      |
| PZU30B,115           | 934059779115 | PZU30B           |
| BZX84-C5V6,215       | 933137400215 | BZX84-C5V6       |
| 2N7002,235           | 934003470235 | 2N7002           |
| "74HC1G66GW,125"     | 935245770125 | 74HC1G66GW       |
| 74HCT11PW-Q100J      | 935300063118 | 74HCT11PW-Q100   |
| BCM856DS,115         | 934062057115 | BCM856DS         |
| BAT754C,215          | 934055731215 | BAT754C          |
| PZU5.1B2A,115        | 934062777115 | PZU5.1B2A        |
| BC857BS,115          | 934042510115 | BC857BS          |
| 1N4738A,113          | 933931640113 | 1N4738A          |
| "74LVC1G00GV,125"    | 935272027125 | 74LVC1G00GV      |
| "74AUP2G07GW,125"    | 935279985125 | 74AUP2G07GW      |
| BZX384-B16,115       | 934057378115 | BZX384-B16       |
| PBSS8110Z,135        | 934057977135 | PBSS8110Z        |
| BZV49-C6V8,115       | 933605920115 | BZV49-C6V8       |
| 74LVC1G58GW-Q100H    | 935304437125 | 74LVC1G58GW-Q100 |
| PMP4501V,115         | 934060008115 | PMP4501V         |
| 74AHC74D,118         | 935263078118 | 74AHC74D         |
| 74HC125D,652         | 933756990652 | 74HC125D         |
| 74ALVC125BQ,115      | 935285553115 | 74ALVC125BQ      |
| PRMH10Z              | 934070178147 | PRMH10           |
| PUMH20,115           | 934057902115 | PUMH20           |
| BZX384-C13,115       | 934057643115 | BZX384-C13       |
| TDZ30J,115           | 934065796115 | TDZ30J           |
| 74LVT04DB,118        | 935209000118 | 74LVT04DB        |
| BC847BV,315          | 934056535315 | BC847BV          |

|                   |              |                 |
|-------------------|--------------|-----------------|
| BUK7D25-40EX      | 934660215115 | BUK7D25-40E     |
| PTVS22VP1UP,115   | 934064174115 | PTVS22VP1UP     |
| PBSS4240DPN,115   | 934057314115 | PBSS4240DPN     |
| PSMN1R0-40YSHX    | 934660722115 | PSMN1R0-40YSH   |
| BUK98150-55A/CUF  | 934068293135 | BUK98150-55A/CU |
| BUK753R1-40E,127  | 934066424127 | BUK753R1-40E    |
| BAS40XY,115       | 934059955115 | BAS40XY         |
| BC856S,125        | 934055680125 | BC856S          |
| PMBT3946VPN,115   | 934063474115 | PMBT3946VPN     |
| BZX84-C8V2,215    | 933137440215 | BZX84-C8V2      |
| 74LVT2244PW,118   | 935217810118 | 74LVT2244PW     |
| PDTC114YU,115     | 934055207115 | PDTC114YU       |
| BAS70-06,215      | 934020820215 | BAS70-06        |
| BCX71K,215        | 933483680215 | BCX71K          |
| BZV55-C9V1,115    | 933699510115 | BZV55-C9V1      |
| PSMN038-100YLX    | 934067517115 | PSMN038-100YL   |
| 74HCT00PW,112     | 935182810112 | 74HCT00PW       |
| "74LVC1G86GW,125" | 935268824125 | 74LVC1G86GW     |
| 74HC366PW,118     | 935283208118 | 74HC366PW       |
| BZX84J-C9V1,115   | 934061022115 | BZX84J-C9V1     |
| PEMH24,115        | 934058935115 | PEMH24          |
| 74ABT126D,623     | 935053090623 | 74ABT126D       |
| PBSS5220V,115     | 934059261115 | PBSS5220V       |
| PTVS14VS1UR,115   | 934061352115 | PTVS14VS1UR     |
| BAT85,113         | 933624760113 | BAT85           |
| BZV85-C4V7,113    | 933659380113 | BZV85-C4V7      |
| 74ALVC574PW,118   | 935269739118 | 74ALVC574PW     |
| BAT754A,215       | 934055730215 | BAT754A         |
| PZTA44,115        | 934025880115 | PZTA44          |
| 74AHCT541APWJ     | 935306647118 | 74AHCT541APW    |
| BCX51-16,115      | 933674710115 | BCX51-16        |
| 74LVC823APW,118   | 935262541118 | 74LVC823APW     |
| PBSS5620PA,115    | 934063495115 | PBSS5620PA      |
| BUK7Y7R8-80EX     | 934067418115 | BUK7Y7R8-80E    |
| 74LVC2244APW,118  | 935213570118 | 74LVC2244APW    |
| 74LVC1G34GF,132   | 935282421132 | 74LVC1G34GF     |
| PSMN011-60MLX     | 934067783115 | PSMN011-60ML    |
| 74LVC2G126GF,115  | 935291504115 | 74LVC2G126GF    |
| 74LVT244BDB,118   | 935262792118 | 74LVT244BDB     |
| BAS29,215         | 933723180215 | BAS29           |
| PTVS24VS1UR/8X    | 934660627115 | PTVS24VS1UR/8   |
| BZB84-C18,215     | 934063328215 | BZB84-C18       |
| PBRN123ET,215     | 934058992215 | PBRN123ET       |
| BZV90-C18,115     | 934014820115 | BZV90-C18       |
| PDTC143TU,115     | 934057542115 | PDTC143TU       |
| "74HC393D,652"    | 933714110652 | 74HC393D        |

|                    |              |                  |
|--------------------|--------------|------------------|
| PMEG2002AESF,315   | 934065236315 | PMEG2002AESF     |
| PTVS22VZ1USKYL     | 934070852315 | PTVS22VZ1USK     |
| 74LVC4245ADB,118   | 935260750118 | 74LVC4245ADB     |
| "74LVC4245AD,112"  | 935260749112 | 74LVC4245AD      |
| BAS40-05,235       | 934034540235 | BAS40-05         |
| "74LVC1G332GW,125" | 935282688125 | 74LVC1G332GW     |
| PMSTA06,115        | 934042660115 | PMSTA06          |
| PMEG2010EPA,115    | 934063484115 | PMEG2010EPA      |
| "74AUP1G18GM,132"  | 935279953132 | 74AUP1G18GM      |
| PBHV8118T,215      | 934064195215 | PBHV8118T        |
| BZV85-C27,133      | 933500750133 | BZV85-C27        |
| BZX384-C3V3,115    | 934057628115 | BZX384-C3V3      |
| "74HC1G04GV,125"   | 935271884125 | 74HC1G04GV       |
| PHB27NQ10T,118     | 934055809118 | PHB27NQ10T       |
| BCX54-16,135       | 933674740135 | BCX54-16         |
| BZX84-C5V6,235     | 933137400235 | BZX84-C5V6       |
| 74AHCT17APWJ       | 935338682118 | 74AHCT17APW      |
| PTVS60VP1UP,115    | 934064189115 | PTVS60VP1UP      |
| BCP56-10,135       | 933917250135 | BCP56-10         |
| BZT52H-B62,115     | 934064815115 | BZT52H-B62       |
| 74LVC245APW,118    | 935211540118 | 74LVC245APW      |
| BZX384-B24,115     | 934057382115 | BZX384-B24       |
| 74LVT16374ADL,118  | 935184410118 | 74LVT16374ADL    |
| BSS87,115          | 933943940115 | BSS87            |
| PTVS6V5S1UR,115    | 934061341115 | PTVS6V5S1UR      |
| BUK9M6R6-30EX      | 934070075115 | BUK9M6R6-30E     |
| NZX12C,133         | 934061981133 | NZX12C           |
| 74AUP1G08GF,132    | 935281109132 | 74AUP1G08GF      |
| 74LV1T125GXH       | 935690105125 | 74LV1T125GX      |
| 74AHCT32BQ,115     | 935276454115 | 74AHCT32BQ       |
| 74HC540DB,112      | 935190130112 | 74HC540DB        |
| 74HC4538PW,118     | 935187530118 | 74HC4538PW       |
| BZV55-C6V2,115     | 933699470115 | BZV55-C6V2       |
| PSMN8R0-80YLX      | 934069898115 | PSMN8R0-80YL     |
| PESD5V0F1USF,315   | 934065146315 | PESD5V0F1USF     |
| 74LVC2T45DC-Q100H  | 935300461125 | 74LVC2T45DC-Q100 |
| PBSS4320X,135      | 934057107135 | PBSS4320X        |
| PESD5V0L2BT,215    | 934058864215 | PESD5V0L2BT      |
| PMDPB80XP,115      | 934066579115 | PMDPB80XP        |
| BZT52H-B47,115     | 934064812115 | BZT52H-B47       |
| 74LVC4245ADB,112   | 935260750112 | 74LVC4245ADB     |
| PESD5V0U1BLD,315   | 934065314315 | PESD5V0U1BLD     |
| PSMN040-100MSEX    | 934067473115 | PSMN040-100MSE   |
| PESD5V0L2-MZ       | 934661051305 | PESD5V0L2-M      |
| BZX84-C68,215      | 933388420215 | BZX84-C68        |
| BC807W,115         | 934027170115 | BC807W           |

|                      |              |                   |
|----------------------|--------------|-------------------|
| "74LVC1G11GW,125"    | 935277225125 | 74LVC1G11GW       |
| BC847C,235           | 933589600235 | BC847C            |
| RB520CS3002LYL       | 934067837315 | RB520CS3002L      |
| 74LVT08DB,118        | 935209030118 | 74LVT08DB         |
| BCV26,215            | 933806210215 | BCV26             |
| 74HC138PW-Q100,118   | 935298744118 | 74HC138PW-Q100    |
| 74CB3Q3253BQX        | 935339208115 | 74CB3Q3253BQ      |
| BZV55-C13,135        | 933699550135 | BZV55-C13         |
| PSMN7R6-60BS,118     | 934066199118 | PSMN7R6-60BS      |
| 74HC374PW,118        | 935174860118 | 74HC374PW         |
| BF821,235            | 933665130235 | BF821             |
| 74HCT2G125DC-Q100H   | 935300075125 | 74HCT2G125DC-Q100 |
| "74LVT245BD,112"     | 935263657112 | 74LVT245BD        |
| 74AXP1T125GMH        | 935306985125 | 74AXP1T125GM      |
| BZV55-C8V2,115       | 933699500115 | BZV55-C8V2        |
| PSMN1R0-25YLDX       | 934069908115 | PSMN1R0-25YLD     |
| 74AVCH4T245PW,118    | 935284589118 | 74AVCH4T245PW     |
| 74LVC1G123DC,125     | 935295665125 | 74LVC1G123DC      |
| BST39,115            | 933516290115 | BST39             |
| "74LVTH16245BDL,112" | 935281752112 | 74LVTH16245BDL    |
| BZT52-B5V6X          | 934071153115 | BZT52-B5V6        |
| 74AHCT245D,112       | 935261960112 | 74AHCT245D        |
| BC807-40QAZ          | 934067157147 | BC807-40QA        |
| "74AUP1G86GM,132"    | 935279053132 | 74AUP1G86GM       |
| CBT3257ABQ,115       | 935285609115 | CBT3257ABQ        |
| 74AHCT244D,112       | 935261957112 | 74AHCT244D        |
| BZX84-B3V9,215       | 933643790215 | BZX84-B3V9        |
| 74HCT365D,653        | 933715150653 | 74HCT365D         |
| PUMD18,115           | 934058903115 | PUMD18            |
| NZX5V1A,133          | 934063531133 | NZX5V1A           |
| BZX84J-C11,115       | 934060983115 | BZX84J-C11        |
| 74AHCT245D,118       | 935261960118 | 74AHCT245D        |
| PMEG2005ESFYL        | 934068324315 | PMEG2005ESF       |
| PSMN026-80YS,115     | 934063933115 | PSMN026-80YS      |
| 74HCT32D,653         | 933719470653 | 74HCT32D          |
| 74LV595PW,118        | 935198290118 | 74LV595PW         |
| BAS40W,115           | 934044280115 | BAS40W            |
| 74HC2G14GV-Q100H     | 935301613125 | 74HC2G14GV-Q100   |
| 74LV123DB,118        | 935210260118 | 74LV123DB         |
| PMEG4010CPASX        | 934068146115 | PMEG4010CPAS      |
| 74AUP1G80GM,115      | 935279051115 | 74AUP1G80GM       |
| BUK7Y18-75B,115      | 934063302115 | BUK7Y18-75B       |
| 74AUP2G132DC,125     | 935280732125 | 74AUP2G132DC      |
| BZX384-C36,115       | 934057653115 | BZX384-C36        |
| 74HC377PW,118        | 935188440118 | 74HC377PW         |
| BF550,215            | 933450900215 | BF550             |

|                    |              |                   |
|--------------------|--------------|-------------------|
| 74AHCT74BQ,115     | 935278809115 | 74AHCT74BQ        |
| BZT52-C3V3J        | 934071103118 | BZT52-C3V3        |
| PUSB3F96X          | 934067685115 | PUSB3F96          |
| BZX79-C4V7,113     | 933117710113 | BZX79-C4V7        |
| 74HCT541D,652      | 933715610652 | 74HCT541D         |
| BZX384-B3V6,115    | 934057363115 | BZX384-B3V6       |
| 74LVC126ADB,118    | 935241110118 | 74LVC126ADB       |
| NZH15B,115         | 934064371115 | NZH15B            |
| 74LVC14ABQ,115     | 935273481115 | 74LVC14ABQ        |
| BZX384-B12,115     | 934057375115 | BZX384-B12        |
| BZT52H-B11,115     | 934064795115 | BZT52H-B11        |
| 74AUP1G74GXX       | 935308441115 | 74AUP1G74GX       |
| 74AUP1T50GWH       | 935690083125 | 74AUP1T50GW       |
| "74HC40103D,652"   | 933714730652 | 74HC40103D        |
| NZX6V2C,133        | 934062034133 | NZX6V2C           |
| PZU20B2,115        | 934059835115 | PZU20B2           |
| BZX84-C16,235      | 933388270235 | BZX84-C16         |
| 74LVC1G32GM,115    | 935277189115 | 74LVC1G32GM       |
| 74LVC2T45GM,125    | 935286054125 | 74LVC2T45GM       |
| BSH103,215         | 934054713215 | BSH103            |
| 74HCT245PW,118     | 935165230118 | 74HCT245PW        |
| NX7002BKVL         | 934068055235 | NX7002BK          |
| BCM62B,215         | 934059882215 | BCM62B            |
| BZV55-B8V2,115     | 933827730115 | BZV55-B8V2        |
| PSMN6R7-40MLDX     | 934661314115 | PSMN6R7-40MLD     |
| 74LVC373ADB,112    | 935218640112 | 74LVC373ADB       |
| PDTA123YMB,315     | 934065926315 | PDTA123YMB        |
| 2N7002BKW,115      | 934064283115 | 2N7002BKW         |
| 74HC138PW,112      | 935174380112 | 74HC138PW         |
| 74HC04DB,118       | 935174240118 | 74HC04DB          |
| "HEF4094BT,652"    | 933406660652 | HEF4094BT         |
| 74AXP1G08GMH       | 935303209125 | 74AXP1G08GM       |
| BZX384-C5V6,115    | 934057634115 | BZX384-C5V6       |
| BAS321JF           | 934660321135 | BAS321J           |
| 74LVC244APW-Q100J  | 935299302118 | 74LVC244APW-Q100  |
| 74HCT4051PW-Q100,1 | 935298452118 | 74HCT4051PW-Q100  |
| "74HCT126D,652"    | 933757050652 | 74HCT126D         |
| BC807-16,215       | 933628560215 | BC807-16          |
| BZV49-C15,115      | 933606000115 | BZV49-C15         |
| 74AHC1GU04GW-Q100H | 935299884125 | 74AHC1GU04GW-Q100 |
| BUK98180-100A/CUX  | 934068289115 | BUK98180-100A/CU  |
| BZV90-C6V2,115     | 934014710115 | BZV90-C6V2        |
| 74HC00DB,118       | 935174120118 | 74HC00DB          |
| PMN42XPEAH         | 934068548125 | PMN42XPEA         |
| BZX84-C12,215      | 933137480215 | BZX84-C12         |
| 74AHC138D,112      | 935262999112 | 74AHC138D         |

|                    |              |                  |
|--------------------|--------------|------------------|
| BZX84-C3V0,235     | 933516940235 | BZX84-C3V0       |
| 74HCT04D,652       | 933714340652 | 74HCT04D         |
| PMEG060V050EPDAZ   | 934067905139 | PMEG060V050EPD   |
| 74LVC1G386GV,125   | 935274998125 | 74LVC1G386GV     |
| PESD2ETH-DX        | 934070746115 | PESD2ETH-D       |
| BZB784-C3V3,115    | 934056299115 | BZB784-C3V3      |
| 74VHCT126BQ,115    | 935289626115 | 74VHCT126BQ      |
| 74HCT4094DB,118    | 935190050118 | 74HCT4094DB      |
| 74HC4051PW-Q100,11 | 935298448118 | 74HC4051PW-Q100  |
| "74AHC1G66GV,125"  | 935271669125 | 74AHC1G66GV      |
| 74AHCT240BQ,115    | 935282627115 | 74AHCT240BQ      |
| PMPB20XNEAZ        | 934069561184 | PMPB20XNEA       |
| PTVS5V0S1UR/8X     | 934660643115 | PTVS5V0S1UR/8    |
| 74LVC2245APW,118   | 935251310118 | 74LVC2245APW     |
| BZX884-B22,315     | 934057441315 | BZX884-B22       |
| TL431IDBZR,215     | 935288017215 | TL431IDBZR       |
| 74VHCT245PW,118    | 935289586118 | 74VHCT245PW      |
| 74LVC541ADB,118    | 935260902118 | 74LVC541ADB      |
| "74AHC1G02GV,125"  | 935271650125 | 74AHC1G02GV      |
| HEF40244BT,653     | 933638680653 | HEF40244BT       |
| "74HC107D,652"     | 933713920652 | 74HC107D         |
| HEF4030BT,653      | 933372820653 | HEF4030BT        |
| BZT52-C22J         | 934071134118 | BZT52-C22        |
| 74HC373D,653       | 933715470653 | 74HC373D         |
| 74LVC1T45GW-Q100H  | 935300935125 | 74LVC1T45GW-Q100 |
| "74HCT1G126GW,125" | 935245700125 | 74HCT1G126GW     |
| 74AUP1G97GXZ       | 935307123147 | 74AUP1G97GX      |
| PMG85XP,115        | 934064765115 | PMG85XP          |
| PMEG4010ET,215     | 934061051215 | PMEG4010ET       |
| 74HC688D,652       | 933713900652 | 74HC688D         |
| 74HC373DB,112      | 935174840112 | 74HC373DB        |
| PSMN021-100YLX     | 934069906115 | PSMN021-100YL    |
| 74HCT259D,652      | 933715130652 | 74HCT259D        |
| 74LVC1G53DP,125    | 935279944125 | 74LVC1G53DP      |
| 74HC74D,653        | 933713380653 | 74HC74D          |
| "74ALVC74PW,118"   | 935269740118 | 74ALVC74PW       |
| BAS32L,135         | 933913910135 | BAS32L           |
| PMBD7100,215       | 934057973215 | PMBD7100         |
| BZX384-C5V1,115    | 934057633115 | BZX384-C5V1      |
| BZX384-B9V1,115    | 934057372115 | BZX384-B9V1      |
| PEMB11,115         | 934056864115 | PEMB11           |
| BZX79-C13,133      | 933117820133 | BZX79-C13        |
| PHPT61003PYX       | 934067882115 | PHPT61003PY      |
| "74HCU04PW,112"    | 935187580112 | 74HCU04PW        |
| "74ABT245PW,112"   | 935176430112 | 74ABT245PW       |
| "74AHC1G08GW,125"  | 935262755125 | 74AHC1G08GW      |

|                      |              |                 |
|----------------------|--------------|-----------------|
| "74HC244PW,112"      | 935174640112 | 74HC244PW       |
| BZX84-C13,235        | 933388250235 | BZX84-C13       |
| "HEF4049BT,652"      | 933372920652 | HEF4049BT       |
| PESD5V0S1BB,335      | 934058005335 | PESD5V0S1BB     |
| "74HC1G02GW-Q100,12" | 935298774125 | 74HC1G02GW-Q100 |
| "74AHC1G00GV,125"    | 935271649125 | 74AHC1G00GV     |
| 74AHCT123ABQ,115     | 935285425115 | 74AHCT123ABQ    |
| HEF4070BT,653        | 933373010653 | HEF4070BT       |
| PHPT61010PYX         | 934068586115 | PHPT61010PY     |
| PMPB27EP,115         | 934066875115 | PMPB27EP        |
| "74HC2G34GW,125"     | 935281036125 | 74HC2G34GW      |
| 74HC423D,653         | 933714870653 | 74HC423D        |
| "74LVC1G14GX,125"    | 935298222125 | 74LVC1G14GX     |
| PSMN075-100MSEX      | 934067474115 | PSMN075-100MSE  |
| BZX84-B33,215        | 933770460215 | BZX84-B33       |
| "74AHCT126PW,112"    | 935262767112 | 74AHCT126PW     |
| BUK9606-75B,118      | 934057114118 | BUK9606-75B     |
| PMEG40T20ERX         | 934070413115 | PMEG40T20ER     |
| NX3008NBKMB,315      | 934065864315 | NX3008NBKMB     |
| 74LVC74AD,118        | 935260734118 | 74LVC74AD       |
| PUMD10,115           | 934055239115 | PUMD10          |
| PMEG3010EJ,115       | 934058525115 | PMEG3010EJ      |
| 74AHC594D,118        | 935282018118 | 74AHC594D       |
| BZT52-C33J           | 934071118118 | BZT52-C33       |
| PEMD18,115           | 934058923115 | PEMD18          |
| PUMH9,135            | 934055557135 | PUMH9           |
| PMDPB55XP,115        | 934066506115 | PMDPB55XP       |
| PBHV8140Z,115        | 934063482115 | PBHV8140Z       |
| BZX84J-C47,115       | 934061006115 | BZX84J-C47      |
| BCX56-10,135         | 933663090135 | BCX56-10        |
| BZT52-C18J           | 934071132118 | BZT52-C18       |
| "HEF40106BTT,118"    | 935270276118 | HEF40106BTT     |
| PMEG60T50ELPX        | 934660232115 | PMEG60T50ELP    |
| BZT52-C68J           | 934071139118 | BZT52-C68       |
| 74LVT245BD,118       | 935263657118 | 74LVT245BD      |
| PUMH10Z              | 934056189165 | PUMH10          |
| PMEG10010ELRX        | 934068673115 | PMEG10010ELR    |
| PHT6NQ10T,135        | 934055876135 | PHT6NQ10T       |
| BC847CMB,315         | 934065887315 | BC847CMB        |
| 74LVC163PW,118       | 935210560118 | 74LVC163PW      |
| PTVS30VS1UTR,115     | 934065499115 | PTVS30VS1UTR    |
| NZH9V1B,115          | 934064365115 | NZH9V1B         |
| BZV55-C30,115        | 933699630115 | BZV55-C30       |
| BZX384-B47,115       | 934057389115 | BZX384-B47      |
| BC55-16PA,115        | 934065808115 | BC55-16PA       |
| "74HC21PW,118"       | 935290399118 | 74HC21PW        |

|                     |              |                 |
|---------------------|--------------|-----------------|
| PMEG60T20ELPX       | 934070875115 | PMEG60T20ELP    |
| CBT3245APW,118      | 935271055118 | CBT3245APW      |
| 74HCT126DB,118      | 935183590118 | 74HCT126DB      |
| BAT160S,115         | 934051420115 | BAT160S         |
| 74HC2G125DC,125     | 935274715125 | 74HC2G125DC     |
| 74HC174PW,118       | 935188360118 | 74HC174PW       |
| PHB32N06LT,118      | 934056954118 | PHB32N06LT      |
| 74AHCT02D,118       | 935262690118 | 74AHCT02D       |
| PDZ10BGWJ           | 934071042118 | PDZ10BGW        |
| "74HC4017D,652"     | 933714760652 | 74HC4017D       |
| PSMN4R0-40YS,115    | 934063937115 | PSMN4R0-40YS    |
| 1N4735A,113         | 933931610113 | 1N4735A         |
| 74LVCH2T45GF,115    | 935291522115 | 74LVCH2T45GF    |
| BCW70,215           | 933149380215 | BCW70           |
| PMEG6020EP,115      | 934061479115 | PMEG6020EP      |
| 74HC2G08DC,125      | 935274803125 | 74HC2G08DC      |
| 74LVC2G66DC,125     | 935274429125 | 74LVC2G66DC     |
| BZX384-C6V8,115     | 934057636115 | BZX384-C6V8     |
| 74LV1T04GWH         | 935690195125 | 74LV1T04GW      |
| TDZ5V1J,115         | 934065714115 | TDZ5V1J         |
| 74HC273D,653        | 933715440653 | 74HC273D        |
| BAV23,235           | 933720770235 | BAV23           |
| "74HC85D,652"       | 933714950652 | 74HC85D         |
| 74HC175D,653        | 933714580653 | 74HC175D        |
| 74HC04D-Q100,118    | 935298728118 | 74HC04D-Q100    |
| 74HCT4052D-Q100,11  | 935298847118 | 74HCT4052D-Q100 |
| 74LVC3G34DC,125     | 935275565125 | 74LVC3G34DC     |
| PSMN010-80YLX       | 934069899115 | PSMN010-80YL    |
| PESD2ETH-AXR        | 934070158215 | PESD2ETH-AX     |
| "74HCT27D,652"      | 933714180652 | 74HCT27D        |
| PSMN013-100BS,118   | 934065179118 | PSMN013-100BS   |
| PDTC124ET,235       | 934031020235 | PDTC124ET       |
| "74LV245D,112"      | 935063210112 | 74LV245D        |
| "74ALVT16373DL,112" | 935209580112 | 74ALVT16373DL   |
| PSMN5R5-60YS,115    | 934064397115 | PSMN5R5-60YS    |
| 74AUP1G14GX4Z       | 935340116147 | 74AUP1G14GX4    |
| BAT54AWF            | 934028890135 | BAT54AW         |
| BSR19A,215          | 933737140215 | BSR19A          |
| PESD3V3S1UL,315     | 934059975315 | PESD3V3S1UL     |
| "74LVC1G57GW,125"   | 935276071125 | 74LVC1G57GW     |
| "74LV08D,112"       | 935063150112 | 74LV08D         |
| BZV55-C3V9,115      | 933699420115 | BZV55-C3V9      |
| BZV55-B9V1,115      | 933827740115 | BZV55-B9V1      |
| 74AVC1T1004DPJ      | 935690122118 | 74AVC1T1004DP   |
| 74HCT541PW,118      | 935187550118 | 74HCT541PW      |
| 74AUP2G08GN,115     | 935292219115 | 74AUP2G08GN     |



|                     |              |               |
|---------------------|--------------|---------------|
| PESD5V0U5BV,115     | 934061954115 | PESD5V0U5BV   |
| NZX5V6C,133         | 934062029133 | NZX5V6C       |
| "74LV02D,112"       | 935063110112 | 74LV02D       |
| BAT46GWX            | 934070363115 | BAT46GW       |
| 74AVC1T45GXZ        | 935308468147 | 74AVC1T45GX   |
| PXT2907A,115        | 933821830115 | PXT2907A      |
| 74LV165AD,118       | 935273176118 | 74LV165AD     |
| PBSS5160U,115       | 934058123115 | PBSS5160U     |
| PMBD353,215         | 933912210215 | PMBD353       |
| BCP56-10HX          | 934070291115 | BCP56-10H     |
| PTVS64VP1UP,115     | 934064191115 | PTVS64VP1UP   |
| BSS84AK,215         | 934065304215 | BSS84AK       |
| PESD12VSA-LZ        | 934660596303 | PESD12VSA-L   |
| PESD12VS1UL,315     | 934059977315 | PESD12VS1UL   |
| BZV55-C62,115       | 933699740115 | BZV55-C62     |
| PMPB215ENEAX        | 934067477115 | PMPB215ENEA   |
| BZX79-B6V2,133      | 933166830133 | BZX79-B6V2    |
| BUK9Y3R0-40E,115    | 934067043115 | BUK9Y3R0-40E  |
| "74AUP1G06GX,125"   | 935298356125 | 74AUP1G06GX   |
| PMEG3005ET,215      | 934059427215 | PMEG3005ET    |
| "74AVCH4T245PW,112" | 935284589112 | 74AVCH4T245PW |
| PMV27UPEAR          | 934069523215 | PMV27UPEA     |
| BZA968A,115         | 934056531115 | BZA968A       |
| PSMN1R0-30YLC,115   | 934065072115 | PSMN1R0-30YLC |
| 74AHC86D,118        | 935263563118 | 74AHC86D      |
| PMXB360ENEAZ        | 934067475147 | PMXB360ENEA   |
| 74HC259D,653        | 933714650653 | 74HC259D      |
| "74HC4075D,652"     | 933714190652 | 74HC4075D     |
| PZU9.1BL,315        | 934061679315 | PZU9.1BL      |
| BZX79-C20,113       | 933117860113 | BZX79-C20     |
| PDTA144WT,215       | 934057526215 | PDTA144WT     |
| BAS20,235           | 933502030235 | BAS20         |
| BZX585-B6V2,115     | 934055866115 | BZX585-B6V2   |
| "74AUP1T34GM,132"   | 935280517132 | 74AUP1T34GM   |
| PZTA42,115          | 933982060115 | PZTA42        |
| PSMN5R0-80PS,127    | 934063912127 | PSMN5R0-80PS  |
| 74HCT4046AD,118     | 933809570118 | 74HCT4046AD   |
| PESD5Z5.0F          | 934061265135 | PESD5Z5.0     |
| 74HC273DB,118       | 935174730118 | 74HC273DB     |
| BAS86,115           | 933939380115 | BAS86         |
| BZX84-C36,215       | 933388350215 | BZX84-C36     |
| PBSS4160V,115       | 934058118115 | PBSS4160V     |
| PDTB123YT/APGR      | 934067936215 | PDTB123YT/APG |
| BZX884-B3V3,315     | 934057187315 | BZX884-B3V3   |
| 74LVC3G14DC,125     | 935275559125 | 74LVC3G14DC   |
| BZX84-C3V3,215      | 933516950215 | BZX84-C3V3    |

|                      |              |                   |
|----------------------|--------------|-------------------|
| 74ALVT16244DGG,118   | 935209570118 | 74ALVT16244DGG    |
| "74HC1G14GW,125"     | 935245730125 | 74HC1G14GW        |
| 74CBTLV3257D,118     | 935290005118 | 74CBTLV3257D      |
| BUK7214-75B,118      | 934057718118 | BUK7214-75B       |
| PSMN4R4-80PS,127     | 934063914127 | PSMN4R4-80PS      |
| 74HC273D,652         | 933715440652 | 74HC273D          |
| 74AHC138PW,118       | 935263000118 | 74AHC138PW        |
| PESD5V0L5UV,115      | 934057797115 | PESD5V0L5UV       |
| BZX884-C2V4,315      | 934057208315 | BZX884-C2V4       |
| 74LVC139PW,118       | 935196010118 | 74LVC139PW        |
| 74HC4094D-Q100J      | 935300048118 | 74HC4094D-Q100    |
| BZX79-C12,113        | 933117810113 | BZX79-C12         |
| 74AHCT08BQ,115       | 935285533115 | 74AHCT08BQ        |
| PUMD20,115           | 934058901115 | PUMD20            |
| BZV55-C75,115        | 933699760115 | BZV55-C75         |
| 74HC4052D,653        | 933714830653 | 74HC4052D         |
| PMEG1020EA,115       | 934057137115 | PMEG1020EA        |
| BZV85-C36,113        | 933500780113 | BZV85-C36         |
| PMEG2010EPK,315      | 934065381315 | PMEG2010EPK       |
| BZT52-C27X           | 934071136115 | BZT52-C27         |
| PMPB215ENEA/FX       | 934070282115 | PMPB215ENEA/F     |
| PZU4.7B3A,115        | 934062612115 | PZU4.7B3A         |
| "74HC1G08GW,125"     | 935245670125 | 74HC1G08GW        |
| 74HC4053PW,118       | 935186940118 | 74HC4053PW        |
| 74HC191D,653         | 933714600653 | 74HC191D          |
| PZU6.2B1A,115        | 934062785115 | PZU6.2B1A         |
| 74AHC3G14DC,125      | 935275103125 | 74AHC3G14DC       |
| BAS716,115           | 934057972115 | BAS716            |
| 74LVC1G17GM,115      | 935277181115 | 74LVC1G17GM       |
| BZX585-C3V0,115      | 934055838115 | BZX585-C3V0       |
| "74AHCT1G32GW-Q100," | 935298651125 | 74AHCT1G32GW-Q100 |
| BC817RAZ             | 934070165147 | BC817RA           |
| BZB784-C5V6,115      | 934056305115 | BZB784-C5V6       |
| 74LVC32ADB,118       | 935250070118 | 74LVC32ADB        |
| BUK7Y9R9-80EX        | 934067419115 | BUK7Y9R9-80E      |
| PMEG6010ER,115       | 934061463115 | PMEG6010ER        |
| PMEG4020EPK,315      | 934066738315 | PMEG4020EPK       |
| PESD3V3W1BESFYL      | 934661932315 | PESD3V3W1BESF     |
| BC817W,115           | 934021910115 | BC817W            |
| 1PS70SB14,115        | 934054918115 | 1PS70SB14         |
| HEF4021BT,653        | 933372740653 | HEF4021BT         |
| PESD12VS2UQ,115      | 934057836115 | PESD12VS2UQ       |
| 74AUP2G04GXZ         | 935307097147 | 74AUP2G04GX       |
| "CBT3253ADS,112"     | 935275886112 | CBT3253ADS        |
| PMEG2005EPK,315      | 934065379315 | PMEG2005EPK       |
| PMN55ENEX            | 934660265115 | PMN55ENE          |

|                   |              |                |
|-------------------|--------------|----------------|
| BZX884-B3V9,315   | 934057189315 | BZX884-B3V9    |
| PDTC144ET,215     | 934031030215 | PDTC144ET      |
| "74LVC595APW,112" | 935282471112 | 74LVC595APW    |
| BZX84J-C36,115    | 934060998115 | BZX84J-C36     |
| BZV85-C56,133     | 933500830133 | BZV85-C56      |
| "74HC4520PW,112"  | 935189130112 | 74HC4520PW     |
| PZU2.4BA,115      | 934062383115 | PZU2.4BA       |
| BZV85-C7V5,133    | 933500620133 | BZV85-C7V5     |
| PBSS5560PA,115    | 934063497115 | PBSS5560PA     |
| 74AVC8T245PW,118  | 935284593118 | 74AVC8T245PW   |
| PSMN4R0-25YLC,115 | 934065075115 | PSMN4R0-25YLC  |
| PMEG050T150EPDZ   | 934069826146 | PMEG050T150EPD |
| "74AUP1G57GW,125" | 935279957125 | 74AUP1G57GW    |
| BAT120C,115       | 934051350115 | BAT120C        |
| 74HCT157D,653     | 933713750653 | 74HCT157D      |
| NX138BKR          | 934070058215 | NX138BK        |
| PSMN7R5-60Y LX    | 934069896115 | PSMN7R5-60YL   |
| 74AHC74PW-Q100J   | 935300324118 | 74AHC74PW-Q100 |
| "74HC173D,652"    | 933714560652 | 74HC173D       |
| "74AUP1G14GW,125" | 935279022125 | 74AUP1G14GW    |
| BAV99,215         | 933215370215 | BAV99          |
| BUK966R5-60E,118  | 934066653118 | BUK966R5-60E   |
| 74LV245ATPWJ      | 935307853118 | 74LV245ATPW    |
| PHPT60406PYX      | 934068571115 | PHPT60406PY    |
| BZV55-C24,135     | 933699610135 | BZV55-C24      |
| PSMN8R9-100BSEJ   | 934660184118 | PSMN8R9-100BSE |
| 74LV4051D,112     | 935190970112 | 74LV4051D      |
| 74HC166D,653      | 933714550653 | 74HC166D       |
| PSMN2R2-25YLC,115 | 934065199115 | PSMN2R2-25YLC  |
| 1PS76SB10,115     | 934045390115 | 1PS76SB10      |
| BZT52-C43J        | 934071122118 | BZT52-C43      |
| PDZ3.6BGWJ        | 934071061118 | PDZ3.6BGW      |
| BC847BW,135       | 934021770135 | BC847BW        |
| 74LVC257ABQ,115   | 935275174115 | 74LVC257ABQ    |
| PSMN8R7-80PS,127  | 934064001127 | PSMN8R7-80PS   |
| 74HCT3G34DC,125   | 935274779125 | 74HCT3G34DC    |
| 1N4737A,113       | 933931630113 | 1N4737A        |
| PMZ350UPEYL       | 934068442315 | PMZ350UPE      |
| 74HC4060BQ,115    | 935286402115 | 74HC4060BQ     |
| 74HCT2G32DP,125   | 935271848125 | 74HCT2G32DP    |
| CBTD16210DGG,118  | 935268484118 | CBTD16210DGG   |
| BAV99S,135        | 934056610135 | BAV99S         |
| PBSS5440D,115     | 934057955115 | PBSS5440D      |
| "74LVC573APW,112" | 935219020112 | 74LVC573APW    |
| PHPT61002NYCX     | 934067867115 | PHPT61002NYC   |
| BZX79-B4V7,113    | 933166800113 | BZX79-B4V7     |

|                      |              |                |
|----------------------|--------------|----------------|
| BSR33,115            | 933418140115 | BSR33          |
| "74HCT30PW,118"      | 935189600118 | 74HCT30PW      |
| "74AUP2G08GT,115"    | 935280712115 | 74AUP2G08GT    |
| 74HC244PW,118        | 935174640118 | 74HC244PW      |
| PBHV2160ZX           | 934068593115 | PBHV2160Z      |
| HEF4050BT-Q100J      | 935302273118 | HEF4050BT-Q100 |
| 74LVC1G08GF,132      | 935282407132 | 74LVC1G08GF    |
| 74HCT238PW,112       | 935189560112 | 74HCT238PW     |
| "74HCT1G08GW,125"    | 935245660125 | 74HCT1G08GW    |
| BCW61C,215           | 933324140215 | BCW61C         |
| PSMN015-100YLX       | 934069904115 | PSMN015-100YL  |
| TDZ2V4J,115          | 934065701115 | TDZ2V4J        |
| 74HC10D,653          | 933714280653 | 74HC10D        |
| BUK9Y153-100E,115    | 934067042115 | BUK9Y153-100E  |
| PTVS58VP1UTP,115     | 934065563115 | PTVS58VP1UTP   |
| "74HC393PW,118"      | 935187430118 | 74HC393PW      |
| PMEG4005ESFYL        | 934068552315 | PMEG4005ESF    |
| PMST3904,115         | 934026920115 | PMST3904       |
| CBT3253ADS,118       | 935275886118 | CBT3253ADS     |
| 74HCT165D,653        | 933713790653 | 74HCT165D      |
| 74AUP1T97GXZ         | 935307073147 | 74AUP1T97GX    |
| BCP56TF              | 934070117135 | BCP56T         |
| 74CBTLV3257BQ,115    | 935290004115 | 74CBTLV3257BQ  |
| 74LVC1G34GM,115      | 935277184115 | 74LVC1G34GM    |
| PMEG6020ER,115       | 934061464115 | PMEG6020ER     |
| 74LVTH244APW,118     | 935262071118 | 74LVTH244APW   |
| BZX384-B36,115       | 934057386115 | BZX384-B36     |
| 74HC109D,653         | 933714480653 | 74HC109D       |
| BZB784-C12,115       | 934056313115 | BZB784-C12     |
| 74HC3GU04DP,125      | 935272691125 | 74HC3GU04DP    |
| PESD24VL1BA,115      | 934058424115 | PESD24VL1BA    |
| PMV75UP,215          | 934066296215 | PMV75UP        |
| 74HC173D,653         | 933714560653 | 74HC173D       |
| TL431QDBZR,215       | 935288018215 | TL431QDBZR     |
| BZX84-B75,215        | 933770550215 | BZX84-B75      |
| BUK9608-55B,118      | 934057716118 | BUK9608-55B    |
| "74AHCT573PW,112"    | 935263074112 | 74AHCT573PW    |
| "74AHC14PW-Q100,118" | 935298495118 | 74AHC14PW-Q100 |
| 74LVC827ADB,118      | 935262419118 | 74LVC827ADB    |
| 74AUP1G86GF,132      | 935281119132 | 74AUP1G86GF    |
| 74ABT162244DL,118    | 935203810118 | 74ABT162244DL  |
| BZT52-B33X           | 934071162115 | BZT52-B33      |
| PESD3V3U1BCSFYL      | 934069101315 | PESD3V3U1BCSF  |
| BAT54,235            | 933742280235 | BAT54          |
| 74HCT244DB,112       | 935166880112 | 74HCT244DB     |
| PZU5.1B3A,115        | 934062778115 | PZU5.1B3A      |

|                     |              |                 |
|---------------------|--------------|-----------------|
| "74AHCT1G125GW,125" | 935263001125 | 74AHCT1G125GW   |
| PSMN025-80YLX       | 934069902115 | PSMN025-80YL    |
| BAS21J,115          | 934060933115 | BAS21J          |
| "74AHC1G14GW,125"   | 935263009125 | 74AHC1G14GW     |
| "74HC4046APW,112"   | 935187460112 | 74HC4046APW     |
| "74HC4066PW,118"    | 935175000118 | 74HC4066PW      |
| PTVS22VU1UPAZ       | 934071206147 | PTVS22VU1UPA    |
| BCW89,215           | 933495320215 | BCW89           |
| PSMN2R2-40PS,127    | 934063915127 | PSMN2R2-40PS    |
| BZX79-C3V9,143      | 933117690143 | BZX79-C3V9      |
| BZB84-C3V9,215      | 934061684215 | BZB84-C3V9      |
| 74ABT245DB,112      | 935064910112 | 74ABT245DB      |
| "74HCT10D,652"      | 933714360652 | 74HCT10D        |
| HEF4027BT,653       | 933372790653 | HEF4027BT       |
| BC847C,215          | 933589600215 | BC847C          |
| BUK7M27-80EX        | 934070064115 | BUK7M27-80E     |
| BUK7K18-40EX        | 934067813115 | BUK7K18-40E     |
| "74HC7014D,112"     | 935059840112 | 74HC7014D       |
| BZX84-B12,215       | 933770370215 | BZX84-B12       |
| 1N4729A,113         | 933931550113 | 1N4729A         |
| 74LVC1G157GM,115    | 935278312115 | 74LVC1G157GM    |
| 74LVTH16245BDGG,11  | 935281753118 | 74LVTH16245BDGG |
| PBSS305PX,115       | 934059018115 | PBSS305PX       |
| 74AXP1T34GWH        | 935306994125 | 74AXP1T34GW     |
| 74ALVCH16245DGG,11  | 935210830118 | 74ALVCH16245DGG |
| BC817-25W,135       | 934021930135 | BC817-25W       |
| PMST2222A,115       | 934035350115 | PMST2222A       |
| 74LVC2T45DC,125     | 935284757125 | 74LVC2T45DC     |
| 74LVC1G11GM,115     | 935279532115 | 74LVC1G11GM     |
| PMEG4005EJ/ZLX      | 934070447115 | PMEG4005EJ/ZL   |
| NZH27C,115          | 934064377115 | NZH27C          |
| 74VHC08D,118        | 935289497118 | 74VHC08D        |
| BZX84-C22,215       | 933388300215 | BZX84-C22       |
| PEMH20,115          | 934058934115 | PEMH20          |
| PTVS26VS1UTR,115    | 934065496115 | PTVS26VS1UTR    |
| BZX585-B12,135      | 934055873135 | BZX585-B12      |
| BAV70W,115          | 934024390115 | BAV70W          |
| BZX585-C43,115      | 934057431115 | BZX585-C43      |
| PMPB55ENEAX         | 934068622115 | PMPB55ENEA      |
| BAT54S,235          | 933976380235 | BAT54S          |
| "74AHC32D,112"      | 935262642112 | 74AHC32D        |
| BZX79-B7V5,113      | 933166840113 | BZX79-B7V5      |
| PMCM4402UPEZ        | 934070415084 | PMCM4402UPE     |
| BZX585-C4V7,135     | 934055843135 | BZX585-C4V7     |
| PCMF1HDMI14SZ       | 934070709087 | PCMF1HDMI14S    |
| BCW66HR             | 934070943215 | BCW66H          |

|                    |              |                 |
|--------------------|--------------|-----------------|
| 74HC73DB,118       | 935190270118 | 74HC73DB        |
| 74LVC07APW-Q100J   | 935299497118 | 74LVC07APW-Q100 |
| PTVS4V5D1BLYL      | 934070788315 | PTVS4V5D1BL     |
| PBSS4032NX,115     | 934063406115 | PBSS4032NX      |
| "74HCT164D,652"    | 933714080652 | 74HCT164D       |
| BCX52-16,135       | 933674720135 | BCX52-16        |
| PTVS15VP1UP,115    | 934064168115 | PTVS15VP1UP     |
| BF622,115          | 933387860115 | BF622           |
| PMEG10020ELRX      | 934068674115 | PMEG10020ELR    |
| BZT52H-C47,115     | 934059419115 | BZT52H-C47      |
| 74HC00D-Q100,118   | 935298684118 | 74HC00D-Q100    |
| BZA856AVL,115      | 934057488115 | BZA856AVL       |
| PMEG6020ETR,115    | 934067092115 | PMEG6020ETR     |
| PTVS13VP1UP,115    | 934064166115 | PTVS13VP1UP     |
| BZT52H-C2V4,115    | 934059384115 | BZT52H-C2V4     |
| PESD5V0F1BLD,315   | 934065987315 | PESD5V0F1BLD    |
| PMEG2010AEH,115    | 934059275115 | PMEG2010AEH     |
| PESD3V3S2UQ,115    | 934057839115 | PESD3V3S2UQ     |
| PBSS4021PT,215     | 934062762215 | PBSS4021PT      |
| 74ALVC245BQ,115    | 935285552115 | 74ALVC245BQ     |
| PTVS3V3S1UR,115    | 934061337115 | PTVS3V3S1UR     |
| BZX884-B12,315     | 934057206315 | BZX884-B12      |
| 74HCT4040D,653     | 933715260653 | 74HCT4040D      |
| BZT52-B8V2J        | 934071157118 | BZT52-B8V2      |
| PMEG045T100EPDAZ   | 934068776139 | PMEG045T100EPD  |
| "74HC1G00GV,125"   | 935272010125 | 74HC1G00GV      |
| 74AUP1T02GXH       | 935690043125 | 74AUP1T02GX     |
| PMEG3002ESFYL      | 934068036315 | PMEG3002ESF     |
| PTVS20VU1UPAZ      | 934071205147 | PTVS20VU1UPA    |
| PIMZ2,115          | 934057906115 | PIMZ2           |
| PUSB3AB6Z          | 934069202471 | PUSB3AB6        |
| PBSS2540M,315      | 934057157315 | PBSS2540M       |
| 74LVC132AD,118     | 935282821118 | 74LVC132AD      |
| 74HC2G17GV,125     | 935281033125 | 74HC2G17GV      |
| PUMH11F            | 934049930135 | PUMH11          |
| 74AUP1T17GWH       | 935690081125 | 74AUP1T17GW     |
| BZX884-C16,315     | 934057455315 | BZX884-C16      |
| BC856BW,135        | 934021820135 | BC856BW         |
| 74HC08D-Q100,118   | 935298749118 | 74HC08D-Q100    |
| PMEG2010EA,135     | 934057100135 | PMEG2010EA      |
| PSMN017-80BS,118   | 934066205118 | PSMN017-80BS    |
| BZT52-C43X         | 934071122115 | BZT52-C43       |
| BZT52H-C4V7,115    | 934059392115 | BZT52H-C4V7     |
| 74LVC162245ADGG:11 | 935237700118 | 74LVC162245ADGG |
| PHPT61002PYCLHX    | 934071079115 | PHPT61002PYCLH  |
| 74HC4851BQ-Q100,11 | 935298461115 | 74HC4851BQ-Q100 |

|                   |              |               |
|-------------------|--------------|---------------|
| BZX84-A7V5,215    | 934023660215 | BZX84-A7V5    |
| BUK7613-75B,118   | 934057739118 | BUK7613-75B   |
| BZV55-C13,115     | 933699550115 | BZV55-C13     |
| PBSS4330X,115     | 934058036115 | PBSS4330X     |
| PZU11B3A,115      | 934062335115 | PZU11B3A      |
| BZT52H-B56,115    | 934064814115 | BZT52H-B56    |
| 74HC123DB,118     | 935190330118 | 74HC123DB     |
| "74HCT163D,652"   | 933715020652 | 74HCT163D     |
| 74AVC1T8832GSX    | 935690694115 | 74AVC1T8832GS |
| "74LVC1T45GS,132" | 935292925132 | 74LVC1T45GS   |
| BZV85-C15,133     | 933500690133 | BZV85-C15     |
| PBSS5350D,115     | 934055946115 | PBSS5350D     |
| 74AHCT123AD,118   | 935265561118 | 74AHCT123AD   |
| "74LVC1G02GV,125" | 935272025125 | 74LVC1G02GV   |
| 1N4531,133        | 933203980133 | 1N4531        |
| PESD5V0G1BLYL     | 934067955315 | PESD5V0G1BL   |
| BZV55-B27,115     | 933931790115 | BZV55-B27     |
| "74HC2G14GW,125"  | 935281021125 | 74HC2G14GW    |
| BC55-10PA,115     | 934065807115 | BC55-10PA     |
| 74HCT3G14DC,125   | 935274771125 | 74HCT3G14DC   |
| 74HCT139D,652     | 933713510652 | 74HCT139D     |
| 74HC75D,653       | 933714940653 | 74HC75D       |
| 74AUP1T87GWH      | 935690108125 | 74AUP1T87GW   |
| "HEF4538BT,652"   | 933507970652 | HEF4538BT     |
| BAT54SW,115       | 934028910115 | BAT54SW       |
| 1PS76SB40,115     | 934055193115 | 1PS76SB40     |
| 74LV4053D,118     | 935175860118 | 74LV4053D     |
| BZX585-B3V9,135   | 934055861135 | BZX585-B3V9   |
| BUK9M15-60EX      | 934070048115 | BUK9M15-60E   |
| BZX84-B11,215     | 933770360215 | BZX84-B11     |
| "74LVC574APW,112" | 935219050112 | 74LVC574APW   |
| PTVS43VS1UR,115   | 934061367115 | PTVS43VS1UR   |
| "74HCT4051PW,112" | 935270418112 | 74HCT4051PW   |
| 74HC573DB,118     | 935175080118 | 74HC573DB     |
| BZX84J-B3V3,115   | 934060959115 | BZX84J-B3V3   |
| BC857C,235        | 933769900235 | BC857C        |
| PMEG6010CEGWX     | 934070372115 | PMEG6010CEGW  |
| NCR402TR          | 934069488215 | NCR402T       |
| BZV55-B51,115     | 933931860115 | BZV55-B51     |
| PDZ2.7BGWJ        | 934071057118 | PDZ2.7BGW     |
| BUK7E1R8-40E,127  | 934066512127 | BUK7E1R8-40E  |
| PDTA114YT,215     | 934055236215 | PDTA114YT     |
| "74AUP1G00GX,125" | 935298353125 | 74AUP1G00GX   |
| PMF250XNEX        | 934068842115 | PMF250XNE     |
| PUSB3FA2Z         | 934660524471 | PUSB3FA2      |
| PZU2.7BL,315      | 934061653315 | PZU2.7BL      |

|                    |              |                 |
|--------------------|--------------|-----------------|
| 74LVC2G241DP,125   | 935272006125 | 74LVC2G241DP    |
| "74AHC14PW,112"    | 935262759112 | 74AHC14PW       |
| PMEG60T20ELRX      | 934070786115 | PMEG60T20ELR    |
| 74AHCT541PW,118    | 935261978118 | 74AHCT541PW     |
| BZX884-B75,315     | 934057454315 | BZX884-B75      |
| BC817-40W,135      | 934021940135 | BC817-40W       |
| "74AUP1G00GW,125"  | 935278998125 | 74AUP1G00GW     |
| 74HCT366PW-Q100,11 | 935298935118 | 74HCT366PW-Q100 |
| 74LV123PW,112      | 935210280112 | 74LV123PW       |
| BUK78150-55A/CUX   | 934068292115 | BUK78150-55A/CU |
| BAS40-05,215       | 934034540215 | BAS40-05        |
| "74LVC07APW,112"   | 935265482112 | 74LVC07APW      |
| 74HCT151D,653      | 933713710653 | 74HCT151D       |
| PBHV9040X,115      | 934061419115 | PBHV9040X       |
| PDZ24B,115         | 934054868115 | PDZ24B          |
| BC859C,235         | 933628690235 | BC859C          |
| "74AVC4T245PW,112" | 935284588112 | 74AVC4T245PW    |
| BC847A,215         | 933589580215 | BC847A          |
| 74LVC1G125GXH      | 935298386125 | 74LVC1G125GX    |
| BUK7M6R3-40EX      | 934070078115 | BUK7M6R3-40E    |
| 74AUP2G04GM,115    | 935279979115 | 74AUP2G04GM     |
| BUK9M35-80EX       | 934070065115 | BUK9M35-80E     |
| 74HCT540D,653      | 933715600653 | 74HCT540D       |
| BSR41,115          | 933418080115 | BSR41           |
| 74HCT04PW,112      | 935174220112 | 74HCT04PW       |
| BZX884-B27,315     | 934057443315 | BZX884-B27      |
| 74LVC16374ADGG,118 | 935235190118 | 74LVC16374ADGG  |
| PBSS4160U,115      | 934058117115 | PBSS4160U       |
| 74LVC132APW,118    | 935282823118 | 74LVC132APW     |
| "74HC4094PW,112"   | 935188490112 | 74HC4094PW      |
| PMPB15XP,115       | 934066615115 | PMPB15XP        |
| 74AUP1G07GF,132    | 935281108132 | 74AUP1G07GF     |
| BZT52H-C13,115     | 934059405115 | BZT52H-C13      |
| PSMN059-150Y,115   | 934061773115 | PSMN059-150Y    |
| 74HCT4017D,652     | 933715240652 | 74HCT4017D      |
| PZU7.5B2A,115      | 934062795115 | PZU7.5B2A       |
| "74HC10D,652"      | 933714280652 | 74HC10D         |
| 74LVC14APW,112     | 935260739112 | 74LVC14APW      |
| PDZ27BGWJ          | 934071044118 | PDZ27BGW        |
| "74HC30PW,118"     | 935189030118 | 74HC30PW        |
| 74AUP3G34GXX       | 935339794115 | 74AUP3G34GX     |
| 74LVC2G66DP,125    | 935274428125 | 74LVC2G66DP     |
| BZX84J-C3V3,115    | 934061002115 | BZX84J-C3V3     |
| BZX585-C30,115     | 934057427115 | BZX585-C30      |
| 74AHCT2G32DC,125   | 935275133125 | 74AHCT2G32DC    |
| 74LVC08APW,118     | 935250040118 | 74LVC08APW      |



|                     |              |                  |
|---------------------|--------------|------------------|
| 74ABT16244ADL,118   | 935183120118 | 74ABT16244ADL    |
| PSMN1R1-25YLC,115   | 934065196115 | PSMN1R1-25YLC    |
| "74ALVC244PW,112"   | 935269725112 | 74ALVC244PW      |
| HEF4007UBT,653      | 933372620653 | HEF4007UBT       |
| 74HC574DB,112       | 935187010112 | 74HC574DB        |
| BZV55-B33,115       | 933931810115 | BZV55-B33        |
| PSMN1R5-25YL,115    | 934063451115 | PSMN1R5-25YL     |
| PTVS10VS1UR,115     | 934061347115 | PTVS10VS1UR      |
| PBHV3160ZX          | 934068594115 | PBHV3160Z        |
| "74HC5555D,112"     | 933998590112 | 74HC5555D        |
| 74LVC02AD,118       | 935249990118 | 74LVC02AD        |
| BAV99S,115          | 934056610115 | BAV99S           |
| "74HCT374D,652"     | 933713490652 | 74HCT374D        |
| PESD5V0X1BL,315     | 934061649315 | PESD5V0X1BL      |
| 74AXP2G14GXZ        | 935307133147 | 74AXP2G14GX      |
| PUMB20,115          | 934057888115 | PUMB20           |
| BSH111BKR           | 934068056215 | BSH111BK         |
| "74HC02D,652"       | 933714150652 | 74HC02D          |
| BZX84J-B33,115      | 934060952115 | BZX84J-B33       |
| "74AHC1G02GW,125"   | 935262750125 | 74AHC1G02GW      |
| PTVS33VS1UR,115     | 934061364115 | PTVS33VS1UR      |
| 74LVCH16244ADGG,11  | 935238450118 | 74LVCH16244ADGG  |
| "74LVC1G3157GW,125" | 935277231125 | 74LVC1G3157GW    |
| BZV55-B10,115       | 933827750115 | BZV55-B10        |
| BAW56/DG/B4R        | 934068404215 | BAW56/DG/B4      |
| "74HC132PW,118"     | 935185800118 | 74HC132PW        |
| PMDPB70XP,115       | 934066054115 | PMDPB70XP        |
| PSMN069-100YS,115   | 934064536115 | PSMN069-100YS    |
| BZX884-C6V2,315     | 934057218315 | BZX884-C6V2      |
| PMP4201Y,135        | 934059038135 | PMP4201Y         |
| 74HC4075D,653       | 933714190653 | 74HC4075D        |
| PDZ16B,115          | 934054864115 | PDZ16B           |
| 1N4739A,133         | 933931650133 | 1N4739A          |
| BZX84-B5V6/DG/B4R   | 934070231215 | BZX84-B5V6/DG/B4 |
| BZX84J-B8V2,115     | 934060979115 | BZX84J-B8V2      |
| "74HC174D,652"      | 933714570652 | 74HC174D         |
| PMEG2005EH,115      | 934059023115 | PMEG2005EH       |
| PSMN1R7-25YLDX      | 934069911115 | PSMN1R7-25YLD    |
| 74LVC74ABQ,115      | 935273502115 | 74LVC74ABQ       |
| "74LVC157AD,112"    | 935260898112 | 74LVC157AD       |
| 74HC4538DB,118      | 935186970118 | 74HC4538DB       |
| BCW66FR             | 934070941215 | BCW66F           |
| "74AVCH1T45GM,132"  | 935284155132 | 74AVCH1T45GM     |
| PBHV8560ZX          | 934068592115 | PBHV8560Z        |
| 74HC165BQ-Q100,115  | 935298766115 | 74HC165BQ-Q100   |
| PESD1LIN/DG/B2,115  | 934062441115 | PESD1LIN/DG/B2   |

|                    |              |                   |
|--------------------|--------------|-------------------|
| "74HCT573PW,112"   | 935186990112 | 74HCT573PW        |
| BCM847QASZ         | 934071231147 | BCM847QAS         |
| BZV85-C10,133      | 933500650133 | BZV85-C10         |
| 74HC4053PW,112     | 935186940112 | 74HC4053PW        |
| BC856BW,115        | 934021820115 | BC856BW           |
| 74LVT14D,118       | 935209170118 | 74LVT14D          |
| BZV90-C10,115      | 934014760115 | BZV90-C10         |
| BZV55-B3V0,115     | 933827620115 | BZV55-B3V0        |
| BCX53,115          | 933272300115 | BCX53             |
| BSP126,135         | 934000540135 | BSP126            |
| 74HC4067PW-Q100J   | 935306642118 | 74HC4067PW-Q100   |
| PESD2V0Y1BSFYL     | 934660034315 | PESD2V0Y1BSF      |
| "74AUP1G38GX,125"  | 935298364125 | 74AUP1G38GX       |
| HEF4002BT,653      | 933372600653 | HEF4002BT         |
| PEMH14,115         | 934058927115 | PEMH14            |
| 74LVC2G02GN,115    | 935292237115 | 74LVC2G02GN       |
| "74HCT4067D,112"   | 933715680112 | 74HCT4067D        |
| 74HC4538PW-Q100,11 | 935298859118 | 74HC4538PW-Q100   |
| PBHV8115T,215      | 934061416215 | PBHV8115T         |
| PUMD15,115         | 934057891115 | PUMD15            |
| 74LVC8T245BQ-Q100J | 935301104118 | 74LVC8T245BQ-Q100 |
| 74LVC2G02DC,125    | 935274687125 | 74LVC2G02DC       |
| PMPB20XPE,115      | 934066622115 | PMPB20XPE         |
| PHPT610030NPKX     | 934068173115 | PHPT610030NPK     |
| 1PS74SB23,115      | 934054921115 | 1PS74SB23         |
| TDZ5V6J,115        | 934064716115 | TDZ5V6J           |
| 74AXP1T34GXH       | 935306995125 | 74AXP1T34GX       |
| 74HCT366PW,118     | 935283209118 | 74HCT366PW        |
| PMZB150UNEYL       | 934069221315 | PMZB150UNE        |
| PMV65XPEAR         | 934068708215 | PMV65XPEA         |
| 74LVC2G38GXX       | 935339799115 | 74LVC2G38GX       |
| PTVS51VS1UTR,115   | 934065507115 | PTVS51VS1UTR      |
| 74HC2G125DP,125    | 935270085125 | 74HC2G125DP       |
| 74HC299D,653       | 933713540653 | 74HC299D          |
| 74AHCT32D,118      | 935262640118 | 74AHCT32D         |
| BAS16,235          | 933460620235 | BAS16             |
| 74HCT166D,653      | 933715030653 | 74HCT166D         |
| 74LVT162244BDL,118 | 935204080118 | 74LVT162244BDL    |
| BAS16LD,315        | 934064565315 | BAS16LD           |
| PMEG2020EPA,115    | 934064295115 | PMEG2020EPA       |
| BZT52-B3V3J        | 934071146118 | BZT52-B3V3        |
| BZX84-C56,215      | 933388400215 | BZX84-C56         |
| "74LVC1G04GV,125"  | 935271788125 | 74LVC1G04GV       |
| PESD5V0L1UA,115    | 934063222115 | PESD5V0L1UA       |
| BZT52H-C7V5,115    | 934059397115 | BZT52H-C7V5       |
| PDTA143XU,115      | 934057536115 | PDTA143XU         |

|                    |              |                     |
|--------------------|--------------|---------------------|
| PMV90ENER          | 934068847215 | PMV90ENE            |
| NZX6V8A,133        | 934062037133 | NZX6V8A             |
| "74AHC1G126GM,132" | 935285527132 | 74AHC1G126GM        |
| 74LVC1G3157GV,125  | 935277229125 | 74LVC1G3157GV       |
| "74HCT126PW,118"   | 935183550118 | 74HCT126PW          |
| PESD1CAN,215       | 934059097215 | PESD1CAN            |
| BAT854CW,135       | 934056174135 | BAT854CW            |
| 74LVC126ABQ,115    | 935274082115 | 74LVC126ABQ         |
| BZX84-C33,235      | 933388340235 | BZX84-C33           |
| 74LVC1G74DP,125    | 935274974125 | 74LVC1G74DP         |
| 74AUP2G14GXZ       | 935307098147 | 74AUP2G14GX         |
| PMCM6501UNEZ       | 934070323023 | PMCM6501UNE         |
| BUK9K17-60EX       | 934067953115 | BUK9K17-60E         |
| 74LV17APWJ         | 935338679118 | 74LV17APW           |
| 74LVC273D,112      | 935210640112 | 74LVC273D           |
| BZA456A,115        | 934045760115 | BZA456A             |
| "74HC7541D,112"    | 933967940112 | 74HC7541D           |
| 1PS79SB31,115      | 934056795115 | 1PS79SB31           |
| BZX585-C20,115     | 934057423115 | BZX585-C20          |
| 2N7002CK,215       | 934063611215 | 2N7002CK            |
| BZX84J-B2V7,115    | 934060949115 | BZX84J-B2V7         |
| BZX84J-C18,115     | 934060988115 | BZX84J-C18          |
| BZX384-B8V2,115    | 934057371115 | BZX384-B8V2         |
| 74LV165D,118       | 935156060118 | 74LV165D            |
| BZV55-B62,115      | 933931880115 | BZV55-B62           |
| 74AHCV245APWJ      | 935307877118 | 74AHCV245APW        |
| BUK9M53-60EX       | 934070057115 | BUK9M53-60E         |
| BCV28,115          | 933871580115 | BCV28               |
| PMEG6002ELDYL      | 934067662315 | PMEG6002ELD         |
| 74AUP2G02DC,125    | 935280708125 | 74AUP2G02DC         |
| BCW60B,215         | 933324090215 | BCW60B              |
| BZX79-C51,113      | 933117960113 | BZX79-C51           |
| 74HCT123PW,118     | 935186850118 | 74HCT123PW          |
| 74AVC1T45GW-Q100H  | 935299491125 | 74AVC1T45GW-Q100    |
| NX7002BKMYL        | 934068617315 | NX7002BKM           |
| BAW56W,115         | 934026020115 | BAW56W              |
| 74LVC1G10GV,125    | 935284947125 | 74LVC1G10GV         |
| "74AHC1G79GW,125"  | 935263094125 | 74AHC1G79GW         |
| 74AUP2G57GFX       | 935304472115 | 74AUP2G57GF         |
| BZX79-C75,113      | 933118000113 | BZX79-C75           |
| PZT4403,115        | 934012110115 | PZT4403             |
| BZT52H-C3V9,115    | 934059389115 | BZT52H-C3V9         |
| 74AVC16T245DGV-Q1J | 935302847118 | 74AVC16T245DGV-Q100 |
| "74HCT4046AD,112"  | 933809570112 | 74HCT4046AD         |
| 74LVC573APW,118    | 935219020118 | 74LVC573APW         |
| BZV55-C7V5,115     | 933699490115 | BZV55-C7V5          |

|                     |              |                |
|---------------------|--------------|----------------|
| BZX79-B15,133       | 933166910133 | BZX79-B15      |
| 74AHC1G17GWH        | 935303438125 | 74AHC1G17GW    |
| BZX384-B3V3F        | 934057361135 | BZX384-B3V3    |
| BCP53TF             | 934070114135 | BCP53T         |
| "HEF40106BT,652"    | 933406960652 | HEF40106BT     |
| HEF4047BT,653       | 933372910653 | HEF4047BT      |
| 74HCT2G34GV,125     | 935281034125 | 74HCT2G34GV    |
| 74HC4050D,653       | 933714810653 | 74HC4050D      |
| "74HC2G04GW,125"    | 935281023125 | 74HC2G04GW     |
| BZV55-B20,135       | 933827820135 | BZV55-B20      |
| "74HC73D,652"       | 933714430652 | 74HC73D        |
| HEF4071BT,653       | 933373020653 | HEF4071BT      |
| PTVS8V0P1UP,115     | 934064157115 | PTVS8V0P1UP    |
| 74LVC374ABQ,115     | 935273479115 | 74LVC374ABQ    |
| 74LVC573AD,118      | 935219000118 | 74LVC573AD     |
| 74HC688PW,118       | 935189170118 | 74HC688PW      |
| BZV55-C33,115       | 933699640115 | BZV55-C33      |
| BUK9K12-60EX        | 934067948115 | BUK9K12-60E    |
| BAS19,215           | 933502020215 | BAS19          |
| "74LVC1G08GM,132"   | 935277188132 | 74LVC1G08GM    |
| 74HC4851BQ,115      | 935282086115 | 74HC4851BQ     |
| "74LVC16244ADL,112" | 935235140112 | 74LVC16244ADL  |
| "74LV132D,112"      | 935162490112 | 74LV132D       |
| PEMD10,115          | 934056858115 | PEMD10         |
| 74LV123PW,118       | 935210280118 | 74LV123PW      |
| 74LVT16245BDL,118   | 935179190118 | 74LVT16245BDL  |
| "74HC377D,652"      | 933713980652 | 74HC377D       |
| BUK7M15-40HX        | 934660788115 | BUK7M15-40H    |
| PSMN5R8-40YS,115    | 934064147115 | PSMN5R8-40YS   |
| BAS70-07,215        | 934026750215 | BAS70-07       |
| 74LVC1G384GXH       | 935307214125 | 74LVC1G384GX   |
| BZB84-C10,215       | 934061695215 | BZB84-C10      |
| "74AUP1G18GW,125"   | 935279952125 | 74AUP1G18GW    |
| BZX79-C47,143       | 933117950143 | BZX79-C47      |
| PMEG3020EGWX        | 934070367115 | PMEG3020EGW    |
| NZX13C,133          | 934061985133 | NZX13C         |
| PBHV8515QAZ         | 934069064147 | PBHV8515QA     |
| 74LVC240APW,118     | 935210450118 | 74LVC240APW    |
| 74HC157PW-Q100,118  | 935298906118 | 74HC157PW-Q100 |
| MMBZ27VCL,215       | 934061813215 | MMBZ27VCL      |
| BZX585-B4V3,115     | 934055862115 | BZX585-B4V3    |
| PDTA143EU,115       | 934044120115 | PDTA143EU      |
| BZV55-B2V7,115      | 933925190115 | BZV55-B2V7     |
| 74AUP2G32GF,115     | 935291491115 | 74AUP2G32GF    |
| PMEG1030EJ,115      | 934058649115 | PMEG1030EJ     |
| PESD5V0X1ULD,315    | 934065244315 | PESD5V0X1ULD   |

|                    |              |                   |
|--------------------|--------------|-------------------|
| BCW66GVL           | 934070942235 | BCW66G            |
| "74LVC541APW,112"  | 935260903112 | 74LVC541APW       |
| 74AUP2G125DC,125   | 935280727125 | 74AUP2G125DC      |
| 74AXP1G07GXH       | 935307038125 | 74AXP1G07GX       |
| BCW32,215          | 933082791215 | BCW32             |
| BZX384-B3V0,115    | 934057360115 | BZX384-B3V0       |
| 74HC2G00DP,125     | 935270082125 | 74HC2G00DP        |
| BAS40,215          | 934034530215 | BAS40             |
| PMV28UNEAR         | 934068718215 | PMV28UNEA         |
| PMV16XNR           | 934068844215 | PMV16XN           |
| PMBS3904,215       | 933972890215 | PMBS3904          |
| 2PA1576R,115       | 934031790115 | 2PA1576R          |
| PDTC114EM,315      | 934057170315 | PDTC114EM         |
| BZX84-B7V5,215     | 933696010215 | BZX84-B7V5        |
| PZU3.3B2L,315      | 934061656315 | PZU3.3B2L         |
| PDTC123JT,215      | 934054698215 | PDTC123JT         |
| NXS0104PW-Q100J    | 935690809118 | NXS0104PW-Q100    |
| "74HCT4067PW,112"  | 935193260112 | 74HCT4067PW       |
| PSMN1R1-40BS,118   | 934065174118 | PSMN1R1-40BS      |
| BUK7210-55B,118    | 934062095118 | BUK7210-55B       |
| "74HC74D,652"      | 933713380652 | 74HC74D           |
| 74HCT238DB,112     | 935189260112 | 74HCT238DB        |
| BZV49-C4V7,115     | 933605880115 | BZV49-C4V7        |
| "74HC1G08GV,125"   | 935272015125 | 74HC1G08GV        |
| BUK7K8R7-40EX      | 934067811115 | BUK7K8R7-40E      |
| PESD5V0V1BL,315    | 934063248315 | PESD5V0V1BL       |
| "74HC1G126GV,125"  | 935272014125 | 74HC1G126GV       |
| 74LVC1G00GM,115    | 935277186115 | 74LVC1G00GM       |
| 74HC4024D,653      | 933714410653 | 74HC4024D         |
| 74ABT08D,118       | 935207050118 | 74ABT08D          |
| NZH5V1B,115        | 934064358115 | NZH5V1B           |
| BZX585-B8V2,115    | 934055869115 | BZX585-B8V2       |
| "74LVC1G86GV,125"  | 935272026125 | 74LVC1G86GV       |
| BCW60C,235         | 933324100235 | BCW60C            |
| "74AHCT138D,112"   | 935262997112 | 74AHCT138D        |
| 74AHC574D,118      | 935263080118 | 74AHC574D         |
| PESD18VF1BLYL      | 934067602315 | PESD18VF1BL       |
| BZT52-C4V7J        | 934071107118 | BZT52-C4V7        |
| PLVA662A,215       | 934017380215 | PLVA662A          |
| 74HCT153PW-Q100J   | 935300782118 | 74HCT153PW-Q100   |
| BSP31,115          | 933981970115 | BSP31             |
| "74LV74PW,118"     | 935175140118 | 74LV74PW          |
| "74AHCT04PW,118"   | 935263039118 | 74AHCT04PW        |
| 74LVC1G123DP-Q100H | 935302107125 | 74LVC1G123DP-Q100 |
| NX7002AKW,115      | 934066297115 | NX7002AKW         |
| BZX84-A2V4,235     | 933959650235 | BZX84-A2V4        |

|                    |              |                   |
|--------------------|--------------|-------------------|
| PBHV9515QAZ        | 934069065147 | PBHV9515QA        |
| BZB84-B3V6,215     | 934061705215 | BZB84-B3V6        |
| BCP54-16,115       | 933917200115 | BCP54-16          |
| BZX84-C6V2,215     | 933137410215 | BZX84-C6V2        |
| 74LVCH16245ADGG,11 | 935238470118 | 74LVCH16245ADGG   |
| "74LVTH125PW,118"  | 935281723118 | 74LVTH125PW       |
| PMBT2907AYSX       | 934069062115 | PMBT2907AYS       |
| 74HC1G04GW-Q100H   | 935299988125 | 74HC1G04GW-Q100   |
| PEMB9,115          | 934057047115 | PEMB9             |
| "74LVT08PW,118"    | 935209040118 | 74LVT08PW         |
| BC856B,235         | 933589730235 | BC856B            |
| 74AVC4T774GUX      | 935341327115 | 74AVC4T774GU      |
| 74HC123D,653       | 933713960653 | 74HC123D          |
| BAT721C,215        | 934054929215 | BAT721C           |
| "HEF4050BT,652"    | 933372930652 | HEF4050BT         |
| 74LV00PW,118       | 935174100118 | 74LV00PW          |
| BZX79-C9V1,143     | 933117780143 | BZX79-C9V1        |
| PESD5V2S2UT,215    | 934057593215 | PESD5V2S2UT       |
| 74HC4002PW,118     | 935188460118 | 74HC4002PW        |
| BZV90-C15,115      | 934014800115 | BZV90-C15         |
| BZV49-C36,115      | 933606090115 | BZV49-C36         |
| 74HCT157PW,118     | 935188540118 | 74HCT157PW        |
| BST82,215          | 933733110215 | BST82             |
| 74LVT244APW,118    | 935176380118 | 74LVT244APW       |
| "74AUP1GU04GW,125" | 935279065125 | 74AUP1GU04GW      |
| 1N4740A,133        | 933931660133 | 1N4740A           |
| 74LVC125ABQ,115    | 935273344115 | 74LVC125ABQ       |
| 74AVCH8T245PW:118  | 935284594118 | 74AVCH8T245PW     |
| PDZ2.4BGWJ         | 934071023118 | PDZ2.4BGW         |
| "74LVC86APW,112"   | 935250110112 | 74LVC86APW        |
| BUK7237-55A,118    | 934056246118 | BUK7237-55A       |
| BAS16GWJ           | 934070359118 | BAS16GW           |
| "74LVC1G02GW,125"  | 935268379125 | 74LVC1G02GW       |
| BSS138PS,115       | 934064989115 | BSS138PS          |
| PMEG6020ETP,115    | 934066839115 | PMEG6020ETP       |
| 74AVC8T245BQ-Q100J | 935300551118 | 74AVC8T245BQ-Q100 |
| NZH6V2B,115        | 934064361115 | NZH6V2B           |
| BCP56-10,115       | 933917250115 | BCP56-10          |
| PTVS30VP1UTP,115   | 934065553115 | PTVS30VP1UTP      |
| BZX84-B20,215      | 933770420215 | BZX84-B20         |
| 74AUP1G125GM,115   | 935279055115 | 74AUP1G125GM      |
| 74LVC1G11GV,125    | 935277224125 | 74LVC1G11GV       |
| PDZ3.3B,115        | 934054847115 | PDZ3.3B           |
| PBRP123ET,215      | 934058985215 | PBRP123ET         |
| PESD5V0V1BDSF,315  | 934066027315 | PESD5V0V1BDSF     |
| PBSS4140DPN,115    | 934056660115 | PBSS4140DPN       |

|                    |              |                  |
|--------------------|--------------|------------------|
| 74AHC74BQ,115      | 935278807115 | 74AHC74BQ        |
| 74AHC541D,118      | 935262006118 | 74AHC541D        |
| BZV55-B20,115      | 933827820115 | BZV55-B20        |
| BUK7M9R5-40HX      | 934660786115 | BUK7M9R5-40H     |
| 1PS70SB84,115      | 934056489115 | 1PS70SB84        |
| BZV85-C30,113      | 933500760113 | BZV85-C30        |
| 74HC4075PW-Q100J   | 935302014118 | 74HC4075PW-Q100  |
| 74AHCV541APWJ      | 935306648118 | 74AHCV541APW     |
| "74LVC1GU04GX,125" | 935298388125 | 74LVC1GU04GX     |
| 74AHC32BQ,115      | 935276443115 | 74AHC32BQ        |
| BC817K-16HR        | 934660223215 | BC817K-16H       |
| PESD3V3W1BCSFYL    | 934660065315 | PESD3V3W1BCSF    |
| 74LV4051PW,118     | 935191000118 | 74LV4051PW       |
| 74LVC377D,118      | 935210660118 | 74LVC377D        |
| "74HC1G14GV,125"   | 935271883125 | 74HC1G14GV       |
| 74AHC594PW,112     | 935282021112 | 74AHC594PW       |
| BZV90-C20,115      | 934014830115 | BZV90-C20        |
| BUK9230-100B,118   | 934057722118 | BUK9230-100B     |
| "74AHCT125PW,118"  | 935262765118 | 74AHCT125PW      |
| NZX2V4A,133        | 934062007133 | NZX2V4A          |
| 74HC251D,653       | 933713520653 | 74HC251D         |
| PMBT2222AYSX       | 934069057115 | PMBT2222AYS      |
| 74AVC1T45GM-Q100H  | 935299489125 | 74AVC1T45GM-Q100 |
| PSMN7R5-30YLDX     | 934067967115 | PSMN7R5-30YLD    |
| BUK7Y3R0-40HX      | 934660085115 | BUK7Y3R0-40H     |
| BSR30,115          | 933418110115 | BSR30            |
| BUK7M10-40EX       | 934070083115 | BUK7M10-40E      |
| 74HC11D-Q100J      | 935300036118 | 74HC11D-Q100     |
| BAV99QA            | 934069815147 | BAV99QA          |
| 74AHCT541ABQX      | 935306794115 | 74AHCT541ABQ     |
| BZV55-C33,135      | 933699640135 | BZV55-C33        |
| BZX84-B51,215      | 933770510215 | BZX84-B51        |
| PTVS3V3P1UTP,115   | 934065527115 | PTVS3V3P1UTP     |
| PSMN017-80PS,127   | 934063999127 | PSMN017-80PS     |
| "74AVC4T245D,112"  | 935288131112 | 74AVC4T245D      |
| "74AUP1G07GX,125"  | 935297926125 | 74AUP1G07GX      |
| "74HCT14PW,118"    | 935183540118 | 74HCT14PW        |
| BC857RA            | 934070164147 | BC857RA          |
| PBSS4230T,215      | 934057986215 | PBSS4230T        |
| BZV49-C13,115      | 933605990115 | BZV49-C13        |
| BZX79-C10,113      | 933117790113 | BZX79-C10        |
| NX7002BKMBYL       | 934068618315 | NX7002BKMB       |
| BZX384-C8V2,115    | 934057638115 | BZX384-C8V2      |
| BUK7J1R4-40HX      | 934660082115 | BUK7J1R4-40H     |
| HEF4050BT,653      | 933372930653 | HEF4050BT        |
| BZB84-C15,215      | 934061699215 | BZB84-C15        |

|                      |              |                 |
|----------------------|--------------|-----------------|
| 74LVC245AD,112       | 935211510112 | 74LVC245AD      |
| BZT52H-C18,115       | 934059408115 | BZT52H-C18      |
| PSMN2R0-60PS,127     | 934065168127 | PSMN2R0-60PS    |
| 74HC138D,653         | 933713400653 | 74HC138D        |
| "74HCT27PW,112"      | 935189580112 | 74HCT27PW       |
| 74HC4040BQ-Q100X     | 935303845115 | 74HC4040BQ-Q100 |
| 74AHCT157D,118       | 935264000118 | 74AHCT157D      |
| PMEG10020AELPX       | 934069175115 | PMEG10020AELP   |
| BUK9Y41-80E,115      | 934067032115 | BUK9Y41-80E     |
| PTVS54VS1UR,115      | 934061372115 | PTVS54VS1UR     |
| BCP53-10TX           | 934070115115 | BCP53-10T       |
| "74AUP2G06GW,125"    | 935279983125 | 74AUP2G06GW     |
| PSMN1R5-30YL,115     | 934064636115 | PSMN1R5-30YL    |
| BAV23C,215           | 934061767215 | BAV23C          |
| "74HC03D,652"        | 933748660652 | 74HC03D         |
| PZU14B2A,115         | 934062345115 | PZU14B2A        |
| BZV55-B13,115        | 933827780115 | BZV55-B13       |
| PBSS4220PANSX        | 934069679115 | PBSS4220PANS    |
| BZX84J-B4V3,115      | 934060965115 | BZX84J-B4V3     |
| BZX884-C8V2,315      | 934057221315 | BZX884-C8V2     |
| 74HC4515D,653        | 933730180653 | 74HC4515D       |
| 74HC273D-Q100J       | 935301455118 | 74HC273D-Q100   |
| PZU24B1,115          | 934059809115 | PZU24B1         |
| "74HCT08PW-Q100,118" | 935298754118 | 74HCT08PW-Q100  |
| 74AHCT595PW,118      | 935265560118 | 74AHCT595PW     |
| BZX384-C6V2,115      | 934057635115 | BZX384-C6V2     |
| 74AUP2G125GXX        | 935308442115 | 74AUP2G125GX    |
| "74HC166D,652"       | 933714550652 | 74HC166D        |
| BCX53-16,135         | 933674730135 | BCX53-16        |
| 74HCT597D,652        | 933757350652 | 74HCT597D       |
| PBSS2515MB,315       | 934065875315 | PBSS2515MB      |
| RB751V40,115         | 934061305115 | RB751V40        |
| BC846BM,315          | 934066322315 | BC846BM         |
| 74AVC4T774PWJ        | 935341328118 | 74AVC4T774PW    |
| BCX55-16,115         | 933674750115 | BCX55-16        |
| PBSS4021NT,215       | 934062761215 | PBSS4021NT      |
| PDTA114YU,115        | 934057545115 | PDTA114YU       |
| 74LVCH8T245PW,118    | 935290151118 | 74LVCH8T245PW   |
| 2PC4081R,115         | 934031760115 | 2PC4081R        |
| IP4234CZ6,115        | 934063369115 | IP4234CZ6       |
| 74LV595PW,112        | 935198290112 | 74LV595PW       |
| 74AHC2G08DP,125      | 935274676125 | 74AHC2G08DP     |
| BZX84-C30,215        | 933388330215 | BZX84-C30       |
| "74AUP2G04GW,125"    | 935279978125 | 74AUP2G04GW     |
| 74HC4094PW-Q100J     | 935300049118 | 74HC4094PW-Q100 |
| BAV99W,135           | 934026010135 | BAV99W          |



|                    |              |                 |
|--------------------|--------------|-----------------|
| 74AUP1T08GWH       | 935690048125 | 74AUP1T08GW     |
| PMEG2005EJ,115     | 934059001115 | PMEG2005EJ      |
| NZX27B,133         | 934062005133 | NZX27B          |
| BZT52H-C3V3,115    | 934059387115 | BZT52H-C3V3     |
| BCP54,115          | 933917180115 | BCP54           |
| BZX84-B47,215      | 933770500215 | BZX84-B47       |
| 74AUP2G32DC,125    | 935280713125 | 74AUP2G32DC     |
| BZV49-C33,115      | 933606080115 | BZV49-C33       |
| PDTD123YT,215      | 934058982215 | PDTD123YT       |
| HEF4053BTT,118     | 935263512118 | HEF4053BTT      |
| PSMN7R6-60PS,127   | 934064324127 | PSMN7R6-60PS    |
| PMEG6020AELPX      | 934069174115 | PMEG6020AELP    |
| BUK9M8R5-40HX      | 934660808115 | BUK9M8R5-40H    |
| PBSS5360ZX         | 934068208115 | PBSS5360Z       |
| PESD2IVN27-TR      | 934660307215 | PESD2IVN27-T    |
| CBT3257ADS,118     | 935275891118 | CBT3257ADS      |
| BC846S,125         | 934055429125 | BC846S          |
| "74HCT11D,652"     | 933714370652 | 74HCT11D        |
| BZX84-C4V7,235     | 933137380235 | BZX84-C4V7      |
| "74HC1G02GV,125"   | 935272031125 | 74HC1G02GV      |
| PDTA124XT,215      | 934057530215 | PDTA124XT       |
| PMEG2015EJ,115     | 934059005115 | PMEG2015EJ      |
| BC856,215          | 933589710215 | BC856           |
| 74LV07APWJ         | 935308208118 | 74LV07APW       |
| PMBD354,215        | 934057257215 | PMBD354         |
| 74HC259PW,118      | 935174690118 | 74HC259PW       |
| "74HCT4538D,112"   | 933715390112 | 74HCT4538D      |
| 74HC244PW-Q100,118 | 935298914118 | 74HC244PW-Q100  |
| PESD6V0L2UU,115    | 934062752115 | PESD6V0L2UU     |
| BZX84-C2V7,215     | 933516930215 | BZX84-C2V7      |
| 74AVCH4T245BQ,115  | 935284587115 | 74AVCH4T245BQ   |
| PIMH9,115          | 934056728115 | PIMH9           |
| 74AUP1G02GM,115    | 935279001115 | 74AUP1G02GM     |
| PMEG3010ET,215     | 934061049215 | PMEG3010ET      |
| PTVS33VP1UP,115    | 934064179115 | PTVS33VP1UP     |
| 74HCT245D,652      | 933713590652 | 74HCT245D       |
| 74LVC14APW-Q100J   | 935299274118 | 74LVC14APW-Q100 |
| PUMD3,115          | 934050170115 | PUMD3           |
| 74AHCT132PW,118    | 935262996118 | 74AHCT132PW     |
| 74AHC594BQ,115     | 935282022115 | 74AHC594BQ      |
| 74HCT4017BQ,115    | 935285358115 | 74HCT4017BQ     |
| BZX585-B24,115     | 934057408115 | BZX585-B24      |
| BZX585-B6V8,115    | 934055867115 | BZX585-B6V8     |
| 74HC4538D,653      | 933714910653 | 74HC4538D       |
| PTVS43VS1UTR,115   | 934065504115 | PTVS43VS1UTR    |
| BUK7607-55B,118    | 934057714118 | BUK7607-55B     |

|                   |              |                |
|-------------------|--------------|----------------|
| PTVS12VS1UR/8X    | 934660628115 | PTVS12VS1UR/8  |
| PH1430DLSX        | 934068229115 | PH1430DLS      |
| BZX84-B24,215     | 933770440215 | BZX84-B24      |
| 74HCT238D,653     | 933715120653 | 74HCT238D      |
| 74AHCT32PW,118    | 935262641118 | 74AHCT32PW     |
| BUK7Y15-60EX      | 934067439115 | BUK7Y15-60E    |
| 74HC4020PW,118    | 935188470118 | 74HC4020PW     |
| BCP53TX           | 934070114115 | BCP53T         |
| PMBT2907A,215     | 933821800215 | PMBT2907A      |
| BZX79-C24,133     | 933117880133 | BZX79-C24      |
| BZT52-B4V7X       | 934071151115 | BZT52-B4V7     |
| PMV50EPEAR        | 934068706215 | PMV50EPEA      |
| BSR43,115         | 933418100115 | BSR43          |
| 74AUP1G06GF,132   | 935281107132 | 74AUP1G06GF    |
| NX3008CBKV,115    | 934065634115 | NX3008CBKV     |
| BZX79-B22,113     | 933166950113 | BZX79-B22      |
| 74LVT245PW,118    | 935175550118 | 74LVT245PW     |
| 74HC540D,653      | 933715490653 | 74HC540D       |
| 74LV393PW,118     | 935198250118 | 74LV393PW      |
| 74LVC2245AD,118   | 935251290118 | 74LVC2245AD    |
| BCW61C,235        | 933324140235 | BCW61C         |
| 74AHCT245APWJ     | 935307876118 | 74AHCT245APW   |
| BAT46WH,115       | 934064495115 | BAT46WH        |
| CBT3244APW,118    | 935275527118 | CBT3244APW     |
| BC817RAPNZ        | 934070166147 | BC817RAPN      |
| PZU18BA,115       | 934062355115 | PZU18BA        |
| BZV55-C4V7,135    | 933699440135 | BZV55-C4V7     |
| "74AUP1G86GX,125" | 935298367125 | 74AUP1G86GX    |
| 74HC32D,652       | 933714310652 | 74HC32D        |
| PESD12VS1UB,115   | 934058512115 | PESD12VS1UB    |
| "74HC126PW,118"   | 935183560118 | 74HC126PW      |
| BUK761R6-40E,118  | 934066498118 | BUK761R6-40E   |
| PESD5V0L1UB,115   | 934063219115 | PESD5V0L1UB    |
| 74HCT11D-Q100J    | 935300062118 | 74HCT11D-Q100  |
| 74HC11D,653       | 933714290653 | 74HC11D        |
| BZX585-B7V5,115   | 934055868115 | BZX585-B7V5    |
| PHPT60606NYX      | 934068572115 | PHPT60606NY    |
| MMBT2222A,215     | 933545610215 | MMBT2222A      |
| BCM847BV,115      | 934059429115 | BCM847BV       |
| 74LV244DB,118     | 935073680118 | 74LV244DB      |
| PMV65ENEAR        | 934070123215 | PMV65ENEA      |
| BC857QASZ         | 934068723147 | BC857QAS       |
| BC807-40/DG/B4R   | 934068397215 | BC807-40/DG/B4 |
| BZT52-C51J        | 934071124118 | BZT52-C51      |
| 74HC32BQ,115      | 935273688115 | 74HC32BQ       |
| 74HC00D,653       | 933713360653 | 74HC00D        |

|                     |              |                   |
|---------------------|--------------|-------------------|
| PESD3V3S4UD,115     | 934059301115 | PESD3V3S4UD       |
| "CBT3125PW,118"     | 935270670118 | CBT3125PW         |
| PESD3V3S5UD,115     | 934058432115 | PESD3V3S5UD       |
| PBSS8110T,215       | 934057672215 | PBSS8110T         |
| BCW61B,215          | 933324130215 | BCW61B            |
| "74ABT08PW,118"     | 935207100118 | 74ABT08PW         |
| "74HCT4053D,112"    | 933715320112 | 74HCT4053D        |
| 74LV74D,118         | 935063300118 | 74LV74D           |
| BCP68-25,115        | 933969370115 | BCP68-25          |
| PBRN113ZT,215       | 934058987215 | PBRN113ZT         |
| PESD24VS1UB,115     | 934058514115 | PESD24VS1UB       |
| PMXB40UNEZ          | 934067145147 | PMXB40UNE         |
| BZV55-C5V6,115      | 933699460115 | BZV55-C5V6        |
| 74HCT74D,653        | 933713390653 | 74HCT74D          |
| PSMN0R9-25YLC,115   | 934065074115 | PSMN0R9-25YLC     |
| 74LVC1G07GX4Z       | 935690003147 | 74LVC1G07GX4      |
| 74HC595BQ,115       | 935273679115 | 74HC595BQ         |
| 74AHC123ABQ,115     | 935285424115 | 74AHC123ABQ       |
| PTVS8V5S1UR,115     | 934061345115 | PTVS8V5S1UR       |
| 74LVC2G3157GMX      | 935306576115 | 74LVC2G3157GM     |
| NX138AKVL           | 934070096235 | NX138AK           |
| 74LVC373APW,118     | 935218650118 | 74LVC373APW       |
| BAT120A,115         | 934051320115 | BAT120A           |
| BCV65,215           | 933831500215 | BCV65             |
| 74AHC2G125DC-Q100H  | 935301502125 | 74AHC2G125DC-Q100 |
| 74AHCT74D,118       | 935263076118 | 74AHCT74D         |
| "74CBTLV3126PW,118" | 935289344118 | 74CBTLV3126PW     |
| PMBT2222AMYL        | 934660374315 | PMBT2222AM        |
| PMEG2010AET,215     | 934061052215 | PMEG2010AET       |
| PESD3V3L5UY,115     | 934057802115 | PESD3V3L5UY       |
| PBSS302PZ,135       | 934059049135 | PBSS302PZ         |
| BAV199,235          | 934032640235 | BAV199            |
| PBSS4032PX,115      | 934063407115 | PBSS4032PX        |
| BC807,215           | 933589500215 | BC807             |
| PESD3V3S2UT,215     | 934058196215 | PESD3V3S2UT       |
| 74LVT16543ADGGS     | 935203040512 | 74LVT16543ADGG    |
| "74LV595D,112"      | 935181580112 | 74LV595D          |
| 74AHCT245BQ,115     | 935289108115 | 74AHCT245BQ       |
| 2PD1820AS,115       | 934042630115 | 2PD1820AS         |
| 74LV32APWJ          | 935690648118 | 74LV32APW         |
| PHPT610030NKX       | 934068168115 | PHPT610030NK      |
| 74LV244D,118        | 935056370118 | 74LV244D          |
| BUK9880-55A/CUX     | 934068291115 | BUK9880-55A/CU    |
| HEF40175BTT,118     | 935294421118 | HEF40175BTT       |
| PUMD3,165           | 934050170165 | PUMD3             |
| PTVS3V3S1UR/8X      | 934660639115 | PTVS3V3S1UR/8     |

|                    |              |                    |
|--------------------|--------------|--------------------|
| "74LVC1GU04GW,125" | 935268596125 | 74LVC1GU04GW       |
| "74HCT9046AD,112"  | 935044180112 | 74HCT9046AD        |
| PBSS2515VPN,115    | 934056713115 | PBSS2515VPN        |
| "74AUP1G86GW,125"  | 935279052125 | 74AUP1G86GW        |
| PMGD780SN,115      | 934057709115 | PMGD780SN          |
| IP4283CZ10-TBR,115 | 934065613115 | IP4283CZ10-TBR     |
| PUMH7,115          | 934055049115 | PUMH7              |
| 74HC245DB,118      | 935166910118 | 74HC245DB          |
| PMMT591A,215       | 934055114215 | PMMT591A           |
| 74LV1T02GWH        | 935690192125 | 74LV1T02GW         |
| 74LV4052DB,118     | 935174960118 | 74LV4052DB         |
| BAT54A,235         | 933976360235 | BAT54A             |
| 74AUP1G17GX4Z      | 935340117147 | 74AUP1G17GX4       |
| 74HC02BQ,115       | 935287795115 | 74HC02BQ           |
| BCX52,115          | 933272290115 | BCX52              |
| PDTC143TM,315      | 934057166315 | PDTC143TM          |
| 74HC32PW,118       | 935174750118 | 74HC32PW           |
| BAV23QAZ           | 934070979147 | BAV23QA            |
| BZX79-C47,133      | 933117950133 | BZX79-C47          |
| "74AUP2G14GM,132"  | 935279988132 | 74AUP2G14GM        |
| "74AHC574PW,112"   | 935263081112 | 74AHC574PW         |
| PSMN015-60BS,118   | 934066201118 | PSMN015-60BS       |
| 74LVC1G58GM,115    | 935277212115 | 74LVC1G58GM        |
| BZX884-B7V5,315    | 934057201315 | BZX884-B7V5        |
| PMMT591A,235       | 934055114235 | PMMT591A           |
| BAV103,135         | 933699360135 | BAV103             |
| 74LVC3G04DC,125    | 935275223125 | 74LVC3G04DC        |
| PMBT2222AQAZ       | 934660461147 | PMBT2222AQA        |
| 74LVC1G3157GW-Q10H | 935300245125 | 74LVC1G3157GW-Q100 |
| 74LVC2G53DP,125    | 935280383125 | 74LVC2G53DP        |
| 74AHC1G4212GW-Q10H | 935690496125 | 74AHC1G4212GW-Q100 |
| 74HCT132DB,118     | 935187300118 | 74HCT132DB         |
| BZX79-B16,133      | 933166920133 | BZX79-B16          |
| "74HC4067PW,112"   | 935189110112 | 74HC4067PW         |
| 74HCT257D,653      | 933713650653 | 74HCT257D          |
| 74HC32D-Q100,118   | 935298923118 | 74HC32D-Q100       |
| BAS40-04,235       | 933661850235 | BAS40-04           |
| PESD5V0U1BL,315    | 934060853315 | PESD5V0U1BL        |
| 74HCT3G34DP,125    | 935272157125 | 74HCT3G34DP        |
| "74HCT393D,652"    | 933714120652 | 74HCT393D          |
| PHPT61006PYX       | 934068575115 | PHPT61006PY        |
| PDTC124EM,315      | 934057175315 | PDTC124EM          |
| BZX884-B6V8,315    | 934057195315 | BZX884-B6V8        |
| BCX52-16,115       | 933674720115 | BCX52-16           |
| BZX79-B27,113      | 933166970113 | BZX79-B27          |
| PMEG4050ETP,115    | 934065472115 | PMEG4050ETP        |

|                      |              |                |
|----------------------|--------------|----------------|
| PDTB123TT,215        | 934059729215 | PDTB123TT      |
| TDZ11J,115           | 934065785115 | TDZ11J         |
| PBSS5330X,115        | 934058037115 | PBSS5330X      |
| PBSS4350T,215        | 934056604215 | PBSS4350T      |
| "74HC237D,652"       | 933757190652 | 74HC237D       |
| 74LV165APW,118       | 935273177118 | 74LV165APW     |
| "74HC08PW,118"       | 935174270118 | 74HC08PW       |
| PMEG40T20EPX         | 934070405115 | PMEG40T20EP    |
| BZB984-C6V2,115      | 934056723115 | BZB984-C6V2    |
| RB520S30,115         | 934063954115 | RB520S30       |
| "74LVT162374DGG,112" | 935264167112 | 74LVT162374DGG |
| "74HC574PW,112"      | 935187020112 | 74HC574PW      |
| BZX585-B5V1,115      | 934055864115 | BZX585-B5V1    |
| PZU4.7B2A,115        | 934062611115 | PZU4.7B2A      |
| 74HC595DB,118        | 935165210118 | 74HC595DB      |
| 1N4735A,133          | 933931610133 | 1N4735A        |
| BAS85,115            | 933876540115 | BAS85          |
| 74HC42D,652          | 933714860652 | 74HC42D        |
| PMEG6020AELRX        | 934068897115 | PMEG6020AELR   |
| 74HC2G16GVH          | 935307575125 | 74HC2G16GV     |
| BZV49-C22,115        | 933606040115 | BZV49-C22      |
| PBSS5350X,115        | 934055948115 | PBSS5350X      |
| 74HC273PW,118        | 935185830118 | 74HC273PW      |
| BAS28,215            | 933679170215 | BAS28          |
| 74LVC2G240DP,125     | 935272529125 | 74LVC2G240DP   |
| BZX79-C7V5,113       | 933117760113 | BZX79-C7V5     |
| 74LVC2G38DP,125      | 935274579125 | 74LVC2G38DP    |
| BZV55-C51,115        | 933699720115 | BZV55-C51      |
| "74HCT2G04GW,125"    | 935281025125 | 74HCT2G04GW    |
| BZX84-C2V4,235       | 933516920235 | BZX84-C2V4     |
| 74HCT4094D,118       | 933715330118 | 74HCT4094D     |
| 74LVC11PW-Q100J      | 935690355118 | 74LVC11PW-Q100 |
| PHPT610030PKX        | 934068171115 | PHPT610030PK   |
| BZV49-C27,115        | 933606060115 | BZV49-C27      |
| PESD1LIN,115         | 934058897115 | PESD1LIN       |
| BUK7M6R7-40HX        | 934660785115 | BUK7M6R7-40H   |
| PMEG4010CEGWJ        | 934070371118 | PMEG4010CEGW   |
| "74LVC2G08GT,115"    | 935278921115 | 74LVC2G08GT    |
| BZX84J-B27,115       | 934060947115 | BZX84J-B27     |
| 74HCT366D,653        | 933715160653 | 74HCT366D      |
| 74LVC4066BQ,115      | 935273744115 | 74LVC4066BQ    |
| PSMN015-100B,118     | 934055639118 | PSMN015-100B   |
| 74HC107D,653         | 933713920653 | 74HC107D       |
| 74HC00BQ,115         | 935273671115 | 74HC00BQ       |
| 74LVC1G175GV,125     | 935274947125 | 74LVC1G175GV   |
| BZX79-C22,133        | 933117870133 | BZX79-C22      |

|                      |              |                  |
|----------------------|--------------|------------------|
| PTVS15VS1UR,115      | 934061353115 | PTVS15VS1UR      |
| 74LVCH162244ADL:11   | 935238700118 | 74LVCH162244ADL  |
| BUK7Y53-100B,115     | 934063323115 | BUK7Y53-100B     |
| BZX84-C47,215        | 933388380215 | BZX84-C47        |
| "74AUP1G08GX,125"    | 935298227125 | 74AUP1G08GX      |
| 74HC4351DB,118       | 935190070118 | 74HC4351DB       |
| BZX84-A20,215        | 934054975215 | BZX84-A20        |
| BZT52-C27J           | 934071136118 | BZT52-C27        |
| "74LVC1G175GW,125"   | 935274948125 | 74LVC1G175GW     |
| "74LVC1G66GW-Q100,1" | 935299068125 | 74LVC1G66GW-Q100 |
| PESD4V0W1BCSFYL      | 934660197315 | PESD4V0W1BCSF    |
| PMPB24EPX            | 934660839115 | PMPB24EP         |
| BZB84-B4V3,215       | 934061707215 | BZB84-B4V3       |
| 74HCT14D,653         | 933714440653 | 74HCT14D         |
| PSMN014-40YS,115     | 934064146115 | PSMN014-40YS     |
| PDZ33BGWX            | 934071046115 | PDZ33BGW         |
| 74AVC4TD245GU,115    | 935294168115 | 74AVC4TD245GU    |
| 74HC154D,653         | 933713820653 | 74HC154D         |
| 74HCT367D,653        | 933715170653 | 74HCT367D        |
| 74LVC1G04GF,132      | 935282404132 | 74LVC1G04GF      |
| BZX884-C15,315       | 934057228315 | BZX884-C15       |
| 74HC132D-Q100,118    | 935298737118 | 74HC132D-Q100    |
| BZX84-C3V3,235       | 933516950235 | BZX84-C3V3       |
| "74LVC1G79GX,125"    | 935298383125 | 74LVC1G79GX      |
| BAS70-04,215         | 934020800215 | BAS70-04         |
| "74HC4050D,652"      | 933714810652 | 74HC4050D        |
| HEF40098BT,652       | 933373410652 | HEF40098BT       |
| BC817-25QAZ          | 934067156147 | BC817-25QA       |
| BUK7M21-40EX         | 934070087115 | BUK7M21-40E      |
| GAN063-650WSAQ       | 934660022127 | GAN063-650WSA    |
| PUMD14,115           | 934058905115 | PUMD14           |
| 74AHCT2G125DP,125    | 935274675125 | 74AHCT2G125DP    |
| BCP56-10TX           | 934070118115 | BCP56-10T        |
| 74HCT4051D,118       | 933715300118 | 74HCT4051D       |
| BAT854AW,115         | 934056165115 | BAT854AW         |
| PZU3.3B2A,115        | 934062473115 | PZU3.3B2A        |
| BC817-40QAZ          | 934067158147 | BC817-40QA       |
| 74HCT11D,653         | 933714370653 | 74HCT11D         |
| PSMN7R0-100BS,118    | 934066207118 | PSMN7R0-100BS    |
| 74AUP1G58GXZ         | 935307122147 | 74AUP1G58GX      |
| BZV55-C5V6,135       | 933699460135 | BZV55-C5V6       |
| BCV61B,215           | 933792110215 | BCV61B           |
| 74AVCH2T45DC,125     | 935283721125 | 74AVCH2T45DC     |
| 2N7002P,215          | 934064132215 | 2N7002P          |
| 74LVC138AD,118       | 935260745118 | 74LVC138AD       |
| 74HCT132D,653        | 933714140653 | 74HCT132D        |

|                   |              |               |
|-------------------|--------------|---------------|
| PZU12B2,115       | 934059828115 | PZU12B2       |
| BZV55-B5V1,115    | 933827680115 | BZV55-B5V1    |
| BSR16,215         | 933508400215 | BSR16         |
| 74HCT393D,653     | 933714120653 | 74HCT393D     |
| PESD24VF1BSFYL    | 934068024315 | PESD24VF1BSF  |
| PMBT3906,215      | 933776010215 | PMBT3906      |
| BZX79-C2V7,143    | 933298820143 | BZX79-C2V7    |
| BZT52-C22X        | 934071134115 | BZT52-C22     |
| 74LVC139D,118     | 935195990118 | 74LVC139D     |
| 74LVC2G125DC,125  | 935274507125 | 74LVC2G125DC  |
| BCX70H,235        | 933478930235 | BCX70H        |
| 74AXP1G97GMH      | 935301603125 | 74AXP1G97GM   |
| PTVS12VU1UPAZ     | 934068081147 | PTVS12VU1UPA  |
| BZX79-C10,133     | 933117790133 | BZX79-C10     |
| 74HC4017PW,118    | 935189080118 | 74HC4017PW    |
| PMZB350UPE,315    | 934066841315 | PMZB350UPE    |
| PSMN4R5-30YLC,115 | 934065073115 | PSMN4R5-30YLC |
| BSH202,215        | 934054718215 | BSH202        |
| PMEG3005EJ,115    | 934059002115 | PMEG3005EJ    |
| BZX84J-C7V5,115   | 934061019115 | BZX84J-C7V5   |
| 74HC240DB,118     | 935188630118 | 74HC240DB     |
| BZX84-C10,235     | 933137460235 | BZX84-C10     |
| PZU6.8B,115       | 934059754115 | PZU6.8B       |
| PDTA113ZT,215     | 934058195215 | PDTA113ZT     |
| BC51PA,115        | 934065814115 | BC51PA        |
| PCMF3HDMI14SZ     | 934070711087 | PCMF3HDMI14S  |
| PMEG4010EH,115    | 934059032115 | PMEG4010EH    |
| 74AUP1T86GWH      | 935690102125 | 74AUP1T86GW   |
| 74LVC594AD,118    | 935282444118 | 74LVC594AD    |
| 74CB3Q3257PWJ     | 935339459118 | 74CB3Q3257PW  |
| 74HCT165BQ,115    | 935286074115 | 74HCT165BQ    |
| PESD3V3Z1BCSFYL   | 934660541315 | PESD3V3Z1BCSF |
| 74HCT251D,653     | 933713530653 | 74HCT251D     |
| BZX884-B47,315    | 934057449315 | BZX884-B47    |
| PMEG4005ET,215    | 934059428215 | PMEG4005ET    |
| PSMN013-80YS,115  | 934063934115 | PSMN013-80YS  |
| PTVS26VZ1USKYL    | 934069214315 | PTVS26VZ1USK  |
| PHB29N08T,118     | 934057125118 | PHB29N08T     |
| BAV21,113         | 933189210113 | BAV21         |
| 74LVC1G58GF,132   | 935282424132 | 74LVC1G58GF   |
| BZV85-C6V8,133    | 933500610133 | BZV85-C6V8    |
| "74LVC3G14GT,115" | 935278934115 | 74LVC3G14GT   |
| PEMD48,115        | 934056708115 | PEMD48        |
| BC847BS,115       | 934042520115 | BC847BS       |
| BZT52H-B10,115    | 934064794115 | BZT52H-B10    |
| MJD44H11AJ        | 934660551118 | MJD44H11A     |

|                    |              |                    |
|--------------------|--------------|--------------------|
| PMV100XPEAR        | 934068707215 | PMV100XPEA         |
| "74AHCT1G79GW,125" | 935263007125 | 74AHCT1G79GW       |
| 74AXP1G04GXH       | 935304057125 | 74AXP1G04GX        |
| BZT52-C39X         | 934071121115 | BZT52-C39          |
| "74ABT04D,112"     | 935206990112 | 74ABT04D           |
| "74HCT390D,652"    | 933715200652 | 74HCT390D          |
| BC817-25W,115      | 934021930115 | BC817-25W          |
| 74HC7541PW,118     | 935295962118 | 74HC7541PW         |
| 74HCT4020D,653     | 933715250653 | 74HCT4020D         |
| "74HC193D,652"     | 933714620652 | 74HC193D           |
| 74HC590PW,118      | 935278836118 | 74HC590PW          |
| PMV20ENR           | 934068497215 | PMV20EN            |
| 74ALVC573PW,118    | 935269736118 | 74ALVC573PW        |
| 74AHC123AD,118     | 935265563118 | 74AHC123AD         |
| 74AUP1G58GM,115    | 935279961115 | 74AUP1G58GM        |
| BAV23S,215         | 933947770215 | BAV23S             |
| 74AUP1G08GW-Q100H  | 935300359125 | 74AUP1G08GW-Q100   |
| PUMD48,115         | 934055444115 | PUMD48             |
| BAV99,235          | 933215370235 | BAV99              |
| HEF4043BT,653      | 933372880653 | HEF4043BT          |
| 74AVCH16T245DGG,18 | 935286233118 | 74AVCH16T245DGG    |
| PESD15VS1ULD,315   | 934065312315 | PESD15VS1ULD       |
| 74LV00DB,118       | 935170130118 | 74LV00DB           |
| 74AUP1G32GM,115    | 935279027115 | 74AUP1G32GM        |
| 74LV245PW,118      | 935174660118 | 74LV245PW          |
| "74ABT125PW,118"   | 935201060118 | 74ABT125PW         |
| 74HCT125PW,118     | 935187290118 | 74HCT125PW         |
| PTVS22VS1UTR,115   | 934065494115 | PTVS22VS1UTR       |
| 74HCT125PW,112     | 935187290112 | 74HCT125PW         |
| BUK7275-100A,118   | 934056484118 | BUK7275-100A       |
| PESD3V3L4UF,115    | 934061194115 | PESD3V3L4UF        |
| PESD18VF1BSFYL     | 934067603315 | PESD18VF1BSF       |
| 74HC2G14GV,125     | 935281019125 | 74HC2G14GV         |
| 74CBTLV3126PW-Q10J | 935300956118 | 74CBTLV3126PW-Q100 |
| BUK7Y28-75B,115    | 934063303115 | BUK7Y28-75B        |
| PDTA123YT,215      | 934058187215 | PDTA123YT          |
| BZV55-C18,115      | 933699580115 | BZV55-C18          |
| BZX84-A51,215      | 934054974215 | BZX84-A51          |
| PDTC114ET,215      | 934031010215 | PDTC114ET          |
| BZT52-B75X         | 934071173115 | BZT52-B75          |
| 74HC4520PW,118     | 935189130118 | 74HC4520PW         |
| BZX79-C27,113      | 933117890113 | BZX79-C27          |
| PDZ22B,115         | 934054867115 | PDZ22B             |
| 74AHCT14BQ,115     | 935273734115 | 74AHCT14BQ         |
| PDTC123YU,115      | 934058797115 | PDTC123YU          |
| BC857CW,135        | 934021860135 | BC857CW            |



|                      |              |                 |
|----------------------|--------------|-----------------|
| BZX384-B30,115       | 934057384115 | BZX384-B30      |
| BZX79-C2V4,133       | 933414680133 | BZX79-C2V4      |
| HEF4541BT-Q100Y      | 935302266518 | HEF4541BT-Q100  |
| 74HC244D,653         | 933713420653 | 74HC244D        |
| 74HCT244DB,118       | 935166880118 | 74HCT244DB      |
| 74LVT573DB,118       | 935170710118 | 74LVT573DB      |
| "74HCT595PW,112"     | 935200990112 | 74HCT595PW      |
| PZU16B,115           | 934059771115 | PZU16B          |
| BZX84-C10,215        | 933137460215 | BZX84-C10       |
| PMEG050V030EPDZ      | 934070193146 | PMEG050V030EPD  |
| 74HC163PW,118        | 935187350118 | 74HC163PW       |
| PSMN1R0-30YLDX       | 934068234115 | PSMN1R0-30YLD   |
| PDTC143XT,215        | 934055052215 | PDTC143XT       |
| PMEG6002EJ,115       | 934063241115 | PMEG6002EJ      |
| BZX884-B4V7,315      | 934057191315 | BZX884-B4V7     |
| "74LVT16245BDGG,112" | 935203000112 | 74LVT16245BDGG  |
| PBSS5580PA,115       | 934063925115 | PBSS5580PA      |
| BZX585-B10,115       | 934055871115 | BZX585-B10      |
| 74HC4067PW,118       | 935189110118 | 74HC4067PW      |
| PBSS8110D,115        | 934057979115 | PBSS8110D       |
| PDZ8.2BGWJ           | 934071039118 | PDZ8.2BGW       |
| "74AHC1GU04GV,125"   | 935271674125 | 74AHC1GU04GV    |
| PEMH7,115            | 934056863115 | PEMH7           |
| 74HC4060DB-Q100J     | 935301533118 | 74HC4060DB-Q100 |
| 74LVC1G58GV,125      | 935276074125 | 74LVC1G58GV     |
| BZT52H-B22,115       | 934064803115 | BZT52H-B22      |
| 74HCT245DB,118       | 935166900118 | 74HCT245DB      |
| BZX84J-B7V5,115      | 934060978115 | BZX84J-B7V5     |
| BZT52-C56X           | 934071137115 | BZT52-C56       |
| "74HCT366D,652"      | 933715160652 | 74HCT366D       |
| "74ABT245D,602"      | 935027530602 | 74ABT245D       |
| "74AHCT14D,112"      | 935262760112 | 74AHCT14D       |
| BZX384-C68,115       | 934057660115 | BZX384-C68      |
| BSP33,115            | 933981990115 | BSP33           |
| 74AHC126D,118        | 935262768118 | 74AHC126D       |
| PSMN4R0-30YL,115     | 934063074115 | PSMN4R0-30YL    |
| NZX4V7C,133          | 934062022133 | NZX4V7C         |
| 74CBTLV3253BQ,115    | 935289997115 | 74CBTLV3253BQ   |
| 74LVC2G17GV,125      | 935273319125 | 74LVC2G17GV     |
| 74LVCU04AD,118       | 935260740118 | 74LVCU04AD      |
| PMEG2020EJF          | 934058256135 | PMEG2020EJ      |
| PBSS5320X,135        | 934057106135 | PBSS5320X       |
| BZX84-C15,235        | 933388260235 | BZX84-C15       |
| 74LVC4066PW,118      | 935273718118 | 74LVC4066PW     |
| BCX55-10,115         | 933663080115 | BCX55-10        |
| PEMB9,315            | 934057047315 | PEMB9           |

|                      |              |                   |
|----------------------|--------------|-------------------|
| MMBTA92,215          | 934055964215 | MMBTA92           |
| 74LVC4245APW-Q100J   | 935305303118 | 74LVC4245APW-Q100 |
| 2N7002CKVL           | 934063611235 | 2N7002CK          |
| 74HCT4067PW,118      | 935193260118 | 74HCT4067PW       |
| PEMD3,115            | 934056771115 | PEMD3             |
| BAS321,135           | 934055352135 | BAS321            |
| PESD5V0S1BB,115      | 934058005115 | PESD5V0S1BB       |
| 74HC03D,653          | 933748660653 | 74HC03D           |
| 74LVC1G32GW-Q100H    | 935299291125 | 74LVC1G32GW-Q100  |
| 74LVC04ADB,118       | 935242410118 | 74LVC04ADB        |
| 74HCT109D,653        | 933714960653 | 74HCT109D         |
| PBHV8540X,115        | 934061418115 | PBHV8540X         |
| NZH3V9B,115          | 934064355115 | NZH3V9B           |
| 74HC1G66GW-Q100H     | 935299993125 | 74HC1G66GW-Q100   |
| BZX84J-C75,115       | 934061018115 | BZX84J-C75        |
| BUK7Y2R5-40HX        | 934660084115 | BUK7Y2R5-40H      |
| BUK9610-100B,118     | 934057115118 | BUK9610-100B      |
| 74HCT153D,653        | 933714060653 | 74HCT153D         |
| BZV85-C20,113        | 933500720113 | BZV85-C20         |
| PBHV9540Z,115        | 934063483115 | PBHV9540Z         |
| PSMN034-100PS,127    | 934064325127 | PSMN034-100PS     |
| "74AHCT1G14GW,125"   | 935263008125 | 74AHCT1G14GW      |
| 74LVC2G240DC,125     | 935274508125 | 74LVC2G240DC      |
| PMEG4005CT,215       | 934061753215 | PMEG4005CT        |
| BC817DPN,115         | 934057320115 | BC817DPN          |
| BC848W,115           | 934022060115 | BC848W            |
| PMEG2005EB,115       | 934057301115 | PMEG2005EB        |
| PDTC123JT,235        | 934054698235 | PDTC123JT         |
| BAW56,215            | 933098990215 | BAW56             |
| PEMZ7,115            | 934056714115 | PEMZ7             |
| "74LVC1G17GV-Q100,1" | 935298482125 | 74LVC1G17GV-Q100  |
| NPIC6C596APW-Q100J   | 935302417118 | NPIC6C596APW-Q100 |
| 2PD601BSL,215        | 934064713215 | 2PD601BSL         |
| BZX585-B2V4,115      | 934055856115 | BZX585-B2V4       |
| "74AUP1G132GW,125"   | 935279058125 | 74AUP1G132GW      |
| 74LVC1G175GV-Q100H   | 935301506125 | 74LVC1G175GV-Q100 |
| BC857BMB,315         | 934065889315 | BC857BMB          |
| 74HC374DB,112        | 935174890112 | 74HC374DB         |
| BC846,215            | 933589540215 | BC846             |
| PBLS6004D,115        | 934059267115 | PBLS6004D         |
| PMEG2010AEB,115      | 934057757115 | PMEG2010AEB       |
| "74AUP1G157GM,132"   | 935279971132 | 74AUP1G157GM      |
| 74AHC1G125GW-Q100H   | 935299236125 | 74AHC1G125GW-Q100 |
| 74HCT595BQ,115       | 935273733115 | 74HCT595BQ        |
| BZX84J-B20,115       | 934060944115 | BZX84J-B20        |
| 74HCT573DB,118       | 935186980118 | 74HCT573DB        |

|                   |              |                |
|-------------------|--------------|----------------|
| 74HC3G14DC,125    | 935274768125 | 74HC3G14DC     |
| BAW56SRAZ         | 934070159147 | BAW56SRA       |
| 74LVC16374ADL,118 | 935235180118 | 74LVC16374ADL  |
| 74CBTLV3126DS,118 | 935289343118 | 74CBTLV3126DS  |
| PSMN8R5-100PSQ    | 934067376127 | PSMN8R5-100PS  |
| 74AHC1G4212GWH    | 935307171125 | 74AHC1G4212GW  |
| "74HC4538PW,112"  | 935187530112 | 74HC4538PW     |
| 2N7002NXAKR       | 934661281215 | 2N7002NXAK     |
| 74AUP1Z125GM,115  | 935280525115 | 74AUP1Z125GM   |
| "74HC191D,652"    | 933714600652 | 74HC191D       |
| BZX84-C3V0,215    | 933516940215 | BZX84-C3V0     |
| BZX585-C16,115    | 934057421115 | BZX585-C16     |
| BZT52-C15J        | 934071129118 | BZT52-C15      |
| 1N4740A,113       | 933931660113 | 1N4740A        |
| BZB984-C2V4,115   | 934057231115 | BZB984-C2V4    |
| BUK7K15-80EX      | 934660014115 | BUK7K15-80E    |
| TL431AQDBZR,215   | 935288022215 | TL431AQDBZR    |
| PESD3V3L4UW,115   | 934057791115 | PESD3V3L4UW    |
| PHP28NQ15T,127    | 934059074127 | PHP28NQ15T     |
| MMBZ12VDL,215     | 934061803215 | MMBZ12VDL      |
| "74ABT32PW,112"   | 935208720112 | 74ABT32PW      |
| 74LVC3G06DC,125   | 935275555125 | 74LVC3G06DC    |
| PUMH16,115        | 934057897115 | PUMH16         |
| PTVS11VP1UP,115   | 934064164115 | PTVS11VP1UP    |
| "74HCT595D,112"   | 935009180112 | 74HCT595D      |
| PESD15VS2UT,215   | 934057611215 | PESD15VS2UT    |
| BC817-40,235      | 933628640235 | BC817-40       |
| 74AXP1G17GXH      | 935304105125 | 74AXP1G17GX    |
| 74AUP2G02GS,115   | 935292369115 | 74AUP2G02GS    |
| PMEG3002TV,115    | 934059631115 | PMEG3002TV     |
| "74AHCT74D,112"   | 935263076112 | 74AHCT74D      |
| BCM857BV,115      | 934059435115 | BCM857BV       |
| BAS28,235         | 933679170235 | BAS28          |
| BZX84J-B13,115    | 934060939115 | BZX84J-B13     |
| PSMN3R3-80BS,118  | 934065177118 | PSMN3R3-80BS   |
| BUK6D43-60EX      | 934660212115 | BUK6D43-60E    |
| BUK9Y2R4-40HX     | 934660365115 | BUK9Y2R4-40H   |
| PESD2V0YS-SFYL    | 934661158315 | PESD2V0YS-SF   |
| 74HCT240D,653     | 933713450653 | 74HCT240D      |
| PMEG4005EJ,115    | 934059003115 | PMEG4005EJ     |
| HEF4555BT-Q100J   | 935302272118 | HEF4555BT-Q100 |
| PBSS4130T,215     | 934057985215 | PBSS4130T      |
| "74HC14PW,118"    | 935183530118 | 74HC14PW       |
| 74LVC3G06DP,125   | 935275556125 | 74LVC3G06DP    |
| PXTA92,115        | 933926800115 | PXTA92         |
| BAS70-07S,115     | 934045840115 | BAS70-07S      |

|                     |              |                |
|---------------------|--------------|----------------|
| "74LV14PW,118"      | 935175230118 | 74LV14PW       |
| BAS16QAZ            | 934069885147 | BAS16QA        |
| BUK7K6R2-40EX       | 934067808115 | BUK7K6R2-40E   |
| PMV250EPEAR         | 934067624215 | PMV250EPEA     |
| BAT54J,115          | 934060934115 | BAT54J         |
| 74LVC132APW,112     | 935282823112 | 74LVC132APW    |
| BAT854SW,115        | 934056175115 | BAT854SW       |
| PSMN5R6-60YLX       | 934069895115 | PSMN5R6-60YL   |
| 74LVC1G126GXH       | 935298387125 | 74LVC1G126GX   |
| 74HC4316PW,112      | 935186960112 | 74HC4316PW     |
| BUK7M67-60EX        | 934070042115 | BUK7M67-60E    |
| PSMN8R2-80YS,115    | 934063935115 | PSMN8R2-80YS   |
| PMBTA44,215         | 934061413215 | PMBTA44        |
| PMEG2020EPASX       | 934068149115 | PMEG2020EPAS   |
| BZB84-B2V4,215      | 934061701215 | BZB84-B2V4     |
| PDTD123ET,215       | 934058977215 | PDTD123ET      |
| 74HC4066D,653       | 933714420653 | 74HC4066D      |
| PSMN2R5-30YL,115    | 934063071115 | PSMN2R5-30YL   |
| "74HC257D,652"      | 933713640652 | 74HC257D       |
| PZU9.1BA,115        | 934062807115 | PZU9.1BA       |
| BZX585-C3V9,115     | 934055841115 | BZX585-C3V9    |
| "74HC08PW-Q100,118" | 935298751118 | 74HC08PW-Q100  |
| PDZ10B,115          | 934054859115 | PDZ10B         |
| BUK9K29-100E,115    | 934066975115 | BUK9K29-100E   |
| "74LVC04AD,112"     | 935242400112 | 74LVC04AD      |
| 1N4734A,113         | 933931600113 | 1N4734A        |
| "74HC4002D,652"     | 933714320652 | 74HC4002D      |
| 74HCT139D,653       | 933713510653 | 74HCT139D      |
| BZX79-C8V2,113      | 933117770113 | BZX79-C8V2     |
| BZV85-C7V5,113      | 933500620113 | BZV85-C7V5     |
| PSMN3R4-30BL,118    | 934066329118 | PSMN3R4-30BL   |
| PBSS4041PZ,115      | 934063396115 | PBSS4041PZ     |
| BAS16L,315          | 934057247315 | BAS16L         |
| 74HC138BQ,115       | 935273778115 | 74HC138BQ      |
| BZV85-C6V8,113      | 933500610113 | BZV85-C6V8     |
| BZV85-C5V6,133      | 933500590133 | BZV85-C5V6     |
| IP4369CX4-H500,315  | 934066484315 | IP4369CX4-H500 |
| 74HCT2G66DP,125     | 935272944125 | 74HCT2G66DP    |
| "74LVC32APW,112"    | 935250080112 | 74LVC32APW     |
| "74AHC14D,112"      | 935262758112 | 74AHC14D       |
| 74HC377D,653        | 933713980653 | 74HC377D       |
| 74AVCH8T245BQ,118   | 935284592118 | 74AVCH8T245BQ  |
| IP4369CX4YL         | 934067403315 | IP4369CX4      |
| 74AHCT541D,118      | 935261963118 | 74AHCT541D     |
| PESD3V3S1UB,115     | 934058509115 | PESD3V3S1UB    |
| BZT52H-C27,115      | 934059413115 | BZT52H-C27     |

|                    |              |                 |
|--------------------|--------------|-----------------|
| PDZ36B,115         | 934054872115 | PDZ36B          |
| BZX84J-C39,115     | 934060999115 | BZX84J-C39      |
| 74HCT00DB,118      | 935174130118 | 74HCT00DB       |
| HEF40106BT,653     | 933406960653 | HEF40106BT      |
| "74HCT4066PW,118"  | 935187510118 | 74HCT4066PW     |
| 74HCT4094D-Q100J   | 935300071118 | 74HCT4094D-Q100 |
| PBLS4003Y,115      | 934058646115 | PBLS4003Y       |
| BZV49-C20,115      | 933606030115 | BZV49-C20       |
| 74HC373DB,118      | 935174840118 | 74HC373DB       |
| BZX384-B51,115     | 934057390115 | BZX384-B51      |
| "74LVC07APW,118"   | 935265482118 | 74LVC07APW      |
| 74HC7541DB,118     | 935190300118 | 74HC7541DB      |
| PESD5V0S2BQAZ      | 934069538147 | PESD5V0S2BQA    |
| BSS138BKS,115      | 934065728115 | BSS138BKS       |
| BC52PA,115         | 934065817115 | BC52PA          |
| BC817K-25HVL       | 934660224235 | BC817K-25H      |
| 74HCT4066BQ,115    | 935273727115 | 74HCT4066BQ     |
| 74HCT4851PW,118    | 935285731118 | 74HCT4851PW     |
| PTVS18VS1UR,115    | 934061356115 | PTVS18VS1UR     |
| PBSS4140T,215      | 934056515215 | PBSS4140T       |
| BUK9222-55A,118    | 934056697118 | BUK9222-55A     |
| BZX84-A43,215      | 934054973215 | BZX84-A43       |
| PBLS1503Y,115      | 934058054115 | PBLS1503Y       |
| 74HCT373D,652      | 933715580652 | 74HCT373D       |
| "74LVTH125PW,112"  | 935281723112 | 74LVTH125PW     |
| 74LVC161PW,118     | 935210530118 | 74LVC161PW      |
| BC847BS,135        | 934042520135 | BC847BS         |
| 2N7002PS,125       | 934064134125 | 2N7002PS        |
| "74AHC123AD,112"   | 935265563112 | 74AHC123AD      |
| 74AUP1T14GWH       | 935690085125 | 74AUP1T14GW     |
| PSMN1R7-60BS,118   | 934065175118 | PSMN1R7-60BS    |
| BUK9624-55A,118    | 934056287118 | BUK9624-55A     |
| BZX84-A10,215      | 933958270215 | BZX84-A10       |
| BZA956A,115        | 934056529115 | BZA956A         |
| PZU6.2B2,115       | 934059821115 | PZU6.2B2        |
| 74AVCH16245DGG,118 | 935266779118 | 74AVCH16245DGG  |
| "74AVCH2T45GT,115" | 935283722115 | 74AVCH2T45GT    |
| BAS116GWX          | 934070361115 | BAS116GW        |
| TDZ6V8J,115        | 934065716115 | TDZ6V8J         |
| 74HCT574D,653      | 933715630653 | 74HCT574D       |
| HEF4794BT,118      | 935069140118 | HEF4794BT       |
| BUK9628-100A,118   | 934055884118 | BUK9628-100A    |
| PMEG45T15EPDAZ     | 934069546146 | PMEG45T15EPD    |
| 74HCT573D,653      | 933713570653 | 74HCT573D       |
| "74HC423D,652"     | 933714870652 | 74HC423D        |
| PDTA124EU,135      | 934044110135 | PDTA124EU       |

|                     |              |                  |
|---------------------|--------------|------------------|
| BZX79-C6V8,133      | 933117750133 | BZX79-C6V8       |
| PDZ15BGWX           | 934071052115 | PDZ15BGW         |
| "74LVC1G32GX,125"   | 935298226125 | 74LVC1G32GX      |
| 74HC574PW,118       | 935187020118 | 74HC574PW        |
| 74HC245D,652        | 933713580652 | 74HC245D         |
| BF621,115           | 933659270115 | BF621            |
| BZT52-B3V9X         | 934071148115 | BZT52-B3V9       |
| BCP56-16TX          | 934070119115 | BCP56-16T        |
| 74HC273PW-Q100J     | 935301456118 | 74HC273PW-Q100   |
| PTVS33VS1UTR,115    | 934065501115 | PTVS33VS1UTR     |
| "74LVC4245APW,112"  | 935260751112 | 74LVC4245APW     |
| "74HC164PW,118"     | 935187370118 | 74HC164PW        |
| 74AHCV17APWJ        | 935330431118 | 74AHCV17APW      |
| BZT52-C3V6X         | 934071104115 | BZT52-C3V6       |
| NX3020NAK,215       | 934067059215 | NX3020NAK        |
| IP4786CZ32Y         | 934064725518 | IP4786CZ32       |
| PDZ7.5BGWJ          | 934071038118 | PDZ7.5BGW        |
| 74AHCT138PW,118     | 935262998118 | 74AHCT138PW      |
| BZX585-C6V2,115     | 934055846115 | BZX585-C6V2      |
| PESD6V5C1USFYL      | 934660138315 | PESD6V5C1USF     |
| PEMD12,315          | 934056859315 | PEMD12           |
| 74HC154BQ,118       | 935275416118 | 74HC154BQ        |
| "74ABT125D,602"     | 935056850602 | 74ABT125D        |
| 74AHC138PW-Q100J    | 935300183118 | 74AHC138PW-Q100  |
| "74HCT174D,652"     | 933715050652 | 74HCT174D        |
| PMEG4020EPASX       | 934068154115 | PMEG4020EPAS     |
| BZX585-C6V8,135     | 934055847135 | BZX585-C6V8      |
| BUK9Y25-60E/DMANX   | 934661401115 | BUK9Y25-60E/DMAN |
| BUK9275-100A,118    | 934056253118 | BUK9275-100A     |
| "74HC74PW-Q100,118" | 935298882118 | 74HC74PW-Q100    |
| BZX384-C30,115      | 934057651115 | BZX384-C30       |
| BAS321/8X           | 934660131115 | BAS321/8         |
| PSMN012-80BS,118    | 934066204118 | PSMN012-80BS     |
| NX7002AKVL          | 934066291235 | NX7002AK         |
| 74AHC595PW,118      | 935265568118 | 74AHC595PW       |
| BC847BPN,135        | 934042530135 | BC847BPN         |
| 74HC138DB,118       | 935174410118 | 74HC138DB        |
| PUMB30,115          | 934059933115 | PUMB30           |
| PDTA114EU,135       | 934043510135 | PDTA114EU        |
| BZX884-B36,315      | 934057446315 | BZX884-B36       |
| BAS116H,115         | 934059308115 | BAS116H          |
| PBSS4032PT,215      | 934062766215 | PBSS4032PT       |
| 74AHC02BQ,115       | 935285538115 | 74AHC02BQ        |
| BZX79-C3V9,133      | 933117690133 | BZX79-C3V9       |
| BCP53-16TF          | 934070116135 | BCP53-16T        |
| "74AHC04PW,112"     | 935263041112 | 74AHC04PW        |

|                    |              |                  |
|--------------------|--------------|------------------|
| BC857C,215         | 933769900215 | BC857C           |
| MMBZ5V6AL,215      | 934063462215 | MMBZ5V6AL        |
| BZX84-C3V9,215     | 933516970215 | BZX84-C3V9       |
| "74HC126D,652"     | 933757030652 | 74HC126D         |
| "74LVC1G386GW,125" | 935274997125 | 74LVC1G386GW     |
| 74LVT244BPW,118    | 935262793118 | 74LVT244BPW      |
| PDTC114TU,115      | 934044080115 | PDTC114TU        |
| 1N4728A,113        | 933931540113 | 1N4728A          |
| "74LVC1T45GM,132"  | 935284752132 | 74LVC1T45GM      |
| 74HC123PW,118      | 935186860118 | 74HC123PW        |
| HEF4077BT,652      | 933373070652 | HEF4077BT        |
| PDZ2.7B,115        | 934054843115 | PDZ2.7B          |
| NX1029X,115        | 934065643115 | NX1029X          |
| 74HC14D,653        | 933714400653 | 74HC14D          |
| BCV61C,215         | 933792120215 | BCV61C           |
| 74AHC00D,118       | 935262686118 | 74AHC00D         |
| BZT52-C62J         | 934071138118 | BZT52-C62        |
| "74HC153D,652"     | 933714050652 | 74HC153D         |
| BUK9K134-100EX     | 934067943115 | BUK9K134-100E    |
| HEF4014BT,653      | 933372670653 | HEF4014BT        |
| "74HC7540D,112"    | 933967860112 | 74HC7540D        |
| 74AHCT244D,118     | 935261957118 | 74AHCT244D       |
| PSMN4R0-30YLDX     | 934067796115 | PSMN4R0-30YLD    |
| PMEG4010CEH,115    | 934061055115 | PMEG4010CEH      |
| 74HCT273PW,118     | 935185820118 | 74HCT273PW       |
| BCM847BS,115       | 934058507115 | BCM847BS         |
| PMPB48EPAX         | 934070933115 | PMPB48EPA        |
| 74HCT74BQ,115      | 935273615115 | 74HCT74BQ        |
| "74HCT02PW,118"    | 935186240118 | 74HCT02PW        |
| PESD1IVN27-UX      | 934070276115 | PESD1IVN27-U     |
| "74HC75D,652"      | 933714940652 | 74HC75D          |
| 74LV1T08GWH        | 935690116125 | 74LV1T08GW       |
| PZT2222A,115       | 933975330115 | PZT2222A         |
| BZT52-B15J         | 934071175118 | BZT52-B15        |
| BAS21GWJ           | 934070362118 | BAS21GW          |
| 74AHCT541PW-Q100J  | 935300709118 | 74AHCT541PW-Q100 |
| PTVS26VU1UPAZ      | 934068084147 | PTVS26VU1UPA     |
| 74LV165PW,118      | 935174540118 | 74LV165PW        |
| "74AUP1G02GW,125"  | 935278999125 | 74AUP1G02GW      |
| PESD12VV1BL,315    | 934066585315 | PESD12VV1BL      |
| "74HC2G17GW,125"   | 935281031125 | 74HC2G17GW       |
| PEMD9,115          | 934056706115 | PEMD9            |
| BZX585-C9V1,135    | 934055850135 | BZX585-C9V1      |
| 74LVT244ADB,112    | 935167140112 | 74LVT244ADB      |
| BZT52-C3V0J        | 934071101118 | BZT52-C3V0       |
| PESD1LIN,135       | 934058897135 | PESD1LIN         |

|                    |              |                |
|--------------------|--------------|----------------|
| 74HC251PW,118      | 935188390118 | 74HC251PW      |
| "74HC2G66GT,115"   | 935293604115 | 74HC2G66GT     |
| BZX84-C8V2,235     | 933137440235 | BZX84-C8V2     |
| PESD3V3L2UM,315    | 934057782315 | PESD3V3L2UM    |
| PBSS4032PZ,115     | 934063398115 | PBSS4032PZ     |
| BAS416,115         | 934057494115 | BAS416         |
| BZX384-C27,115     | 934057650115 | BZX384-C27     |
| PESD5Z3.3,115      | 934061264115 | PESD5Z3.3      |
| PMEG060V100EPDAZ   | 934067907139 | PMEG060V100EPD |
| BZT52-B39X         | 934071164115 | BZT52-B39      |
| 74LV4052D,118      | 935175840118 | 74LV4052D      |
| 1PS10SB82,315      | 934057250315 | 1PS10SB82      |
| BZV90-C3V9,115     | 934014670115 | BZV90-C3V9     |
| PUMD9,135          | 934055050135 | PUMD9          |
| "74LVC1G00GW,125"  | 935268378125 | 74LVC1G00GW    |
| NX138AKSX          | 934070155115 | NX138AKS       |
| 74LV00BQ,115       | 935285559115 | 74LV00BQ       |
| BUK7219-55A,118    | 934056242118 | BUK7219-55A    |
| 74HCT541D,653      | 933715610653 | 74HCT541D      |
| PZU10BA,115        | 934062327115 | PZU10BA        |
| 74ABT16240ADL,118  | 935212200118 | 74ABT16240ADL  |
| 74AHCT14D,118      | 935262760118 | 74AHCT14D      |
| PMZ390UNEYL        | 934068614315 | PMZ390UNE      |
| BUK9Y25-80E,115    | 934067031115 | BUK9Y25-80E    |
| 74AUP1G14GM,115    | 935279023115 | 74AUP1G14GM    |
| "74AHCT1G32GW,125" | 935262757125 | 74AHCT1G32GW   |
| 74LVC827APW,118    | 935262420118 | 74LVC827APW    |
| 74CB3Q3253PWJ      | 935339209118 | 74CB3Q3253PW   |
| PZU3.0BA,115       | 934062467115 | PZU3.0BA       |
| 74AHCT3G04DC,125   | 935274904125 | 74AHCT3G04DC   |
| PMEG3002AEL,315    | 934058011315 | PMEG3002AEL    |
| BZX79-C5V1,113     | 933117720113 | BZX79-C5V1     |
| 74LVC3G07DC,125    | 935275557125 | 74LVC3G07DC    |
| BAT54C,235         | 933976370235 | BAT54C         |
| 74AVC2T45DP,125    | 935286774125 | 74AVC2T45DP    |
| BUK964R8-60E,118   | 934066635118 | BUK964R8-60E   |
| 74HCT574D,652      | 933715630652 | 74HCT574D      |
| BAS21GWX           | 934070362115 | BAS21GW        |
| PESD5V0L5UY,115    | 934057803115 | PESD5V0L5UY    |
| 74HC04PW,118       | 935174200118 | 74HC04PW       |
| PMEG3005EL,315     | 934060115315 | PMEG3005EL     |
| BZX84J-C12,115     | 934060984115 | BZX84J-C12     |
| BCM857BS,135       | 934058729135 | BCM857BS       |
| 74AHCT164D,118     | 935265463118 | 74AHCT164D     |
| BUK626R2-40C,118   | 934065903118 | BUK626R2-40C   |
| BUK9616-75B,118    | 934057742118 | BUK9616-75B    |



|                     |              |                  |
|---------------------|--------------|------------------|
| 74LVC823ABQ-Q100J   | 935332776118 | 74LVC823ABQ-Q100 |
| 74HC3GU04DC,125     | 935272730125 | 74HC3GU04DC      |
| BZT52-C5V1X         | 934071108115 | BZT52-C5V1       |
| PESD5V0X2UMYL       | 934068181315 | PESD5V0X2UM      |
| "74HC14PW,112"      | 935183530112 | 74HC14PW         |
| PBHV8215Z,115       | 934063479115 | PBHV8215Z        |
| PESD2IVN27-UX       | 934070278115 | PESD2IVN27-U     |
| BCX55-16,135        | 933674750135 | BCX55-16         |
| 74HC3G34DP,125      | 935272146125 | 74HC3G34DP       |
| 74AHCT573PW,118     | 935263074118 | 74AHCT573PW      |
| PSMN015-100P,127    | 934055640127 | PSMN015-100P     |
| 74ALVCH162827DGGY   | 935254370518 | 74ALVCH162827DGG |
| 74HCT164D,653       | 933714080653 | 74HCT164D        |
| BC807-40W,115       | 934024260115 | BC807-40W        |
| NX7002AKS,115       | 934066295115 | NX7002AKS        |
| "74AHC132D,112"     | 935262989112 | 74AHC132D        |
| 74HCT139PW,118      | 935188300118 | 74HCT139PW       |
| 74HC4046APW,118     | 935187460118 | 74HC4046APW      |
| PMLL4148L,135       | 933930220135 | PMLL4148L        |
| 74HCT138D,653       | 933713410653 | 74HCT138D        |
| PBSS4320TVL         | 934056854235 | PBSS4320T        |
| PDZ5.1BF            | 934054852135 | PDZ5.1B          |
| BZV55-B39,115       | 933931830115 | BZV55-B39        |
| BZX84-B7V5,235      | 933696010235 | BZX84-B7V5       |
| 74LVC2G17GF,132     | 935282434132 | 74LVC2G17GF      |
| 2PD601ASW,115       | 934057050115 | 2PD601ASW        |
| HEF4082BT,653       | 933373100653 | HEF4082BT        |
| BZX384-B10,115      | 934057373115 | BZX384-B10       |
| 74LVC1G57GW-Q100H   | 935302839125 | 74LVC1G57GW-Q100 |
| 74AUP1T32GWH        | 935690051125 | 74AUP1T32GW      |
| 74HC05D,118         | 935288148118 | 74HC05D          |
| PDTB113ZT,215       | 934058979215 | PDTB113ZT        |
| 1PS76SB10,135       | 934045390135 | 1PS76SB10        |
| 74HC123PW-Q100,118  | 935299043118 | 74HC123PW-Q100   |
| PZU6.8B1A,115       | 934062789115 | PZU6.8B1A        |
| 74HC4316PW,118      | 935186960118 | 74HC4316PW       |
| BZT52H-B24,115      | 934064804115 | BZT52H-B24       |
| 74HC4052D,652       | 933714830652 | 74HC4052D        |
| PMEG6010CEJ,115     | 934059512115 | PMEG6010CEJ      |
| PSMN013-100YSEX     | 934067544115 | PSMN013-100YSE   |
| "74LVC1G80GV,125"   | 935272023125 | 74LVC1G80GV      |
| PBSS5140U,115       | 934056513115 | PBSS5140U        |
| PZTA92,115          | 933982080115 | PZTA92           |
| BAT160C,115         | 934051410115 | BAT160C          |
| "74CBTLV3125PW,118" | 935289335118 | 74CBTLV3125PW    |
| 74LVC138AD,112      | 935260745112 | 74LVC138AD       |

|                   |              |                  |
|-------------------|--------------|------------------|
| BAT74,215         | 933742290215 | BAT74            |
| "74HC173PW,112"   | 935189550112 | 74HC173PW        |
| 74LVC273D,118     | 935210640118 | 74LVC273D        |
| PZU16B3A,115      | 934062354115 | PZU16B3A         |
| PMGD290XN,115     | 934057731115 | PMGD290XN        |
| PMEG4010BEV,115   | 934058331115 | PMEG4010BEV      |
| MMBZ15VDL,215     | 934061809215 | MMBZ15VDL        |
| BCP51-16,115      | 933917290115 | BCP51-16         |
| BC847B,215        | 933589590215 | BC847B           |
| 74HCT74DB,118     | 935175180118 | 74HCT74DB        |
| PRMD12Z           | 934070168147 | PRMD12           |
| BCM857DS,135      | 934059033135 | BCM857DS         |
| BZT52-B30X        | 934071183115 | BZT52-B30        |
| PBSS4260PAN,115   | 934066889115 | PBSS4260PAN      |
| 74HCT3G07DP-Q100H | 935300865125 | 74HCT3G07DP-Q100 |
| PDTB123YT,215     | 934058983215 | PDTB123YT        |
| BC848B,215        | 933589630215 | BC848B           |
| PESD3V3S5UD,125   | 934058432125 | PESD3V3S5UD      |
| PMLL4153,115      | 933834730115 | PMLL4153         |
| BSP250,115        | 934033450115 | BSP250           |
| "74AUP1G79GM,132" | 935279047132 | 74AUP1G79GM      |
| 74ALVC244PW,118   | 935269725118 | 74ALVC244PW      |
| "74AHC126PW,118"  | 935262769118 | 74AHC126PW       |
| 74LVC1G3157GXZ    | 935308636147 | 74LVC1G3157GX    |
| "74HC240PW,112"   | 935185810112 | 74HC240PW        |
| 74HCT4053D,118    | 933715320118 | 74HCT4053D       |
| PESD3V3L2BT,215   | 934058863215 | PESD3V3L2BT      |
| PHDMI2F4X         | 934068932115 | PHDMI2F4         |
| 74LVC2G06GXZ      | 935307079147 | 74LVC2G06GX      |
| 74LVC157AD,118    | 935260898118 | 74LVC157AD       |
| BC847BM,315       | 934057150315 | BC847BM          |
| 2N7002PV,115      | 934064136115 | 2N7002PV         |
| 74HC573PW,118     | 935187000118 | 74HC573PW        |
| BZV55-C8V2,135    | 933699500135 | BZV55-C8V2       |
| PDZ30BGWJ         | 934071045118 | PDZ30BGW         |
| BZB84-B5V6,215    | 934061711215 | BZB84-B5V6       |
| PMPB100ENEX       | 934660355115 | PMPB100ENE       |
| HEF4051BTT,118    | 935278637118 | HEF4051BTT       |
| BSP62,115         | 933969480115 | BSP62            |
| BCM846BSX         | 934069545115 | BCM846BS         |
| "74LVC1G80GX,125" | 935298384125 | 74LVC1G80GX      |
| PZU2.7BA,115      | 934062384115 | PZU2.7BA         |
| PBSS4140DPNF      | 934056660135 | PBSS4140DPN      |
| PDZ4.7BGWJ        | 934071087118 | PDZ4.7BGW        |
| BAT165AX          | 934069934115 | BAT165A          |
| "74HC02PW,112"    | 935174150112 | 74HC02PW         |

|                     |              |                  |
|---------------------|--------------|------------------|
| BZX384-C43,115      | 934057655115 | BZX384-C43       |
| BUK9M24-60EX        | 934070053115 | BUK9M24-60E      |
| BZX79-B12,133       | 933166890133 | BZX79-B12        |
| PESD12VS1UA,115     | 934062103115 | PESD12VS1UA      |
| 74HCT4538D,118      | 933715390118 | 74HCT4538D       |
| HEF4015BT,652       | 933372680652 | HEF4015BT        |
| PSMN3R5-30YL,115    | 934063073115 | PSMN3R5-30YL     |
| "74HCT08D,652"      | 933714350652 | 74HCT08D         |
| BAS521BF            | 934660344135 | BAS521B          |
| 74HC27D,653         | 933714170653 | 74HC27D          |
| "74LVC16374ADL,112" | 935235180112 | 74LVC16374ADL    |
| PMEG3050BEP,115     | 934061477115 | PMEG3050BEP      |
| PMEG6010CEJ/HIX     | 934660141115 | PMEG6010CEJ/HI   |
| BSS138BK,215        | 934065729215 | BSS138BK         |
| 74LVC16244ADL,118   | 935235140118 | 74LVC16244ADL    |
| PBSS306PZ,135       | 934059054135 | PBSS306PZ        |
| "HEF4066BT,652"     | 933372970652 | HEF4066BT        |
| PESD5V0S1BA,115     | 934058004115 | PESD5V0S1BA      |
| BAS521BX            | 934660344115 | BAS521B          |
| PTVS11VS1UTR,115    | 934065484115 | PTVS11VS1UTR     |
| BUK9Y113-100E,115   | 934067041115 | BUK9Y113-100E    |
| BUK765R0-100E,118   | 934066494118 | BUK765R0-100E    |
| BCV61A,215          | 933792100215 | BCV61A           |
| 74LVC2G14GV-Q100H   | 935301404125 | 74LVC2G14GV-Q100 |
| 74LVC2G08GM,125     | 935277238125 | 74LVC2G08GM      |
| PMEG6020EPA,115     | 934063487115 | PMEG6020EPA      |
| 74HCT365D,652       | 933715150652 | 74HCT365D        |
| BZX79-C18,143       | 933117850143 | BZX79-C18        |
| BUK9217-75B,118     | 934057721118 | BUK9217-75B      |
| 74AHCT541BQ,115     | 935285545115 | 74AHCT541BQ      |
| PESD5V0L1ULD,315    | 934065313315 | PESD5V0L1ULD     |
| 74ALVC164245DL,118  | 935202340118 | 74ALVC164245DL   |
| BZT52-C20X          | 934071133115 | BZT52-C20        |
| BZX84-B8V2,215      | 933770330215 | BZX84-B8V2       |
| 74LVT16245BDGG,118  | 935203000118 | 74LVT16245BDGG   |
| NZH16C,115          | 934064372115 | NZH16C           |
| 74HCT4067BQ-Q100J   | 935306682118 | 74HCT4067BQ-Q100 |
| BUK7Y25-80EX        | 934067423115 | BUK7Y25-80E      |
| PCMF3USB3SZ         | 934069589087 | PCMF3USB3S       |
| 74HC86D,652         | 933714030652 | 74HC86D          |
| BZV85-C47,133       | 933500810133 | BZV85-C47        |
| BAS40-06W,115       | 934044310115 | BAS40-06W        |
| TDZ6V2J,115         | 934065715115 | TDZ6V2J          |
| BAT721,215          | 934051290215 | BAT721           |
| NZH5V6B,115         | 934064359115 | NZH5V6B          |
| BZX79-B9V1,143      | 933166860143 | BZX79-B9V1       |

|                     |              |                 |
|---------------------|--------------|-----------------|
| 1PS79SB17,115       | 934058074115 | 1PS79SB17       |
| PTVS40VS1UR,115     | 934061366115 | PTVS40VS1UR     |
| PESD3V3C1BSFYL      | 934069617315 | PESD3V3C1BSF    |
| PBSS303PZ,135       | 934059051135 | PBSS303PZ       |
| BUK7Y65-100EX       | 934067445115 | BUK7Y65-100E    |
| "74HC02PW-Q100,118" | 935298722118 | 74HC02PW-Q100   |
| 74HCT594D,118       | 935043390118 | 74HCT594D       |
| 74LVC2G00GXX        | 935308444115 | 74LVC2G00GX     |
| 74VHC595BQ,115      | 935289511115 | 74VHC595BQ      |
| PESD18VV1BSFYL      | 934071017315 | PESD18VV1BSF    |
| PEMD2,115           | 934056860115 | PEMD2           |
| "74HCT107D,652"     | 933713930652 | 74HCT107D       |
| 74HC393D,653        | 933714110653 | 74HC393D        |
| BF722,115           | 933917370115 | BF722           |
| BZV85-C24,113       | 933500740113 | BZV85-C24       |
| BUK7K6R8-40E,115    | 934066989115 | BUK7K6R8-40E    |
| 74AVC9112DCH        | 935690124125 | 74AVC9112DC     |
| 74LVC3G17DC,125     | 935275563125 | 74LVC3G17DC     |
| "74LVC2G17GM,132"   | 935277163132 | 74LVC2G17GM     |
| BAT17,215           | 933410700215 | BAT17           |
| PMV27UPER           | 934068498215 | PMV27UPE        |
| BUK9Y12-100E,115    | 934067035115 | BUK9Y12-100E    |
| PMN52XPX            | 934069335115 | PMN52XP         |
| PMEG6010CEH,115     | 934061056115 | PMEG6010CEH     |
| PDTA114ET,215       | 934031060215 | PDTA114ET       |
| 74VHC32BQ,115       | 935289543115 | 74VHC32BQ       |
| BZT52H-C36,115      | 934059416115 | BZT52H-C36      |
| "74HC1G00GW,125"    | 935245610125 | 74HC1G00GW      |
| BUK9J0R9-40HX       | 934660369115 | BUK9J0R9-40H    |
| PBSS4420D,115       | 934058273115 | PBSS4420D       |
| BCX70K,235          | 933476670235 | BCX70K          |
| BUK7626-100B,118    | 934057741118 | BUK7626-100B    |
| BC807DS,115         | 934057318115 | BC807DS         |
| BC817-40,215        | 933628640215 | BC817-40        |
| 74AHCT2G08DP,125    | 935274677125 | 74AHCT2G08DP    |
| BSH114,215          | 934056506215 | BSH114          |
| "74HC165D,652"      | 933713780652 | 74HC165D        |
| 74HCT245PW-Q100J    | 935301022118 | 74HCT245PW-Q100 |
| PESD2IVN-UX         | 934069204115 | PESD2IVN-U      |
| 74HCT4094D,112      | 933715330112 | 74HCT4094D      |
| PSMN8R3-40YS,115    | 934063936115 | PSMN8R3-40YS    |
| 74HC7540D,118       | 933967860118 | 74HC7540D       |
| PEMB10,115          | 934056870115 | PEMB10          |
| 74HC08BQ,115        | 935273683115 | 74HC08BQ        |
| 74AUP1G07GX4Z       | 935340115147 | 74AUP1G07GX4    |
| PRMB11Z             | 934070181147 | PRMB11          |

|                    |              |                 |
|--------------------|--------------|-----------------|
| 2N7002BK,215       | 934063609215 | 2N7002BK        |
| 74HC4066BQ,115     | 935273684115 | 74HC4066BQ      |
| BC859C,215         | 933628690215 | BC859C          |
| BZX384-C2V7,115    | 934057626115 | BZX384-C2V7     |
| 74AHC373PW,118     | 935262652118 | 74AHC373PW      |
| 74HCT2G125DP,125   | 935270086125 | 74HCT2G125DP    |
| BZX884-C3V6,315    | 934057212315 | BZX884-C3V6     |
| PMZ130UNEYL        | 934068608315 | PMZ130UNE       |
| PESD16VV1BSFYL     | 934070992315 | PESD16VV1BSF    |
| BZV90-C3V6,115     | 934014650115 | BZV90-C3V6      |
| 74LVC162245ADGG,11 | 935237700112 | 74LVC162245ADGG |
| 74HCT32DB,118      | 935174790118 | 74HCT32DB       |
| PMEG040V050EPDZ    | 934070192146 | PMEG040V050EPD  |
| BZX84-B2V4,215     | 933770280215 | BZX84-B2V4      |
| PTVS10VP1UP,115    | 934064163115 | PTVS10VP1UP     |
| PBHV9560ZX         | 934068591115 | PBHV9560Z       |
| PCMF1USB30Z        | 934069586087 | PCMF1USB30      |
| BZT52-C12X         | 934071127115 | BZT52-C12       |
| BZX79-C33,133      | 933117910133 | BZX79-C33       |
| 74HC32PW,112       | 935174750112 | 74HC32PW        |
| PMV20XNER          | 934068845215 | PMV20XNE        |
| "74HCT4075D,652"   | 933714200652 | 74HCT4075D      |
| TDZ9V1J,115        | 934065783115 | TDZ9V1J         |
| BAS31,215          | 933723190215 | BAS31           |
| BZX84-B18,215      | 933770410215 | BZX84-B18       |
| 74AUP1G04GX4Z      | 935340114147 | 74AUP1G04GX4    |
| PESD1IVN27-AX      | 934660121115 | PESD1IVN27-A    |
| BZT52-C5V6X        | 934071109115 | BZT52-C5V6      |
| BUK9Y40-55B,115    | 934058367115 | BUK9Y40-55B     |
| BAT721A,215        | 934054928215 | BAT721A         |
| PSMN8R7-100YSFX    | 934071221115 | PSMN8R7-100YSF  |
| "74LVT08PW,112"    | 935209040112 | 74LVT08PW       |
| PMZ320UPEYL        | 934068611315 | PMZ320UPE       |
| 74LV7032APWJ       | 935690649118 | 74LV7032APW     |
| PMEG3002EJ,115     | 934063238115 | PMEG3002EJ      |
| BUK6D43-40PX       | 934660216115 | BUK6D43-40P     |
| BZX384-C62,115     | 934057659115 | BZX384-C62      |
| BZX84-C22,235      | 933388300235 | BZX84-C22       |
| PMEG2010BEA,115    | 934057916115 | PMEG2010BEA     |
| 74HC590D,118       | 935278827118 | 74HC590D        |
| 74LV4052PW-Q100J   | 935301549118 | 74LV4052PW-Q100 |
| BZX384-C33,115     | 934057652115 | BZX384-C33      |
| BZX585-C75,115     | 934057437115 | BZX585-C75      |
| PZU5.6BL,315       | 934061669315 | PZU5.6BL        |
| BSS138AKAR         | 934067515215 | BSS138AKA       |
| PSMN1R0-40YLDX     | 934067786115 | PSMN1R0-40YLD   |

|                      |              |                   |
|----------------------|--------------|-------------------|
| "74LVC1G08GW-Q100,1" | 935298476125 | 74LVC1G08GW-Q100  |
| BZX79-C18,133        | 933117850133 | BZX79-C18         |
| 74HC2G14GW-Q100H     | 935301614125 | 74HC2G14GW-Q100   |
| BZT52-C3V9X          | 934071105115 | BZT52-C3V9        |
| BUK9M3R3-40HX        | 934660791115 | BUK9M3R3-40H      |
| 74HC125PW,118        | 935174340118 | 74HC125PW         |
| 74HC4052PW/C4J       | 935301855118 | 74HC4052PW/C4     |
| PBSS5160DS,115       | 934058121115 | PBSS5160DS        |
| 74HCT1G14GW-Q100H    | 935299228125 | 74HCT1G14GW-Q100  |
| 74HC3G07DP,125       | 935272999125 | 74HC3G07DP        |
| PMEG2002AESFBL       | 934071188315 | PMEG2002AESFB     |
| 74AHC138D,118        | 935262999118 | 74AHC138D         |
| PTVS58VP1UP,115      | 934064188115 | PTVS58VP1UP       |
| BF720,115            | 933917360115 | BF720             |
| PSMNR51-25YLHX       | 934660322115 | PSMNR51-25YLH     |
| 74AHC02BQ-Q100X      | 935300981115 | 74AHC02BQ-Q100    |
| 74AHC1G4210GWH       | 935307091125 | 74AHC1G4210GW     |
| PESD5V0R1BSFYL       | 934068764315 | PESD5V0R1BSF      |
| "74AHC1G126GW,125"   | 935263003125 | 74AHC1G126GW      |
| BCX54-10,115         | 933663070115 | BCX54-10          |
| "74HCT7540D,112"     | 933967900112 | 74HCT7540D        |
| 74HCT4052DB,118      | 935190000118 | 74HCT4052DB       |
| BUK755R4-100E,127    | 934066483127 | BUK755R4-100E     |
| 74LVC08AD,118        | 935250020118 | 74LVC08AD         |
| BZV85-C51,113        | 933500820113 | BZV85-C51         |
| PDTC144ETVL          | 934031030235 | PDTC144ET         |
| BZX384-B3V3,115      | 934057361115 | BZX384-B3V3       |
| BZV85-C62,133        | 933500840133 | BZV85-C62         |
| 74HC573D-Q100,118    | 935298864118 | 74HC573D-Q100     |
| 74HCT2G00DP,125      | 935271850125 | 74HCT2G00DP       |
| 74CBTLVD3244PW,118   | 935294101118 | 74CBTLVD3244PW    |
| "74HCT132PW,118"     | 935187310118 | 74HCT132PW        |
| "74HC4051PW,112"     | 935187480112 | 74HC4051PW        |
| 74HCT14DB,118        | 935174470118 | 74HCT14DB         |
| PSMN2R0-30YL,115     | 934063069115 | PSMN2R0-30YL      |
| 74LVC139BQ,115       | 935273887115 | 74LVC139BQ        |
| "74AHC00PW,112"      | 935262687112 | 74AHC00PW         |
| BZV55-C3V0,115       | 933699390115 | BZV55-C3V0        |
| PZU5.1B,115          | 934059751115 | PZU5.1B           |
| PUMD2,115            | 934049950115 | PUMD2             |
| PDTC143ET,215        | 934030990215 | PDTC143ET         |
| "74HC154D,652"       | 933713820652 | 74HC154D          |
| 74LVC1G175GW-Q100H   | 935301507125 | 74LVC1G175GW-Q100 |
| PSMN1R2-25YLC,115    | 934065197115 | PSMN1R2-25YLC     |
| BZX884-C39,315       | 934057464315 | BZX884-C39        |
| BZX585-B5V1,135      | 934055864135 | BZX585-B5V1       |

|                      |              |                  |
|----------------------|--------------|------------------|
| 74AUP1T50GXH         | 935690084125 | 74AUP1T50GX      |
| 74LVC4245ABQ,118     | 935285619118 | 74LVC4245ABQ     |
| PSMN1R4-40YLDX       | 934068724115 | PSMN1R4-40YLD    |
| PMEG6002TV,115       | 934060005115 | PMEG6002TV       |
| PSMN8R5-60YS,115     | 934064402115 | PSMN8R5-60YS     |
| 74HCT86D,652         | 933714040652 | 74HCT86D         |
| 74LVC594APW,118      | 935282467118 | 74LVC594APW      |
| "HEF4541BT,518"      | 933508000518 | HEF4541BT        |
| 74LVC1G19GV,125      | 935273469125 | 74LVC1G19GV      |
| BAT54H,115           | 934059278115 | BAT54H           |
| BZB84-C47,215        | 934063339215 | BZB84-C47        |
| PMEG2005AESFYL       | 934068325315 | PMEG2005AESF     |
| PESD12VS1ULD,315     | 934065311315 | PESD12VS1ULD     |
| 74LVT126BQ,115       | 935275706115 | 74LVT126BQ       |
| BZX84J-C43,115       | 934061005115 | BZX84J-C43       |
| "74AHC14PW,118"      | 935262759118 | 74AHC14PW        |
| NX3020NAKW,115       | 934067071115 | NX3020NAKW       |
| BAV170QAZ            | 934069814147 | BAV170QA         |
| "74LVCH16373ADGG,11" | 935238490112 | 74LVCH16373ADGG  |
| BZT52H-C11,115       | 934059402115 | BZT52H-C11       |
| 74HCT2G34GW-Q100H    | 935301184125 | 74HCT2G34GW-Q100 |
| PMEG060V050EPDZ      | 934067905146 | PMEG060V050EPD   |
| PLVA659A,215         | 934017370215 | PLVA659A         |
| 74HCT04BQ,115        | 935273594115 | 74HCT04BQ        |
| PMPB95ENEAX          | 934067476115 | PMPB95ENEA       |
| 74LV165APW,112       | 935273177112 | 74LV165APW       |
| BZT52-B27X           | 934071182115 | BZT52-B27        |
| BAV756S,115          | 934052910115 | BAV756S          |
| PMPB15XPAX           | 934070926115 | PMPB15XPA        |
| PESD5V0V1BB,115      | 934063245115 | PESD5V0V1BB      |
| MMBZ33VCL,215        | 934061814215 | MMBZ33VCL        |
| 74AVC2T45DP/C,125    | 935294803125 | 74AVC2T45DP/C    |
| BZX84J-C5V1,115      | 934061012115 | BZX84J-C5V1      |
| BUK7Y3R5-40HX        | 934660066115 | BUK7Y3R5-40H     |
| BZT52H-C15,115       | 934059406115 | BZT52H-C15       |
| PMBT3904M,315        | 934063475315 | PMBT3904M        |
| BZX84W-B27X          | 934660405115 | BZX84W-B27       |
| BZB84-B20,215        | 934063453215 | BZB84-B20        |
| PMEG2020EH,115       | 934059026115 | PMEG2020EH       |
| PMPB19XP,115         | 934066871115 | PMPB19XP         |
| PBRP113ET,215        | 934058986215 | PBRP113ET        |
| NZX9V1C,133          | 934063537133 | NZX9V1C          |
| BUK9Y19-100E,115     | 934066629115 | BUK9Y19-100E     |
| PSMN011-80YS,115     | 934064151115 | PSMN011-80YS     |
| BZX84-B5V6,235       | 933564710235 | BZX84-B5V6       |
| PTVS11VS1UR,115      | 934061348115 | PTVS11VS1UR      |

|                     |              |                   |
|---------------------|--------------|-------------------|
| PCMF2HDMI2SZ        | 934070093087 | PCMF2HDMI2S       |
| BZX84-C39,215       | 933388360215 | BZX84-C39         |
| BUK766R0-60E,118    | 934066645118 | BUK766R0-60E      |
| BZX585-C68,115      | 934057436115 | BZX585-C68        |
| BC807-16W,115       | 934024240115 | BC807-16W         |
| 74LVC04AD,118       | 935242400118 | 74LVC04AD         |
| BZX585-C11,115      | 934055852115 | BZX585-C11        |
| PMEG2005ELD,315     | 934065336315 | PMEG2005ELD       |
| "74AVC16245DGG,112" | 935264444112 | 74AVC16245DGG     |
| BZX84-A13,215       | 934055056215 | BZX84-A13         |
| BZV55-B43,115       | 933931840115 | BZV55-B43         |
| PDZ6.8BGWJ          | 934071037118 | PDZ6.8BGW         |
| PZU18B2A,115        | 934062381115 | PZU18B2A          |
| "74ABT08D,112"      | 935207050112 | 74ABT08D          |
| BZV85-C33,113       | 933500770113 | BZV85-C33         |
| PESD5V0X2UAMYL      | 934068182315 | PESD5V0X2UAM      |
| 2N7002BKV,115       | 934064288115 | 2N7002BKV         |
| BC54PA,115          | 934065738115 | BC54PA            |
| BZB84-B15,215       | 934061722215 | BZB84-B15         |
| BC807-40,215        | 933628580215 | BC807-40          |
| BC850CW,115         | 934022080115 | BC850CW           |
| BCX71H,215          | 933483660215 | BCX71H            |
| 74LVC1G14GM,115     | 935277179115 | 74LVC1G14GM       |
| PUSB3TB6AZ          | 934068238471 | PUSB3TB6          |
| 74LVC2G125GM,125    | 935277214125 | 74LVC2G125GM      |
| BCX54,115           | 933272310115 | BCX54             |
| BAS31,235           | 933723190235 | BAS31             |
| "74HCT1G32GV,125"   | 935272009125 | 74HCT1G32GV       |
| NZX5V1C,133         | 934062025133 | NZX5V1C           |
| BUK7M20-40HX        | 934660789115 | BUK7M20-40H       |
| TDZ15J,115          | 934065789115 | TDZ15J            |
| PEMD13,115          | 934056866115 | PEMD13            |
| "PRTR5V0U4D,125"    | 934058881125 | PRTR5V0U4D        |
| MMBD4148,215        | 934063957215 | MMBD4148          |
| BUK9Y8R5-80EX       | 934067596115 | BUK9Y8R5-80E      |
| PESD1CAN-UX         | 934067396115 | PESD1CAN-U        |
| PBSS305NX,115       | 934059012115 | PBSS305NX         |
| 74AUP1G332GM,115    | 935280752115 | 74AUP1G332GM      |
| 2PD602AQL,215       | 934062311215 | 2PD602AQL         |
| PMV120ENEAR         | 934068712215 | PMV120ENEA        |
| BZX84-B3V6VL        | 933770310235 | BZX84-B3V6        |
| BCP54-16,135        | 933917200135 | BCP54-16          |
| PESD24VS1ULD,315    | 934064957315 | PESD24VS1ULD      |
| PMPB85ENEAX         | 934067478115 | PMPB85ENEA        |
| 74AUP2GU04GW-Q100H  | 935305394125 | 74AUP2GU04GW-Q100 |
| PH2625L,115         | 934058202115 | PH2625L           |



|                    |              |                    |
|--------------------|--------------|--------------------|
| PMZB290UN,315      | 934065866315 | PMZB290UN          |
| PSMN5R6-100BS,118  | 934066336118 | PSMN5R6-100BS      |
| PBSS4160T,215      | 934057667215 | PBSS4160T          |
| PMBTA56,235        | 933816490235 | PMBTA56            |
| BZX84-B56,215      | 933770520215 | BZX84-B56          |
| "74AUP1G17GW,125"  | 935279024125 | 74AUP1G17GW        |
| BZX79-B5V6,113     | 933166820113 | BZX79-B5V6         |
| "74HC74PW,118"     | 935175130118 | 74HC74PW           |
| BUK9M156-100EX     | 934070073115 | BUK9M156-100E      |
| PSMN004-60B,118    | 934057041118 | PSMN004-60B        |
| PMEG3020EPA,115    | 934063485115 | PMEG3020EPA        |
| PESD12VL2BT,215    | 934058865215 | PESD12VL2BT        |
| BUK9245-55A,118    | 934056853118 | BUK9245-55A        |
| BUK964R2-55B,118   | 934057093118 | BUK964R2-55B       |
| 74LV1T32GWH        | 935690201125 | 74LV1T32GW         |
| 74AHCT1G17GWH      | 935303456125 | 74AHCT1G17GW       |
| BAS70-05W,115      | 934034490115 | BAS70-05W          |
| BSS84AKM,315       | 934065309315 | BSS84AKM           |
| NPIC6C595PW,118    | 935297271118 | NPIC6C595PW        |
| PDTA123ET,215      | 934054696215 | PDTA123ET          |
| 74LVC2G08GXX       | 935308435115 | 74LVC2G08GX        |
| 74LVC04ABQ,115     | 935273675115 | 74LVC04ABQ         |
| 74HC4060D-Q100,118 | 935298892118 | 74HC4060D-Q100     |
| 74HCT390D,653      | 933715200653 | 74HCT390D          |
| BZX84-B43,215      | 933770490215 | BZX84-B43          |
| "HEF4013BT,652"    | 933372660652 | HEF4013BT          |
| BZT52H-C20,115     | 934059409115 | BZT52H-C20         |
| PBSS5250X,115      | 934055629115 | PBSS5250X          |
| 74LVT245DB,118     | 935155220118 | 74LVT245DB         |
| BZX384-B15,115     | 934057377115 | BZX384-B15         |
| PBSS4350X,115      | 934055628115 | PBSS4350X          |
| HEF4021BT,652      | 933372740652 | HEF4021BT          |
| BCW68FVL           | 934070944235 | BCW68F             |
| PMEG3005EGWX       | 934070451115 | PMEG3005EGW        |
| "74HC6323AD,112"   | 935013710112 | 74HC6323AD         |
| 74VHCT541PW,118    | 935289528118 | 74VHCT541PW        |
| 74LVC1G34GX4Z      | 935690006147 | 74LVC1G34GX4       |
| BZX585-C39,115     | 934057430115 | BZX585-C39         |
| BUK9212-55B,118    | 934057605118 | BUK9212-55B        |
| PMEG4010CEGWX      | 934070371115 | PMEG4010CEGW       |
| BZX84J-C27,115     | 934060993115 | BZX84J-C27         |
| PESD18VV1BDSF/S5YL | 934660567315 | PESD18VV1BDSF/S500 |
| BZX384-B18,115     | 934057379115 | BZX384-B18         |
| BUK7M15-60EX       | 934070049115 | BUK7M15-60E        |
| IP4786CZ32S,118    | 934066666118 | IP4786CZ32S        |
| BZV49-C2V7,115     | 933605820115 | BZV49-C2V7         |

|                      |              |                    |
|----------------------|--------------|--------------------|
| "74AHCT1G126GW,125"  | 935263004125 | 74AHCT1G126GW      |
| PSMN1R3-30YL,115     | 934063811115 | PSMN1R3-30YL       |
| 74LVC161D,118        | 935210510118 | 74LVC161D          |
| BZT52-C6V2X          | 934071111115 | BZT52-C6V2         |
| BZX79-C75,133        | 933118000133 | BZX79-C75          |
| BAS70XY,115          | 934059956115 | BAS70XY            |
| PDZ6.2BGWX           | 934071025115 | PDZ6.2BGW          |
| 74HC174PW,112        | 935188360112 | 74HC174PW          |
| "CBTD3306PW,118"     | 935270512118 | CBTD3306PW         |
| PMEG2015EPK,315      | 934065382315 | PMEG2015EPK        |
| 74AUP1T34GM,115      | 935280517115 | 74AUP1T34GM        |
| PMEG2015EA,115       | 934057622115 | PMEG2015EA         |
| BZX84-C47,235        | 933388380235 | BZX84-C47          |
| PDTA144EU,135        | 934044130135 | PDTA144EU          |
| 74HCT7540D,118       | 933967900118 | 74HCT7540D         |
| PSMN3R0-30YLDX       | 934067966115 | PSMN3R0-30YLD      |
| BZX884-C33,315       | 934057462315 | BZX884-C33         |
| 74HC3G14DP,125       | 935272126125 | 74HC3G14DP         |
| "74LVC1GX04GW,125"   | 935274024125 | 74LVC1GX04GW       |
| "74LVT244APW,112"    | 935176380112 | 74LVT244APW        |
| PMP5201Y,115         | 934059041115 | PMP5201Y           |
| 74HCT4514D,653       | 933715690653 | 74HCT4514D         |
| 74HC2G86DC,125       | 935274825125 | 74HC2G86DC         |
| BUK9M120-100EX       | 934070072115 | BUK9M120-100E      |
| HEF4066BT,653        | 933372970653 | HEF4066BT          |
| PDTA143EMB,315       | 934065924315 | PDTA143EMB         |
| 74HCT4067D,118       | 933715680118 | 74HCT4067D         |
| 74LVC00ABQ,115       | 935273496115 | 74LVC00ABQ         |
| BUK9Y7R6-40E,115     | 934067046115 | BUK9Y7R6-40E       |
| BZT52H-B13,115       | 934064797115 | BZT52H-B13         |
| "74LVC2G86GT,115"    | 935278927115 | 74LVC2G86GT        |
| BUK9K8R7-40EX        | 934067812115 | BUK9K8R7-40E       |
| "74HCT1G86GV,125"    | 935272017125 | 74HCT1G86GV        |
| 74HC4017D-Q100J      | 935302477118 | 74HC4017D-Q100     |
| "74HC1G08GW-Q100,12" | 935298485125 | 74HC1G08GW-Q100    |
| NX3008NBKW,115       | 934065635115 | NX3008NBKW         |
| 74HC11PW-Q100J       | 935300037118 | 74HC11PW-Q100      |
| BUK7613-100E,118     | 934066665118 | BUK7613-100E       |
| BAT720,215           | 934051280215 | BAT720             |
| 74LV1T34GWH          | 935690203125 | 74LV1T34GW         |
| PBSS306NX,115        | 934059013115 | PBSS306NX          |
| PMLL4448,135         | 933834760135 | PMLL4448           |
| "74AUP1GU04GM,132"   | 935279066132 | 74AUP1GU04GM       |
| 74HCT4051PW,118      | 935270418118 | 74HCT4051PW        |
| 74CBTLV3245BQ-Q10X   | 935308527115 | 74CBTLV3245BQ-Q100 |
| "74AUP1G19GW,125"    | 935279954125 | 74AUP1G19GW        |

|                    |              |                    |
|--------------------|--------------|--------------------|
| 74HC02DB,118       | 935166850118 | 74HC02DB           |
| BUK9Y15-100E,115   | 934067036115 | BUK9Y15-100E       |
| 74LVC2G38GF,115    | 935291508115 | 74LVC2G38GF        |
| BAS70W,115         | 934034470115 | BAS70W             |
| 74ALVCH16373DGG:11 | 935205120118 | 74ALVCH16373DGG    |
| HEF4017BT,653      | 933372700653 | HEF4017BT          |
| PMV60ENEAR         | 934661154215 | PMV60ENEA          |
| 74AUP1T17GXH       | 935690082125 | 74AUP1T17GX        |
| 74LVTH16244BDL,118 | 935281749118 | 74LVTH16244BDL     |
| BUK7Y25-60EX       | 934067441115 | BUK7Y25-60E        |
| "74AHC1G86GW,125"  | 935263006125 | 74AHC1G86GW        |
| HEF4894BT-Q100,118 | 935298525118 | HEF4894BT-Q100     |
| PSMN057-200B,118   | 934056599118 | PSMN057-200B       |
| 74LVC125APW,112    | 935231720112 | 74LVC125APW        |
| BZX79-C56,113      | 933117970113 | BZX79-C56          |
| PDZ3.3BGWJ         | 934071059118 | PDZ3.3BGW          |
| 74LVTH16245BDGG:11 | 935281753112 | 74LVTH16245BDGG    |
| PUSB3AB4Z          | 934069201471 | PUSB3AB4           |
| PMEG2010ET,215     | 934061048215 | PMEG2010ET         |
| PTVS7V5S1UR,115    | 934061343115 | PTVS7V5S1UR        |
| BZX84J-C5V6,115    | 934061013115 | BZX84J-C5V6        |
| BCP56-16,115       | 933917260115 | BCP56-16           |
| BZV55-B47,115      | 933931850115 | BZV55-B47          |
| PTVS30VS1UR,115    | 934061363115 | PTVS30VS1UR        |
| PDTD114ETR         | 934031040215 | PDTD114ET          |
| BSS84AKV,115       | 934065306115 | BSS84AKV           |
| 74AHC573PW,118     | 935263072118 | 74AHC573PW         |
| "74ALVC14PW,118"   | 935269723118 | 74ALVC14PW         |
| 74HC4051BQ,115     | 935273693115 | 74HC4051BQ         |
| 74HC373PW-Q100,118 | 935299036118 | 74HC373PW-Q100     |
| "74LVC06AD,112"    | 935265479112 | 74LVC06AD          |
| 74LVC8T245PW,118   | 935290149118 | 74LVC8T245PW       |
| 74HCT2G08DP,125    | 935271869125 | 74HCT2G08DP        |
| PRMD16Z            | 934070174147 | PRMD16             |
| PMBT2907,215       | 933846840215 | PMBT2907           |
| BZX84-B10,215      | 933770350215 | BZX84-B10          |
| BSP50,115          | 933986330115 | BSP50              |
| PEMH19,115         | 934058933115 | PEMH19             |
| PESD4V0Z1BCSFYL    | 934660542315 | PESD4V0Z1BCSF      |
| 74AHC1G4210GW-Q10H | 935690495125 | 74AHC1G4210GW-Q100 |
| BSP43,115          | 933982030115 | BSP43              |
| PESD7V0R1BSFYL     | 934660173315 | PESD7V0R1BSF       |
| 74HC191PW,118      | 935188370118 | 74HC191PW          |
| 74HC597D,653       | 933757330653 | 74HC597D           |
| 74HC4514PW,118     | 935262415118 | 74HC4514PW         |
| BC847W,115         | 934021720115 | BC847W             |

|                    |              |                   |
|--------------------|--------------|-------------------|
| 74HC174D,653       | 933714570653 | 74HC174D          |
| PSMN2R7-30PL,127   | 934064005127 | PSMN2R7-30PL      |
| "74AHC00D,112"     | 935262686112 | 74AHC00D          |
| BAT46WJF           | 934064494135 | BAT46WJ           |
| BZV55-C56,115      | 933699730115 | BZV55-C56         |
| BZX79-B75,113      | 933167080113 | BZX79-B75         |
| BC846BS,115        | 934063582115 | BC846BS           |
| 74AHCT04D,118      | 935263038118 | 74AHCT04D         |
| 74LVC14ADB,118     | 935260738118 | 74LVC14ADB        |
| PMV45EN2R          | 934068494215 | PMV45EN2          |
| BAS516,135         | 934055217135 | BAS516            |
| PMBTA45,215        | 934063606215 | PMBTA45           |
| PESD3USB30Z        | 934069599087 | PESD3USB30        |
| BUK7Y1R7-40HX      | 934069303115 | BUK7Y1R7-40H      |
| BCX56-16,135       | 933674760135 | BCX56-16          |
| "74LVT04PW,112"    | 935209010112 | 74LVT04PW         |
| IP4251CZ16-8-TTL,1 | 934064678132 | IP4251CZ16-8-TTL  |
| 74HCT138PW,118     | 935187320118 | 74HCT138PW        |
| PTVS3V3D1BALYL     | 934660478315 | PTVS3V3D1BAL      |
| PBSS4330PASX       | 934068106115 | PBSS4330PAS       |
| BUK9M15-40HX       | 934660798115 | BUK9M15-40H       |
| "74AHC273PW,112"   | 935263593112 | 74AHC273PW        |
| PSMN8R5-40MLDX     | 934661553115 | PSMN8R5-40MLD     |
| 74AHC32PW-Q100J    | 935300193118 | 74AHC32PW-Q100    |
| PZU12B2A,115       | 934062338115 | PZU12B2A          |
| BC847RAZ           | 934070163147 | BC847RA           |
| 74HCT2G66DC,125    | 935274797125 | 74HCT2G66DC       |
| PHPT60610PYX       | 934068584115 | PHPT60610PY       |
| MMBZ33VALVL        | 934061802235 | MMBZ33VAL         |
| BUK7M11-40HX       | 934660787115 | BUK7M11-40H       |
| PMZ290UNE2YL       | 934068801315 | PMZ290UNE2        |
| 74LVT08D,118       | 935209020118 | 74LVT08D          |
| BZT52H-C4V3,115    | 934059391115 | BZT52H-C4V3       |
| "74HCT253D,652"    | 933713870652 | 74HCT253D         |
| PMST4401,115       | 934026880115 | PMST4401          |
| NPIC6C596ABQ-Q100X | 935302416115 | NPIC6C596ABQ-Q100 |
| PMBTA14,215        | 933816530215 | PMBTA14           |
| 1PS300,115         | 934033580115 | 1PS300            |
| BSR41F             | 933418080135 | BSR41             |
| PMEG4010ETR/BX     | 934067558115 | PMEG4010ETR/B     |
| 74HC7540DB,112     | 935190290112 | 74HC7540DB        |
| PUMH4,115          | 934054931115 | PUMH4             |
| BZT52H-B6V8,115    | 934064789115 | BZT52H-B6V8       |
| 74AUP1T87GXH       | 935690109125 | 74AUP1T87GX       |
| PMEG2005EL,315     | 934058008315 | PMEG2005EL        |
| "74LVT245BPW,112"  | 935263679112 | 74LVT245BPW       |

|                      |              |                |
|----------------------|--------------|----------------|
| BUK7M8R5-40HX        | 934660807115 | BUK7M8R5-40H   |
| 74LVCH2T45DC,125     | 935284761125 | 74LVCH2T45DC   |
| 74AHCT245PW,118      | 935261962118 | 74AHCT245PW    |
| "74HC151PW,112"      | 935188950112 | 74HC151PW      |
| 74LVC86ADB,112       | 935250100112 | 74LVC86ADB     |
| BCP51-16,135         | 933917290135 | BCP51-16       |
| PBSS4240Y,115        | 934056511115 | PBSS4240Y      |
| PMV213SN,215         | 934057521215 | PMV213SN       |
| 74HC4067DB,118       | 935165200118 | 74HC4067DB     |
| "74HCT02PW-Q100,118" | 935298725118 | 74HCT02PW-Q100 |
| PTVS12VS1UR,115      | 934061349115 | PTVS12VS1UR    |
| "74ABT08PW,112"      | 935207100112 | 74ABT08PW      |
| PDZ15BGWJ            | 934071052118 | PDZ15BGW       |
| 74HC4046AD,653       | 933809550653 | 74HC4046AD     |
| PEMZ7,315            | 934056714315 | PEMZ7          |
| 74LVC2G04GV,125      | 935273525125 | 74LVC2G04GV    |
| PMV32UP,215          | 934065645215 | PMV32UP        |
| BC850B,215           | 933589690215 | BC850B         |
| 74LVC541AD,118       | 935260901118 | 74LVC541AD     |
| "74HC109D,652"       | 933714480652 | 74HC109D       |
| BZX384-C10,115       | 934057640115 | BZX384-C10     |
| BZX84-A8V2,215       | 934011750215 | BZX84-A8V2     |
| 74HC240D,652         | 933713440652 | 74HC240D       |
| BAT85,133            | 933624760133 | BAT85          |
| PDTA114YM,315        | 934057160315 | PDTA114YM      |
| 74ABT32D,118         | 935208700118 | 74ABT32D       |
| BZB984-C2V7,115      | 934057232115 | BZB984-C2V7    |
| 74ALVC00BQ,115       | 935273669115 | 74ALVC00BQ     |
| PTVS18VP1UP,115      | 934064172115 | PTVS18VP1UP    |
| "74HC365D,652"       | 933714670652 | 74HC365D       |
| "74LVC1G58GW,125"    | 935276075125 | 74LVC1G58GW    |
| 74AHCT00PW,118       | 935262689118 | 74AHCT00PW     |
| PMEG4020ER,115       | 934061466115 | PMEG4020ER     |
| HEF4040BT,652        | 933372850652 | HEF4040BT      |
| BZT52-C16X           | 934071131115 | BZT52-C16      |
| "74HC00PW-Q100,118"  | 935298685118 | 74HC00PW-Q100  |
| 74AHC273PW,118       | 935263593118 | 74AHC273PW     |
| 74AUP1G09GM,115      | 935288303115 | 74AUP1G09GM    |
| PESD3V3L1UB,115      | 934063221115 | PESD3V3L1UB    |
| BUK7K13-60EX         | 934067949115 | BUK7K13-60E    |
| PSMN2R4-30MLDX       | 934067969115 | PSMN2R4-30MLD  |
| PSMN1R7-30YL,115     | 934063068115 | PSMN1R7-30YL   |
| 74ALVC373BQ,115      | 935285555115 | 74ALVC373BQ    |
| MMBZ16VALVL          | 934070909235 | MMBZ16VAL      |
| PZU5.1B2L,315        | 934061666315 | PZU5.1B2L      |
| BAS45AL,115          | 934031250115 | BAS45AL        |

|                   |              |                 |
|-------------------|--------------|-----------------|
| PMBT3904YS,115    | 934061454115 | PMBT3904YS      |
| PESD5V0C1BSFYL    | 934068766315 | PESD5V0C1BSF    |
| PBSS301PX,115     | 934059014115 | PBSS301PX       |
| PDTC123YMB,315    | 934065947315 | PDTC123YMB      |
| PDZ5.6B,115       | 934054853115 | PDZ5.6B         |
| PZU18B1A,115      | 934062379115 | PZU18B1A        |
| 74ABT244D,623     | 935027510623 | 74ABT244D       |
| 74AUP2G126DC,125  | 935280729125 | 74AUP2G126DC    |
| PMPB20XPEZ        | 934066622184 | PMPB20XPE       |
| "74LVC132AD,112"  | 935282821112 | 74LVC132AD      |
| BSP61,115         | 933986360115 | BSP61           |
| BZB84-B5V1,215    | 934061709215 | BZB84-B5V1      |
| BF723,115         | 933917390115 | BF723           |
| BZX884-C56,315    | 934057468315 | BZX884-C56      |
| PMEG060V030EPDZ   | 934070194146 | PMEG060V030EPD  |
| PMEG4010BEA,135   | 934057918135 | PMEG4010BEA     |
| 74VHCT541D,118    | 935289523118 | 74VHCT541D      |
| PSMN1R8-40YLC,115 | 934066914115 | PSMN1R8-40YLC   |
| BUK7635-55A,118   | 934056192118 | BUK7635-55A     |
| 74AHCU04PW-Q100J  | 935300741118 | 74AHCU04PW-Q100 |
| BF824W,135        | 934028630135 | BF824W          |
| 1N4747A,113       | 933931730113 | 1N4747A         |
| PLVA656A,215      | 934017360215 | PLVA656A        |
| 74AUP2G241DC,125  | 935280738125 | 74AUP2G241DC    |
| BZX84-C18,215     | 933388280215 | BZX84-C18       |
| PEMB20,115        | 934058916115 | PEMB20          |
| 74HCT2G125DC,125  | 935274707125 | 74HCT2G125DC    |
| 74LVC1G04GX4Z     | 935690002147 | 74LVC1G04GX4    |
| BAT721S,215       | 934054930215 | BAT721S         |
| PMEG045T050EPDZ   | 934070409146 | PMEG045T050EPD  |
| "74AUP2G34GW,125" | 935279993125 | 74AUP2G34GW     |
| 74LV1T126GXH      | 935690211125 | 74LV1T126GX     |
| BZT52-C3V9J       | 934071105118 | BZT52-C3V9      |
| BC69-25PASX       | 934068113115 | BC69-25PAS      |
| 74HC4051D,653     | 933714820653 | 74HC4051D       |
| 74LVC1G332GXZ     | 935307075147 | 74LVC1G332GX    |
| BZX79-C12,133     | 933117810133 | BZX79-C12       |
| PMEG3015EJ,115    | 934059004115 | PMEG3015EJ      |
| BZX79-B4V7,133    | 933166800133 | BZX79-B4V7      |
| NPIC6C596APWJ     | 935302409118 | NPIC6C596APW    |
| "74HCT32PW,112"   | 935186910112 | 74HCT32PW       |
| "74AVC1T45GW,125" | 935284153125 | 74AVC1T45GW     |
| "74LVC1G00GX,125" | 935298374125 | 74LVC1G00GX     |
| PMEG4010CEJ,115   | 934059511115 | PMEG4010CEJ     |
| "74HC1G32GV,125"  | 935272007125 | 74HC1G32GV      |
| HEF4067BT,653     | 933372980653 | HEF4067BT       |

|                      |              |                  |
|----------------------|--------------|------------------|
| HEF4093BT-Q100,118   | 935298524118 | HEF4093BT-Q100   |
| 74HCT74D-Q100,118    | 935298884118 | 74HCT74D-Q100    |
| BZV55-B6V2,115       | 933827700115 | BZV55-B6V2       |
| PBSS4580PA,115       | 934063923115 | PBSS4580PA       |
| BUK761R7-40E,118     | 934066432118 | BUK761R7-40E     |
| 74ALVC16245DGG,118   | 935251810118 | 74ALVC16245DGG   |
| PESD5V0S1UB,115      | 934058511115 | PESD5V0S1UB      |
| "74HCT02PW,112"      | 935186240112 | 74HCT02PW        |
| BZV49-C18,115        | 933606020115 | BZV49-C18        |
| PSMN0R9-30YLDX       | 934068233115 | PSMN0R9-30YLD    |
| PEMH11,115           | 934056861115 | PEMH11           |
| "74LVC1G384GV,125"   | 935274582125 | 74LVC1G384GV     |
| "74AHC1G32GW-Q100,1" | 935298648125 | 74AHC1G32GW-Q100 |
| NX3008PBKW,115       | 934065636115 | NX3008PBKW       |
| 74HCT2G08DC,125      | 935274804125 | 74HCT2G08DC      |
| "74LV245PW,112"      | 935174660112 | 74LV245PW        |
| PSMN4R5-40PS,127     | 934063908127 | PSMN4R5-40PS     |
| PTVS5V0Z1USKPYL      | 934070853315 | PTVS5V0Z1USKP    |
| BZV55-B15,115        | 933827790115 | BZV55-B15        |
| BC846S,115           | 934055429115 | BC846S           |
| BZX585-B3V6,115      | 934055860115 | BZX585-B3V6      |
| BCP69,135            | 933969380135 | BCP69            |
| PMZB390UNEYL         | 934068613315 | PMZB390UNE       |
| PMV50UPE,215         | 934067139215 | PMV50UPE         |
| PZU5.6B2L,315        | 934061668315 | PZU5.6B2L        |
| BAT854CW,115         | 934056174115 | BAT854CW         |
| 74AHCT1G04GM,115     | 935297566115 | 74AHCT1G04GM     |
| BUK7Y43-60EX         | 934067482115 | BUK7Y43-60E      |
| 74LVCH245ADB,118     | 935211560118 | 74LVCH245ADB     |
| BST82,235            | 933733110235 | BST82            |
| BCX17,215            | 933209620215 | BCX17            |
| 74HC4520D,118        | 933714900118 | 74HC4520D        |
| PMBD914,215          | 933856870215 | PMBD914          |
| PUMD24,115           | 934058902115 | PUMD24           |
| PESD2USB30Z          | 934069598087 | PESD2USB30       |
| 74AUP2G07GM,115      | 935279986115 | 74AUP2G07GM      |
| 74LV14D,118          | 935069490118 | 74LV14D          |
| "74AUP1G157GW,125"   | 935279969125 | 74AUP1G157GW     |
| PESD1USB30Z          | 934069595087 | PESD1USB30       |
| 74HCT04D,653         | 933714340653 | 74HCT04D         |
| "74LVC827APW,112"    | 935262420112 | 74LVC827APW      |
| PSMN1R1-30PL,127     | 934065166127 | PSMN1R1-30PL     |
| 74CBTLV3245BQ,115    | 935293822115 | 74CBTLV3245BQ    |
| BC857B,235           | 933589760235 | BC857B           |
| BZX84J-B39,115       | 934060954115 | BZX84J-B39       |
| BZX84J-C16,115       | 934060987115 | BZX84J-C16       |

|                      |              |                  |
|----------------------|--------------|------------------|
| PMEG100V080ELPDAZ    | 934069521139 | PMEG100V080ELPD  |
| BUK7Y153-100EX       | 934067447115 | BUK7Y153-100E    |
| 74LVC595APW,118      | 935282471118 | 74LVC595APW      |
| 74LVC2G00GM,125      | 935277235125 | 74LVC2G00GM      |
| BZX384-C24,115       | 934057649115 | BZX384-C24       |
| "74LVT162245BDGG,11" | 935204110112 | 74LVT162245BDGG  |
| 74HCT4051DB,118      | 935173800118 | 74HCT4051DB      |
| 74LV165PW-Q100J      | 935301545118 | 74LV165PW-Q100   |
| BZV55-C16,115        | 933699570115 | BZV55-C16        |
| BZX79-B3V3,133       | 933549950133 | BZX79-B3V3       |
| HEF4081BT,653        | 933373090653 | HEF4081BT        |
| BAT54CW,115          | 934028900115 | BAT54CW          |
| 74AHCT07APWJ         | 935308212118 | 74AHCT07APW      |
| BUK9Y14-80E,115      | 934067029115 | BUK9Y14-80E      |
| 74LV07ATPWJ          | 935308209118 | 74LV07ATPW       |
| PMV450ENEAR          | 934068702215 | PMV450ENEA       |
| PMEG4010BEA/DG,115   | 934063576115 | PMEG4010BEA/DG   |
| BZX84-A30,215        | 934065157215 | BZX84-A30        |
| 74HCT04PW,118        | 935174220118 | 74HCT04PW        |
| 74HC20D-Q100,118     | 935298781118 | 74HC20D-Q100     |
| 74HCT125PW-Q100J     | 935300332118 | 74HCT125PW-Q100  |
| 1N4742A,133          | 933931680133 | 1N4742A          |
| BZV55-C3V6,115       | 933699410115 | BZV55-C3V6       |
| BUK9Y21-40E,115      | 934067048115 | BUK9Y21-40E      |
| "74LVC1G125GW,125"   | 935268720125 | 74LVC1G125GW     |
| 74HC367D,653         | 933714690653 | 74HC367D         |
| PBSS4480X,135        | 934058209135 | PBSS4480X        |
| "74AHCT1G32GV,125"   | 935271667125 | 74AHCT1G32GV     |
| 74LVC2G04GW-Q100H    | 935302657125 | 74LVC2G04GW-Q100 |
| PBSS4140T,235        | 934056515235 | PBSS4140T        |
| PTVS3V3P1UP,115      | 934064143115 | PTVS3V3P1UP      |
| 74HCT573PW,118       | 935186990118 | 74HCT573PW       |
| PSMN3R0-60BS,118     | 934066328118 | PSMN3R0-60BS     |
| 74HC4017D,653        | 933714760653 | 74HC4017D        |
| "74LVC1G32GV,125"    | 935272013125 | 74LVC1G32GV      |
| PESD24VS1UA,115      | 934065353115 | PESD24VS1UA      |
| PMPB29XPE,115        | 934066873115 | PMPB29XPE        |
| "HEF4020BT,652"      | 933372730652 | HEF4020BT        |
| PMEG60T10ELRX        | 934070785115 | PMEG60T10ELR     |
| BC869-25,115         | 933975320115 | BC869-25         |
| BZX585-B3V9,115      | 934055861115 | BZX585-B3V9      |
| BZX84-C5V1,235       | 933137390235 | BZX84-C5V1       |
| BUK9M24-40EX         | 934070088115 | BUK9M24-40E      |
| PMEG030V030EPDZ      | 934070188146 | PMEG030V030EPD   |
| 74LVC2G02DP,125      | 935273579125 | 74LVC2G02DP      |
| PZU10DB2,115         | 934061545115 | PZU10DB2         |



|                      |              |                  |
|----------------------|--------------|------------------|
| PBRN123YT,215        | 934058989215 | PBRN123YT        |
| 74CBTLV3257PW,118    | 935290007118 | 74CBTLV3257PW    |
| BZX84-B5V6,215       | 933564710215 | BZX84-B5V6       |
| "74HC21D,652"        | 933756870652 | 74HC21D          |
| 74HCT00PW,118        | 935182810118 | 74HCT00PW        |
| BZX79-C5V6,133       | 933117730133 | BZX79-C5V6       |
| BC858W,115           | 934021870115 | BC858W           |
| BCW60D,235           | 933324110235 | BCW60D           |
| PESD5Z6.0,115        | 934061266115 | PESD5Z6.0        |
| NZH8V2B,115          | 934064364115 | NZH8V2B          |
| PMEG3005EGWJ         | 934070451118 | PMEG3005EGW      |
| "74LVCH162373ADGG,1" | 935238750112 | 74LVCH162373ADGG |
| PMEG4002AESFYL       | 934068039315 | PMEG4002AESF     |
| PMST3906,115         | 934026930115 | PMST3906         |
| PTVS36VS1UR/8X       | 934660642115 | PTVS36VS1UR/8    |
| PMEG2015EH,115       | 934059276115 | PMEG2015EH       |
| BZT52-C33X           | 934071118115 | BZT52-C33        |
| 74AHC157PW,118       | 935263999118 | 74AHC157PW       |
| PMEG2010EA,115       | 934057100115 | PMEG2010EA       |
| 74HC194DB,118        | 935189740118 | 74HC194DB        |
| PDTC114TT,215        | 934034900215 | PDTC114TT        |
| NZH3V0B,115          | 934064352115 | NZH3V0B          |
| PDTC144WU,115        | 934054828115 | PDTC144WU        |
| BZX884-B5V1,315      | 934057192315 | BZX884-B5V1      |
| 74LVC2G32GXX         | 935339798115 | 74LVC2G32GX      |
| "74AUP1G04GX,125"    | 935298355125 | 74AUP1G04GX      |
| "74LVC162244ADGG,11" | 935237680112 | 74LVC162244ADGG  |
| 74ALVC245PW,118      | 935269726118 | 74ALVC245PW      |
| PDZ18B,115           | 934054865115 | PDZ18B           |
| BZT52-C12J           | 934071127118 | BZT52-C12        |
| 74AXP1T34GMH         | 935306991125 | 74AXP1T34GM      |
| "74HCT257D,652"      | 933713650652 | 74HCT257D        |
| BUK9Y107-80EX        | 934067598115 | BUK9Y107-80E     |
| PUSB3FR6Z            | 934068777471 | PUSB3FR6         |
| BZT52-C47J           | 934071123118 | BZT52-C47        |
| BZV49-C7V5,115       | 933605930115 | BZV49-C7V5       |
| 74HC251D,652         | 933713520652 | 74HC251D         |
| BAT86,113            | 933624770113 | BAT86            |
| BCP56TX              | 934070117115 | BCP56T           |
| BAV199,215           | 934032640215 | BAV199           |
| PMPB27EPAX           | 934070932115 | PMPB27EPA        |
| "74AUP1G32GW,125"    | 935279026125 | 74AUP1G32GW      |
| 74AUP2G132GXX        | 935339796115 | 74AUP2G132GX     |
| PBSS5140T,215        | 934056330215 | PBSS5140T        |
| PESD3V3U1UT,215      | 934059101215 | PESD3V3U1UT      |
| 74AUP1G3208GXZ       | 935308466147 | 74AUP1G3208GX    |

|                      |              |                 |
|----------------------|--------------|-----------------|
| BCV62A,215           | 933792130215 | BCV62A          |
| BZV49-C8V2,115       | 933605940115 | BZV49-C8V2      |
| PESD5V0G1BL/XMZ      | 934660597303 | PESD5V0G1BL/XM  |
| 74AUP2G126GXX        | 935308443115 | 74AUP2G126GX    |
| "74LVT162244BDGG,11" | 935204090112 | 74LVT162244BDGG |
| 74HC4053DB,118       | 935166800118 | 74HC4053DB      |
| "74HCT03PW,118"      | 935186250118 | 74HCT03PW       |
| BZX84J-B5V6,115      | 934060971115 | BZX84J-B5V6     |
| PDTA143ET,215        | 934031050215 | PDTA143ET       |
| 74AHC126BQ,115       | 935289621115 | 74AHC126BQ      |
| 74HC2G86DP-Q100H     | 935302243125 | 74HC2G86DP-Q100 |
| "74LVC1G17GX,125"    | 935298379125 | 74LVC1G17GX     |
| 74HC138DB,112        | 935174410112 | 74HC138DB       |
| 74HC08D,653          | 933714270653 | 74HC08D         |
| 74LVC163BQ,115       | 935275615115 | 74LVC163BQ      |
| "74AUP1Z04GW,125"    | 935280519125 | 74AUP1Z04GW     |
| PTVS3V3S1UTR,115     | 934065473115 | PTVS3V3S1UTR    |
| PH2530AL,115         | 934063084115 | PH2530AL        |
| "74AHC32PW,112"      | 935262643112 | 74AHC32PW       |
| PMZB200UNEYL         | 934068606315 | PMZB200UNE      |
| BSS64,215            | 933331500215 | BSS64           |
| 74LVC2G06GV,125      | 935273881125 | 74LVC2G06GV     |
| PMEG3030BEP,115      | 934061476115 | PMEG3030BEP     |
| 74HCT280D,653        | 933713890653 | 74HCT280D       |
| BZV49-C5V1,115       | 933605890115 | BZV49-C5V1      |
| 2PB710ASL,215        | 934062304215 | 2PB710ASL       |
| BZT52-C8V2X          | 934071114115 | BZT52-C8V2      |
| PDZ2.4B,115          | 934054842115 | PDZ2.4B         |
| PDTD113ET,215        | 934058975215 | PDTD113ET       |
| TL431AIDBZR,215      | 935288021215 | TL431AIDBZR     |
| "74ALVC08D,112"      | 935269716112 | 74ALVC08D       |
| "74AHCT595PW,112"    | 935265560112 | 74AHCT595PW     |
| 74HC241D,652         | 933713460652 | 74HC241D        |
| 74AHC132D/S707,118   | 935296676118 | 74AHC132D/S707  |
| BC807-40W,135        | 934024260135 | BC807-40W       |
| 74HC541D-Q100J       | 935300887118 | 74HC541D-Q100   |
| PESD5V0F1BL,315      | 934062806315 | PESD5V0F1BL     |
| 74HC14BQ,115         | 935273486115 | 74HC14BQ        |
| 74LVC2GU04GM,115     | 935277165115 | 74LVC2GU04GM    |
| PBSS9410PA,115       | 934063926115 | PBSS9410PA      |
| 74LVC1G02GM,115      | 935277187115 | 74LVC1G02GM     |
| PESD5V0L5UF,115      | 934061199115 | PESD5V0L5UF     |
| PTVS13VS1UR,115      | 934061351115 | PTVS13VS1UR     |
| PMEG4010EP,115       | 934061482115 | PMEG4010EP      |
| "74LVT125D,112"      | 935170510112 | 74LVT125D       |
| 74AHCV541ABQX        | 935306798115 | 74AHCV541ABQ    |

|                    |              |                  |
|--------------------|--------------|------------------|
| 74ABT16245BDGG,118 | 935203390118 | 74ABT16245BDGG   |
| PBSS9110Z,135      | 934057978135 | PBSS9110Z        |
| BZX79-C4V3,113     | 933117700113 | BZX79-C4V3       |
| "74HC154PW,112"    | 935182580112 | 74HC154PW        |
| BCP53,115          | 933917330115 | BCP53            |
| PBSS3540M,315      | 934057155315 | PBSS3540M        |
| HEF4015BT,653      | 933372680653 | HEF4015BT        |
| BUK9M5R2-30EX      | 934070074115 | BUK9M5R2-30E     |
| PBLS6023D,115      | 934061571115 | PBLS6023D        |
| 74HC164D-Q100J     | 935300442118 | 74HC164D-Q100    |
| 74LVC86AD,118      | 935250090118 | 74LVC86AD        |
| TL431ACDBZR,215    | 935288019215 | TL431ACDBZR      |
| "74HCT280D,652"    | 933713890652 | 74HCT280D        |
| IP4285CZ6-TD,125   | 934066066125 | IP4285CZ6-TD     |
| BC858B,235         | 933589790235 | BC858B           |
| BZV55-B56,115      | 933931870115 | BZV55-B56        |
| PDZ22BGWJ          | 934071056118 | PDZ22BGW         |
| NPIC6C596AD-Q100J  | 935302415118 | NPIC6C596AD-Q100 |
| PESD5V0H1BSFYL     | 934068765315 | PESD5V0H1BSF     |
| PMEG1020EH,115     | 934059028115 | PMEG1020EH       |
| RB520CS30L,315     | 934064974315 | RB520CS30L       |
| 74LVC2G00DC,125    | 935275224125 | 74LVC2G00DC      |
| BZX79-C20,133      | 933117860133 | BZX79-C20        |
| BZX585-C5V6,135    | 934055845135 | BZX585-C5V6      |
| "74LVC2G06GW,125"  | 935273882125 | 74LVC2G06GW      |
| 74HC3G04DP,125     | 935271930125 | 74HC3G04DP       |
| PMBS3906,215       | 933972880215 | PMBS3906         |
| PHDMI2FR4Z         | 934660002471 | PHDMI2FR4        |
| PBSS4540Z,115      | 934055495115 | PBSS4540Z        |
| BZV55-C11,115      | 933699530115 | BZV55-C11        |
| HEF4894BTT-Q100,11 | 935298526118 | HEF4894BTT-Q100  |
| "74LVTH244APW,112" | 935262071112 | 74LVTH244APW     |
| PBHV8115Z,115      | 934061411115 | PBHV8115Z        |
| 74HC175PW,118      | 935174560118 | 74HC175PW        |
| PTVS24VU1UPAZ      | 934071207147 | PTVS24VU1UPA     |
| "74LVC74APW,118"   | 935260736118 | 74LVC74APW       |
| 74AUP2G32GM,125    | 935281426125 | 74AUP2G32GM      |
| BZX84-A3V9,215     | 934011760215 | BZX84-A3V9       |
| 74HC165D,653       | 933713780653 | 74HC165D         |
| PDTB143XUF         | 934068338135 | PDTB143XU        |
| BZX884-B51,315     | 934057450315 | BZX884-B51       |
| PMEG045V050EPDZ    | 934067174146 | PMEG045V050EPD   |
| 74LVC1T45GM,115    | 935284752115 | 74LVC1T45GM      |
| 74HC02D,653        | 933714150653 | 74HC02D          |
| BAV199W,115        | 934054800115 | BAV199W          |
| PESD5V0U5BF,115    | 934061967115 | PESD5V0U5BF      |

|                      |              |                  |
|----------------------|--------------|------------------|
| "74HC4067D,652"      | 933715660652 | 74HC4067D        |
| BUK7277-55A,118      | 934056248118 | BUK7277-55A      |
| "74HCT27PW,118"      | 935189580118 | 74HCT27PW        |
| "74AHC04PW,118"      | 935263041118 | 74AHC04PW        |
| BZT52-B5V1X          | 934071152115 | BZT52-B5V1       |
| PXTA42,115           | 933926790115 | PXTA42           |
| PUMB1,115            | 934057881115 | PUMB1            |
| TDZ16J,115           | 934065791115 | TDZ16J           |
| "74AHC1G09GW,125"    | 935279914125 | 74AHC1G09GW      |
| 74LVC2G14GM,115      | 935277162115 | 74LVC2G14GM      |
| PDTB123YUF           | 934068336135 | PDTB123YU        |
| 74AUP1G175GM,115     | 935280004115 | 74AUP1G175GM     |
| 74LV165PW,112        | 935174540112 | 74LV165PW        |
| "74AVCH1T45GS,132"   | 935294363132 | 74AVCH1T45GS     |
| BZX84-C9V1,215       | 933137450215 | BZX84-C9V1       |
| 74HCT4040PW,112      | 935189100112 | 74HCT4040PW      |
| PBSS304PZ,135        | 934059052135 | PBSS304PZ        |
| BC846BMB,315         | 934066134315 | BC846BMB         |
| PMZ1000UN,315        | 934063419315 | PMZ1000UN        |
| "74HCT132D,652"      | 933714140652 | 74HCT132D        |
| PBSS4021PX,115       | 934063403115 | PBSS4021PX       |
| PBSS5250T,215        | 934057992215 | PBSS5250T        |
| NPIC6C596ABQX        | 935302407115 | NPIC6C596ABQ     |
| "74AHCT1G00GV,125"   | 935271648125 | 74AHCT1G00GV     |
| BZT52-C75J           | 934071141118 | BZT52-C75        |
| 74LVC10AD,118        | 935260743118 | 74LVC10AD        |
| PTVS5V0S1UR,115      | 934061338115 | PTVS5V0S1UR      |
| 74LVC373ABQ,115      | 935275055115 | 74LVC373ABQ      |
| "74ALVC16245DGG,112" | 935251810112 | 74ALVC16245DGG   |
| PMBT2222,215         | 933846830215 | PMBT2222         |
| 1PS70SB44,115        | 934045450115 | 1PS70SB44        |
| BCP68,115            | 933968660115 | BCP68            |
| PDTA123EU,115        | 934057532115 | PDTA123EU        |
| PSMN5R0-30YL,115     | 934063075115 | PSMN5R0-30YL     |
| "74HC595D,112"       | 935009160112 | 74HC595D         |
| PMPB29XPEAX          | 934070928115 | PMPB29XPEA       |
| 74LVC4245AD,118      | 935260749118 | 74LVC4245AD      |
| BUK9Y19-75B,115      | 934063305115 | BUK9Y19-75B      |
| BUK9Y29-40E,115      | 934067049115 | BUK9Y29-40E      |
| BAS16,215            | 933460620215 | BAS16            |
| BZB84-B6V8,215       | 934061713215 | BZB84-B6V8       |
| "74LVC2G34GW,125"    | 935273783125 | 74LVC2G34GW      |
| BZB84-B10,215        | 934061717215 | BZB84-B10        |
| 74LVC1G86GW-Q100H    | 935302545125 | 74LVC1G86GW-Q100 |
| BC817K-16VL          | 934660054235 | BC817K-16        |
| BZT52H-B3V0,115      | 934064779115 | BZT52H-B3V0      |

|                    |              |                |
|--------------------|--------------|----------------|
| PBSS4041SN,115     | 934063412115 | PBSS4041SN     |
| PBSS5480X,135      | 934058211135 | PBSS5480X      |
| 74AVC16T245DGG,118 | 935286228118 | 74AVC16T245DGG |
| BZX84J-B12,115     | 934060938115 | BZX84J-B12     |
| "74LVC1G79GV,125"  | 935272020125 | 74LVC1G79GV    |
| PMPB10XNEAX        | 934070922115 | PMPB10XNEA     |
| PEMT1,115          | 934056707115 | PEMT1          |
| BUK7Y14-80EX       | 934067422115 | BUK7Y14-80E    |
| "74AHCT244PW,112"  | 935261959112 | 74AHCT244PW    |
| PESD5V0C1USFYL     | 934068767315 | PESD5V0C1USF   |
| "74HCT367D,652"    | 933715170652 | 74HCT367D      |
| "74AHCT126PW,118"  | 935262767118 | 74AHCT126PW    |
| BZX384-B22,115     | 934057381115 | BZX384-B22     |
| NPIC6C595D,118     | 935297269118 | NPIC6C595D     |
| 74HC00BQ-Q100,115  | 935298683115 | 74HC00BQ-Q100  |
| PMEG6030EP/8X      | 934070025115 | PMEG6030EP/8   |
| BAS521,135         | 934057766135 | BAS521         |
| NX2301P,215        | 934064624215 | NX2301P        |
| BSP89,115          | 934018750115 | BSP89          |
| PMZ600UNEZ         | 934068653305 | PMZ600UNE      |
| BUK7Y72-80EX       | 934067425115 | BUK7Y72-80E    |
| "HEF4013BTT,118"   | 935283039118 | HEF4013BTT     |
| BZV85-C18,133      | 933500710133 | BZV85-C18      |
| PZU10B,115         | 934059763115 | PZU10B         |
| 74LVC1GX04GV,125   | 935274025125 | 74LVC1GX04GV   |
| PBSS4250X,135      | 934057967135 | PBSS4250X      |
| PMH550UNEH         | 934660491125 | PMH550UNE      |
| 74LVC3G04DP,125    | 935275562125 | 74LVC3G04DP    |
| 74AHCV244APWJ      | 935308263118 | 74AHCV244APW   |
| BC807-25,235       | 933628570235 | BC807-25       |
| BZX585-C4V7,115    | 934055843115 | BZX585-C4V7    |
| BUK9219-55A,118    | 934056240118 | BUK9219-55A    |
| PDTA115ET,215      | 934058185215 | PDTA115ET      |
| 74HCT4060D,653     | 933714020653 | 74HCT4060D     |
| "74AUP2G34GS,132"  | 935292889132 | 74AUP2G34GS    |
| PMBT2222A,215      | 933821790215 | PMBT2222A      |
| PHPT60603NYX       | 934067878115 | PHPT60603NY    |
| BZV85-C16,133      | 933500700133 | BZV85-C16      |
| BF823,215          | 933640900215 | BF823          |
| BZV49-C11,115      | 933605970115 | BZV49-C11      |
| "74AUP2G17GW,125"  | 935279991125 | 74AUP2G17GW    |
| BUK9M12-60EX       | 934070046115 | BUK9M12-60E    |
| 2PA1774QM,315      | 934057143315 | 2PA1774QM      |
| 1N4733A,133        | 933931590133 | 1N4733A        |
| "HEF4007UBT,652"   | 933372620652 | HEF4007UBT     |
| 74LVC1G74DC,125    | 935274973125 | 74LVC1G74DC    |

|                      |              |                   |
|----------------------|--------------|-------------------|
| NX3008NBKS,115       | 934065637115 | NX3008NBKS        |
| HEF4521BT,653        | 933406770653 | HEF4521BT         |
| PBHV9050Z,115        | 934064553115 | PBHV9050Z         |
| BAS21AVD,135         | 934059099135 | BAS21AVD          |
| 74HC7540DB,118       | 935190290118 | 74HC7540DB        |
| BC849CW,115          | 934022070115 | BC849CW           |
| 2PB709ARL,235        | 934062297235 | 2PB709ARL         |
| "HEF4070BT,652"      | 933373010652 | HEF4070BT         |
| BC817W,135           | 934021910135 | BC817W            |
| 74AVC8T245PW:112     | 935284593112 | 74AVC8T245PW      |
| 74HCT00D,652         | 933713370652 | 74HCT00D          |
| "74HC4066PW-Q100,11" | 935298456118 | 74HC4066PW-Q100   |
| "74LVCH162374ADGG,1" | 935238770112 | 74LVCH162374ADGG  |
| "74LV393D,112"       | 935162810112 | 74LV393D          |
| 74AHC573D,118        | 935263075118 | 74AHC573D         |
| PMXB56ENZ            | 934067234147 | PMXB56EN          |
| BSP220,115           | 934000490115 | BSP220            |
| BSH108,215           | 934055571215 | BSH108            |
| BZV55-C12,135        | 933699540135 | BZV55-C12         |
| 74HC165PW-Q100,118   | 935298768118 | 74HC165PW-Q100    |
| PQMD13Z              | 934069748147 | PQMD13            |
| "74LVC1G38GW,125"    | 935276661125 | 74LVC1G38GW       |
| BCX53,146            | 933272300146 | BCX53             |
| PMEG6010CEJF         | 934059512135 | PMEG6010CEJ       |
| BZT52-B75J           | 934071173118 | BZT52-B75         |
| "74HCT2G17GW,125"    | 935281029125 | 74HCT2G17GW       |
| TL431BQDBZR,215      | 935288025215 | TL431BQDBZR       |
| PDTC124TM,315        | 934057176315 | PDTC124TM         |
| 74LVC1G332GW-Q100H   | 935304346125 | 74LVC1G332GW-Q100 |
| NX3008PBKS,115       | 934065638115 | NX3008PBKS        |
| BAS16J,115           | 934060935115 | BAS16J            |
| BC847CQAZ            | 934069068147 | BC847CQA          |
| "74LVT16244BDGG,112" | 935202990112 | 74LVT16244BDGG    |
| 74LV08PW-Q100,118    | 935299071118 | 74LV08PW-Q100     |
| BCP52-16,115         | 933917320115 | BCP52-16          |
| 74HC688D,653         | 933713900653 | 74HC688D          |
| BZX84J-B18,115       | 934060943115 | BZX84J-B18        |
| 74AVC8T245BQ,118     | 935284591118 | 74AVC8T245BQ      |
| HEC4027BT,118        | 935209340118 | HEC4027BT         |
| PDTC114EU,135        | 934044140135 | PDTC114EU         |
| PMEG2010EJ,115       | 934058524115 | PMEG2010EJ        |
| MMBZ6V8AL,215        | 934063465215 | MMBZ6V8AL         |
| PBSS4260PANP,115     | 934066892115 | PBSS4260PANP      |
| BUK7631-100E,118     | 934066642118 | BUK7631-100E      |
| "74HCT151D,652"      | 933713710652 | 74HCT151D         |
| PMEG045V050EPDAZ     | 934067174139 | PMEG045V050EPD    |

|                      |              |                 |
|----------------------|--------------|-----------------|
| BCP55-16,115         | 933917230115 | BCP55-16        |
| BC849B,235           | 933589660235 | BC849B          |
| BAS40,235            | 934034530235 | BAS40           |
| 74LVC161DB,118       | 935210520118 | 74LVC161DB      |
| PSMN2R7-30BL,118     | 934066326118 | PSMN2R7-30BL    |
| BCP54,135            | 933917180135 | BCP54           |
| "74HCT1G00GW,125"    | 935245600125 | 74HCT1G00GW     |
| PHPT61002PYCX        | 934067877115 | PHPT61002PYC    |
| PMEG2005AEA,115      | 934057738115 | PMEG2005AEA     |
| 1N4741A,113          | 933931670113 | 1N4741A         |
| BZV55-C3V3,115       | 933699400115 | BZV55-C3V3      |
| PMEG3020ER,115       | 934061461115 | PMEG3020ER      |
| 74HC125PW-Q100J      | 935300329118 | 74HC125PW-Q100  |
| 74HC86PW,118         | 935187570118 | 74HC86PW        |
| PESD2IVN24-TR        | 934070274215 | PESD2IVN24-T    |
| "74HC245PW,112"      | 935183570112 | 74HC245PW       |
| PMV48XP,215          | 934065361215 | PMV48XP         |
| "74LVC594AD,112"     | 935282444112 | 74LVC594AD      |
| 74LV4053PW,118       | 935174970118 | 74LV4053PW      |
| "74CBTLV1G125GW,125" | 935280319125 | 74CBTLV1G125GW  |
| 74AUP1G11GF,132      | 935281354132 | 74AUP1G11GF     |
| 74HC4052BQ,115       | 935273689115 | 74HC4052BQ      |
| 74LVC132ABQ,115      | 935282822115 | 74LVC132ABQ     |
| 74HCT238BQ,115       | 935283682115 | 74HCT238BQ      |
| PESD5V0X1UALD,315    | 934065595315 | PESD5V0X1UALD   |
| "74LVCH162373ADL,11" | 935238740112 | 74LVCH162373ADL |
| PSMN8R5-40MSDX       | 934661554115 | PSMN8R5-40MSD   |
| BZV85-C5V6,113       | 933500590113 | BZV85-C5V6      |
| PMCM440VNEZ          | 934068625084 | PMCM440VNE      |
| 74AXP2T3407GTX       | 935306977115 | 74AXP2T3407GT   |
| 74LVT126PW,112       | 935209470112 | 74LVT126PW      |
| BZX79-C16,133        | 933117840133 | BZX79-C16       |
| 74HC75PW,118         | 935188530118 | 74HC75PW        |
| 74LVC2G74GM,125      | 935281298125 | 74LVC2G74GM     |
| 74HCT153D-Q100J      | 935300781118 | 74HCT153D-Q100  |
| PHB47NQ10T,118       | 934056745118 | PHB47NQ10T      |
| 74AHCT00D,118        | 935262688118 | 74AHCT00D       |
| BZV85-C56,113        | 933500830113 | BZV85-C56       |
| BCX19,235            | 933209640235 | BCX19           |
| PHPT60410NYX         | 934068581115 | PHPT60410NY     |
| PUMD13,115           | 934056288115 | PUMD13          |
| "74HC688PW,112"      | 935189170112 | 74HC688PW       |
| BZV90-C13,115        | 934014790115 | BZV90-C13       |
| 74HCT373PW,118       | 935174830118 | 74HCT373PW      |
| BCM857QASZ           | 934660013147 | BCM857QAS       |
| PESD5V0U4BW,115      | 934061953115 | PESD5V0U4BW     |

|                    |              |                     |
|--------------------|--------------|---------------------|
| PMN30XPEX          | 934660262115 | PMN30XPE            |
| PSMN0R7-25YLDX     | 934069083115 | PSMN0R7-25YLD       |
| BUK7628-100A,118   | 934055882118 | BUK7628-100A        |
| BZT52H-B9V1,115    | 934064793115 | BZT52H-B9V1         |
| 74ALVCH162245DGG,1 | 935210840112 | 74ALVCH162245DGG    |
| BZX79-B6V2,113     | 933166830113 | BZX79-B6V2          |
| BZX84-B27,215      | 933770450215 | BZX84-B27           |
| 74AUP1G98GXZ       | 935307128147 | 74AUP1G98GX         |
| 74HC151PW,118      | 935188950118 | 74HC151PW           |
| BAS70-04,235       | 934020800235 | BAS70-04            |
| PTVS20VP1UP,115    | 934064173115 | PTVS20VP1UP         |
| IP4220CZ6F         | 934058429135 | IP4220CZ6           |
| 74LVC3G14DP,125    | 935275561125 | 74LVC3G14DP         |
| 74LVC4T3144PWJ     | 935339706118 | 74LVC4T3144PW       |
| 74LV541ATPWJ       | 935306646118 | 74LV541ATPW         |
| "74AUP1G11GW,125"  | 935280745125 | 74AUP1G11GW         |
| "74AHC32PW,118"    | 935262643118 | 74AHC32PW           |
| 74AXP1G125GXH      | 935303211125 | 74AXP1G125GX        |
| 74AHCT132D,112     | 935262995112 | 74AHCT132D          |
| "74AUP1T34GW,125"  | 935280516125 | 74AUP1T34GW         |
| BZT52H-C16,115     | 934059407115 | BZT52H-C16          |
| BCP54-10,135       | 933917190135 | BCP54-10            |
| PMEG45U10EPDZ      | 934068206146 | PMEG45U10EPD        |
| "74HCT1G125GW,125" | 935245680125 | 74HCT1G125GW        |
| "74HC151D,652"     | 933713700652 | 74HC151D            |
| BZT52-C62X         | 934071138115 | BZT52-C62           |
| BZX84-B3V3,215     | 933551430215 | BZX84-B3V3          |
| BAS70L,315         | 934057251315 | BAS70L              |
| PBSS5250THR        | 934071077215 | PBSS5250TH          |
| PSMN3R4-30BLE,118  | 934066899118 | PSMN3R4-30BLE       |
| BZX84-C3V6,215     | 933516960215 | BZX84-C3V6          |
| "HEF4093BT,652"    | 933373130652 | HEF4093BT           |
| PSSI2021SAY,115    | 934056564115 | PSSI2021SAY         |
| BZX84-A18,215      | 934065154215 | BZX84-A18           |
| BAV20,113          | 933189200113 | BAV20               |
| 74LVT240PW,118     | 935176340118 | 74LVT240PW          |
| 74LVC2G34GW-Q100/H | 935340098125 | 74LVC2G34GW-Q100/CU |
| BCW71,215          | 933149390215 | BCW71               |
| BC56-10PASX        | 934068132115 | BC56-10PAS          |
| 74AHC273D,118      | 935263592118 | 74AHC273D           |
| PESD5V0V2BMYL      | 934069288315 | PESD5V0V2BM         |
| PMSTA42,115        | 934042280115 | PMSTA42             |
| 74AVC1T45GM,115    | 935284154115 | 74AVC1T45GM         |
| PSMN2R4-30YLDX     | 934067965115 | PSMN2R4-30YLD       |
| BAS40H,115         | 934059281115 | BAS40H              |
| PDTC143XU,115      | 934057543115 | PDTC143XU           |



|                      |              |                  |
|----------------------|--------------|------------------|
| BC817K-40HVL         | 934660225235 | BC817K-40H       |
| PSMN2R9-30MLC,115    | 934066936115 | PSMN2R9-30MLC    |
| "74LVC1G07GX,125"    | 935298377125 | 74LVC1G07GX      |
| BZT52-B5V6J          | 934071153118 | BZT52-B5V6       |
| BC868,115            | 933678770115 | BC868            |
| PUMD3,135            | 934050170135 | PUMD3            |
| BZX384-B4V7,115      | 934057365115 | BZX384-B4V7      |
| BZX384-C16,115       | 934057645115 | BZX384-C16       |
| "74AUP1G175GN,132"   | 935291728132 | 74AUP1G175GN     |
| BFS19,215            | 933083501215 | BFS19            |
| BZX84-C39,235        | 933388360235 | BZX84-C39        |
| PBSS4160PANSX        | 934068999115 | PBSS4160PANS     |
| 74LVCH162245ADGG:1   | 935238730118 | 74LVCH162245ADGG |
| BAS70-06W,115        | 934034500115 | BAS70-06W        |
| 74HCT374PW,118       | 935174880118 | 74HCT374PW       |
| BZX384-C15,115       | 934057644115 | BZX384-C15       |
| "74AUP1G17GX,125"    | 935298228125 | 74AUP1G17GX      |
| BUK9M43-100EX        | 934070071115 | BUK9M43-100E     |
| 74LVC594ABQ,115      | 935282466115 | 74LVC594ABQ      |
| HEF4520BT,653        | 933373250653 | HEF4520BT        |
| 74AHCT245PW-Q100J    | 935300204118 | 74AHCT245PW-Q100 |
| BZV55-B18,115        | 933827810115 | BZV55-B18        |
| PESD5V0X1BCAL,315    | 934066311315 | PESD5V0X1BCAL    |
| "74AHC1G125GV,125"   | 935271661125 | 74AHC1G125GV     |
| "74HC390D,652"       | 933714720652 | 74HC390D         |
| PDZ10BGWX            | 934071042115 | PDZ10BGW         |
| PESD2ETH-XR          | 934070187215 | PESD2ETH-X       |
| "74HCT1G125GV,125"   | 935271789125 | 74HCT1G125GV     |
| BAS40-07V,115        | 934056717115 | BAS40-07V        |
| "74ABT125PW,112"     | 935201060112 | 74ABT125PW       |
| "74ALVT16373DGG,112" | 935209640112 | 74ALVT16373DGG   |
| BZX84J-B36,115       | 934060953115 | BZX84J-B36       |
| 74LVC157ABQ,115      | 935273682115 | 74LVC157ABQ      |
| BC868-25,115         | 934005380115 | BC868-25         |
| BF822,215            | 933640890215 | BF822            |
| PMBF170,215          | 933966340215 | PMBF170          |
| BZT52H-B8V2,115      | 934064792115 | BZT52H-B8V2      |
| 74LVTH16245BDL,118   | 935281752118 | 74LVTH16245BDL   |
| PZU30BA,115          | 934062481115 | PZU30BA          |
| PEMZ1,115            | 934056705115 | PEMZ1            |
| BZX79-C39,133        | 933117930133 | BZX79-C39        |
| "74HC27D,652"        | 933714170652 | 74HC27D          |
| BCX17,235            | 933209620235 | BCX17            |
| BZT52-C9V1J          | 934071117118 | BZT52-C9V1       |
| BUK9M85-60EX         | 934070043115 | BUK9M85-60E      |
| 74LVC244AD,112       | 935210400112 | 74LVC244AD       |

|                    |              |                   |
|--------------------|--------------|-------------------|
| BZB784-C4V7,115    | 934056303115 | BZB784-C4V7       |
| 2N7002PS,115       | 934064134115 | 2N7002PS          |
| BSN20BKR           | 934068054215 | BSN20BK           |
| PESD24VS2UAT,215   | 934058066215 | PESD24VS2UAT      |
| PESD5V0L1UL,315    | 934062738315 | PESD5V0L1UL       |
| 74AXP1G14GXH       | 935304076125 | 74AXP1G14GX       |
| 74HC20PW,118       | 935188990118 | 74HC20PW          |
| 74AHC04BQ,115      | 935278823115 | 74AHC04BQ         |
| PUSB2X4DH          | 934068076125 | PUSB2X4D          |
| 74HCT3G14DP,125    | 935272125125 | 74HCT3G14DP       |
| 74LVC06AD-Q100J    | 935301427118 | 74LVC06AD-Q100    |
| BZX84-B13,215      | 933770380215 | BZX84-B13         |
| PMZ950UPEYL        | 934068445315 | PMZ950UPE         |
| PBSS3515M,315      | 934057156315 | PBSS3515M         |
| PTVS13VP1UTP,115   | 934065541115 | PTVS13VP1UTP      |
| BZX884-B6V2,315    | 934057194315 | BZX884-B6V2       |
| BCP52,135          | 933917300135 | BCP52             |
| "74AUP1T97GS,132"  | 935292881132 | 74AUP1T97GS       |
| 74LVC2G126DC-Q100H | 935306529125 | 74LVC2G126DC-Q100 |
| 74AHCV07APWJ       | 935308213118 | 74AHCV07APW       |
| PMEG40T30EPX       | 934070406115 | PMEG40T30EP       |
| 74HC166PW,118      | 935188960118 | 74HC166PW         |
| 74AHC2G00DP-Q100H  | 935300195125 | 74AHC2G00DP-Q100  |
| "74AHCT74PW,118"   | 935263077118 | 74AHCT74PW        |
| TDZ4V7J,115        | 934065713115 | TDZ4V7J           |
| PBHV9215Z,115      | 934063481115 | PBHV9215Z         |
| "74AUP1G08GW,125"  | 935279019125 | 74AUP1G08GW       |
| PMBT4401,215       | 933821810215 | PMBT4401          |
| PESD5V0X1UAB,115   | 934064539115 | PESD5V0X1UAB      |
| 74HC573D,653       | 933713560653 | 74HC573D          |
| BZX884-B9V1,315    | 934057203315 | BZX884-B9V1       |
| PMEG6030ETPX       | 934067348115 | PMEG6030ETP       |
| PMST5550,115       | 934030860115 | PMST5550          |
| 74AUP2G79GS,115    | 935292788115 | 74AUP2G79GS       |
| 74AHCT594PW,118    | 935282016118 | 74AHCT594PW       |
| 74LVC273D-Q100J    | 935302461118 | 74LVC273D-Q100    |
| BCW72,235          | 933149400235 | BCW72             |
| "74LVC1G86GX,125"  | 935298385125 | 74LVC1G86GX       |
| 74ALVC244BQ,115    | 935273548115 | 74ALVC244BQ       |
| 74LVC1G157GV-Q100H | 935300355125 | 74LVC1G157GV-Q100 |
| 74HC2G02DP,125     | 935270078125 | 74HC2G02DP        |
| 74HCT2G17GV,125    | 935281028125 | 74HCT2G17GV       |
| BZT52-C11X         | 934071126115 | BZT52-C11         |
| "74LV165D,112"     | 935156060112 | 74LV165D          |
| BZT52H-C6V8,115    | 934059396115 | BZT52H-C6V8       |
| 74HCT597D,653      | 933757350653 | 74HCT597D         |

|                     |              |               |
|---------------------|--------------|---------------|
| PMV50XPR            | 934068894215 | PMV50XP       |
| PMEG40T50EPX        | 934070407115 | PMEG40T50EP   |
| BAT54CM,315         | 934057252315 | BAT54CM       |
| 74HCT377PW,118      | 935188430118 | 74HCT377PW    |
| PESD3V3Z1BSFYL      | 934070334315 | PESD3V3Z1BSF  |
| BZX84-C2V4,215      | 933516920215 | BZX84-C2V4    |
| "74LVC2T45GT,115"   | 935284758115 | 74LVC2T45GT   |
| PESD12VS5UD,115     | 934058434115 | PESD12VS5UD   |
| BCV71,215           | 933495330215 | BCV71         |
| PBLS4005Y,115       | 934058648115 | PBLS4005Y     |
| PSMN1R2-30YLC,115   | 934065187115 | PSMN1R2-30YLC |
| 1N4737A,133         | 933931630133 | 1N4737A       |
| BZX384-B20,115      | 934057380115 | BZX384-B20    |
| 74LVC08ABQ,115      | 935273545115 | 74LVC08ABQ    |
| BZX384-B68,115      | 934057393115 | BZX384-B68    |
| PZU5.6B2A,115       | 934062782115 | PZU5.6B2A     |
| BZX84-A2V7,215      | 934023110215 | BZX84-A2V7    |
| PSMNR90-30BL,118    | 934065173118 | PSMNR90-30BL  |
| BZV55-C24,115       | 933699610115 | BZV55-C24     |
| "74HC4017PW,112"    | 935189080112 | 74HC4017PW    |
| BC807-40,235        | 933628580235 | BC807-40      |
| 74HCT00D,653        | 933713370653 | 74HCT00D      |
| 74HCT2G02DP,125     | 935271871125 | 74HCT2G02DP   |
| NZH6V8B,115         | 934064362115 | NZH6V8B       |
| "74AUP1G125GN,132"  | 935291722132 | 74AUP1G125GN  |
| BAS21VD,135         | 934057662135 | BAS21VD       |
| BZX84-C6V2,235      | 933137410235 | BZX84-C6V2    |
| PDZ3.9BGWX          | 934071082115 | PDZ3.9BGW     |
| "74AHC1G32GW,125"   | 935262756125 | 74AHC1G32GW   |
| PCMF2USB3SZ         | 934069591087 | PCMF2USB3S    |
| BCX55,115           | 933272320115 | BCX55         |
| 74LV08APWJ          | 935690645118 | 74LV08APW     |
| PDTC115TT,215       | 934058193215 | PDTC115TT     |
| PXT2222A,115        | 933821820115 | PXT2222A      |
| HEF40098BT,653      | 933373410653 | HEF40098BT    |
| BCV62C,215          | 933792150215 | BCV62C        |
| "74LVC16245ADL,112" | 935234900112 | 74LVC16245ADL |
| 74LVC257ADB,118     | 935260679118 | 74LVC257ADB   |
| 74HC240PW,118       | 935185810118 | 74HC240PW     |
| PDTC124XU,115       | 934057541115 | PDTC124XU     |
| PMPB47XP,115        | 934066876115 | PMPB47XP      |
| BAS45A,113          | 934031240113 | BAS45A        |
| PBSS4560PA,115      | 934063493115 | PBSS4560PA    |
| 74AHCT2G125DC,125   | 935275131125 | 74AHCT2G125DC |
| 74HC574D,652        | 933715520652 | 74HC574D      |
| BAS16VY,115         | 934057343115 | BAS16VY       |

|                      |              |                  |
|----------------------|--------------|------------------|
| BUK9Y43-60E,115      | 934067024115 | BUK9Y43-60E      |
| TDZ3V6J,115          | 934065705115 | TDZ3V6J          |
| 74AHC86BQ-Q100X      | 935301399115 | 74AHC86BQ-Q100   |
| BCW29,215            | 933082731215 | BCW29            |
| 74HCT125D,653        | 933757010653 | 74HCT125D        |
| BZT52H-B33,115       | 934064807115 | BZT52H-B33       |
| PSMN2R8-80BS,118     | 934065176118 | PSMN2R8-80BS     |
| BUK9K52-60E,115      | 934066978115 | BUK9K52-60E      |
| 74AHCT1G125GF,132    | 935285526132 | 74AHCT1G125GF    |
| PBSM5240PFH,115      | 934066562115 | PBSM5240PFH      |
| BAS70-07V,115        | 934056718115 | BAS70-07V        |
| "74HCT1G08GW-Q100,1" | 935298487125 | 74HCT1G08GW-Q100 |
| BZX384-B7V5,115      | 934057370115 | BZX384-B7V5      |
| PLVA653A,215         | 934017350215 | PLVA653A         |
| PUMB11,115           | 934056289115 | PUMB11           |
| "74HCT153D,652"      | 933714060652 | 74HCT153D        |
| 74ALVC08BQ,115       | 935273691115 | 74ALVC08BQ       |
| BZX585-B30,115       | 934057409115 | BZX585-B30       |
| 1PS76SB70,135        | 934054923135 | 1PS76SB70        |
| 74LV541APWJ          | 935306645118 | 74LV541APW       |
| PTVS16VS1UR,115      | 934061354115 | PTVS16VS1UR      |
| PRMD10Z              | 934070172147 | PRMD10           |
| "74AUP2G06GM,132"    | 935279984132 | 74AUP2G06GM      |
| BZT52H-B27,115       | 934064805115 | BZT52H-B27       |
| PDTA113ZU,115        | 934058793115 | PDTA113ZU        |
| BZX884-B11,315       | 934057205315 | BZX884-B11       |
| "74AHCT245PW,112"    | 935261962112 | 74AHCT245PW      |
| "74HC126PW,112"      | 935183560112 | 74HC126PW        |
| 1PS70SB85,115        | 934056490115 | 1PS70SB85        |
| "74HCU04D,652"       | 933714000652 | 74HCU04D         |
| "74VHCT125PW,118"    | 935289509118 | 74VHCT125PW      |
| BZX84-A6V2,215       | 934015430215 | BZX84-A6V2       |
| BUK7K12-60EX         | 934067947115 | BUK7K12-60E      |
| PESD7V0H1BSFYL       | 934660172315 | PESD7V0H1BSF     |
| BZX884-B39,315       | 934057447315 | BZX884-B39       |
| BZX384-B39,115       | 934057387115 | BZX384-B39       |
| NPIC6C596BQ,115      | 935297272115 | NPIC6C596BQ      |
| BZT52-C36X           | 934071119115 | BZT52-C36        |
| 74AHCT08D,118        | 935262676118 | 74AHCT08D        |
| "74HC163D,652"       | 933714540652 | 74HC163D         |
| BZX84-B4V7,215       | 933567980215 | BZX84-B4V7       |
| BZX79-B4V3,143       | 933549970143 | BZX79-B4V3       |
| PBSS4320T,215        | 934056854215 | PBSS4320T        |
| PDZ6.8B,115          | 934054855115 | PDZ6.8B          |
| "74LVT02PW,118"      | 935208980118 | 74LVT02PW        |
| BSH103,235           | 934054713235 | BSH103           |

|                    |              |                   |
|--------------------|--------------|-------------------|
| "74AUP1G08GN,132"  | 935291718132 | 74AUP1G08GN       |
| BZV49-C9V1,115     | 933605950115 | BZV49-C9V1        |
| BZX84-C24,235      | 933388310235 | BZX84-C24         |
| BZT52-C8V2J        | 934071114118 | BZT52-C8V2        |
| PTVS14VS1UTR,115   | 934065487115 | PTVS14VS1UTR      |
| 74LVT16373ADGG,118 | 935203090118 | 74LVT16373ADGG    |
| PESD5V0X1UB,135    | 934064538135 | PESD5V0X1UB       |
| BC847AMB,315       | 934065885315 | BC847AMB          |
| 74HC595PW,112      | 935188520112 | 74HC595PW         |
| 74LVC1G14GX4Z      | 935690004147 | 74LVC1G14GX4      |
| PTVS12VS1UTR,115   | 934065485115 | PTVS12VS1UTR      |
| BZX585-C3V3,115    | 934055839115 | BZX585-C3V3       |
| 74HC164D,653       | 933714070653 | 74HC164D          |
| BST61,115          | 933644290115 | BST61             |
| 74AHC244D,118      | 935262001118 | 74AHC244D         |
| "74LVC2G14GW,125"  | 935273895125 | 74LVC2G14GW       |
| PESD5V0S2UAT,215   | 934058063215 | PESD5V0S2UAT      |
| BZX79-C11,133      | 933117800133 | BZX79-C11         |
| BZX585-C8V2,115    | 934055849115 | BZX585-C8V2       |
| PEMD24,115         | 934058926115 | PEMD24            |
| BZV49-C30,115      | 933606070115 | BZV49-C30         |
| BC860C,215         | 933628700215 | BC860C            |
| BUK7Y13-40B,115    | 934060169115 | BUK7Y13-40B       |
| "74LVC1G04GX,125"  | 935298225125 | 74LVC1G04GX       |
| RB751S40,115       | 934061303115 | RB751S40          |
| PMEG6010EP,115     | 934061478115 | PMEG6010EP        |
| BSS84AKMB,315      | 934065863315 | BSS84AKMB         |
| PMEG3020EH,115     | 934059027115 | PMEG3020EH        |
| 74AUP1G04GW-Q100H  | 935303014125 | 74AUP1G04GW-Q100  |
| PMST4403,115       | 934026890115 | PMST4403          |
| 74LVC4066D,112     | 935273717112 | 74LVC4066D        |
| PESD4V0MS-SFYL     | 934660873315 | PESD4V0MS-SF      |
| PESD15VS2UQ,115    | 934057837115 | PESD15VS2UQ       |
| BUK7K52-60EX       | 934067954115 | BUK7K52-60E       |
| PMV65XPER          | 934068499215 | PMV65XPE          |
| PMSTA92,115        | 934042290115 | PMSTA92           |
| BCX51,115          | 933272280115 | BCX51             |
| 74AVC4T245BQ-Q100X | 935301113115 | 74AVC4T245BQ-Q100 |
| HEF4082BT,652      | 933373100652 | HEF4082BT         |
| BAV70SRAZ          | 934070161147 | BAV70SRA          |
| NUP1301,215        | 934063605215 | NUP1301           |
| PMV230ENEAR        | 934068711215 | PMV230ENEA        |
| NZX5V6A,133        | 934062027133 | NZX5V6A           |
| 74LVC2G74DP,125    | 935280388125 | 74LVC2G74DP       |
| PDZ12BGWX          | 934071049115 | PDZ12BGW          |
| 74AUP1T02GWH       | 935690042125 | 74AUP1T02GW       |

|                    |              |                 |
|--------------------|--------------|-----------------|
| BZT52H-C5V1,115    | 934059393115 | BZT52H-C5V1     |
| PBSS304NX,115      | 934059011115 | PBSS304NX       |
| "74LVC1G17GV,125"  | 935270081125 | 74LVC1G17GV     |
| PDZ3.0B,115        | 934054846115 | PDZ3.0B         |
| BZX884-C36,315     | 934057463315 | BZX884-C36      |
| 74LVT16244BDGG,118 | 935202990118 | 74LVT16244BDGG  |
| BSP225,115         | 934000510115 | BSP225          |
| PBSS4350SS,115     | 934061031115 | PBSS4350SS      |
| 74AUP2G157DC,125   | 935280734125 | 74AUP2G157DC    |
| "74AUP1G86GS,132"  | 935292872132 | 74AUP1G86GS     |
| 74HC4053BQ,115     | 935273668115 | 74HC4053BQ      |
| 74HCT4514PW,118    | 935262414118 | 74HCT4514PW     |
| 74HC30D,653        | 933756910653 | 74HC30D         |
| "74LVC157APW,112"  | 935260900112 | 74LVC157APW     |
| BZV90-C27,115      | 934014860115 | BZV90-C27       |
| BAT754,215         | 934055714215 | BAT754          |
| BZX84-C75,215      | 933388430215 | BZX84-C75       |
| PHPT60415NYX       | 934068587115 | PHPT60415NY     |
| BZV55-C39,115      | 933699660115 | BZV55-C39       |
| 74HCT244D,652      | 933713430652 | 74HCT244D       |
| PDTA124XU,115      | 934057534115 | PDTA124XU       |
| "74HCT30D,652"     | 933756930652 | 74HCT30D        |
| "74AHC1G32GV,125"  | 935271666125 | 74AHC1G32GV     |
| BUK764R2-80E,118   | 934066646118 | BUK764R2-80E    |
| BZX84-C16,215      | 933388270215 | BZX84-C16       |
| PMEG60T10ELPX      | 934070874115 | PMEG60T10ELP    |
| RB521CS30L,315     | 934064973315 | RB521CS30L      |
| BUK9620-100B,118   | 934062452118 | BUK9620-100B    |
| 1N4749A,133        | 933931750133 | 1N4749A         |
| BZX384-B13,115     | 934057376115 | BZX384-B13      |
| 2PC4081Q,115       | 934031750115 | 2PC4081Q        |
| NZH3V3A,115        | 934064353115 | NZH3V3A         |
| BZV55-C5V1,135     | 933699450135 | BZV55-C5V1      |
| PSMN7R0-30YL,115   | 934063077115 | PSMN7R0-30YL    |
| 74AHC2G125DP,125   | 935274673125 | 74AHC2G125DP    |
| 74HC4060PW,112     | 935242080112 | 74HC4060PW      |
| 74LVC2G17GM,115    | 935277163115 | 74LVC2G17GM     |
| "74HCT4052D,112"   | 933715310112 | 74HCT4052D      |
| PESD5V0S5UD,115    | 934058433115 | PESD5V0S5UD     |
| PESD5V0L4UG,115    | 934057785115 | PESD5V0L4UG     |
| 74LVC1G3157GM,115  | 935277228115 | 74LVC1G3157GM   |
| PEMH9,315          | 934056769315 | PEMH9           |
| HEF40106BT-Q100J   | 935299242118 | HEF40106BT-Q100 |
| "74AUP1G97GN,132"  | 935291748132 | 74AUP1G97GN     |
| PSMN1R5-30BLEJ     | 934067368118 | PSMN1R5-30BLE   |
| PLVA2668A,215      | 934030960215 | PLVA2668A       |

|                      |              |                   |
|----------------------|--------------|-------------------|
| BF623,115            | 933387870115 | BF623             |
| "74LVC02APW,112"     | 935250010112 | 74LVC02APW        |
| IP4254CZ8-4-TTL,13   | 934064671132 | IP4254CZ8-4-TTL   |
| "74AHC1GU04GW,125"   | 935263016125 | 74AHC1GU04GW      |
| PTVS45VS1UR,115      | 934061368115 | PTVS45VS1UR       |
| "74LVC1G66GV,125"    | 935272034125 | 74LVC1G66GV       |
| 74HCT02D,653         | 933714160653 | 74HCT02D          |
| PMEG045T150EPDZ      | 934068775146 | PMEG045T150EPD    |
| BZV55-C5V1,115       | 933699450115 | BZV55-C5V1        |
| PESD5V0S1UA,115      | 934062102115 | PESD5V0S1UA       |
| "74HC11D,652"        | 933714290652 | 74HC11D           |
| PBSS4160DS,115       | 934058115115 | PBSS4160DS        |
| "74AUP1G125GX,125"   | 935298368125 | 74AUP1G125GX      |
| BUK9875-100A/CUX     | 934068286115 | BUK9875-100A/CU   |
| BZB84-C3V3,215       | 934061723215 | BZB84-C3V3        |
| BZV49-C56,115        | 933606140115 | BZV49-C56         |
| BUK9Y8R7-60E,115     | 934067021115 | BUK9Y8R7-60E      |
| 74LV4052PW,118       | 935174950118 | 74LV4052PW        |
| 74AHC164D,118        | 935265465118 | 74AHC164D         |
| 74LVC1G157GW-Q100H   | 935300356125 | 74LVC1G157GW-Q100 |
| 74AXP1T14GXH         | 935308975125 | 74AXP1T14GX       |
| "74AHC126PW-Q100,11" | 935298639118 | 74AHC126PW-Q100   |
| IP3319CX6,135        | 934066068135 | IP3319CX6         |
| BC846B/DG/B4R        | 934068354215 | BC846B/DG/B4      |
| 74ALVT162245DGG:11   | 935217890118 | 74ALVT162245DGG   |
| BZV55-B3V9,115       | 933827650115 | BZV55-B3V9        |
| PMBT3904MB,315       | 934065892315 | PMBT3904MB        |
| BF821,215            | 933665130215 | BF821             |
| 74LVT125D,118        | 935170510118 | 74LVT125D         |
| PTVS24VS1UTR,115     | 934065495115 | PTVS24VS1UTR      |
| 1N4734A,133          | 933931600133 | 1N4734A           |
| BUK7E3R5-60E,127     | 934066632127 | BUK7E3R5-60E      |
| 74AHC1G00GV-Q100H    | 935300691125 | 74AHC1G00GV-Q100  |
| "74LVT125PW,112"     | 935197940112 | 74LVT125PW        |
| PSMN9R5-30YLC,115    | 934066009115 | PSMN9R5-30YLC     |
| BZX884-B20,315       | 934057440315 | BZX884-B20        |
| "74AUP1G175GW,125"   | 935280003125 | 74AUP1G175GW      |
| BAV99W,115           | 934026010115 | BAV99W            |
| PTVS51VS1UR,115      | 934061371115 | PTVS51VS1UR       |
| 74AHC2G00DP,125      | 935274678125 | 74AHC2G00DP       |
| BCX51-10,115         | 933663040115 | BCX51-10          |
| PMEG3005CT,215       | 934061752215 | PMEG3005CT        |
| PESD15VL2BT,215      | 934058866215 | PESD15VL2BT       |
| PESD8V0S1ULDYL       | 934660252315 | PESD8V0S1ULD      |
| NPIC6C4894DY         | 935302549518 | NPIC6C4894D       |
| PTVS5V0Z1USKYL       | 934069205315 | PTVS5V0Z1USK      |

|                    |              |                  |
|--------------------|--------------|------------------|
| 74HC153D,653       | 933714050653 | 74HC153D         |
| BZT52H-B4V3,115    | 934064784115 | BZT52H-B4V3      |
| NZH18C,115         | 934064373115 | NZH18C           |
| BC846A,235         | 933589550235 | BC846A           |
| 74LVC244APW,118    | 935210420118 | 74LVC244APW      |
| PMEG4030ER/8X      | 934070021115 | PMEG4030ER/8     |
| PZU15B2A,115       | 934062348115 | PZU15B2A         |
| BZX79-C5V1,133     | 933117720133 | BZX79-C5V1       |
| BUK768R3-60E,118   | 934066644118 | BUK768R3-60E     |
| 74HCT2G04GV,125    | 935281024125 | 74HCT2G04GV      |
| PDTC114YT,215      | 934054701215 | PDTC114YT        |
| PDTC143ET,235      | 934030990235 | PDTC143ET        |
| PMEG3002AELD,315   | 934065337315 | PMEG3002AELD     |
| BZV90-C39,115      | 934014900115 | BZV90-C39        |
| PHPT60406NYX       | 934068569115 | PHPT60406NY      |
| 1N4744A,113        | 933931700113 | 1N4744A          |
| 74AVC1T8128GSX     | 935690695115 | 74AVC1T8128GS    |
| BZT52H-B36,115     | 934064808115 | BZT52H-B36       |
| "74LVC245APW,112"  | 935211540112 | 74LVC245APW      |
| 74HC4052PW,118     | 935187490118 | 74HC4052PW       |
| BZX84-C9V1,235     | 933137450235 | BZX84-C9V1       |
| "74LVC11PW,118"    | 935205930118 | 74LVC11PW        |
| BCV46,215          | 933932330215 | BCV46            |
| PESD5V0S4UD,115    | 934059302115 | PESD5V0S4UD      |
| PMZ370UNEYL        | 934068439315 | PMZ370UNE        |
| 74HC244D,652       | 933713420652 | 74HC244D         |
| PDTA114EU,115      | 934043510115 | PDTA114EU        |
| "74HCT1G14GW,125"  | 935245720125 | 74HCT1G14GW      |
| BZT52-B3V9J        | 934071148118 | BZT52-B3V9       |
| BZX79-C43,113      | 933117940113 | BZX79-C43        |
| "74AUP1GU04GX,125" | 935298373125 | 74AUP1GU04GX     |
| PESD5V0X1BCSFYL    | 934069673315 | PESD5V0X1BCSF    |
| 74LVC1G17GW/C5H    | 935690013125 | 74LVC1G17GW/C5   |
| 74LV00APWJ         | 935690646118 | 74LV00APW        |
| PMEG10020AELR/BX   | 934068785115 | PMEG10020AELR/B  |
| "74AUP1G04GW,125"  | 935279003125 | 74AUP1G04GW      |
| PZU6.2B3A,115      | 934062787115 | PZU6.2B3A        |
| BZX384-B5V1,115    | 934057366115 | BZX384-B5V1      |
| PDTC123EU,115      | 934057538115 | PDTC123EU        |
| BZB784-C3V9,115    | 934056301115 | BZB784-C3V9      |
| 74HCT1G32GW-Q100H  | 935299231125 | 74HCT1G32GW-Q100 |
| TL431CDBZR,215     | 935288016215 | TL431CDBZR       |
| "HEF4030BT,652"    | 933372820652 | HEF4030BT        |
| "74AUP1G34GX,125"  | 935298363125 | 74AUP1G34GX      |
| 74LVC1G126GM,115   | 935277204115 | 74LVC1G126GM     |
| IP4252CZ8-4-TTL,13 | 934064754132 | IP4252CZ8-4-TTL  |



|                      |              |                 |
|----------------------|--------------|-----------------|
| BST51,115            | 933644260115 | BST51           |
| 74AUP3G14GSX         | 935307185115 | 74AUP3G14GS     |
| BZX384-C18,115       | 934057646115 | BZX384-C18      |
| PUMD10,125           | 934055239125 | PUMD10          |
| PMEG050V150EPDZ      | 934068489146 | PMEG050V150EPD  |
| 74LVCH245APW,118     | 935211570118 | 74LVCH245APW    |
| 74LVC2G34GXZ         | 935307082147 | 74LVC2G34GX     |
| PMEG2005EGWJ         | 934070365118 | PMEG2005EGW     |
| PBSS5260PAP,115      | 934066891115 | PBSS5260PAP     |
| "74HCT00PW-Q100,118" | 935298903118 | 74HCT00PW-Q100  |
| BSS192,115           | 933943950115 | BSS192          |
| 74ABT162245ADL,118   | 935204120118 | 74ABT162245ADL  |
| 74ABT162245ADGG:11   | 935204130118 | 74ABT162245ADGG |
| 74LVC1G86GM,115      | 935277202115 | 74LVC1G86GM     |
| BZV55-B3V6,115       | 933827640115 | BZV55-B3V6      |
| PTVS20VP1UTP,115     | 934065547115 | PTVS20VP1UTP    |
| BZX585-B47,115       | 934057415115 | BZX585-B47      |
| PMBT2369,215         | 933828890215 | PMBT2369        |
| 74LV244APWJ          | 935308259118 | 74LV244APW      |
| 74ALVC164245DGG:11   | 935202350118 | 74ALVC164245DGG |
| 2PA1576S,115         | 934031800115 | 2PA1576S        |
| "74HC08PW,112"       | 935174270112 | 74HC08PW        |
| PBRP123YT,215        | 934058991215 | PBRP123YT       |
| PMEG6020ELRX         | 934067654115 | PMEG6020ELR     |
| PMEG100V060ELPDAZ    | 934069522139 | PMEG100V060ELPD |
| "74HC153PW,112"      | 935174480112 | 74HC153PW       |
| "74LVC1G384GW,125"   | 935274581125 | 74LVC1G384GW    |
| 74LVC06AD,118        | 935265479118 | 74LVC06AD       |
| 74HCT157D,652        | 933713750652 | 74HCT157D       |
| "74AHC02PW,118"      | 935262693118 | 74AHC02PW       |
| PDTD143XT            | 934068351215 | PDTD143XT       |
| PMEG45U10EPDAZ       | 934068206139 | PMEG45U10EPD    |
| PTVS7V5U1UPAZ        | 934068078147 | PTVS7V5U1UPA    |
| 74HCT4052D,118       | 933715310118 | 74HCT4052D      |
| BZT52-B22X           | 934071179115 | BZT52-B22       |
| PRMD2Z               | 934070171147 | PRMD2           |
| PMST2369,115         | 934030840115 | PMST2369        |
| BZT52H-C3V6,115      | 934059388115 | BZT52H-C3V6     |
| BC856BS,135          | 934063583135 | BC856BS         |
| PMCPB5530X,115       | 934066582115 | PMCPB5530X      |
| BZX84-B9V1,215       | 933770340215 | BZX84-B9V1      |
| BC817,215            | 933589520215 | BC817           |
| "74ABT00PW,112"      | 935206910112 | 74ABT00PW       |
| BZV90-C47,115        | 934014920115 | BZV90-C47       |
| "74LVC1G14GV,125"    | 935272019125 | 74LVC1G14GV     |
| "74LVC2G126GT,115"   | 935278925115 | 74LVC2G126GT    |

|                    |              |                  |
|--------------------|--------------|------------------|
| "74HC161D,652"     | 933714520652 | 74HC161D         |
| "74AHCT541PW,112"  | 935261978112 | 74AHCT541PW      |
| BZV55-C43,115      | 933699700115 | BZV55-C43        |
| PMZ390UN,315       | 934060156315 | PMZ390UN         |
| 74LVC245AD,118     | 935211510118 | 74LVC245AD       |
| IP4254CZ16-8-TTL,1 | 934064675132 | IP4254CZ16-8-TTL |
| "74LVC74APW,112"   | 935260736112 | 74LVC74APW       |
| "74LVC1G27GW,125"  | 935297278125 | 74LVC1G27GW      |
| 74AHC1G09GW-Q100H  | 935299233125 | 74AHC1G09GW-Q100 |
| PESD5V0S2BT,215    | 934058007215 | PESD5V0S2BT      |
| BC857B,215         | 933589760215 | BC857B           |
| 74AHC32D,118       | 935262642118 | 74AHC32D         |
| BZT52-C4V3J        | 934071106118 | BZT52-C4V3       |
| PMEG4010EPK,315    | 934065384315 | PMEG4010EPK      |
| BUK9Y1R6-40HX      | 934660361115 | BUK9Y1R6-40H     |
| HEF4028BT,653      | 933372800653 | HEF4028BT        |
| PTVS16VS1UTR,115   | 934065489115 | PTVS16VS1UTR     |
| PBSS9110X,135      | 934057976135 | PBSS9110X        |
| "74AHCT1G08GV,125" | 935271659125 | 74AHCT1G08GV     |
| BUK9Y38-100E,115   | 934067038115 | BUK9Y38-100E     |
| BCM856BSH          | 934062056125 | BCM856BS         |
| 74HCT02DB,112      | 935166840112 | 74HCT02DB        |
| BCP56-16TF         | 934070119135 | BCP56-16T        |
| "74AUP1G58GM,132"  | 935279961132 | 74AUP1G58GM      |
| NX138BKSX          | 934070156115 | NX138BKS         |
| BZV55-C27,115      | 933699620115 | BZV55-C27        |
| "74HC4051D,652"    | 933714820652 | 74HC4051D        |
| BSP19,115          | 933983400115 | BSP19            |
| "74HCT594D,112"    | 935043390112 | 74HCT594D        |
| "74HC374D,652"     | 933713480652 | 74HC374D         |
| HEF40106BTT-Q100J  | 935299243118 | HEF40106BTT-Q100 |
| BUK6Y14-40PX       | 934661181115 | BUK6Y14-40P      |
| BZT52H-C9V1,115    | 934059399115 | BZT52H-C9V1      |
| 74HC4051PW,118     | 935187480118 | 74HC4051PW       |
| 74HC240D,653       | 933713440653 | 74HC240D         |
| PESD3V3V1BCSFYL    | 934069359315 | PESD3V3V1BCSF    |
| "74HCT540D,652"    | 933715600652 | 74HCT540D        |
| 74LVC1G17GW/C4H    | 935301945125 | 74LVC1G17GW/C4   |
| BAV70M,315         | 934061269315 | BAV70M           |
| "74AHC74PW,118"    | 935263079118 | 74AHC74PW        |
| PSMN7R5-30MLDX     | 934067972115 | PSMN7R5-30MLD    |
| BZV49-C6V2,115     | 933605910115 | BZV49-C6V2       |
| BZV85-C75,133      | 933500860133 | BZV85-C75        |
| BZX84J-B30,115     | 934060951115 | BZX84J-B30       |
| PMEG6020EPASX      | 934068152115 | PMEG6020EPAS     |
| PXTA14,115         | 933834420115 | PXTA14           |

|                   |              |               |
|-------------------|--------------|---------------|
| 1PS76SB21,115     | 934054922115 | 1PS76SB21     |
| HEF4071BT,652     | 933373020652 | HEF4071BT     |
| "74HCT373PW,112"  | 935174830112 | 74HCT373PW    |
| 74LVC1G99GF,115   | 935290508115 | 74LVC1G99GF   |
| BZX585-C22,115    | 934057424115 | BZX585-C22    |
| "74ALVC32PW,118"  | 935269729118 | 74ALVC32PW    |
| "74ALVC08PW,118"  | 935269717118 | 74ALVC08PW    |
| 74LV244ATPWJ      | 935308261118 | 74LV244ATPW   |
| BZX585-B27,115    | 934057410115 | BZX585-B27    |
| PSMN1R8-30PL,127  | 934064002127 | PSMN1R8-30PL  |
| 74HCT154D,653     | 933713830653 | 74HCT154D     |
| BCP69-25,135      | 933969390135 | BCP69-25      |
| BC55-16PASX       | 934068129115 | BC55-16PAS    |
| 74AHC244BQ,115    | 935285537115 | 74AHC244BQ    |
| 74HC42D,653       | 933714860653 | 74HC42D       |
| 74ABT74D,118      | 935208740118 | 74ABT74D      |
| BC847B,235        | 933589590235 | BC847B        |
| PDTA143ZT,215     | 934054699215 | PDTA143ZT     |
| PSMN1R2-30YLDX    | 934068235115 | PSMN1R2-30YLD |
| 74AHCT574PW,118   | 935263083118 | 74AHCT574PW   |
| 74HCT574PW,118    | 935188510118 | 74HCT574PW    |
| "74HCT1G02GW,125" | 935245620125 | 74HCT1G02GW   |
| PBSS4160DPN,115   | 934058119115 | PBSS4160DPN   |
| TL431MFDT,215     | 935293277215 | TL431MFDT     |
| PBSS305PZ,135     | 934059053135 | PBSS305PZ     |
| BZV85-C3V6,133    | 933659350133 | BZV85-C3V6    |
| "74HC4046AD,652"  | 933809550652 | 74HC4046AD    |
| BZX384-B56,115    | 934057391115 | BZX384-B56    |
| "74LV04D,112"     | 935063130112 | 74LV04D       |
| BZX384-B5V6,115   | 934057367115 | BZX384-B5V6   |
| BZV90-C33,115     | 934014880115 | BZV90-C33     |
| PBSS5230T,215     | 934057991215 | PBSS5230T     |
| BZX585-B16,115    | 934057404115 | BZX585-B16    |
| 74LVC14AD,118     | 935260737118 | 74LVC14AD     |
| BUK7Y4R4-40EX     | 934067431115 | BUK7Y4R4-40E  |
| PDTD143ETR        | 934068349215 | PDTD143ET     |
| PESD5V0U1BA,115   | 934060854115 | PESD5V0U1BA   |
| PBSS8510PA,115    | 934063924115 | PBSS8510PA    |
| BZT52H-C33,115    | 934059415115 | BZT52H-C33    |
| BZV55-C2V4,115    | 933699370115 | BZV55-C2V4    |
| BZV85-C27,113     | 933500750113 | BZV85-C27     |
| BZX884-C5V6,315   | 934057217315 | BZX884-C5V6   |
| PTVS6V0P1UP,115   | 934064153115 | PTVS6V0P1UP   |
| BZX84-A36,215     | 934039570215 | BZX84-A36     |
| PDZ8.2B,115       | 934054857115 | PDZ8.2B       |
| "74HC112D,652"    | 933714490652 | 74HC112D      |

|                      |               |                  |
|----------------------|---------------|------------------|
| PMEG2005AEL,315      | 934058079315  | PMEG2005AEL      |
| 74LVC2G14GV,125      | 935273894125  | 74LVC2G14GV      |
| PBSS2515YPN,115      | 934056661115  | PBSS2515YPN      |
| BZV85-C12,113        | 933500670113  | BZV85-C12        |
| "HEF4104BT,652"      | 933373140652  | HEF4104BT        |
| BZX84J-C4V7,115      | 934061008115  | BZX84J-C4V7      |
| BZX585-C33,115       | 934057428115  | BZX585-C33       |
| "74HCT244PW,112"     | 935165220112  | 74HCT244PW       |
| 74HC7541DB,112       | 935190300112  | 74HC7541DB       |
| PESD5V0U2BT,215      | 934060856215  | PESD5V0U2BT      |
| 74LVC4066BQ-Q100X    | 935299339115  | 74LVC4066BQ-Q100 |
| BC846B,215           | 933589560215  | BC846B           |
| 74HC4053BQ-Q100,11   | 935298851115  | 74HC4053BQ-Q100  |
| TDZ10J,115           | 934065784115  | TDZ10J           |
| 74AHC138BQ,115       | 935285572115  | 74AHC138BQ       |
| PMBT4401,235         | 933821810235  | PMBT4401         |
| BZT52-B12X           | 934071165115  | BZT52-B12        |
| BZV90-C7V5,115       | 934014730115  | BZV90-C7V5       |
| "74HCT123D,652"      | 933713970652  | 74HCT123D        |
| BAW56M,315           | 934061271315  | BAW56M           |
| BZX84-B6V8,215       | 933671130215  | BZX84-B6V8       |
| PDTC114TT,235        | 934034900235  | PDTC114TT        |
| BZX384-C4V7,115      | 934057632115  | BZX384-C4V7      |
| "74LVC1G08GW,125"    | 935268380125  | 74LVC1G08GW      |
| PMBT3904QAZ          | 934660463147  | PMBT3904QA       |
| 74HCT00BQ,115        | 935273697115  | 74HCT00BQ        |
| PSMN027-100PS,127    | 934064326127  | PSMN027-100PS    |
| 1PS66SB82,115        | 934058746115  | 1PS66SB82        |
| BUK7K45-100EX        | 934067944115  | BUK7K45-100E     |
| PMEG2010BER,115      | 934061457115  | PMEG2010BER      |
| PMCM6501VNEZ         | 934068873023  | PMCM6501VNE      |
| BCV47,235            | 933932320235  | BCV47            |
| BZX585-C27,115       | 934057426115  | BZX585-C27       |
| PESD5Z7.0,115        | 934061267115  | PESD5Z7.0        |
| 74HC132DB,118        | 935171440118  | 74HC132DB        |
| 74ALVCH16244DGG,11   | 935205100112  | 74ALVCH16244DGG  |
| BZB984-C10,115       | 934057244115  | BZB984-C10       |
| BZT52-C6V2J          | 9340711111115 | BZT52-C6V2       |
| "74HC4514PW,112"     | 935262415112  | 74HC4514PW       |
| 74HCT377D,653        | 933713990653  | 74HCT377D        |
| BZX84-C24,215        | 933388310215  | BZX84-C24        |
| 74HC4094PW,118       | 935188490118  | 74HC4094PW       |
| BZX84J-C10,115       | 934060982115  | BZX84J-C10       |
| 74LVC1G04GW-Q100H    | 935300243125  | 74LVC1G04GW-Q100 |
| "74AHC1G14GW-Q100,1" | 935298659125  | 74AHC1G14GW-Q100 |
| BC856AW,115          | 934021810115  | BC856AW          |

|                      |              |                   |
|----------------------|--------------|-------------------|
| BZX79-B11,113        | 933166880113 | BZX79-B11         |
| BZX84-A27,215        | 934016170215 | BZX84-A27         |
| PMEG4020ETR,115      | 934065455115 | PMEG4020ETR       |
| 74LVC1GX04GV-Q100H   | 935301453125 | 74LVC1GX04GV-Q100 |
| BZX585-C5V1,115      | 934055844115 | BZX585-C5V1       |
| 74HC241D,653         | 933713460653 | 74HC241D          |
| BZX84-C5V1,215       | 933137390215 | BZX84-C5V1        |
| BUK664R4-55C,118     | 934064235118 | BUK664R4-55C      |
| BUK9D23-40EX         | 934660213115 | BUK9D23-40E       |
| 74LV4051D,118        | 935190970118 | 74LV4051D         |
| "74HCT74D,652"       | 933713390652 | 74HCT74D          |
| BCM847BS,135         | 934058507135 | BCM847BS          |
| BAS16VV,115          | 934058225115 | BAS16VV           |
| BAW156,215           | 934032650215 | BAW156            |
| "74LVC32APW,118"     | 935250080118 | 74LVC32APW        |
| 74HCT4053PW,112      | 935188480112 | 74HCT4053PW       |
| 74LVC2G86GXX         | 935339801115 | 74LVC2G86GX       |
| 74AHCT2G08DC,125     | 935275127125 | 74AHCT2G08DC      |
| "74HC20D,652"        | 933714300652 | 74HC20D           |
| 74AHC30BQ,115        | 935289764115 | 74AHC30BQ         |
| "74LVC257AD,112"     | 935260678112 | 74LVC257AD        |
| BSR31,115            | 933418120115 | BSR31             |
| NPIC6C596PW-Q100,1   | 935298531118 | NPIC6C596PW-Q100  |
| BZA462A,115          | 934054822115 | BZA462A           |
| PDTD123EUX           | 934068332115 | PDTD123EU         |
| BC847BQAZ            | 934069067147 | BC847BQA          |
| BC856A,215           | 933589720215 | BC856A            |
| BAS45A,133           | 934031240133 | BAS45A            |
| BFS20W,115           | 934055191115 | BFS20W            |
| BZX585-C8V2,135      | 934055849135 | BZX585-C8V2       |
| BCV63B,215           | 933835230215 | BCV63B            |
| "74AUP1G02GX,125"    | 935298354125 | 74AUP1G02GX       |
| 74AHC14BQ,115        | 935273779115 | 74AHC14BQ         |
| PHB33NQ20T,118       | 934058109118 | PHB33NQ20T        |
| "HEF4011BT,652"      | 933372640652 | HEF4011BT         |
| 74LVC14AD,112        | 935260737112 | 74LVC14AD         |
| BZX585-C2V7,115      | 934055837115 | BZX585-C2V7       |
| "74LVC1G126GV,125"   | 935271888125 | 74LVC1G126GV      |
| BZX79-B12,143        | 933166890143 | BZX79-B12         |
| TL431AMFDT,215       | 935293278215 | TL431AMFDT        |
| BCP56-16HX           | 934070292115 | BCP56-16H         |
| PESD36VS1UJX         | 934069338115 | PESD36VS1UJ       |
| "74CBTLV1G125GV,125" | 935280318125 | 74CBTLV1G125GV    |
| BZX84-A3V3,215       | 934031330215 | BZX84-A3V3        |
| BZX384-B62,115       | 934057392115 | BZX384-B62        |
| 74LVC374AD,118       | 935218660118 | 74LVC374AD        |

|                    |              |                 |
|--------------------|--------------|-----------------|
| PHB45NQ10T,118     | 934055802118 | PHB45NQ10T      |
| NPIC6C595BQ,115    | 935297268115 | NPIC6C595BQ     |
| 74LVT162245BDGG:11 | 935204110118 | 74LVT162245BDGG |
| 2PD1820AR,115      | 934042620115 | 2PD1820AR       |
| PESD24VF1BLYL      | 934068025315 | PESD24VF1BL     |
| BZT52H-B6V2,115    | 934064788115 | BZT52H-B6V2     |
| BC846W,115         | 934021970115 | BC846W          |
| 1PS79SB70,115      | 934054924115 | 1PS79SB70       |
| PSMN6R1-25MLDX     | 934069918115 | PSMN6R1-25MLD   |
| "74AUP1G32GM,132"  | 935279027132 | 74AUP1G32GM     |
| 74HC157D,653       | 933713740653 | 74HC157D        |
| IP4256CZ5-W,115    | 934063153115 | IP4256CZ5-W     |
| BC847BPN,125       | 934042530125 | BC847BPN        |
| PBSS4630PA,115     | 934063492115 | PBSS4630PA      |
| BUK9Y15-60E,115    | 934067022115 | BUK9Y15-60E     |
| PSMN9R8-30MLC,115  | 934066941115 | PSMN9R8-30MLC   |
| PMBT6429,215       | 933872630215 | PMBT6429        |
| PDTC123ET,215      | 934054697215 | PDTC123ET       |
| BUK9M10-30EX       | 934070076115 | BUK9M10-30E     |
| PBSS8110X,135      | 934057975135 | PBSS8110X       |
| "74LVC1G125GV,125" | 935272018125 | 74LVC1G125GV    |
| 74AHC573PW-Q100J   | 935300317118 | 74AHC573PW-Q100 |
| 74AHC541BQ,115     | 935285544115 | 74AHC541BQ      |
| 74HC366D,653       | 933714680653 | 74HC366D        |
| "74AUP1G373GW,125" | 935280621125 | 74AUP1G373GW    |
| 74HC245DB,112      | 935166910112 | 74HC245DB       |
| 74LVC138APW,112    | 935260747112 | 74LVC138APW     |
| PZT2907A,115       | 933982040115 | PZT2907A        |
| BUK9M19-60EX       | 934070051115 | BUK9M19-60E     |
| 74AVC4T3144GU12X   | 935690174115 | 74AVC4T3144GU12 |
| BZV85-C39,113      | 933500790113 | BZV85-C39       |
| 74HCT244PW,118     | 935165220118 | 74HCT244PW      |
| BZT52-C36J         | 934071119118 | BZT52-C36       |
| BZV85-C5V1,113     | 933500580113 | BZV85-C5V1      |
| BUK9M34-100EX      | 934070069115 | BUK9M34-100E    |
| HEF4011BT,653      | 933372640653 | HEF4011BT       |
| BUK7212-55B,118    | 934057707118 | BUK7212-55B     |
| 74LVC74APW-Q100J   | 935300464118 | 74LVC74APW-Q100 |
| 74AVC4TD245PW,118  | 935295415118 | 74AVC4TD245PW   |
| "74LVC1G126GW,125" | 935268721125 | 74LVC1G126GW    |
| BZX84-B2V7,215     | 933770290215 | BZX84-B2V7      |
| "74LV14D,112"      | 935069490112 | 74LV14D         |
| BZX79-B4V7,143     | 933166800143 | BZX79-B4V7      |
| 74AHC374PW,118     | 935262681118 | 74AHC374PW      |
| BAS21SW,115        | 934063271115 | BAS21SW         |
| 74AUP1G74GS,115    | 935292775115 | 74AUP1G74GS     |

|                      |              |                  |
|----------------------|--------------|------------------|
| 74AHC86BQ,115        | 935285547115 | 74AHC86BQ        |
| PMBD6100,215         | 933859230215 | PMBD6100         |
| TL431BCDBZR,215      | 935288023215 | TL431BCDBZR      |
| BUK7K25-40E,115      | 934066991115 | BUK7K25-40E      |
| HEF4053BT,653        | 933372960653 | HEF4053BT        |
| 74LVC2G02GS,115      | 935292371115 | 74LVC2G02GS      |
| 74HC9115D,118        | 933987840118 | 74HC9115D        |
| 74LV164BQ,115        | 935278654115 | 74LV164BQ        |
| PMT560ENEAX          | 934068624115 | PMT560ENEA       |
| "74HC541PW,112"      | 935171460112 | 74HC541PW        |
| 74AVC1T1022GUX       | 935305832115 | 74AVC1T1022GU    |
| PDTA114TT,215        | 934034870215 | PDTA114TT        |
| "74HCT154PW,112"     | 935182560112 | 74HCT154PW       |
| 74HC4316D,653        | 933757450653 | 74HC4316D        |
| BC860B,215           | 933589850215 | BC860B           |
| PHPT610035NKX        | 934068169115 | PHPT610035NK     |
| "74AHC573PW,112"     | 935263072112 | 74AHC573PW       |
| PUMD9,115            | 934055050115 | PUMD9            |
| BAS321,115           | 934055352115 | BAS321           |
| BAS16VY,125          | 934057343125 | BAS16VY          |
| 74HC173PW,118        | 935189550118 | 74HC173PW        |
| 74LVC2G02DC-Q100H    | 935300458125 | 74LVC2G02DC-Q100 |
| BZV55-C6V2,135       | 933699470135 | BZV55-C6V2       |
| BAS316Z              | 934054945145 | BAS316           |
| BZB84-B16VL          | 934063346235 | BZB84-B16        |
| 74HCT373D,653        | 933715580653 | 74HCT373D        |
| PUMT1,115            | 934034200115 | PUMT1            |
| 74LV08D,118          | 935063150118 | 74LV08D          |
| PESD5V0F1BSF,315     | 934064776315 | PESD5V0F1BSF     |
| PMEG3050EP,115       | 934061475115 | PMEG3050EP       |
| 74AHC594PW-Q100,11   | 935298654118 | 74AHC594PW-Q100  |
| 74HC40103PW,118      | 935189620118 | 74HC40103PW      |
| BZB784-C9V1,115      | 934056310115 | BZB784-C9V1      |
| "74HCT14PW,112"      | 935183540112 | 74HCT14PW        |
| 74AHC139PW,118       | 935263566118 | 74AHC139PW       |
| BZB784-C6V2,115      | 934056306115 | BZB784-C6V2      |
| PMEG4010BEA,115      | 934057918115 | PMEG4010BEA      |
| BUK7M12-40EX         | 934070085115 | BUK7M12-40E      |
| "74LVC1G14GW-Q100,1" | 935298481125 | 74LVC1G14GW-Q100 |
| PTVS17VS1UR,115      | 934061355115 | PTVS17VS1UR      |
| 74HCT123D,653        | 933713970653 | 74HCT123D        |
| PMDXB950UPELZ        | 934070431147 | PMDXB950UPEL     |
| BAS21QAZ             | 934070964147 | BAS21QA          |
| PEMD30,115           | 934059928115 | PEMD30           |
| 74LV4060D,118        | 935066190118 | 74LV4060D        |
| PSMN041-80YLX        | 934067516115 | PSMN041-80YL     |

|                      |              |                  |
|----------------------|--------------|------------------|
| PMEG2005ET,215       | 934059426215 | PMEG2005ET       |
| PIMD3,115            | 934058728115 | PIMD3            |
| 74HC20D,653          | 933714300653 | 74HC20D          |
| HEF40175BT,653       | 933373470653 | HEF40175BT       |
| "74LV4066PW,118"     | 935175010118 | 74LV4066PW       |
| 74HC73D,653          | 933714430653 | 74HC73D          |
| BZX79-C2V7,133       | 933298820133 | BZX79-C2V7       |
| PTVS18VP1UTP,115     | 934065546115 | PTVS18VP1UTP     |
| PTVS6V0S1UR,115      | 934061339115 | PTVS6V0S1UR      |
| BZX84J-B22,115       | 934060945115 | BZX84J-B22       |
| "74HC139D,652"       | 933713500652 | 74HC139D         |
| 74LVC2GU04GV,125     | 935274028125 | 74LVC2GU04GV     |
| "74HCT08PW,118"      | 935174290118 | 74HCT08PW        |
| 74LVT244ADB,118      | 935167140118 | 74LVT244ADB      |
| PMZ1200UPEYL         | 934069329315 | PMZ1200UPE       |
| BZV55-C10,115        | 933699520115 | BZV55-C10        |
| PZU5.6B1A,115        | 934062781115 | PZU5.6B1A        |
| 74HCT4017D,653       | 933715240653 | 74HCT4017D       |
| 74HC373BQ,115        | 935274585115 | 74HC373BQ        |
| 74AUP1T34GW-Q100H    | 935302098125 | 74AUP1T34GW-Q100 |
| PBSS2515M,315        | 934057145315 | PBSS2515M        |
| BZV49-C16,115        | 933606010115 | BZV49-C16        |
| 74HCU04D,653         | 933714000653 | 74HCU04D         |
| BSS63,215            | 933330390215 | BSS63            |
| BZX384-B6V2,115      | 934057368115 | BZX384-B6V2      |
| IP4292CZ10-TBR,115   | 934065615115 | IP4292CZ10-TBR   |
| 74HCT273BQ,115       | 935274588115 | 74HCT273BQ       |
| BC817-40W,115        | 934021940115 | BC817-40W        |
| PDTA144ET,215        | 934031080215 | PDTA144ET        |
| 1N4728A,133          | 933931540133 | 1N4728A          |
| PHPT61002NYCLHX      | 934070271115 | PHPT61002NYCLH   |
| PSMN3R3-40YS,115     | 934064148115 | PSMN3R3-40YS     |
| BUK964R4-40B,118     | 934057691118 | BUK964R4-40B     |
| 74HCT259PW,118       | 935188410118 | 74HCT259PW       |
| 74HC574DB,118        | 935187010118 | 74HC574DB        |
| PTVS5V0S1UTR,115     | 934065474115 | PTVS5V0S1UTR     |
| "74ABT126PW,118"     | 935201070118 | 74ABT126PW       |
| PMPB20EN,115         | 934066626115 | PMPB20EN         |
| BAS316,135           | 934054945135 | BAS316           |
| "74LVCH162245ADGG,1" | 935238730112 | 74LVCH162245ADGG |
| HEF4518BT,653        | 933373230653 | HEF4518BT        |
| 74LVC08ADB,118       | 935250030118 | 74LVC08ADB       |
| BCP53-10HX           | 934070287115 | BCP53-10H        |
| PESD5V0S4UF,115      | 934061201115 | PESD5V0S4UF      |
| NX3008PBKV,115       | 934065633115 | NX3008PBKV       |
| PUMD9,165            | 934055050165 | PUMD9            |



|                    |              |                  |
|--------------------|--------------|------------------|
| BZT52-C30J         | 934071142118 | BZT52-C30        |
| BCV49,135          | 934003660135 | BCV49            |
| 74HC390D,653       | 933714720653 | 74HC390D         |
| BZX79-C18,113      | 933117850113 | BZX79-C18        |
| HEF4013BT-Q100J    | 935299245118 | HEF4013BT-Q100   |
| 74HC2G08DP-Q100H   | 935300847125 | 74HC2G08DP-Q100  |
| BZX585-C9V1,115    | 934055850115 | BZX585-C9V1      |
| PESD15VS1UB,115    | 934058513115 | PESD15VS1UB      |
| PMGD290UCEAX       | 934067604115 | PMGD290UCEA      |
| 74LVC2G14GW-Q100H  | 935301405125 | 74LVC2G14GW-Q100 |
| 74LVC2G34GM,115    | 935277164115 | 74LVC2G34GM      |
| PMV33UPE,215       | 934066842215 | PMV33UPE         |
| BAT86,133          | 933624770133 | BAT86            |
| BZV55-C22,115      | 933699600115 | BZV55-C22        |
| PBSS5330X,135      | 934058037135 | PBSS5330X        |
| 74AHC14D,118       | 935262758118 | 74AHC14D         |
| "HEF4001BT,652"    | 933372590652 | HEF4001BT        |
| BZX79-B18,113      | 933166930113 | BZX79-B18        |
| PMEG4010EJ,115     | 934058526115 | PMEG4010EJ       |
| BUK7Y41-80EX       | 934067424115 | BUK7Y41-80E      |
| "74AUP1T45GW,125"  | 935280513125 | 74AUP1T45GW      |
| BZT52-C68X         | 934071139115 | BZT52-C68        |
| PMEG2005AELD,315   | 934065335315 | PMEG2005AELD     |
| 74LVC139D,112      | 935195990112 | 74LVC139D        |
| BC817-16,215       | 933628620215 | BC817-16         |
| "74LV244PW,112"    | 935174650112 | 74LV244PW        |
| BZV85-C9V1,133     | 933500640133 | BZV85-C9V1       |
| BAT760,115         | 934055715115 | BAT760           |
| 74HCT86D,653       | 933714040653 | 74HCT86D         |
| 74HC393BQ,115      | 935278648115 | 74HC393BQ        |
| 74HCT126DB,112     | 935183590112 | 74HCT126DB       |
| 74HC165BQ,115      | 935286073115 | 74HC165BQ        |
| "74HC1GU04GV,125"  | 935271787125 | 74HC1GU04GV      |
| 74AHCT132BQ,115    | 935278806115 | 74AHCT132BQ      |
| 74VHCT595PW,118    | 935289516118 | 74VHCT595PW      |
| 74HCT4051D,112     | 933715300112 | 74HCT4051D       |
| BZX84-C7V5,215     | 933137430215 | BZX84-C7V5       |
| 74LV1T126GWH       | 935690209125 | 74LV1T126GW      |
| 74HCT259PW,112     | 935188410112 | 74HCT259PW       |
| PDZ4.7B,135        | 934054851135 | PDZ4.7B          |
| "74HC03PW,118"     | 935174180118 | 74HC03PW         |
| 74HC595PW-Q100,118 | 935298875118 | 74HC595PW-Q100   |
| BZX79-C27,133      | 933117890133 | BZX79-C27        |
| PBSS5540Z,115      | 934055496115 | PBSS5540Z        |
| BC857BW,115        | 934021850115 | BC857BW          |
| BZX84-C5V1/DG/B4R  | 934070258215 | BZX84-C5V1/DG/B4 |

|                      |              |                   |
|----------------------|--------------|-------------------|
| PBLS6024D,115        | 934061572115 | PBLS6024D         |
| 74AHC245D,112        | 935262003112 | 74AHC245D         |
| BC817K-40HR          | 934660225215 | BC817K-40H        |
| PESD3V3U1UA,115      | 934062951115 | PESD3V3U1UA       |
| 74AUP2G125GM,125     | 935281433125 | 74AUP2G125GM      |
| PTVS64VP1UTP,115     | 934065565115 | PTVS64VP1UTP      |
| "74HCT32PW,118"      | 935186910118 | 74HCT32PW         |
| "74AHCT1G08GW-Q100," | 935298625125 | 74AHCT1G08GW-Q100 |
| PMEG4020ETP,115      | 934065469115 | PMEG4020ETP       |
| PHPT61006NYX         | 934068574115 | PHPT61006NY       |
| PMEG3020BER,115      | 934061462115 | PMEG3020BER       |
| PDZ15BZ              | 934054863145 | PDZ15B            |
| 74LVC1G74DP-Q100H    | 935299294125 | 74LVC1G74DP-Q100  |
| PMDXB600UNEZ         | 934067655147 | PMDXB600UNE       |
| BZV55-C10,135        | 933699520135 | BZV55-C10         |
| 74HCT4075D,653       | 933714200653 | 74HCT4075D        |
| BF824,215            | 933722350215 | BF824             |
| PTVS36VP1UP,115      | 934064181115 | PTVS36VP1UP       |
| PSMN020-100YS,115    | 934064431115 | PSMN020-100YS     |
| "74LVC1G125GS,132"   | 935292901132 | 74LVC1G125GS      |
| PHPT60410PYX         | 934068582115 | PHPT60410PY       |
| 74LV1T86GXH          | 935690206125 | 74LV1T86GX        |
| 74LVC273PW,118       | 935210650118 | 74LVC273PW        |
| 74HCT541PW-Q100J     | 935300891118 | 74HCT541PW-Q100   |
| 74LVC1G11GXZ         | 935307081147 | 74LVC1G11GX       |
| BZT52H-C2V7,115      | 934059385115 | BZT52H-C2V7       |
| "74HCT1G66GW,125"    | 935245760125 | 74HCT1G66GW       |
| BC69-25PA,115        | 934065813115 | BC69-25PA         |
| 74AUP2G126GS,115     | 935292376115 | 74AUP2G126GS      |
| BZT52H-B2V4,115      | 934064777115 | BZT52H-B2V4       |
| "74AHC541PW,112"     | 935262008112 | 74AHC541PW        |
| 74LVC4066D,118       | 935273717118 | 74LVC4066D        |
| 74AHC08PW-Q100J      | 935300959118 | 74AHC08PW-Q100    |
| BCX56-10,115         | 933663090115 | BCX56-10          |
| "74AHCT14PW,112"     | 935262761112 | 74AHCT14PW        |
| PDZ30B,115           | 934054870115 | PDZ30B            |
| BUK9Y4R8-60E,115     | 934067017115 | BUK9Y4R8-60E      |
| PZU3.9BA,115         | 934062477115 | PZU3.9BA          |
| PMEG6010ELRX         | 934067653115 | PMEG6010ELR       |
| BUK9Y3R5-40E,115     | 934067044115 | BUK9Y3R5-40E      |
| BZX84-C13,215        | 933388250215 | BZX84-C13         |
| PTVS24VS1UR,115      | 934061359115 | PTVS24VS1UR       |
| PESD5V0X1BQ,115      | 934062183115 | PESD5V0X1BQ       |
| BSS84AKW,115         | 934065305115 | BSS84AKW          |
| BZX384-C4V3,115      | 934057631115 | BZX384-C4V3       |
| BZV55-B11,115        | 933827760115 | BZV55-B11         |

|                    |              |                   |
|--------------------|--------------|-------------------|
| PESD12VS1UJ,115    | 934063242115 | PESD12VS1UJ       |
| PZU16B2A,115       | 934062353115 | PZU16B2A          |
| PMZ600UNELYL       | 934070429315 | PMZ600UNEL        |
| "74HCT7541D,112"   | 933967980112 | 74HCT7541D        |
| BZX84-C20,215      | 933388290215 | BZX84-C20         |
| PESD36VS1UL,315    | 934066318315 | PESD36VS1UL       |
| BZX384-B75,115     | 934057394115 | BZX384-B75        |
| "74HC14D,652"      | 933714400652 | 74HC14D           |
| 74VHC245PW,118     | 935289583118 | 74VHC245PW        |
| PDZ11B,115         | 934054860115 | PDZ11B            |
| PZU10B2A,115       | 934062329115 | PZU10B2A          |
| BZX84J-B9V1,115    | 934060981115 | BZX84J-B9V1       |
| 74LVCH16245ADL,118 | 935238460118 | 74LVCH16245ADL    |
| BZX585-C18,115     | 934057422115 | BZX585-C18        |
| 74LVC2G126DC,125   | 935274583125 | 74LVC2G126DC      |
| BAS116,235         | 934032170235 | BAS116            |
| 74AUP1G175GW-Q100H | 935300511125 | 74AUP1G175GW-Q100 |
| PDTC115ET,215      | 934057527215 | PDTC115ET         |
| 74HC4852D,118      | 935282088118 | 74HC4852D         |
| 74LV138PW,118      | 935174390118 | 74LV138PW         |
| BZT52-C75X         | 934071141115 | BZT52-C75         |
| "74ABT244D,602"    | 935027510602 | 74ABT244D         |
| 74HC3G14DC-Q100H   | 935300873125 | 74HC3G14DC-Q100   |
| BZV85-C15,113      | 933500690113 | BZV85-C15         |
| PBSS4041PT,215     | 934062764215 | PBSS4041PT        |
| PEMH9,115          | 934056769115 | PEMH9             |
| HEF4093BT/C4J      | 935301974118 | HEF4093BT/C4      |
| 74HCT7541D,118     | 933967980118 | 74HCT7541D        |
| BZT52-C4V7X        | 934071107115 | BZT52-C4V7        |
| BZT52-B10X         | 934071159115 | BZT52-B10         |
| BCP53-10,115       | 933917340115 | BCP53-10          |
| PZU36BL,315        | 934061607315 | PZU36BL           |
| 74HCT4351D,118     | 933774600118 | 74HCT4351D        |
| 74LVC2244ADB,118   | 935213560118 | 74LVC2244ADB      |
| PBHV9050T,215      | 934063607215 | PBHV9050T         |
| 74LVC245APW-Q100J  | 935299257118 | 74LVC245APW-Q100  |
| "74LVC00AD,112"    | 935249960112 | 74LVC00AD         |
| BC847BMB,315       | 934065886315 | BC847BMB          |
| "74HC4050PW,112"   | 935187470112 | 74HC4050PW        |
| PMST5089,115       | 934026940115 | PMST5089          |
| 74LVC8T245PW-Q100J | 935300465118 | 74LVC8T245PW-Q100 |
| BZT52-B6V2X        | 934071154115 | BZT52-B6V2        |
| "74HC157D,652"     | 933713740652 | 74HC157D          |
| BZX79-B8V2,133     | 933166850133 | BZX79-B8V2        |
| 74AHCT138D,118     | 935262997118 | 74AHCT138D        |
| PDZ33B,115         | 934054871115 | PDZ33B            |

|                    |              |                    |
|--------------------|--------------|--------------------|
| PMT280ENEAX        | 934068623115 | PMT280ENEAX        |
| 74AUP2G32GXX       | 935339797115 | 74AUP2G32GXX       |
| BCX54-16,115       | 933674740115 | BCX54-16           |
| BUK7E1R9-40E,127   | 934066982127 | BUK7E1R9-40E       |
| PBSS5160T,215      | 934057668215 | PBSS5160T          |
| BSS138P,215        | 934064988215 | BSS138P            |
| 74AUP2G08GXX       | 935308433115 | 74AUP2G08GXX       |
| PTVS36VS1UTR,115   | 934065502115 | PTVS36VS1UTR       |
| PMSS3906,115       | 934026910115 | PMSS3906           |
| 74LVC16245ADGG,118 | 935235090118 | 74LVC16245ADGG     |
| BUK7208-40B,118    | 934057607118 | BUK7208-40B        |
| MMBZ15VAL,215      | 934061797215 | MMBZ15VAL          |
| "74HC594D,112"     | 935043380112 | 74HC594D           |
| BCP51,115          | 933917270115 | BCP51              |
| 74AUP1G17GM,115    | 935279025115 | 74AUP1G17GM        |
| NZX3V9B,133        | 934063522133 | NZX3V9B            |
| "74AUP1G80GX,125"  | 935298366125 | 74AUP1G80GX        |
| PBSS5350Z,135      | 934056527135 | PBSS5350Z          |
| BZV90-C2V4,115     | 934014610115 | BZV90-C2V4         |
| "74LVC1G02GX,125"  | 935298375125 | 74LVC1G02GX        |
| BZV55-C6V8,115     | 933699480115 | BZV55-C6V8         |
| HEF4894BT,118      | 935194380118 | HEF4894BT          |
| 74HCT27D-Q100J     | 935300794118 | 74HCT27D-Q100      |
| BST52,135          | 933644270135 | BST52              |
| BC817-25,215       | 933628630215 | BC817-25           |
| PUSB2X4YH          | 934067937125 | PUSB2X4Y           |
| BCW33,215          | 933099650215 | BCW33              |
| 74HC2G00DC,125     | 935274812125 | 74HC2G00DC         |
| 74LVCH16244ADL,118 | 935238440118 | 74LVCH16244ADL     |
| 74HC2G32DC,125     | 935274823125 | 74HC2G32DC         |
| BC846BPN,115       | 934063471115 | BC846BPN           |
| 74HC237D,653       | 933757190653 | 74HC237D           |
| 74ABT04D,118       | 935206990118 | 74ABT04D           |
| BZV55-C27,135      | 933699620135 | BZV55-C27          |
| BCW60C,215         | 933324100215 | BCW60C             |
| BCP51-10,135       | 933917280135 | BCP51-10           |
| PESD3V3L4UG,115    | 934057784115 | PESD3V3L4UG        |
| 74AVCH4T245BQ-Q10X | 935302455115 | 74AVCH4T245BQ-Q100 |
| 74AHCT132D,118     | 935262995118 | 74AHCT132D         |
| 74LVCH162244ADGG,1 | 935238710118 | 74LVCH162244ADGG   |
| BUK7M19-60EX       | 934070052115 | BUK7M19-60E        |
| 74AHC245D,118      | 935262003118 | 74AHC245D          |
| BAV74,235          | 933700010235 | BAV74              |
| BAT46GWJ           | 934070363118 | BAT46GW            |
| 74AHCT2G126DC,125  | 935275135125 | 74AHCT2G126DC      |
| 74HC373D,652       | 933715470652 | 74HC373D           |

|                   |              |                  |
|-------------------|--------------|------------------|
| 74HC139PW,118     | 935174430118 | 74HC139PW        |
| PTVS40VP1UP,115   | 934064182115 | PTVS40VP1UP      |
| BZX84-B30,215     | 933551440215 | BZX84-B30        |
| 74HC541PW,118     | 935171460118 | 74HC541PW        |
| "74LVC07AD,112"   | 935265481112 | 74LVC07AD        |
| MMBZ27VCL,235     | 934061813235 | MMBZ27VCL        |
| BZX84-C4V7,215    | 933137380215 | BZX84-C4V7       |
| BZX84-A24,215     | 934065156215 | BZX84-A24        |
| BZX585-B5V6,115   | 934055865115 | BZX585-B5V6      |
| "74HCT1G14GV,125" | 935271882125 | 74HCT1G14GV      |
| PEMD4,115         | 934056873115 | PEMD4            |
| 74HC86D,653       | 933714030653 | 74HC86D          |
| PHPT61010NYX      | 934068585115 | PHPT61010NY      |
| BUK7Y4R8-60EX     | 934067436115 | BUK7Y4R8-60E     |
| 74HC573BQ,115     | 935273694115 | 74HC573BQ        |
| PMMT491A,215      | 934055113215 | PMMT491A         |
| 74HCT4316PW,118   | 935188500118 | 74HCT4316PW      |
| 74AXP1G86GXH      | 935306695125 | 74AXP1G86GX      |
| PBSS304NZ,135     | 934059045135 | PBSS304NZ        |
| PMCM4401UNEZ      | 934070325084 | PMCM4401UNE      |
| PBSS4120T,215     | 934057984215 | PBSS4120T        |
| BZV85-C6V2,133    | 933500600133 | BZV85-C6V2       |
| 74LVC3GU04DC,125  | 935275567125 | 74LVC3GU04DC     |
| PTVS6V0S1UR/8X    | 934660629115 | PTVS6V0S1UR/8    |
| PMEG030V050EPDZ   | 934070189146 | PMEG030V050EPD   |
| 74AUP1GU04GM,115  | 935279066115 | 74AUP1GU04GM     |
| PUMZ1,115         | 934034220115 | PUMZ1            |
| PSMN1R2-25YL,115  | 934063812115 | PSMN1R2-25YL     |
| 74AUP1G74DC,125   | 935280717125 | 74AUP1G74DC      |
| 74LVC2G17GW-Q100H | 935299308125 | 74LVC2G17GW-Q100 |
| PESD12VU1UT,215   | 934059104215 | PESD12VU1UT      |
| PZU3.6B2A,115     | 934062476115 | PZU3.6B2A        |
| 74HC157PW,118     | 935186880118 | 74HC157PW        |
| "74AUP1G58GW,125" | 935279959125 | 74AUP1G58GW      |
| BZV49-C5V6,115    | 933605900115 | BZV49-C5V6       |
| BC846BW,115       | 934021740115 | BC846BW          |
| BZX585-C51,115    | 934057433115 | BZX585-C51       |
| "74AHC1G04GW,125" | 935262753125 | 74AHC1G04GW      |
| "74LV138D,112"    | 935063190112 | 74LV138D         |
| BZX384-C3V0,115   | 934057627115 | BZX384-C3V0      |
| PSMN013-30YLC,115 | 934066015115 | PSMN013-30YLC    |
| "74LVC1G19GW,125" | 935273468125 | 74LVC1G19GW      |
| BZT52-C20J        | 934071133118 | BZT52-C20        |
| PESD5V0U2BMB,315  | 934065859315 | PESD5V0U2BMB     |
| "74HC4060D,652"   | 933714010652 | 74HC4060D        |
| BZB984-C15,115    | 934057243115 | BZB984-C15       |

|                   |              |                |
|-------------------|--------------|----------------|
| 74LV132DB,118     | 935230090118 | 74LV132DB      |
| 74HC4040D,653     | 933714780653 | 74HC4040D      |
| 74LVC1T45GF,132   | 935286094132 | 74LVC1T45GF    |
| 74AHC541PW,118    | 935262008118 | 74AHC541PW     |
| PMBT3906VS,115    | 934063473115 | PMBT3906VS     |
| BSP60,115         | 933986350115 | BSP60          |
| "74HC273PW,112"   | 935185830112 | 74HC273PW      |
| BZV85-C43,133     | 933500800133 | BZV85-C43      |
| BUK9M52-40EX      | 934070091115 | BUK9M52-40E    |
| BSH203,215        | 934054719215 | BSH203         |
| BCW31,215         | 933082781215 | BCW31          |
| BCP69-16,115      | 934009430115 | BCP69-16       |
| PEMD14,115        | 934058918115 | PEMD14         |
| BCX53-16TF        | 934660824135 | BCX53-16T      |
| PTVS13VS1UTR,115  | 934065486115 | PTVS13VS1UTR   |
| BUK9Y2R8-40HX     | 934660366115 | BUK9Y2R8-40H   |
| HEF4077BT,653     | 933373070653 | HEF4077BT      |
| BAT54GWX          | 934070364115 | BAT54GW        |
| CBTD3384PW,118    | 935268324118 | CBTD3384PW     |
| BZV49-C24,115     | 933606050115 | BZV49-C24      |
| PLVA650A,215      | 934017340215 | PLVA650A       |
| 74HC193PW,118     | 935188980118 | 74HC193PW      |
| 74HC4040PW,112    | 935174920112 | 74HC4040PW     |
| 1N4743A,133       | 933931690133 | 1N4743A        |
| BCW66HVL          | 934070943235 | BCW66H         |
| 74LVC1G125GM,115  | 935277203115 | 74LVC1G125GM   |
| PZU2.4B,115       | 934059741115 | PZU2.4B        |
| "74HCT4066PW,112" | 935187510112 | 74HCT4066PW    |
| PMBT2907AMBYL     | 934660372315 | PMBT2907AMB    |
| BZT52-B20J        | 934071178118 | BZT52-B20      |
| 74AHC32BQ-Q100X   | 935300191115 | 74AHC32BQ-Q100 |
| BZX84-A3V6,215    | 934043110215 | BZX84-A3V6     |
| PSMN1R5-30YLC,115 | 934065188115 | PSMN1R5-30YLC  |
| PSMN2R0-25YLDX    | 934069912115 | PSMN2R0-25YLD  |
| BC857CM,315       | 934057148315 | BC857CM        |
| BZX585-B8V2,135   | 934055869135 | BZX585-B8V2    |
| PMEG4050EP,115    | 934061485115 | PMEG4050EP     |
| BZX84-B3V0,215    | 933770300215 | BZX84-B3V0     |
| 74LVC1G17GX4Z     | 935690005147 | 74LVC1G17GX4   |
| 74HCT27D,653      | 933714180653 | 74HCT27D       |
| "74LVC126APW,118" | 935241120118 | 74LVC126APW    |
| BF820,215         | 933665120215 | BF820          |
| HEF4555BT,652     | 933373310652 | HEF4555BT      |
| 74AUP2G00GX       | 935308439115 | 74AUP2G00GX    |
| PSMN012-100YS,115 | 934064395115 | PSMN012-100YS  |
| BZX84-C12,235     | 933137480235 | BZX84-C12      |

|                     |              |                  |
|---------------------|--------------|------------------|
| 74HCT1G04GW-Q100H   | 935299998125 | 74HCT1G04GW-Q100 |
| BZT52-B7V5X         | 934071156115 | BZT52-B7V5       |
| PMGD175XNEX         | 934068835115 | PMGD175XNE       |
| "74HC1G125GV,125"   | 935271790125 | 74HC1G125GV      |
| 1N4746A,113         | 933931720113 | 1N4746A          |
| BZX884-B10,315      | 934057204315 | BZX884-B10       |
| "74AUP2GU04GW,125"  | 935279998125 | 74AUP2GU04GW     |
| BZT52-B11X          | 934071161115 | BZT52-B11        |
| 74LVC273DB,118      | 935174740118 | 74LVC273DB       |
| PSMN028-100YS,115   | 934064534115 | PSMN028-100YS    |
| BZV55-B68,115       | 933931890115 | BZV55-B68        |
| PZU10B2L,315        | 934061608315 | PZU10B2L         |
| "74AHCT1G126GV,125" | 935271663125 | 74AHCT1G126GV    |
| 74AVC4T245GU,115    | 935294132115 | 74AVC4T245GU     |
| "74AUP2G14GW,125"   | 935279987125 | 74AUP2G14GW      |
| "74HCT1G08GV,125"   | 935272021125 | 74HCT1G08GV      |
| 74AUP2G34GM,115     | 935279995115 | 74AUP2G34GM      |
| PDTD114ETVL         | 934031040235 | PDTD114ET        |
| 74VHC244PW,118      | 935289613118 | 74VHC244PW       |
| PMEG6010ETR,115     | 934066838115 | PMEG6010ETR      |
| BC869,115           | 933678780115 | BC869            |
| BCV48,115           | 934021680115 | BCV48            |
| PSMN4R8-100BSEJ     | 934067369118 | PSMN4R8-100BSE   |
| BZV55-C68,115       | 933699750115 | BZV55-C68        |
| BUK9K18-40E,115     | 934067072115 | BUK9K18-40E      |
| PDZ4.7B,115         | 934054851115 | PDZ4.7B          |
| 74LV14APWJ          | 935308161118 | 74LV14APW        |
| 74LVC1G08GM,115     | 935277188115 | 74LVC1G08GM      |
| BZT52-C6V8X         | 934071112115 | BZT52-C6V8       |
| HEF4001BT,653       | 933372590653 | HEF4001BT        |
| 74AUP1T32GXH        | 935690052125 | 74AUP1T32GX      |
| BZT52H-B15,115      | 934064798115 | BZT52H-B15       |
| BUK7Y3R5-40E,115    | 934066628115 | BUK7Y3R5-40E     |
| "74AHC126PW,112"    | 935262769112 | 74AHC126PW       |
| 2N7002BKS,115       | 934064284115 | 2N7002BKS        |
| BC857BS,135         | 934042510135 | BC857BS          |
| 74LVC2G53DC,125     | 935280382125 | 74LVC2G53DC      |
| "74HC4024D,652"     | 933714410652 | 74HC4024D        |
| PMEG3010EP,115      | 934061468115 | PMEG3010EP       |
| BZX84-A16,215       | 934065153215 | BZX84-A16        |
| BZT52H-B3V9,115     | 934064783115 | BZT52H-B3V9      |
| PHB45NQ15T,118      | 934058108118 | PHB45NQ15T       |
| 74HC4052PW-Q100,11  | 935298845118 | 74HC4052PW-Q100  |
| 74HC4060PW,118      | 935242080118 | 74HC4060PW       |
| PMEG040V030EPDZ     | 934070191146 | PMEG040V030EPD   |
| 74AUP1G132GM,115    | 935279059115 | 74AUP1G132GM     |

|                    |              |                    |
|--------------------|--------------|--------------------|
| 74VHCT541BQ,115    | 935289518115 | 74VHCT541BQ        |
| BZT52-B3V3X        | 934071146115 | BZT52-B3V3         |
| PMEG3020EP,115     | 934061472115 | PMEG3020EP         |
| 74LVC125ADB,118    | 935231710118 | 74LVC125ADB        |
| HEF4069UBT,653     | 933373000653 | HEF4069UBT         |
| BCX71K,235         | 933483680235 | BCX71K             |
| 74HCT240D,652      | 933713450652 | 74HCT240D          |
| BUK9K35-60E,115    | 934066977115 | BUK9K35-60E        |
| PUMH24,115         | 934057903115 | PUMH24             |
| 74HCT175PW,118     | 935188970118 | 74HCT175PW         |
| BZV49-C10,115      | 933605960115 | BZV49-C10          |
| PBSS5330PA,115     | 934064273115 | PBSS5330PA         |
| BZX79-C5V6,113     | 933117730113 | BZX79-C5V6         |
| BZV55-B7V5,115     | 933827720115 | BZV55-B7V5         |
| 74LVC32AD,118      | 935250060118 | 74LVC32AD          |
| BC53PA,115         | 934065821115 | BC53PA             |
| BAS70-04W,115      | 934034480115 | BAS70-04W          |
| PESD2IVN24-UX      | 934070277115 | PESD2IVN24-U       |
| BC847,215          | 933589570215 | BC847              |
| BC857A,215         | 933589750215 | BC857A             |
| 74AHCT2G125DC-Q10H | 935301504125 | 74AHCT2G125DC-Q100 |
| 74AXP1G08GXH       | 935303206125 | 74AXP1G08GX        |
| BZX585-B11,115     | 934055872115 | BZX585-B11         |
| TL431BIDBZR,215    | 935288024215 | TL431BIDBZR        |
| PMXB120EPEZ        | 934067154147 | PMXB120EPE         |
| 74LVT16244BDL,118  | 935183090118 | 74LVT16244BDL      |
| 74HCT273D,652      | 933715550652 | 74HCT273D          |
| MMBT3904,215       | 933864360215 | MMBT3904           |
| HEF4017BT,652      | 933372700652 | HEF4017BT          |
| BSS138BKW,115      | 934065731115 | BSS138BKW          |
| PMBT3904,215       | 933776000215 | PMBT3904           |
| BSR33,135          | 933418140135 | BSR33              |
| 74HC241PW,118      | 935174580118 | 74HC241PW          |
| PSMN8R7-80BS,118   | 934066203118 | PSMN8R7-80BS       |
| 74LVC138ADB,118    | 935260746118 | 74LVC138ADB        |
| 74LVC1G57GM,115    | 935277211115 | 74LVC1G57GM        |
| BF840,215          | 933792670215 | BF840              |
| NZH4V3B,115        | 934064356115 | NZH4V3B            |
| BZX84-A22,215      | 934065155215 | BZX84-A22          |
| BZT52-C56J         | 934071137118 | BZT52-C56          |
| 74ALVC74BQ,115     | 935273692115 | 74ALVC74BQ         |
| TL431BMFDT,215     | 935293279215 | TL431BMFDT         |
| BZT52H-B30,115     | 934064806115 | BZT52H-B30         |
| "74HCT1G66GV,125"  | 935271886125 | 74HCT1G66GV        |
| BAS16GWX           | 934070359115 | BAS16GW            |
| MMBZ10VAL,215      | 934063467215 | MMBZ10VAL          |



|                      |              |                 |
|----------------------|--------------|-----------------|
| BZT52-B16J           | 934071176118 | BZT52-B16       |
| PESD12VSA-LYL        | 934660596315 | PESD12VSA-L     |
| "74HCT574PW,112"     | 935188510112 | 74HCT574PW      |
| 74AHC2G126DP,125     | 935274672125 | 74AHC2G126DP    |
| 74LVC1G53DC,125      | 935279945125 | 74LVC1G53DC     |
| PHPT60415PYX         | 934068588115 | PHPT60415PY     |
| BCX71J,215           | 933483670215 | BCX71J          |
| PMEG10030ELPX        | 934068902115 | PMEG10030ELP    |
| 74LVC3G34DP,125      | 935275566125 | 74LVC3G34DP     |
| HEF4538BT,653        | 933507970653 | HEF4538BT       |
| PMEG045V150EPDAZ     | 934067178146 | PMEG045V150EPD  |
| PMV25ENEAR           | 934068716215 | PMV25ENEA       |
| HEF4043BT,652        | 933372880652 | HEF4043BT       |
| 74HC4852PW-Q100,11   | 935298469118 | 74HC4852PW-Q100 |
| BZX84J-B2V4,115      | 934060948115 | BZX84J-B2V4     |
| PTVS54VP1UP,115      | 934064187115 | PTVS54VP1UP     |
| NX3020NAKS,115       | 934066973115 | NX3020NAKS      |
| BZT52-C11J           | 934071126118 | BZT52-C11       |
| BC847DS,115          | 934063469115 | BC847DS         |
| 74HC259BQ,115        | 935288455115 | 74HC259BQ       |
| IP4233CZ6,125        | 934062614125 | IP4233CZ6       |
| BUK9K45-100E,115     | 934066974115 | BUK9K45-100E    |
| PHB21N06LT,118       | 934054570118 | PHB21N06LT      |
| BUK9M6R7-40HX        | 934660795115 | BUK9M6R7-40H    |
| "74LVC1G04GW,125"    | 935268456125 | 74LVC1G04GW     |
| PMEG2010AEJ,115      | 934059006115 | PMEG2010AEJ     |
| 74LVC2G74DC,125      | 935280391125 | 74LVC2G74DC     |
| 1N4531,113           | 933203980113 | 1N4531          |
| PBSS303NZ,135        | 934059044135 | PBSS303NZ       |
| 74LVT14PW,118        | 935209190118 | 74LVT14PW       |
| BC850C,215           | 933589700215 | BC850C          |
| 74LVC74ADB,118       | 935260735118 | 74LVC74ADB      |
| BUK7K17-60EX         | 934067952115 | BUK7K17-60E     |
| 74HCT4316D,118       | 933757470118 | 74HCT4316D      |
| 74HC4040PW-Q100J     | 935300342118 | 74HC4040PW-Q100 |
| 74HCT4851D,118       | 935285729118 | 74HCT4851D      |
| 74LVC2G08DP,125      | 935273582125 | 74LVC2G08DP     |
| "74LVC08APW-Q100,11" | 935299055118 | 74LVC08APW-Q100 |
| PDTC114YM,315        | 934057172315 | PDTC114YM       |
| PMEG4005CEJX         | 934069933115 | PMEG4005CEJ     |
| PBSS4041NZ,115       | 934063395115 | PBSS4041NZ      |
| BZB784-C5V1,115      | 934056304115 | BZB784-C5V1     |
| BC857,215            | 933589740215 | BC857           |
| 74LV1T87GWH          | 935690207125 | 74LV1T87GW      |
| 74LVC244AD,118       | 935210400118 | 74LVC244AD      |
| PESD24VS1UL,315      | 934059979315 | PESD24VS1UL     |

|                      |              |                 |
|----------------------|--------------|-----------------|
| BZX84-B4V3,215       | 933770320215 | BZX84-B4V3      |
| BZV55-B16,115        | 933827800115 | BZV55-B16       |
| HEF4073BT,653        | 933373040653 | HEF4073BT       |
| 74AHC595D,118        | 935265567118 | 74AHC595D       |
| PSMN022-30BL,118     | 934066337118 | PSMN022-30BL    |
| PBSS302PD,115        | 934059132115 | PBSS302PD       |
| PMEG6010CEGWJ        | 934070372118 | PMEG6010CEGW    |
| 74AXP1G09GXH         | 935306257125 | 74AXP1G09GX     |
| BZX585-B68,115       | 934057419115 | BZX585-B68      |
| 74LVC14APW,118       | 935260739118 | 74LVC14APW      |
| "74HC11PW,118"       | 935186360118 | 74HC11PW        |
| 74AHC157BQ,115       | 935285569115 | 74AHC157BQ      |
| "74HC73PW,118"       | 935242070118 | 74HC73PW        |
| 74LVC3G07DP,125      | 935275558125 | 74LVC3G07DP     |
| BZB84-B2V7,215       | 934061702215 | BZB84-B2V7      |
| BZT52H-C8V2,115      | 934059398115 | BZT52H-C8V2     |
| BZX84-B5V1,215       | 933643800215 | BZX84-B5V1      |
| BZX585-C7V5,115      | 934055848115 | BZX585-C7V5     |
| BC807-25,215         | 933628570215 | BC807-25        |
| BUK9Y7R2-60E,115     | 934067019115 | BUK9Y7R2-60E    |
| BC847BVN,115         | 934056712115 | BC847BVN        |
| BSP130,115           | 934023500115 | BSP130          |
| BZX384-B2V4,115      | 934057358115 | BZX384-B2V4     |
| BSV52,215            | 933099000215 | BSV52           |
| NZH3V6B,115          | 934064354115 | NZH3V6B         |
| 74LVT04D,118         | 935208990118 | 74LVT04D        |
| BZT52-C7V5X          | 934071113115 | BZT52-C7V5      |
| BCX53-16,115         | 933674730115 | BCX53-16        |
| PMZB290UNE,315       | 934065873315 | PMZB290UNE      |
| PBSS4350D,115        | 934055947115 | PBSS4350D       |
| PDZ16BGWJ            | 934071053118 | PDZ16BGW        |
| PTVS33VS1UR/8X       | 934660626115 | PTVS33VS1UR/8   |
| BAV74,215            | 933700010215 | BAV74           |
| 74LVT14DB,118        | 935209180118 | 74LVT14DB       |
| BC847BV,115          | 934056535115 | BC847BV         |
| BZT52-B7V5J          | 934071156118 | BZT52-B7V5      |
| "74ALVC164245DGG,11" | 935202350112 | 74ALVC164245DGG |
| 74HC541D,652         | 933715500652 | 74HC541D        |
| PZU6.2B2A,115        | 934062786115 | PZU6.2B2A       |
| 74LVC16373ADL,118    | 935235160118 | 74LVC16373ADL   |
| 74LVC2G86DP,125      | 935273585125 | 74LVC2G86DP     |
| "74AVCH8T245PW,112"  | 935284594112 | 74AVCH8T245PW   |
| BZX384-B4V3,115      | 934057364115 | BZX384-B4V3     |
| PESD5V0S2UQ,115      | 934057835115 | PESD5V0S2UQ     |
| "74ALVC164245DL,112" | 935202340112 | 74ALVC164245DL  |
| PZU3.9BL,315         | 934061661315 | PZU3.9BL        |

|                    |              |               |
|--------------------|--------------|---------------|
| PMBTA42,215        | 933776090215 | PMBTA42       |
| PMPB13XNE,115      | 934066867115 | PMPB13XNE     |
| PMBTA56,215        | 933816490215 | PMBTA56       |
| "74AHCT14PW,118"   | 935262761118 | 74AHCT14PW    |
| BZT52-B5V1J        | 934071152118 | BZT52-B5V1    |
| BAS56,215          | 933742310215 | BAS56         |
| BZT52H-C10,115     | 934059401115 | BZT52H-C10    |
| PTVS6VOS1UTR,115   | 934065475115 | PTVS6VOS1UTR  |
| PSMN039-100YS,115  | 934064535115 | PSMN039-100YS |
| 74HC27PW,112       | 935189010112 | 74HC27PW      |
| NCR402UX           | 934067776115 | NCR402U       |
| "74AHC125D,112"    | 935262762112 | 74AHC125D     |
| BZX84-C62,215      | 933388410215 | BZX84-C62     |
| "74HCT1G04GW,125"  | 935245640125 | 74HCT1G04GW   |
| 74HCT241D,652      | 933713470652 | 74HCT241D     |
| PTVS58VS1UR,115    | 934061373115 | PTVS58VS1UR   |
| BZV49-C2V4,115     | 933605810115 | BZV49-C2V4    |
| "74HC4514D,652"    | 933715670652 | 74HC4514D     |
| "74AHC1G125GW,125" | 935263002125 | 74AHC1G125GW  |
| BC856SF            | 934055680135 | BC856S        |
| PSMN4R0-60YS,115   | 934064465115 | PSMN4R0-60YS  |
| PUMB13,115         | 934057883115 | PUMB13        |
| 74LV4060PW,118     | 935174990118 | 74LV4060PW    |
| PUMH17,115         | 934057898115 | PUMH17        |
| PUMH19,115         | 934057901115 | PUMH19        |
| "74AHC1G07GV,125"  | 935271657125 | 74AHC1G07GV   |
| 74HC4040PW,118     | 935174920118 | 74HC4040PW    |
| CBT3257AD,118      | 935275888118 | CBT3257AD     |
| PMEG40T30ERX       | 934070414115 | PMEG40T30ER   |
| "74HC540D,652"     | 933715490652 | 74HC540D      |
| PBSS5240XF         | 934067253135 | PBSS5240X     |
| BUK9K32-100EX      | 934067941115 | BUK9K32-100E  |
| BZX79-B6V8,113     | 933160890113 | BZX79-B6V8    |
| BZX384-B11,115     | 934057374115 | BZX384-B11    |
| BZX79-C16,143      | 933117840143 | BZX79-C16     |
| 74LVC11D,118       | 935205910118 | 74LVC11D      |
| BZT52-B20X         | 934071178115 | BZT52-B20     |
| 74HCT165DB,118     | 935190350118 | 74HCT165DB    |
| "74AUP1T58GW,125"  | 935280466125 | 74AUP1T58GW   |
| BAT54GWJ           | 934070364118 | BAT54GW       |
| PDTB143ETR         | 934068347215 | PDTB143ET     |
| CBT3257APW,118     | 935275892118 | CBT3257APW    |
| IP4220CZ6,125      | 934058429125 | IP4220CZ6     |
| "74HCT245PW,112"   | 935165230112 | 74HCT245PW    |
| PDTA143TT,215      | 934057525215 | PDTA143TT     |
| BZX585-B13,135     | 934055874135 | BZX585-B13    |

|                    |              |                  |
|--------------------|--------------|------------------|
| PDTC144EU,135      | 934044100135 | PDTC144EU        |
| BZT52H-C24,115     | 934059412115 | BZT52H-C24       |
| PESD24VL2BT,215    | 934058867215 | PESD24VL2BT      |
| BAL99,215          | 933986070215 | BAL99            |
| PESD5V0HS-SFYL     | 934069618315 | PESD5V0HS-SF     |
| BUK9Y30-75B,115    | 934058726115 | BUK9Y30-75B      |
| BC56-16PA,115      | 934065811115 | BC56-16PA        |
| "74AHC08PW,118"    | 935262679118 | 74AHC08PW        |
| 74LVC1G00GF,132    | 935282402132 | 74LVC1G00GF      |
| BAS21AVD,165       | 934059099165 | BAS21AVD         |
| PEMX1,115          | 934056704115 | PEMX1            |
| 74AUP1G157GXZ      | 935307358147 | 74AUP1G157GX     |
| 74ALVCH162245DGG:1 | 935210840118 | 74ALVCH162245DGG |
| PBSS4230PANP,115   | 934066885115 | PBSS4230PANP     |
| PMEG3010CEJ,115    | 934059509115 | PMEG3010CEJ      |
| 74LVC2G06GW-Q100H  | 935299305125 | 74LVC2G06GW-Q100 |
| 74HC595BQ-Q100,115 | 935298873115 | 74HC595BQ-Q100   |
| 74LVC11BQ,115      | 935275339115 | 74LVC11BQ        |
| 74HCT14D-Q100,118  | 935298444118 | 74HCT14D-Q100    |
| TDZ13J,115         | 934065787115 | TDZ13J           |
| PMEG6010AESBYL     | 934068757315 | PMEG6010AESB     |
| "74AHC00PW,118"    | 935262687118 | 74AHC00PW        |
| PUMX1,115          | 934034210115 | PUMX1            |
| PMEG45T15EPDZ      | 934069546139 | PMEG45T15EPD     |
| BCP56-16,135       | 933917260135 | BCP56-16         |
| "74LV04PW,112"     | 935174210112 | 74LV04PW         |
| PMEG100V080ELPDZ   | 934069521146 | PMEG100V080ELPD  |
| PSMN4R3-100PS,127  | 934066115127 | PSMN4R3-100PS    |
| PMSTA55,115        | 934042540115 | PMSTA55          |
| PMEG4010CPA,115    | 934064348115 | PMEG4010CPA      |
| 74HC139D,653       | 933713500653 | 74HC139D         |
| BZT52-C24X         | 934071135115 | BZT52-C24        |
| 74HC191DB,112      | 935188600112 | 74HC191DB        |
| 74HC02PW/C5J       | 935690545118 | 74HC02PW/C5      |
| PMPB20XNEAX        | 934069561115 | PMPB20XNEA       |
| "74HC1G86GW,125"   | 935245790125 | 74HC1G86GW       |
| 74HCT174D,653      | 933715050653 | 74HCT174D        |
| BZX79-C33,113      | 933117910113 | BZX79-C33        |
| PBSS4330PA,115     | 934064272115 | PBSS4330PA       |
| PSMN017-30PL,127   | 934066818127 | PSMN017-30PL     |
| PUSB3FA1Z          | 934660525471 | PUSB3FA1         |
| "74HC21PW,112"     | 935290399112 | 74HC21PW         |
| BAS40-06,215       | 934034550215 | BAS40-06         |
| PBSS4041NX,115     | 934063404115 | PBSS4041NX       |
| 74LVC8T595PWJ      | 935309144118 | 74LVC8T595PW     |
| BAS40-07,215       | 934051550215 | BAS40-07         |

|                      |              |                 |
|----------------------|--------------|-----------------|
| BC856W,115           | 934021750115 | BC856W          |
| "74HCT238D,652"      | 933715120652 | 74HCT238D       |
| "74AUP1T34GS,132"    | 935292876132 | 74AUP1T34GS     |
| 74LV123BQ,115        | 935284317115 | 74LV123BQ       |
| "74HCT4020D,652"     | 933715250652 | 74HCT4020D      |
| BZX84J-B47,115       | 934060964115 | BZX84J-B47      |
| 1PS70SB10,115        | 934054917115 | 1PS70SB10       |
| BZV90-C8V2,115       | 934014740115 | BZV90-C8V2      |
| 74HC245BQ,115        | 935278645115 | 74HC245BQ       |
| PSMN7R6-100BSEJ      | 934067543118 | PSMN7R6-100BSE  |
| RB521S30,115         | 934063955115 | RB521S30        |
| BZX585-C36,115       | 934057429115 | BZX585-C36      |
| "74LVC1G34GW,125"    | 935280576125 | 74LVC1G34GW     |
| BAS40-04,215         | 933661850215 | BAS40-04        |
| 74LVT245DB,112       | 935155220112 | 74LVT245DB      |
| "74HCT85D,652"       | 933715430652 | 74HCT85D        |
| PMEG4030ETP,115      | 934065471115 | PMEG4030ETP     |
| "74AHC1G14GV,125"    | 935271665125 | 74AHC1G14GV     |
| 74HC373PW,118        | 935165240118 | 74HC373PW       |
| BZX84-A5V1,215       | 934013620215 | BZX84-A5V1      |
| 74AXP1G57GXZ         | 935307074147 | 74AXP1G57GX     |
| HEF4520BT,652        | 933373250652 | HEF4520BT       |
| BSS138PW,115         | 934064987115 | BSS138PW        |
| BZX84-B68,215        | 933770540215 | BZX84-B68       |
| BCV72,215            | 933495340215 | BCV72           |
| "74HCT132PW-Q100,11" | 935298741118 | 74HCT132PW-Q100 |
| 74AHC00BQ-Q100X      | 935300609115 | 74AHC00BQ-Q100  |
| BUK7Y12-100EX        | 934067427115 | BUK7Y12-100E    |
| BUK9640-100A,118     | 934056025118 | BUK9640-100A    |
| 74AHC1G4214GWH       | 935307182125 | 74AHC1G4214GW   |
| HEF4030BT-Q100J      | 935302271118 | HEF4030BT-Q100  |
| BZV85-C51,133        | 933500820133 | BZV85-C51       |
| HEF4093BT,653        | 933373130653 | HEF4093BT       |
| 74AHCT595D,118       | 935265559118 | 74AHCT595D      |
| BZV85-C47,113        | 933500810113 | BZV85-C47       |
| 74LV595D,118         | 935181580118 | 74LV595D        |
| HEF4049BT,653        | 933372920653 | HEF4049BT       |
| 1PS302,115           | 934033600115 | 1PS302          |
| PMXB43UNEZ           | 934067147147 | PMXB43UNE       |
| 74HC4053D,653        | 933714840653 | 74HC4053D       |
| 74AUP2G07GXZ         | 935307096147 | 74AUP2G07GX     |
| PMEG2020EJ,115       | 934058256115 | PMEG2020EJ      |
| 74ALVC16244DGG,118   | 935251800118 | 74ALVC16244DGG  |
| "74HCT221D,112"      | 933715110112 | 74HCT221D       |
| PESD2CAN/HIR         | 934660124215 | PESD2CAN/HI     |
| BZT52-B6V2J          | 934071154118 | BZT52-B6V2      |

|                     |              |                   |
|---------------------|--------------|-------------------|
| "74LVC1G06GX,125"   | 935298376125 | 74LVC1G06GX       |
| BZX84J-B56,115      | 934060968115 | BZX84J-B56        |
| PMEG3020EJ,115      | 934058652115 | PMEG3020EJ        |
| 74AHCT139PW,118     | 935263568118 | 74AHCT139PW       |
| 74HCT4053PW,118     | 935188480118 | 74HCT4053PW       |
| PESD24VS5UD,115     | 934058436115 | PESD24VS5UD       |
| PSMN2R0-30YLE,115   | 934066896115 | PSMN2R0-30YLE     |
| 74CBTLV3253PW,118   | 935289999118 | 74CBTLV3253PW     |
| 74HC160D,653        | 933714510653 | 74HC160D          |
| 74LVC2244ABQ,115    | 935273000115 | 74LVC2244ABQ      |
| PMCM4401VPEZ        | 934068874084 | PMCM4401VPE       |
| PESD5V0G1BL/XMYL    | 934660597315 | PESD5V0G1BL/XM    |
| "74HCT4514D,652"    | 933715690652 | 74HCT4514D        |
| BUK7Y6R0-60EX       | 934067437115 | BUK7Y6R0-60E      |
| 74AHC245PW,118      | 935262005118 | 74AHC245PW        |
| PDTC114EU,115       | 934044140115 | PDTC114EU         |
| 74LVC02ABQ,115      | 935273685115 | 74LVC02ABQ        |
| "74AHC245PW,112"    | 935262005112 | 74AHC245PW        |
| "74HC14PW-Q100,118" | 935298442118 | 74HC14PW-Q100     |
| 74HC1G14GW-Q100H    | 935299224125 | 74HC1G14GW-Q100   |
| PESD3V6Z1BCSFYL     | 934660622315 | PESD3V6Z1BCSF     |
| 74LVC86ADB,118      | 935250100118 | 74LVC86ADB        |
| 74HC4094DB,118      | 935187520118 | 74HC4094DB        |
| BZX585-C12,135      | 934055853135 | BZX585-C12        |
| BZV55-B36,115       | 933931820115 | BZV55-B36         |
| "HEF4053BT,652"     | 933372960652 | HEF4053BT         |
| BUK7Y1R4-40HX       | 934660368115 | BUK7Y1R4-40H      |
| BZV85-C4V7,133      | 933659380133 | BZV85-C4V7        |
| PMEG4020EP,115      | 934061483115 | PMEG4020EP        |
| BZX79-B15,143       | 933166910143 | BZX79-B15         |
| 74LVC2G08DC,125     | 935274766125 | 74LVC2G08DC       |
| 74HCT32BQ,115       | 935273731115 | 74HCT32BQ         |
| PMEG2020CPA,115     | 934064346115 | PMEG2020CPA       |
| 74LVC16244ADGG,118  | 935235150118 | 74LVC16244ADGG    |
| 74AHCT157PW,118     | 935264001118 | 74AHCT157PW       |
| PMV130ENEAR         | 934067623215 | PMV130ENEA        |
| PESD5V0L2UU,115     | 934062747115 | PESD5V0L2UU       |
| "74LVC1G80GW,125"   | 935268676125 | 74LVC1G80GW       |
| PSMN045-80YS,115    | 934064149115 | PSMN045-80YS      |
| 74LVC1G123DC-Q100H  | 935302106125 | 74LVC1G123DC-Q100 |
| 74LVC125AD,118      | 935231700118 | 74LVC125AD        |
| 74CBTLV3125BQ,115   | 935289334115 | 74CBTLV3125BQ     |
| "74LVC2G66GT,115"   | 935280087115 | 74LVC2G66GT       |
| "74HCT1G04GV,125"   | 935271885125 | 74HCT1G04GV       |
| BUK9M9R5-40HX       | 934660796115 | BUK9M9R5-40H      |
| BZX84-C4V3,215      | 933516980215 | BZX84-C4V3        |

|                    |              |                   |
|--------------------|--------------|-------------------|
| PDTC124ET,215      | 934031020215 | PDTC124ET         |
| 74HC4067D,653      | 933715660653 | 74HC4067D         |
| 74AHC125D,118      | 935262762118 | 74AHC125D         |
| PDZ18BGWX          | 934071054115 | PDZ18BGW          |
| BUK963R3-60E,118   | 934066651118 | BUK963R3-60E      |
| "74HCT2G14GW,125"  | 935281018125 | 74HCT2G14GW       |
| BC846B,235         | 933589560235 | BC846B            |
| PDTC124EU,115      | 934044150115 | PDTC124EU         |
| HEF4013BT,653      | 933372660653 | HEF4013BT         |
| 74LVC126AD,118     | 935241100118 | 74LVC126AD        |
| PMSTA56,115        | 934042270115 | PMSTA56           |
| PESD3V3U1UB,115    | 934062952115 | PESD3V3U1UB       |
| PMDT290UNE,115     | 934065732115 | PMDT290UNE        |
| PDTA123TM,315      | 934059929315 | PDTA123TM         |
| BC850BW,115        | 934022040115 | BC850BW           |
| PMBT2907A,235      | 933821800235 | PMBT2907A         |
| "74AHCT1G04GW,125" | 935262752125 | 74AHCT1G04GW      |
| "74VHC14PW,118"    | 935289534118 | 74VHC14PW         |
| 74HC4514D,653      | 933715670653 | 74HC4514D         |
| "74LVT2245PW,112"  | 935211430112 | 74LVT2245PW       |
| 74AHC139D,118      | 935263565118 | 74AHC139D         |
| BZX84-A2V4,215     | 933959650215 | BZX84-A2V4        |
| "74HCT541PW,112"   | 935187550112 | 74HCT541PW        |
| PTVS15VU1UPAZ      | 934068082147 | PTVS15VU1UPA      |
| BZX79-C3V6,133     | 933117680133 | BZX79-C3V6        |
| "74HC137D,652"     | 933757070652 | 74HC137D          |
| "74AHCT1G08GW,125" | 935262754125 | 74AHCT1G08GW      |
| "74LVCH1T45GW,125" | 935284754125 | 74LVCH1T45GW      |
| 74LVC2G86DC,125    | 935278826125 | 74LVC2G86DC       |
| PBSS302PX,115      | 934059015115 | PBSS302PX         |
| PMEG1030EH,115     | 934059274115 | PMEG1030EH        |
| 74LVCV2G66DC,125   | 935274432125 | 74LVCV2G66DC      |
| PMBTA92,215        | 933776100215 | PMBTA92           |
| 74LVC157ADB,118    | 935260899118 | 74LVC157ADB       |
| PBSS4360XX         | 934660028115 | PBSS4360X         |
| 74AXP1G58GXZ       | 935307129147 | 74AXP1G58GX       |
| 74LVC1G126GW-Q100H | 935299659125 | 74LVC1G126GW-Q100 |
| PESD5V0S1ULD,315   | 934064564315 | PESD5V0S1ULD      |
| PESD3V3S4UF,115    | 934061196115 | PESD3V3S4UF       |
| PMCM6501UPEZ       | 934070324023 | PMCM6501UPE       |
| BAW101,215         | 934057613215 | BAW101            |
| 74LVC1G04GM,115    | 935277172115 | 74LVC1G04GM       |
| 74AHC1GU04GV-Q100H | 935299883125 | 74AHC1GU04GV-Q100 |
| 74HC175D,652       | 933714580652 | 74HC175D          |
| "74LV4066D,112"    | 935088370112 | 74LV4066D         |
| PBHV9115X,115      | 934061422115 | PBHV9115X         |

|                    |              |                  |
|--------------------|--------------|------------------|
| 74HC85D,653        | 933714950653 | 74HC85D          |
| PMEG3010EB,115     | 934060116115 | PMEG3010EB       |
| BZX585-B39,115     | 934057413115 | BZX585-B39       |
| BZV55-C18,135      | 933699580135 | BZV55-C18        |
| PMEG4002EB,115     | 934059739115 | PMEG4002EB       |
| 74HC4851PW,118     | 935282084118 | 74HC4851PW       |
| 74AUP1G885DC,125   | 935280765125 | 74AUP1G885DC     |
| 74HCT154BQ,118     | 935275417118 | 74HCT154BQ       |
| PTVS15VP1UTP,115   | 934065543115 | PTVS15VP1UTP     |
| MMBT3906,215       | 933864370215 | MMBT3906         |
| PTVS12VZ1USKYL     | 934069946315 | PTVS12VZ1USK     |
| 74AUP1G74GM,125    | 935281287125 | 74AUP1G74GM      |
| BZV90-C9V1,115     | 934014750115 | BZV90-C9V1       |
| PSMN3R0-30MLC,115  | 934066937115 | PSMN3R0-30MLC    |
| 74HC540DB,118      | 935190130118 | 74HC540DB        |
| 74HC123BQ,115      | 935282453115 | 74HC123BQ        |
| BUK9214-30A,118    | 934057076118 | BUK9214-30A      |
| 74AXP1G06GXH       | 935303202125 | 74AXP1G06GX      |
| BC55PA,115         | 934065742115 | BC55PA           |
| 74LVC273PW-Q100J   | 935302462118 | 74LVC273PW-Q100  |
| 74HC194D,653       | 933714090653 | 74HC194D         |
| 74LVC16240ADGG,118 | 935235110118 | 74LVC16240ADGG   |
| "74AHCT1G02GV,125" | 935271651125 | 74AHCT1G02GV     |
| 74LVC125AD,112     | 935231700112 | 74LVC125AD       |
| PRTR5V0U2X,215     | 934058998215 | PRTR5V0U2X       |
| 2PC4617QM,315      | 934057152315 | 2PC4617QM        |
| BCX53-10,135       | 933663060135 | BCX53-10         |
| 2PD601ARL,215      | 934062306215 | 2PD601ARL        |
| 74AHC2G125DC,125   | 935275128125 | 74AHC2G125DC     |
| BZT52-C47X         | 934071123115 | BZT52-C47        |
| 74HCT4052BQ-Q100,1 | 935298846115 | 74HCT4052BQ-Q100 |
| "74VHCT126PW,118"  | 935289631118 | 74VHCT126PW      |
| PDTC144WT,215      | 934054702215 | PDTC144WT        |
| PZU15BA,115        | 934062346115 | PZU15BA          |
| PBSS4032SPN,115    | 934063417115 | PBSS4032SPN      |
| "74LVC86APW,118"   | 935250110118 | 74LVC86APW       |
| PTVS28VS1UR,115    | 934061362115 | PTVS28VS1UR      |
| 2PD2150,115        | 934059292115 | 2PD2150          |
| PSMN9R1-30YL,115   | 934064948115 | PSMN9R1-30YL     |
| PDTC144EU,115      | 934044100115 | PDTC144EU        |
| BAW56,235          | 933098990235 | BAW56            |
| "74HCT173D,652"    | 933715040652 | 74HCT173D        |
| PUMD16,115         | 934057892115 | PUMD16           |
| BCW61D,215         | 933324150215 | BCW61D           |
| PDTC123YT,215      | 934058194215 | PDTC123YT        |
| PDZ20BGWJ          | 934071055118 | PDZ20BGW         |



|                    |              |                 |
|--------------------|--------------|-----------------|
| "74VHC125PW,118"   | 935289506118 | 74VHC125PW      |
| 74CBTLV3244PW,118  | 935293821118 | 74CBTLV3244PW   |
| PDZ16BGWX          | 934071053115 | PDZ16BGW        |
| PESD3V3L1UL,315    | 934062988315 | PESD3V3L1UL     |
| PTVS24VP1UP,115    | 934064175115 | PTVS24VP1UP     |
| BUK9Y104-100B,115  | 934063324115 | BUK9Y104-100B   |
| 74HC112D,653       | 933714490653 | 74HC112D        |
| 74HC541D,653       | 933715500653 | 74HC541D        |
| PBSS4240T,215      | 934056606215 | PBSS4240T       |
| 74LVC257APW,118    | 935260680118 | 74LVC257APW     |
| PDZ5.1B,115        | 934054852115 | PDZ5.1B         |
| PTVS22VS1UR,115    | 934061358115 | PTVS22VS1UR     |
| BZX84J-B3V6,115    | 934060961115 | BZX84J-B3V6     |
| 74HCT597DB,118     | 935190180118 | 74HCT597DB      |
| PBSS5350T,215      | 934056605215 | PBSS5350T       |
| BZV49-C3V9,115     | 933605860115 | BZV49-C3V9      |
| "74LVC1G17GW,125"  | 935270079125 | 74LVC1G17GW     |
| 74HC154PW,118      | 935182580118 | 74HC154PW       |
| 74HC27BQ,115       | 935283678115 | 74HC27BQ        |
| 74AXP1G02GXH       | 935304053125 | 74AXP1G02GX     |
| 2N7002BKVL         | 934063609235 | 2N7002BK        |
| 74HC238D,653       | 933714640653 | 74HC238D        |
| BC53-10PA,115      | 934065822115 | BC53-10PA       |
| 74LV4066D,118      | 935088370118 | 74LV4066D       |
| 74LVC4066PW,112    | 935273718112 | 74LVC4066PW     |
| "74ABT244PW,112"   | 935176420112 | 74ABT244PW      |
| PESD24VU1UT,215    | 934059106215 | PESD24VU1UT     |
| HEF4555BT,653      | 933373310653 | HEF4555BT       |
| BUK9M23-80EX       | 934070061115 | BUK9M23-80E     |
| PDTC143ZT,235      | 934054700235 | PDTC143ZT       |
| PESD5V0S1BLD,315   | 934064563315 | PESD5V0S1BLD    |
| PMEG2010BELD,315   | 934066836315 | PMEG2010BELD    |
| PESD15VL1BA,115    | 934058423115 | PESD15VL1BA     |
| 74AHC595BQ-Q100,11 | 935298631115 | 74AHC595BQ-Q100 |
| PBSS5220PAPSX      | 934069682115 | PBSS5220PAPS    |
| BCX51-16,135       | 933674710135 | BCX51-16        |
| PBSS5320T,215      | 934056855215 | PBSS5320T       |
| PSMN4R6-60PS,127   | 934064296127 | PSMN4R6-60PS    |
| PZU13B3,115        | 934059852115 | PZU13B3         |
| PTVS15VZ1USKYL     | 934069212315 | PTVS15VZ1USK    |
| HEF4049BT-Q100J    | 935300106118 | HEF4049BT-Q100  |
| BAS70,235          | 934020790235 | BAS70           |
| BCP68-25,135       | 933969370135 | BCP68-25        |
| NZX7V5C,133        | 934063534133 | NZX7V5C         |
| 74HC04D,652        | 933714260652 | 74HC04D         |
| BZX884-C12,315     | 934057225315 | BZX884-C12      |

|                      |              |                 |
|----------------------|--------------|-----------------|
| NCR405UX             | 934067777115 | NCR405U         |
| "74LVC1G06GW,125"    | 935266680125 | 74LVC1G06GW     |
| PESD5V0X1BT,215      | 934062182215 | PESD5V0X1BT     |
| BUK7675-55A,118      | 934056270118 | BUK7675-55A     |
| BZV55-B24,115        | 933931780115 | BZV55-B24       |
| TL431FDT,215         | 935293274215 | TL431FDT        |
| "74LVC1G34GV,125"    | 935280575125 | 74LVC1G34GV     |
| 74HCT153PW,118       | 935189540118 | 74HCT153PW      |
| "74LVC1G32GW,125"    | 935268381125 | 74LVC1G32GW     |
| 74LVC2G07GM,115      | 935277169115 | 74LVC2G07GM     |
| 74HC132PW-Q100,118   | 935298738118 | 74HC132PW-Q100  |
| PSMN4R2-30MLDX       | 934067971115 | PSMN4R2-30MLD   |
| PXT4401,115          | 933890540115 | PXT4401         |
| PEMD16,115           | 934058921115 | PEMD16          |
| PZU8.2B2A,115        | 934062799115 | PZU8.2B2A       |
| PESD5Z5.0,115        | 934061265115 | PESD5Z5.0       |
| "74HCT4066D,112"     | 933714460112 | 74HCT4066D      |
| PHDMI2AB4Z           | 934660001471 | PHDMI2AB4       |
| PBSS4041NT,215       | 934062763215 | PBSS4041NT      |
| 74LVCH8T245BQ,118    | 935290148118 | 74LVCH8T245BQ   |
| 74HCT4002D,118       | 933714210118 | 74HCT4002D      |
| 74LVC244ABQ,115      | 935272505115 | 74LVC244ABQ     |
| 74HC573DB,112        | 935175080112 | 74HC573DB       |
| BZT52-C39J           | 934071121118 | BZT52-C39       |
| 74LVC2G00DP,125      | 935273581125 | 74LVC2G00DP     |
| "74AUP2G14GS,132"    | 935292887132 | 74AUP2G14GS     |
| "74HC1G08GV-Q100,12" | 935298484125 | 74HC1G08GV-Q100 |
| PESD5V0L4UF,115      | 934061198115 | PESD5V0L4UF     |
| PESD5V0U1UB,115      | 934062186115 | PESD5V0U1UB     |
| PMCXB900UEZ          | 934067143147 | PMCXB900UE      |
| 74LVCH244APW,118     | 935210350118 | 74LVCH244APW    |
| PMEG10020AELRX       | 934068675115 | PMEG10020AELR   |
| BZV55-C2V7,115       | 933699380115 | BZV55-C2V7      |
| "74HCU04PW,118"      | 935187580118 | 74HCU04PW       |
| HEF4094BT,653        | 933406660653 | HEF4094BT       |
| "74ALVC125D,112"     | 935269718112 | 74ALVC125D      |
| 74HC74BQ,115         | 935273672115 | 74HC74BQ        |
| "74LV04PW,118"       | 935174210118 | 74LV04PW        |
| PMEG2020CPASX        | 934068148115 | PMEG2020CPAS    |
| PSMNR90-40YLHX       | 934660721115 | PSMNR90-40YLH   |
| BC847CM,315          | 934057151315 | BC847CM         |
| PMBT3904,235         | 933776000235 | PMBT3904        |
| "HEF4052BT,652"      | 933372950652 | HEF4052BT       |
| BZX84J-B3V9,115      | 934060962115 | BZX84J-B3V9     |
| BZX84J-B16,115       | 934060942115 | BZX84J-B16      |
| BAT54VV,115          | 934058224115 | BAT54VV         |

|                    |              |                |
|--------------------|--------------|----------------|
| 1PS79SB10,115      | 934054914115 | 1PS79SB10      |
| 74LVC16245ADL,118  | 935234900118 | 74LVC16245ADL  |
| PMDXB550UNEZ       | 934069326147 | PMDXB550UNE    |
| BAS21VD,165        | 934057662165 | BAS21VD        |
| BZX585-C24,115     | 934057425115 | BZX585-C24     |
| "74HC4511D,652"    | 933714880652 | 74HC4511D      |
| BZX84J-C2V7,115    | 934060995115 | BZX84J-C2V7    |
| BZX84J-C8V2,115    | 934061021115 | BZX84J-C8V2    |
| "HEF4046BT,652"    | 933372900652 | HEF4046BT      |
| BZX84-C4V3,235     | 933516980235 | BZX84-C4V3     |
| PMBTA06,235        | 933776020235 | PMBTA06        |
| BSH105,235         | 934054715235 | BSH105         |
| HEF4052BT-Q100,118 | 935298522118 | HEF4052BT-Q100 |
| PESD3V3L1BA,115    | 934058419115 | PESD3V3L1BA    |
| PBSS8110Y,115      | 934057982115 | PBSS8110Y      |
| "74AUP1G240GX,125" | 935298372125 | 74AUP1G240GX   |
| BZT52H-B39,115     | 934064809115 | BZT52H-B39     |
| BC856B,215         | 933589730215 | BC856B         |
| "74HC10PW,118"     | 935186290118 | 74HC10PW       |
| 74HC7541D,118      | 933967940118 | 74HC7541D      |
| BAV23,215          | 933720770215 | BAV23          |
| BAS20,215          | 933502030215 | BAS20          |
| PMPB25ENEX         | 934660353115 | PMPB25ENE      |
| 74AUP2G08DC,125    | 935280711125 | 74AUP2G08DC    |
| BC849B,215         | 933589660215 | BC849B         |
| "74LVC04APW,118"   | 935242420118 | 74LVC04APW     |
| PTVS20VS1UR/8X     | 934660638115 | PTVS20VS1UR/8  |
| 74LVC162245ADL,118 | 935237690118 | 74LVC162245ADL |
| 74LVCH1T45GM,115   | 935284755115 | 74LVCH1T45GM   |
| PMGD280UN,115      | 934057726115 | PMGD280UN      |
| BZX84-A4V3,215     | 934028460215 | BZX84-A4V3     |
| 74HCT238DB,118     | 935189260118 | 74HCT238DB     |
| PBSS5120T,215      | 934057987215 | PBSS5120T      |
| BC847BPN,165       | 934042530165 | BC847BPN       |
| PMN48XP,115        | 934064772115 | PMN48XP        |
| BAT120S,115        | 934051360115 | BAT120S        |
| PMN30XPX           | 934070095115 | PMN30XP        |
| "74HC74PW,112"     | 935175130112 | 74HC74PW       |
| "74HC132D,652"     | 933714130652 | 74HC132D       |
| 74LVC07ABQ,115     | 935273332115 | 74LVC07ABQ     |
| BAT54CV,115        | 934058073115 | BAT54CV        |
| ON5464J            | 934067514118 | ON5464         |
| "74LVC273PW,112"   | 935210650112 | 74LVC273PW     |
| PSMN016-100PS,127  | 934064505127 | PSMN016-100PS  |
| 74LV1T08GXH        | 935690117125 | 74LV1T08GX     |
| "74LVC1G80GM,132"  | 935277201132 | 74LVC1G80GM    |

|                      |              |                  |
|----------------------|--------------|------------------|
| PDTA114TU,115        | 934044040115 | PDTA114TU        |
| PMPB10ENZ            | 934660554184 | PMPB10EN         |
| "HEF40244BT,652"     | 933638680652 | HEF40244BT       |
| BUK7M6R0-40HX        | 934660784115 | BUK7M6R0-40H     |
| PSMN5R2-60YLX        | 934069894115 | PSMN5R2-60YL     |
| PMEG6002EB,115       | 934060004115 | PMEG6002EB       |
| BC856S,115           | 934055680115 | BC856S           |
| BZX84J-C15,115       | 934060986115 | BZX84J-C15       |
| 74HC158D,653         | 933713760653 | 74HC158D         |
| BAS35,215            | 933723200215 | BAS35            |
| 74CBTLV3861PW,118    | 935294092118 | 74CBTLV3861PW    |
| 74LV04ATPWJ          | 935338675118 | 74LV04ATPW       |
| 74LV123D,112         | 935210250112 | 74LV123D         |
| "74HCT164PW,112"     | 935188330112 | 74HCT164PW       |
| 74AHC08D,118         | 935262678118 | 74AHC08D         |
| BZX384-C12,115       | 934057642115 | BZX384-C12       |
| PDTC123EMB,315       | 934065948315 | PDTC123EMB       |
| BUK6D23-40EX         | 934660304115 | BUK6D23-40E      |
| 74AUP1T34GF,132      | 935281321132 | 74AUP1T34GF      |
| 74AHCT573D,118       | 935263073118 | 74AHCT573D       |
| PESD3USB3SZ          | 934069685087 | PESD3USB3S       |
| BZX84-B5V1,235       | 933643800235 | BZX84-B5V1       |
| 74LVC1G97GXZ         | 935338983147 | 74LVC1G97GX      |
| PESD3V3S2UAT,215     | 934058062215 | PESD3V3S2UAT     |
| 74HC595D-Q100,118    | 935298874118 | 74HC595D-Q100    |
| BZB784-C15,115       | 934056315115 | BZB784-C15       |
| BC807RAZ             | 934070167147 | BC807RA          |
| "74HCT164PW,118"     | 935188330118 | 74HCT164PW       |
| 74HC161D,653         | 933714520653 | 74HC161D         |
| BZX585-C5V1,135      | 934055844135 | BZX585-C5V1      |
| 74AUP1GU04GF,132     | 935281125132 | 74AUP1GU04GF     |
| "74HC1G126GW,125"    | 935245710125 | 74HC1G126GW      |
| BZX84-B16,215        | 933770400215 | BZX84-B16        |
| PSMN018-80YS,115     | 934064152115 | PSMN018-80YS     |
| BC858B,215           | 933589790215 | BC858B           |
| PMPB20XPEAX          | 934070927115 | PMPB20XPEA       |
| BUK7Y12-40EX         | 934067433115 | BUK7Y12-40E      |
| "74LVC2G34GW-Q100,1" | 935299052125 | 74LVC2G34GW-Q100 |
| 74LV540APWJ          | 935309238118 | 74LV540APW       |
| PDZ12B,115           | 934054861115 | PDZ12B           |
| PHPT60603PYX         | 934067879115 | PHPT60603PY      |
| BZT52-B18X           | 934071177115 | BZT52-B18        |
| BZX79-C4V3,133       | 933117700133 | BZX79-C4V3       |
| 74LVC4245APW,118     | 935260751118 | 74LVC4245APW     |
| PDTC115EM,315        | 934057173315 | PDTC115EM        |
| PDZ5.6BGWJ           | 934071089118 | PDZ5.6BGW        |

|                    |              |                    |
|--------------------|--------------|--------------------|
| "HEF4047BT,652"    | 933372910652 | HEF4047BT          |
| PUMH15,115         | 934057896115 | PUMH15             |
| 74HC32BQ-Q100,115  | 935298922115 | 74HC32BQ-Q100      |
| BZT52-C10J         | 934071125118 | BZT52-C10          |
| BUK7Y7R6-40EX      | 934067432115 | BUK7Y7R6-40E       |
| PMV65XP,215        | 934058736215 | PMV65XP            |
| PESD5V0U1UA,115    | 934062185115 | PESD5V0U1UA        |
| PTVS18VU1UPAZ      | 934068083147 | PTVS18VU1UPA       |
| BZT52H-C62,115     | 934059423115 | BZT52H-C62         |
| BC856BS,115        | 934063583115 | BC856BS            |
| BUK9Y4R4-40E,115   | 934067045115 | BUK9Y4R4-40E       |
| "74HCT86PW,112"    | 935185850112 | 74HCT86PW          |
| PDTA123JT,215      | 934055395215 | PDTA123JT          |
| 74AVC4T245PW,118   | 935284588118 | 74AVC4T245PW       |
| BZT52-C3V3X        | 934071103115 | BZT52-C3V3         |
| 74LVTH244ADB,118   | 935262070118 | 74LVTH244ADB       |
| BZX585-B13,115     | 934055874115 | BZX585-B13         |
| PMP5501V,115       | 934060011115 | PMP5501V           |
| 74ALVC04BQ,115     | 935273686115 | 74ALVC04BQ         |
| 74HCT240BQ,115     | 935283684115 | 74HCT240BQ         |
| "74LVT245PW,112"   | 935175550112 | 74LVT245PW         |
| BC817DPN,125       | 934057320125 | BC817DPN           |
| 74LVC1G157GF,132   | 935282413132 | 74LVC1G157GF       |
| PUMH2,115          | 934055787115 | PUMH2              |
| 74AXP1G00GXH       | 935304081125 | 74AXP1G00GX        |
| BCM847DS,115       | 934059058115 | BCM847DS           |
| 74AUP1T86GXH       | 935690103125 | 74AUP1T86GX        |
| PBSS4032NT,215     | 934062765215 | PBSS4032NT         |
| "74LVC2245APW,112" | 935251310112 | 74LVC2245APW       |
| 74LVCH8T245PW-Q10J | 935301102118 | 74LVCH8T245PW-Q100 |
| PHP79NQ08LT,127    | 934059363127 | PHP79NQ08LT        |
| BUK9226-75A,118    | 934056478118 | BUK9226-75A        |
| BC859B,215         | 933589820215 | BC859B             |
| 74AVC16373DGG,118  | 935265483118 | 74AVC16373DGG      |
| "74AHC1G08GV,125"  | 935271658125 | 74AHC1G08GV        |
| 74HC74DB,118       | 935175170118 | 74HC74DB           |
| "74HC1G32GW,125"   | 935245750125 | 74HC1G32GW         |
| 74AVC1T1022DPJ     | 935305831118 | 74AVC1T1022DP      |
| PMEG3015EH,115     | 934059277115 | PMEG3015EH         |
| "74AHC1G66GW,125"  | 935268459125 | 74AHC1G66GW        |
| 74HC125DB,118      | 935166870118 | 74HC125DB          |
| "74HCT1G86GW,125"  | 935245780125 | 74HCT1G86GW        |
| PMEG60T30ELRX      | 934070787115 | PMEG60T30ELR       |
| BZX84-B18,235      | 933770410235 | BZX84-B18          |
| BAS21,215          | 933502040215 | BAS21              |
| 74AVC16245DGG,118  | 935264444118 | 74AVC16245DGG      |

|                    |              |                   |
|--------------------|--------------|-------------------|
| BZV85-C6V2,113     | 933500600113 | BZV85-C6V2        |
| 74AUP2G14GM,115    | 935279988115 | 74AUP2G14GM       |
| BUK9215-55A,118    | 934056699118 | BUK9215-55A       |
| 74ABT244DB,112     | 935064900112 | 74ABT244DB        |
| 74AUP2G125GF,115   | 935290549115 | 74AUP2G125GF      |
| PMDT290UCEH        | 934065733125 | PMDT290UCE        |
| PRMH9Z             | 934070175147 | PRMH9             |
| NX7002BKSX         | 934068619115 | NX7002BKS         |
| PMEG3020EGWJ       | 934070367118 | PMEG3020EGW       |
| 74HCT594DB,118     | 935280939118 | 74HCT594DB        |
| BCP53-10TF         | 934070115135 | BCP53-10T         |
| BZT52-C16J         | 934071131118 | BZT52-C16         |
| PMF170XP,115       | 934064763115 | PMF170XP          |
| 2N7002,215         | 934003470215 | 2N7002            |
| 74HCT4851BQ,115    | 935285732115 | 74HCT4851BQ       |
| 74AUP1G125GW-Q100H | 935300766125 | 74AUP1G125GW-Q100 |
| BCP53-10,135       | 933917340135 | BCP53-10          |
| 74AHC573BQ,115     | 935280555115 | 74AHC573BQ        |
| BCM847BV,315       | 934059429315 | BCM847BV          |
| BUK9M11-40EX       | 934070084115 | BUK9M11-40E       |
| PMEG3010EGWX       | 934070452115 | PMEG3010EGW       |
| PCMF1HDMI2SZ       | 934070092087 | PCMF1HDMI2S       |
| PUMH30,115         | 934059932115 | PUMH30            |
| PMV35EPER          | 934070454215 | PMV35EPE          |
| PDTC114TM,315      | 934057171315 | PDTC114TM         |
| BC807-25W,115      | 934024250115 | BC807-25W         |
| BZX884-B33,315     | 934057445315 | BZX884-B33        |
| BZX585-C6V8,115    | 934055847115 | BZX585-C6V8       |
| BAL74,215          | 934002810215 | BAL74             |
| PDZ18BGWJ          | 934071054118 | PDZ18BGW          |
| BZX79-B3V9,133     | 933471100133 | BZX79-B3V9        |
| 74LV1T86GWH        | 935690205125 | 74LV1T86GW        |
| 1PS70SB20,115      | 934055690115 | 1PS70SB20         |
| BSP126,115         | 934000540115 | BSP126            |
| PDZ33BGWJ          | 934071046118 | PDZ33BGW          |
| PSMN4R6-60BS,118   | 934066334118 | PSMN4R6-60BS      |
| 74AUP1G97UKAZ      | 935307346084 | 74AUP1G97UK       |
| 74LVC377PW,118     | 935210680118 | 74LVC377PW        |
| 74LVC2G125DP,125   | 935272175125 | 74LVC2G125DP      |
| 74HC257D,653       | 933713640653 | 74HC257D          |
| BUK9207-30B,118    | 934057609118 | BUK9207-30B       |
| PESD1FLEX,215      | 934061259215 | PESD1FLEX         |
| 74HC2G86DP,125     | 935271932125 | 74HC2G86DP        |
| BC857BV,115        | 934056711115 | BC857BV           |
| 1N4744A,133        | 933931700133 | 1N4744A           |
| 74AVCH2T45GF,115   | 935291498115 | 74AVCH2T45GF      |

|                  |              |                 |
|------------------|--------------|-----------------|
| PMPB29XNE,115    | 934066868115 | PMPB29XNE       |
| "74LVT04PW,118"  | 935209010118 | 74LVT04PW       |
| 74LVC373AD,118   | 935218630118 | 74LVC373AD      |
| 74LV4053DB,118   | 935174980118 | 74LV4053DB      |
| PTVS17VS1UR/8X   | 934660641115 | PTVS17VS1UR/8   |
| 1PS76SB70,115    | 934054923115 | 1PS76SB70       |
| PMFPB8032XP,115  | 934066583115 | PMFPB8032XP     |
| 74LVC2G07GV,125  | 935274164125 | 74LVC2G07GV     |
| 74LVC2G02GF,115  | 935291502115 | 74LVC2G02GF     |
| PBSS5540X,135    | 934057104135 | PBSS5540X       |
| PMEG100V100ELPDZ | 934069519146 | PMEG100V100ELPD |
| BCP55,115        | 933917210115 | BCP55           |
| BZT52H-B18,115   | 934064801115 | BZT52H-B18      |
| PMEG060V100EPDZ  | 934067907146 | PMEG060V100EPD  |
| 74HC4050PW,118   | 935187470118 | 74HC4050PW      |
| "74HCT4060D,652" | 933714020652 | 74HCT4060D      |
| PMV65UNER        | 934068853215 | PMV65UNE        |
| 74HC4351D,653    | 933771700653 | 74HC4351D       |
| 74LVC541ABQ,115  | 935274977115 | 74LVC541ABQ     |
| BAS16H,115       | 934058257115 | BAS16H          |
| BZX79-C5V1,143   | 933117720143 | BZX79-C5V1      |
| "74HCT74PW,118"  | 935175150118 | 74HCT74PW       |
| PDTA123JM,315    | 934057161315 | PDTA123JM       |
| PSMN1R2-25YLDX   | 934069909115 | PSMN1R2-25YLD   |
| "74LVC04APW,112" | 935242420112 | 74LVC04APW      |
| 74LVC157APW,118  | 935260900118 | 74LVC157APW     |
| PMV280ENEAR      | 934070697215 | PMV280ENEA      |
| 74ABT125D,623    | 935056850623 | 74ABT125D       |
| PBSS4130PAN,115  | 934066879115 | PBSS4130PAN     |
| BUK7K32-100EX    | 934067942115 | BUK7K32-100E    |
| PMEG6030EP,115   | 934061481115 | PMEG6030EP      |
| HEF4014BT,652    | 933372670652 | HEF4014BT       |
| BZT52H-C22,115   | 934059411115 | BZT52H-C22      |
| 2N7002P,235      | 934064132235 | 2N7002P         |
| PDTA123JU,115    | 934057533115 | PDTA123JU       |
| "74AHC132PW,118" | 935262991118 | 74AHC132PW      |
| BUK7Y2R0-40HX    | 934069304115 | BUK7Y2R0-40H    |
| 74HC259D,652     | 933714650652 | 74HC259D        |
| BAV170,215       | 934032160215 | BAV170          |
| PMEG2020EPK,315  | 934066737315 | PMEG2020EPK     |
| PBSS5220T,215    | 934057989215 | PBSS5220T       |
| BZT52-C9V1X      | 934071117115 | BZT52-C9V1      |
| 74AUP2G80DC,125  | 935280722125 | 74AUP2G80DC     |
| PMBD6050,215     | 933859220215 | PMBD6050        |
| PMV30XPEAR       | 934068709215 | PMV30XPEA       |
| BZV85-C18,113    | 933500710113 | BZV85-C18       |

|                    |              |                   |
|--------------------|--------------|-------------------|
| 74HC04PW,112       | 935174200112 | 74HC04PW          |
| PESD5V0L4UW,115    | 934057792115 | PESD5V0L4UW       |
| 74LVC1G332GV-Q100H | 935304365125 | 74LVC1G332GV-Q100 |
| PESD5V0S1UL,315    | 934059976315 | PESD5V0S1UL       |
| BAT74V,115         | 934056719115 | BAT74V            |
| "HEF4051BT,652"    | 933372940652 | HEF4051BT         |
| PMEG6002EBF        | 934060004135 | PMEG6002EB        |
| "74LVC3G17GT,115"  | 935278935115 | 74LVC3G17GT       |
| 74HC1G66GV-Q100H   | 935299992125 | 74HC1G66GV-Q100   |
| 74HC02D-Q100,118   | 935298721118 | 74HC02D-Q100      |
| "74LVC1G79GW,125"  | 935268675125 | 74LVC1G79GW       |
| BAT54W,115         | 934028880115 | BAT54W            |
| "74ALVC04PW,118"   | 935269714118 | 74ALVC04PW        |
| BZX84-C2V7,235     | 933516930235 | BZX84-C2V7        |
| 74HC4049D,653      | 933714800653 | 74HC4049D         |
| 74LVC2G04GM,115    | 935277161115 | 74LVC2G04GM       |
| 74AVC2T45DC-Q100H  | 935300361125 | 74AVC2T45DC-Q100  |
| "74HC253D,652"     | 933713860652 | 74HC253D          |
| BZX84-A4V7,215     | 934032230215 | BZX84-A4V7        |
| PMV20XNEAR         | 934068717215 | PMV20XNEA         |
| 74HC126D,653       | 933757030653 | 74HC126D          |
| BZX884-B15,315     | 934057227315 | BZX884-B15        |
| 74LVC245ABQ,115    | 935273595115 | 74LVC245ABQ       |
| PMBS3904,235       | 933972890235 | PMBS3904          |
| BAS17,215          | 933526230215 | BAS17             |
| "74AUP1G125GW,125" | 935279054125 | 74AUP1G125GW      |
| PMEG3020CEP,115    | 934063199115 | PMEG3020CEP       |
| BZX84J-C30,115     | 934060996115 | BZX84J-C30        |
| BC857W,115         | 934021830115 | BC857W            |
| 74LV164D,118       | 935067450118 | 74LV164D          |
| "74HCT154D,652"    | 933713830652 | 74HCT154D         |
| "74ABT04PW,112"    | 935207010112 | 74ABT04PW         |
| IP4252CZ16-8-TTL,1 | 934064753132 | IP4252CZ16-8-TTL  |
| PMBT2907AMYL       | 934660375315 | PMBT2907AM        |
| BZX384-B27,115     | 934057383115 | BZX384-B27        |
| 74LVC162373ADGG,11 | 935237720118 | 74LVC162373ADGG   |
| 74AHCT2G32DP,125   | 935274669125 | 74AHCT2G32DP      |
| 74HC00PW,112       | 935174110112 | 74HC00PW          |
| "74ALVC04D,112"    | 935269715112 | 74ALVC04D         |
| NX138AKR           | 934070096215 | NX138AK           |
| PDTC124XT,215      | 934057529215 | PDTC124XT         |
| PMBT2222AMBYL      | 934660373315 | PMBT2222AMB       |
| BFS20,215          | 933092111215 | BFS20             |
| 74ABT245PW,118     | 935176430118 | 74ABT245PW        |
| PBSS5350THR        | 934071078215 | PBSS5350TH        |
| BZV55-B75,115      | 933931900115 | BZV55-B75         |



|                      |              |                  |
|----------------------|--------------|------------------|
| BUK7M8R0-40EX        | 934070081115 | BUK7M8R0-40E     |
| BZX79-C6V2,133       | 933117740133 | BZX79-C6V2       |
| 74HCT4851BQ-Q100,1   | 935298464115 | 74HCT4851BQ-Q100 |
| 74AUP1G373GF,132     | 935281332132 | 74AUP1G373GF     |
| 74AHCT244PW,118      | 935261959118 | 74AHCT244PW      |
| "74HCT240PW,112"     | 935189570112 | 74HCT240PW       |
| PUMB4,115            | 934049940115 | PUMB4            |
| PZU3.3BA,115         | 934062471115 | PZU3.3BA         |
| BZT52-C51X           | 934071124115 | BZT52-C51        |
| BUK6D38-30EX         | 934660948115 | BUK6D38-30E      |
| PMEG2020AEA,115      | 934057933115 | PMEG2020AEA      |
| PUMD3,125            | 934050170125 | PUMD3            |
| BZX384-C47,115       | 934057656115 | BZX384-C47       |
| PDTA143XT,215        | 934055053215 | PDTA143XT        |
| 74AHC04D,118         | 935263040118 | 74AHC04D         |
| PMLL4148L,115        | 933930220115 | PMLL4148L        |
| BZX79-C6V8,113       | 933117750113 | BZX79-C6V8       |
| 74HC4316D,652        | 933757450652 | 74HC4316D        |
| 74HCT4066D,118       | 933714460118 | 74HCT4066D       |
| 74HCT374DB,118       | 935186920118 | 74HCT374DB       |
| PBHV9115T,215        | 934061417215 | PBHV9115T        |
| 74ALVC541D,118       | 935269734118 | 74ALVC541D       |
| 74AXP2G07GXZ         | 935307132147 | 74AXP2G07GX      |
| PMEG4030EP,115       | 934061484115 | PMEG4030EP       |
| BAS70,215            | 934020790215 | BAS70            |
| MMBZ27VAL,235        | 934061801235 | MMBZ27VAL        |
| BZT52-B16X           | 934071176115 | BZT52-B16        |
| "74HCT1G32GW,125"    | 935245740125 | 74HCT1G32GW      |
| "74HC4016D,652"      | 933714330652 | 74HC4016D        |
| PMEG4010EGWX         | 934070369115 | PMEG4010EGW      |
| 74LVC1G18GW-Q100H    | 935301509125 | 74LVC1G18GW-Q100 |
| "HEF40106BTT,112"    | 935270276112 | HEF40106BTT      |
| 74HCT2G08DP-Q100H    | 935300849125 | 74HCT2G08DP-Q100 |
| PDTC124ET/DG/B4,21   | 934066951215 | PDTC124ET/DG/B4  |
| BCX70J,215           | 933476660215 | BCX70J           |
| "74LVC16245ADGG,112" | 935235090112 | 74LVC16245ADGG   |
| TDZ2V7J,115          | 934065702115 | TDZ2V7J          |
| BZV85-C24,133        | 933500740133 | BZV85-C24        |
| 74LVC1G157GV,125     | 935278313125 | 74LVC1G157GV     |
| PDTC114ET,235        | 934031010235 | PDTC114ET        |
| "74HC123D,652"       | 933713960652 | 74HC123D         |
| PIMN31,115           | 934061307115 | PIMN31           |
| PUMD17,115           | 934057893115 | PUMD17           |
| BZT52H-C3V0,115      | 934059386115 | BZT52H-C3V0      |
| PBSS302NX,115        | 934059008115 | PBSS302NX        |
| HEF4028BT,652        | 933372800652 | HEF4028BT        |

|                      |              |                   |
|----------------------|--------------|-------------------|
| "HEF4069UBT,652"     | 933373000652 | HEF4069UBT        |
| BUK9M6R0-40HX        | 934660794115 | BUK9M6R0-40H      |
| NPIC6C596ADJ         | 935302408118 | NPIC6C596AD       |
| BAS70-05,235         | 933834100235 | BAS70-05          |
| PMV100ENEAR          | 934068713215 | PMV100ENEA        |
| "74LVC2G17GW,125"    | 935273321125 | 74LVC2G17GW       |
| BZX884-B3V0,315      | 934057186315 | BZX884-B3V0       |
| PIMC31,115           | 934063433115 | PIMC31            |
| BAV20,133            | 933189200133 | BAV20             |
| 74ABT245DB,118       | 935064910118 | 74ABT245DB        |
| PDTA114ET,235        | 934031060235 | PDTA114ET         |
| 74HC4060D,653        | 933714010653 | 74HC4060D         |
| 74AUP2G34GXZ         | 935307072147 | 74AUP2G34GX       |
| PBSS4021NX,115       | 934063402115 | PBSS4021NX        |
| 74LVT240D,118        | 935167180118 | 74LVT240D         |
| PMBF170,235          | 933966340235 | PMBF170           |
| 74AHCT374D,118       | 935262682118 | 74AHCT374D        |
| 74HCT14BQ,115        | 935273541115 | 74HCT14BQ         |
| 74HC4002PW,112       | 935188460112 | 74HC4002PW        |
| 74AVC9112GTX         | 935690125115 | 74AVC9112GT       |
| 74AHC3G14DP,125      | 935274685125 | 74AHC3G14DP       |
| 74HCT374D,653        | 933713490653 | 74HCT374D         |
| BAV70,215            | 933184910215 | BAV70             |
| NZX22B,133           | 934062001133 | NZX22B            |
| PDTA123YM,315        | 934058823315 | PDTA123YM         |
| "74HC1G125GW,125"    | 935245690125 | 74HC1G125GW       |
| PBSS304PX,115        | 934059017115 | PBSS304PX         |
| 1N4733A,113          | 933931590113 | 1N4733A           |
| CBTD3384D,118        | 935269654118 | CBTD3384D         |
| 74CB3Q3257BQX        | 935339458115 | 74CB3Q3257BQ      |
| "74ABT32D,112"       | 935208700112 | 74ABT32D          |
| BC859CW,115          | 934024320115 | BC859CW           |
| BC54PASX             | 934068124115 | BC54PAS           |
| IP4856CX25/CZ        | 934068531014 | IP4856CX25/C      |
| NX7002AK,215         | 934066291215 | NX7002AK          |
| BUK7610-55AL,118     | 934059225118 | BUK7610-55AL      |
| BZX79-C3V6,113       | 933117680113 | BZX79-C3V6        |
| BC52PASX             | 934068117115 | BC52PAS           |
| PEMH10,115           | 934056770115 | PEMH10            |
| PDTC143ZT,215        | 934054700215 | PDTC143ZT         |
| BZX84-C43,215        | 933388370215 | BZX84-C43         |
| PMV37EN2R            | 934068492215 | PMV37EN2          |
| "74LVC2GU04GW-Q100," | 935299058125 | 74LVC2GU04GW-Q100 |
| BZX84J-C6V2,115      | 934061016115 | BZX84J-C6V2       |
| PESD5V0S1BSF,315     | 934064605315 | PESD5V0S1BSF      |
| BCM61B,215           | 934059881215 | BCM61B            |

|                    |              |                 |
|--------------------|--------------|-----------------|
| BSS192,135         | 933943950135 | BSS192          |
| 74VHC541BQ,115     | 935289517115 | 74VHC541BQ      |
| 74HCT241PW,118     | 935174600118 | 74HCT241PW      |
| 74AUP1G97GM,115    | 935279963115 | 74AUP1G97GM     |
| PMEG045T150EIPDZ   | 934070411146 | PMEG045T150EIPD |
| 74HCT151PW,118     | 935188940118 | 74HCT151PW      |
| 74AHC244PW-Q100,11 | 935298435118 | 74AHC244PW-Q100 |
| PSMN7R0-60YS,115   | 934064403115 | PSMN7R0-60YS    |
| 74LVC11D-Q100J     | 935690357118 | 74LVC11D-Q100   |
| BCV27,215          | 933806220215 | BCV27           |
| PESD2USB3B/CX      | 934660294115 | PESD2USB3B/C    |
| "74AUP1G79GV,125"  | 935290077125 | 74AUP1G79GV     |
| BZT52H-C12,115     | 934059403115 | BZT52H-C12      |
| BZX79-B5V6,133     | 933166820133 | BZX79-B5V6      |
| BZV55-C15,115      | 933699560115 | BZV55-C15       |
| BUK762R9-40E,118   | 934066435118 | BUK762R9-40E    |
| 2N7002PW,115       | 934064137115 | 2N7002PW        |
| BAV23A,215         | 934061766215 | BAV23A          |
| 74LVC595AD,112     | 935282469112 | 74LVC595AD      |
| BZX84-C20,235      | 933388290235 | BZX84-C20       |
| PMEG2005CT,215     | 934061751215 | PMEG2005CT      |
| BZT52H-B12,115     | 934064796115 | BZT52H-B12      |
| PMBTA42DS,125      | 934059919125 | PMBTA42DS       |
| "74HC165PW,112"    | 935174530112 | 74HC165PW       |
| NZX15C,133         | 934063546133 | NZX15C          |
| BAT854W,115        | 934056176115 | BAT854W         |
| HEF4046BT,653      | 933372900653 | HEF4046BT       |
| PDTB113ZUX         | 934068334115 | PDTB113ZU       |
| BZT52-B3V6X        | 934071147115 | BZT52-B3V6      |
| 74HCT165PW,112     | 935188350112 | 74HCT165PW      |
| BZX84J-C62,115     | 934061014115 | BZX84J-C62      |
| PMST5551,115       | 934051560115 | PMST5551        |
| 74AHC125BQ,115     | 935285542115 | 74AHC125BQ      |
| PMEG6010ESBYL      | 934068756315 | PMEG6010ESB     |
| "74HC30D,652"      | 933756910652 | 74HC30D         |
| BC847QAPNZ         | 934067159147 | BC847QAPN       |
| 74LVC07AD,118      | 935265481118 | 74LVC07AD       |
| BUK7227-100B,118   | 934057719118 | BUK7227-100B    |
| 74LVC3G17DP,125    | 935275564125 | 74LVC3G17DP     |
| PBHV9050ZF         | 934064553135 | PBHV9050Z       |
| 74LVC2G241DC,125   | 935274509125 | 74LVC2G241DC    |
| BC817K-16HVL       | 934660223235 | BC817K-16H      |
| 1N4745A,113        | 933931710113 | 1N4745A         |
| "74AUP1G14GX,125"  | 935298361125 | 74AUP1G14GX     |
| PMDXB600UNELZ      | 934070432147 | PMDXB600UNEL    |
| 74HCT241D,653      | 933713470653 | 74HCT241D       |

|                      |              |                   |
|----------------------|--------------|-------------------|
| BC817DS,115          | 934057319115 | BC817DS           |
| 74HCT173D,653        | 933715040653 | 74HCT173D         |
| BC53-16PA,115        | 934065823115 | BC53-16PA         |
| BAV102,115           | 933699350115 | BAV102            |
| 74HCT238PW,118       | 935189560118 | 74HCT238PW        |
| BZV49-C68,115        | 933606160115 | BZV49-C68         |
| PZU27BA,115          | 934062466115 | PZU27BA           |
| ON5474J              | 934067774118 | ON5474            |
| BUK9Y59-60E,115      | 934067025115 | BUK9Y59-60E       |
| BUK7Y19-100EX        | 934067442115 | BUK7Y19-100E      |
| 74CBTLV3253D,118     | 935289998118 | 74CBTLV3253D      |
| 74LV4051PW,112       | 935191000112 | 74LV4051PW        |
| BZX884-C4V3,315      | 934057214315 | BZX884-C4V3       |
| BC847QASZ            | 934068722147 | BC847QAS          |
| PZU7.5BA,115         | 934062797115 | PZU7.5BA          |
| PMEG3010AESBYL       | 934068753315 | PMEG3010AESB      |
| BZX84-B6V2,215       | 933671120215 | BZX84-B6V2        |
| PMV30UN2R            | 934068491215 | PMV30UN2          |
| 74AHC2G08DC,125      | 935275125125 | 74AHC2G08DC       |
| 74AHC08BQ,115        | 935285532115 | 74AHC08BQ         |
| 74LVT573D,118        | 935170700118 | 74LVT573D         |
| BUK9240-100A,118     | 934056252118 | BUK9240-100A      |
| BC817-16W,115        | 934021920115 | BC817-16W         |
| BZX79-B5V1,133       | 933166810133 | BZX79-B5V1        |
| BAS21AW,115          | 934063269115 | BAS21AW           |
| 74HC4002D,653        | 933714320653 | 74HC4002D         |
| PMEG4002ELD,315      | 934065339315 | PMEG4002ELD       |
| "74LVC573AD,112"     | 935219000112 | 74LVC573AD        |
| 74LV1T04GXH          | 935690196125 | 74LV1T04GX        |
| PDTB114ETR           | 934031090215 | PDTB114ET         |
| BZX79-C6V2,113       | 933117740113 | BZX79-C6V2        |
| PMZB550UNEYL         | 934069331315 | PMZB550UNE        |
| 74AHCT1G79GW-Q100H   | 935300084125 | 74AHCT1G79GW-Q100 |
| BZX84J-C13,115       | 934060985115 | BZX84J-C13        |
| PSMNR58-30YLHX       | 934660323115 | PSMNR58-30YLH     |
| PZU18B,115           | 934059772115 | PZU18B            |
| BUK762R6-60E,118     | 934066664118 | BUK762R6-60E      |
| 74HCT14BQ-Q100,115   | 935298443115 | 74HCT14BQ-Q100    |
| BZX884-C30,315       | 934057461315 | BZX884-C30        |
| 74HC132BQ-Q100X      | 935690579115 | 74HC132BQ-Q100    |
| "74AVCH16T245DGG,11" | 935286233112 | 74AVCH16T245DGG   |
| "74LVC240APW,112"    | 935210450112 | 74LVC240APW       |
| TDZ3V0J,115          | 934065703115 | TDZ3V0J           |
| 74HC2G66DP,125       | 935272945125 | 74HC2G66DP        |
| 74LVCH162245ADL:11   | 935238720118 | 74LVCH162245ADL   |
| BZB84-C39,215        | 934063337215 | BZB84-C39         |

|                    |              |                   |
|--------------------|--------------|-------------------|
| 74HCT259D,653      | 933715130653 | 74HCT259D         |
| NX7002BKR          | 934068055215 | NX7002BKR         |
| 74HC4851D-Q100,118 | 935298462118 | 74HC4851D-Q100    |
| BZX84-A3V0,215     | 934019950215 | BZX84-A3V0        |
| 74LV08PW,118       | 935174280118 | 74LV08PW          |
| BZX585-C2V4,115    | 934055836115 | BZX585-C2V4       |
| NX3008NBK,215      | 934065641215 | NX3008NBK         |
| "74LVC1GU04GV,125" | 935272022125 | 74LVC1GU04GV      |
| PMEG045T030EPDZ    | 934070408146 | PMEG045T030EPD    |
| PEMH2,115          | 934056868115 | PEMH2             |
| BAS40-05W,115      | 934044300115 | BAS40-05W         |
| BZX884-B18,315     | 934057439315 | BZX884-B18        |
| PMEG3005AEA,115    | 934057751115 | PMEG3005AEA       |
| 74LVC1G384GW-Q100H | 935300457125 | 74LVC1G384GW-Q100 |
| PDTC124TU,115      | 934057540115 | PDTC124TU         |
| 74HC161PW,118      | 935188320118 | 74HC161PW         |
| PSMN6R5-25YLC,115  | 934066017115 | PSMN6R5-25YLC     |
| PDZ3.9BGWJ         | 934071082118 | PDZ3.9BGW         |
| 74AHC125PW,118     | 935262763118 | 74AHC125PW        |
| PMDPB70XPE,115     | 934066844115 | PMDPB70XPE        |
| BUK7Y8R7-60EX      | 934067438115 | BUK7Y8R7-60E      |
| BZX585-C10,115     | 934055851115 | BZX585-C10        |
| BZA408B,115        | 934055171115 | BZA408B           |
| PMCM6501VPEZ       | 934068875023 | PMCM6501VPE       |
| 74LVC00ADB,112     | 935249970112 | 74LVC00ADB        |
| "74AHC1G09GV,125"  | 935285716125 | 74AHC1G09GV       |
| "74HC368D,652"     | 933714700652 | 74HC368D          |
| "74AUP1G80GW,125"  | 935279049125 | 74AUP1G80GW       |
| BAS316,115         | 934054945115 | BAS316            |
| BSR14,215          | 933508380215 | BSR14             |
| "74ALVC125PW,118"  | 935269719118 | 74ALVC125PW       |
| 74LVC2G04GXZ       | 935307076147 | 74LVC2G04GX       |
| PMEG4002EJ,115     | 934063239115 | PMEG4002EJ        |
| 74HCT367PW,118     | 935189050118 | 74HCT367PW        |
| MMBZ20VAL,215      | 934061799215 | MMBZ20VAL         |
| 74HCT595DB,118     | 935190170118 | 74HCT595DB        |
| BUK9Y53-100B,115   | 934061027115 | BUK9Y53-100B      |
| PESD3V3V4UW,115    | 934059176115 | PESD3V3V4UW       |
| BAS116,215         | 934032170215 | BAS116            |
| "74ALVC02PW,118"   | 935269713118 | 74ALVC02PW        |
| PTVS36VS1UR,115    | 934061365115 | PTVS36VS1UR       |
| PMDPB56XNEAX       | 934069878115 | PMDPB56XNEA       |
| PTVS60VS1UR,115    | 934061374115 | PTVS60VS1UR       |
| HEF4104BT,653      | 933373140653 | HEF4104BT         |
| 74LVC1G175GF,132   | 935282414132 | 74LVC1G175GF      |
| PBLS6002D,115      | 934059265115 | PBLS6002D         |

|                    |              |                  |
|--------------------|--------------|------------------|
| BZX884-C5V1,315    | 934057216315 | BZX884-C5V1      |
| BZX384-C7V5,115    | 934057637115 | BZX384-C7V5      |
| PBLS6003D,115      | 934059266115 | PBLS6003D        |
| BUK9Y19-55B,115    | 934058366115 | BUK9Y19-55B      |
| PMV160UP,215       | 934064761215 | PMV160UP         |
| 74LV02APWJ         | 935690647118 | 74LV02APW        |
| NX138BKWX          | 934070157115 | NX138BKW         |
| PBSS5250X,135      | 934055629135 | PBSS5250X        |
| 74LVC2G38DC,125    | 935273584125 | 74LVC2G38DC      |
| 74AUP1G04GM,115    | 935279002115 | 74AUP1G04GM      |
| "74LVC2G04GW,125"  | 935273523125 | 74LVC2G04GW      |
| PMEG3010BEA,115    | 934057917115 | PMEG3010BEA      |
| BCV62,215          | 933677230215 | BCV62            |
| BZX384-B43,115     | 934057388115 | BZX384-B43       |
| "74AHC3G14GT,115"  | 935293751115 | 74AHC3G14GT      |
| BZX84-C33,215      | 933388340215 | BZX84-C33        |
| PMCM4401UPEZ       | 934070326084 | PMCM4401UPE      |
| PESD15VS1UL,315    | 934059978315 | PESD15VS1UL      |
| 74LVCH162373ADL:11 | 935238740118 | 74LVCH162373ADL  |
| 74LVC2G34GV-Q100,1 | 935299051125 | 74LVC2G34GV-Q100 |
| BUK9Y22-100E,115   | 934067037115 | BUK9Y22-100E     |
| PDTA143TU,115      | 934057535115 | PDTA143TU        |
| BUK9Y6R0-60E,115   | 934067018115 | BUK9Y6R0-60E     |
| BZV55-C2V4,135     | 933699370135 | BZV55-C2V4       |
| 74HC594D,118       | 935043380118 | 74HC594D         |
| PH0925CL,115       | 934065078115 | PH0925CL         |
| 74HC4066PW/C4J     | 935301856118 | 74HC4066PW/C4    |
| "74LVC1G10GW,125"  | 935284948125 | 74LVC1G10GW      |
| BCP56,115          | 933917240115 | BCP56            |
| PDZ7.5B,115        | 934054856115 | PDZ7.5B          |
| 74HCT4851PW-Q100,1 | 935298466118 | 74HCT4851PW-Q100 |
| BAT754L,115        | 934056331115 | BAT754L          |
| 74ALVC541PW,118    | 935269735118 | 74ALVC541PW      |
| PUMZ2,115          | 934058172115 | PUMZ2            |
| BZV49-C39,115      | 933606100115 | BZV49-C39        |
| BZV85-C3V9,113     | 933659360113 | BZV85-C3V9       |
| 74HC244D-Q100,118  | 935298913118 | 74HC244D-Q100    |
| BZX585-B12,115     | 934055873115 | BZX585-B12       |
| "74LVT08D,112"     | 935209020112 | 74LVT08D         |
| PMBT3906M,315      | 934063476315 | PMBT3906M        |
| "74HC2GU04GW,125"  | 935281027125 | 74HC2GU04GW      |
| PBSS4041SPN,115    | 934063414115 | PBSS4041SPN      |
| BZX384-C39,115     | 934057654115 | BZX384-C39       |
| BAS21,235          | 933502040235 | BAS21            |
| 74LVTH125D,118     | 935281718118 | 74LVTH125D       |
| BC846BS,135        | 934063582135 | BC846BS          |

|                      |              |                  |
|----------------------|--------------|------------------|
| PDZ24BGWJ            | 934071036118 | PDZ24BGW         |
| 74LVC573ABQ,115      | 935273507115 | 74LVC573ABQ      |
| 74AHCT273D,118       | 935263590118 | 74AHCT273D       |
| BZX585-C12,115       | 934055853115 | BZX585-C12       |
| PMMT491A,235         | 934055113235 | PMMT491A         |
| BZV85-C20,133        | 933500720133 | BZV85-C20        |
| PDTC144EM,315        | 934057200315 | PDTC144EM        |
| PTVS43VP1UP,115      | 934064183115 | PTVS43VP1UP      |
| "74LVC1G157GM,132"   | 935278312132 | 74LVC1G157GM     |
| BAS116LYL            | 934069811315 | BAS116L          |
| BZX84-A9V1,215       | 934014140215 | BZX84-A9V1       |
| IP4788CZ32J          | 934066835118 | IP4788CZ32       |
| BZV55-C4V3,115       | 933699430115 | BZV55-C4V3       |
| PMEG4010ETP,115      | 934065459115 | PMEG4010ETP      |
| "74LVC10APW,118"     | 935260748118 | 74LVC10APW       |
| "HEF4067BT,652"      | 933372980652 | HEF4067BT        |
| 1PS79SB40,115        | 934055508115 | 1PS79SB40        |
| PMBT2222A,235        | 933821790235 | PMBT2222A        |
| PMEG2010ER,115       | 934061456115 | PMEG2010ER       |
| HEF4016BT,652        | 933372690652 | HEF4016BT        |
| 74LVT16374ADGG,118   | 935203010118 | 74LVT16374ADGG   |
| BZX585-B33,115       | 934057411115 | BZX585-B33       |
| "74AHC1G00GW,125"    | 935262777125 | 74AHC1G00GW      |
| PMBTA06,215          | 933776020215 | PMBTA06          |
| 74HCT595D,118        | 935009180118 | 74HCT595D        |
| PMEG3005EH,115       | 934059024115 | PMEG3005EH       |
| "74AUP1G34GW,125"    | 935279028125 | 74AUP1G34GW      |
| "74AHC1G08GW-Q100,1" | 935298623125 | 74AHC1G08GW-Q100 |
| PSMN0R9-25YLDX       | 934069907115 | PSMN0R9-25YLD    |
| BC860CW,115          | 934024350115 | BC860CW          |
| BCX70J,235           | 933476660235 | BCX70J           |
| 74LVC139DB,118       | 935196000118 | 74LVC139DB       |
| BZX384-C56,115       | 934057658115 | BZX384-C56       |
| BZX84J-B15,115       | 934060941115 | BZX84J-B15       |
| BZX585-B9V1,115      | 934055870115 | BZX585-B9V1      |
| PDTC143ZU,115        | 934057544115 | PDTC143ZU        |
| PZU7.5B,115          | 934059755115 | PZU7.5B          |
| PMDXB950UPEZ         | 934067656147 | PMDXB950UPE      |
| BC53PASX             | 934068121115 | BC53PAS          |
| "74AUP1G132GX,125"   | 935298371125 | 74AUP1G132GX     |
| BAV70,235            | 933184910235 | BAV70            |
| PMEG100V100ELPDAZ    | 934069519139 | PMEG100V100ELPD  |
| BZX84J-C3V6,115      | 934061003115 | BZX84J-C3V6      |
| 74AHCT125PW-Q100,1   | 935298425118 | 74AHCT125PW-Q100 |
| BZX84-C30,235        | 933388330235 | BZX84-C30        |
| NUP1301U,115         | 934065389115 | NUP1301U         |

|                    |              |                  |
|--------------------|--------------|------------------|
| PSMN102-200Y,115   | 934061323115 | PSMN102-200Y     |
| HEF4794BT,112      | 935069140112 | HEF4794BT        |
| NX7002BKWX         | 934068621115 | NX7002BKW        |
| BZX79-C3V3,113     | 933117670113 | BZX79-C3V3       |
| "74LVC2G53GT,115"  | 935280384115 | 74LVC2G53GT      |
| 74LVT162374DGG,118 | 935264167118 | 74LVT162374DGG   |
| "74LVC32AD,112"    | 935250060112 | 74LVC32AD        |
| PRMD3Z             | 934070169147 | PRMD3            |
| TDZ3V3J,115        | 934065704115 | TDZ3V3J          |
| BCX70K,215         | 933476670215 | BCX70K           |
| "74HCT20D,652"     | 933714380652 | 74HCT20D         |
| 74AHC244D,112      | 935262001112 | 74AHC244D        |
| BZX585-B20,115     | 934057406115 | BZX585-B20       |
| 74HC2G32DP,125     | 935271849125 | 74HC2G32DP       |
| 74HC4050D-Q100J    | 935300046118 | 74HC4050D-Q100   |
| BZX585-B3V3,115    | 934055859115 | BZX585-B3V3      |
| BUK9675-55A,118    | 934056269118 | BUK9675-55A      |
| PESD3V3L4BHCYL     | 934660987315 | PESD3V3L4BHC     |
| 74HCT154PW,118     | 935182560118 | 74HCT154PW       |
| PUMH13,115         | 934057894115 | PUMH13           |
| 74HC245D,653       | 933713580653 | 74HC245D         |
| BCP56HX            | 934070289115 | BCP56H           |
| PMEG6030EVPX       | 934067592115 | PMEG6030EVP      |
| 74LVC08AD,112      | 935250020112 | 74LVC08AD        |
| "74AVC1T45GS,132"  | 935294361132 | 74AVC1T45GS      |
| 74HC163D,653       | 933714540653 | 74HC163D         |
| 74LVC2G34GF,132    | 935282435132 | 74LVC2G34GF      |
| 74HC04BQ,115       | 935273651115 | 74HC04BQ         |
| NCR420ZX           | 934070332115 | NCR420Z          |
| 74LV1T87GXH        | 935690208125 | 74LV1T87GX       |
| 74LVC1G74DC-Q100H  | 935299293125 | 74LVC1G74DC-Q100 |
| 74AUP1T00GXH       | 935690041125 | 74AUP1T00GX      |
| 74HC238BQ,115      | 935283681115 | 74HC238BQ        |
| "74AUP1G07GW,125"  | 935279017125 | 74AUP1G07GW      |
| BCX56-16,115       | 933674760115 | BCX56-16         |
| BZX84J-B3V0,115    | 934060958115 | BZX84J-B3V0      |
| PMEG2010EH,115     | 934059029115 | PMEG2010EH       |
| BZX84W-C68F        | 934660458135 | BZX84W-C68       |
| 74AUP1T00GWH       | 935690039125 | 74AUP1T00GW      |
| BAV21,133          | 933189210133 | BAV21            |
| 74HCT193D,653      | 933715100653 | 74HCT193D        |
| 74HC126D-Q100J     | 935300038118 | 74HC126D-Q100    |
| PESD15VU1UT,215    | 934059105215 | PESD15VU1UT      |
| BZT52H-B7V5,115    | 934064791115 | BZT52H-B7V5      |
| BZT52-C10X         | 934071125115 | BZT52-C10        |
| PDTC123JU,115      | 934057539115 | PDTC123JU        |



|                    |              |                   |
|--------------------|--------------|-------------------|
| 74HC4511D,653      | 933714880653 | 74HC4511D         |
| BUK7K35-60EX       | 934067833115 | BUK7K35-60E       |
| 74LVCH2T45DC-Q100H | 935301408125 | 74LVCH2T45DC-Q100 |
| PDTA124EU,115      | 934044110115 | PDTA124EU         |
| "74AVCH1T45GW,125" | 935284156125 | 74AVCH1T45GW      |
| PMBT3906,235       | 933776010235 | PMBT3906          |
| BZV90-C22,115      | 934014840115 | BZV90-C22         |
| BZT52H-B4V7,115    | 934064785115 | BZT52H-B4V7       |
| BSP230,135         | 934024380135 | BSP230            |
| "74HC597D,652"     | 933757330652 | 74HC597D          |
| MMBZ18VCL,215      | 934061811215 | MMBZ18VCL         |
| BZV55-B6V8,115     | 933827710115 | BZV55-B6V8        |
| "HEF4541BT,512"    | 933508000512 | HEF4541BT         |
| PUMX2,125          | 934059964125 | PUMX2             |
| BCV49,115          | 934003660115 | BCV49             |
| PESD5V0U1UL,315    | 934062184315 | PESD5V0U1UL       |
| PEMB2,115          | 934056523115 | PEMB2             |
| 74LVC2G04GF,132    | 935282429132 | 74LVC2G04GF       |
| BUK7M33-60EX       | 934070054115 | BUK7M33-60E       |
| PRMH13Z            | 934070179147 | PRMH13            |
| PMBT3904VS,115     | 934063472115 | PMBT3904VS        |
| BZX84J-B6V2,115    | 934060975115 | BZX84J-B6V2       |
| PNE20010ERX        | 934067815115 | PNE20010ER        |
| PBSS4360XF         | 934660028135 | PBSS4360X         |
| BZX84-A15,215      | 934015880215 | BZX84-A15         |
| NX7002BKXBZ        | 934068992147 | NX7002BKXB        |
| "74LVC06APW,118"   | 935265480118 | 74LVC06APW        |
| 74ABT245D,623      | 935027530623 | 74ABT245D         |
| "74AHCT123AD,112"  | 935265561112 | 74AHCT123AD       |
| 1PS301,115         | 934033590115 | 1PS301            |
| 74HC4049PW,118     | 935294435118 | 74HC4049PW        |
| 74AUP1T34GXH       | 935302887125 | 74AUP1T34GX       |
| 74AHCT00PW,112     | 935262689112 | 74AHCT00PW        |
| PMEG050V150EPDAZ   | 934068489139 | PMEG050V150EPD    |
| HEF4052BTT,118     | 935289483118 | HEF4052BTT        |
| 74AVC4TD245BQ,115  | 935294167115 | 74AVC4TD245BQ     |
| 74HC4020D,653      | 933714770653 | 74HC4020D         |
| BZV85-C10,113      | 933500650113 | BZV85-C10         |
| PESD5V0S1BL,315    | 934058006315 | PESD5V0S1BL       |
| BCM856BS,115       | 934062056115 | BCM856BS          |
| BZT52-B4V7J        | 934071151118 | BZT52-B4V7        |
| "74LVC1G08GV,125"  | 935272011125 | 74LVC1G08GV       |
| 74HC573D,652       | 933713560652 | 74HC573D          |
| BCW60D,215         | 933324110215 | BCW60D            |
| "74HC4016PW,118"   | 935174910118 | 74HC4016PW        |
| PCMF2USB30Z        | 934069593087 | PCMF2USB30        |

|                     |              |                   |
|---------------------|--------------|-------------------|
| BAT54AW,115         | 934028890115 | BAT54AW           |
| NPIC6C4894D-Q100Y   | 935302551518 | NPIC6C4894D-Q100  |
| BZX585-C13,115      | 934055854115 | BZX585-C13        |
| "74HC04PW-Q100,118" | 935298729118 | 74HC04PW-Q100     |
| 74HC30PW-Q100J      | 935300225118 | 74HC30PW-Q100     |
| PTVS48VS1UR,115     | 934061369115 | PTVS48VS1UR       |
| 74AHC157D,118       | 935263998118 | 74AHC157D         |
| "74HCT138D,652"     | 933713410652 | 74HCT138D         |
| PZU15B2L,315        | 934061614315 | PZU15B2L          |
| NZH10C,115          | 934064366115 | NZH10C            |
| MMBZ18VAL,215       | 934061798215 | MMBZ18VAL         |
| PTVS8V0S1UR,115     | 934061344115 | PTVS8V0S1UR       |
| IP4294CZ10-TBR,115  | 934065678115 | IP4294CZ10-TBR    |
| PESD5V0L1BA,135     | 934058421135 | PESD5V0L1BA       |
| "74HC1G04GW,125"    | 935245650125 | 74HC1G04GW        |
| 74HCT32D,652        | 933719470652 | 74HCT32D          |
| "74HCT86PW,118"     | 935185850118 | 74HCT86PW         |
| "74AVC2T45GT,115"   | 935283715115 | 74AVC2T45GT       |
| BUK9277-55A,118     | 934056247118 | BUK9277-55A       |
| 74HC4052DB,112      | 935186930112 | 74HC4052DB        |
| 1N4739A,113         | 933931650113 | 1N4739A           |
| BZX585-C7V5,135     | 934055848135 | BZX585-C7V5       |
| 74AUP1G125GF,132    | 935281121132 | 74AUP1G125GF      |
| 74LV04DB,118        | 935169260118 | 74LV04DB          |
| PMBTA13,215         | 933816520215 | PMBTA13           |
| PSMN3R8-100BS,118   | 934065178118 | PSMN3R8-100BS     |
| 74HCT1G125GW-Q100H  | 935300002125 | 74HCT1G125GW-Q100 |
| 74VHCT245D,118      | 935289585118 | 74VHCT245D        |
| PMF63UNEX           | 934068841115 | PMF63UNE          |
| 74AVC4T245BQ,115    | 935284586115 | 74AVC4T245BQ      |
| PMV48XPAR           | 934067201215 | PMV48XPA          |
| BZX84-B36,215       | 933770470215 | BZX84-B36         |
| 74AVC16T245DGG,112  | 935286228112 | 74AVC16T245DGG    |
| BZX79-C9V1,133      | 933117780133 | BZX79-C9V1        |
| IP4283CZ10-TBA,115  | 934064664115 | IP4283CZ10-TBA    |
| 74HCT20D,653        | 933714380653 | 74HCT20D          |
| "74LVC1G07GV,125"   | 935272029125 | 74LVC1G07GV       |
| PTVS5V0P1UP,115     | 934064144115 | PTVS5V0P1UP       |
| BZB984-C5V1,115     | 934056721115 | BZB984-C5V1       |
| BCP53HX             | 934070286115 | BCP53H            |
| PMPB10XNE,115       | 934066863115 | PMPB10XNE         |
| 74AUP1G09GW-Q100H   | 935690914125 | 74AUP1G09GW-Q100  |
| 74LVC1G57GV,125     | 935276073125 | 74LVC1G57GV       |
| BCX53-16,146        | 933674730146 | BCX53-16          |
| PMEG6030ELPX        | 934068901115 | PMEG6030ELP       |
| PZU6.8BL,315        | 934061673315 | PZU6.8BL          |

|                    |              |                 |
|--------------------|--------------|-----------------|
| PBSS4240V,115      | 934057074115 | PBSS4240V       |
| 74AUP2G00DC,125    | 935280706125 | 74AUP2G00DC     |
| 74LVC32ABQ,115     | 935273662115 | 74LVC32ABQ      |
| 74HCT154DB,118     | 935182550118 | 74HCT154DB      |
| BUK9Y1R9-40HX      | 934660364115 | BUK9Y1R9-40H    |
| BZT52-C5V1J        | 934071108118 | BZT52-C5V1      |
| BZT52H-C6V2,115    | 934059395115 | BZT52H-C6V2     |
| PSMN2R2-30YLC,115  | 934065191115 | PSMN2R2-30YLC   |
| 74HCT165PW,118     | 935188350118 | 74HCT165PW      |
| BZT52H-B20,115     | 934064802115 | BZT52H-B20      |
| BCM857DS,115       | 934059033115 | BCM857DS        |
| BZX84-B62,215      | 933770530215 | BZX84-B62       |
| 74LVC00AD,118      | 935249960118 | 74LVC00AD       |
| BUK9Y22-30B,115    | 934063319115 | BUK9Y22-30B     |
| BAS40L,315         | 934057253315 | BAS40L          |
| BZB84-C5V6,215     | 934061688215 | BZB84-C5V6      |
| 74HC365D,653       | 933714670653 | 74HC365D        |
| BZT52H-B16,115     | 934064799115 | BZT52H-B16      |
| BC817K-25HR        | 934660224215 | BC817K-25H      |
| BZX384-B2V7,115    | 934057359115 | BZX384-B2V7     |
| BUK6D120-60PX      | 934660343115 | BUK6D120-60P    |
| 74LVC2G07GXZ       | 935307077147 | 74LVC2G07GX     |
| PUMH11,115         | 934049930115 | PUMH11          |
| PNS40010ER,115     | 934066627115 | PNS40010ER      |
| 74LV165DB,118      | 935166030118 | 74LV165DB       |
| 74HC32D,653        | 933714310653 | 74HC32D         |
| PMDT290UCE,115     | 934065733115 | PMDT290UCE      |
| BZX84J-C20,115     | 934060989115 | BZX84J-C20      |
| PSMN7R8-120PSQ     | 934067448127 | PSMN7R8-120PS   |
| PZU6.2B,115        | 934059753115 | PZU6.2B         |
| 74LVC2G34GV,125    | 935273784125 | 74LVC2G34GV     |
| 74LV1T02GXH        | 935690193125 | 74LV1T02GX      |
| PSMN030-60YS,115   | 934064398115 | PSMN030-60YS    |
| PBSS5160V,115      | 934058114115 | PBSS5160V       |
| RB751CS40,315      | 934061304315 | RB751CS40       |
| "74HC1G66GV,125"   | 935271887125 | 74HC1G66GV      |
| 74HC365PW,118      | 935189040118 | 74HC365PW       |
| 74CBTLV3257DS,118  | 935290006118 | 74CBTLV3257DS   |
| PESD24VS2UQ,115    | 934057838115 | PESD24VS2UQ     |
| "74HCT2G34GW,125"  | 935281035125 | 74HCT2G34GW     |
| PMSS3904,115       | 934026800115 | PMSS3904        |
| "74HCT166D,652"    | 933715030652 | 74HCT166D       |
| 74HCU04PW-Q100J    | 935300231118 | 74HCU04PW-Q100  |
| 74LVCH16373ADGG:11 | 935238490118 | 74LVCH16373ADGG |
| BUK9Y11-30B,115    | 934060171115 | BUK9Y11-30B     |
| BAS21/DG/B4R       | 934660076215 | BAS21/DG/B4     |

|                    |              |                    |
|--------------------|--------------|--------------------|
| 74VHC541PW,118     | 935289527118 | 74VHC541PW         |
| 74HC175PW,112      | 935174560112 | 74HC175PW          |
| PMEG3020BEP,115    | 934061473115 | PMEG3020BEP        |
| PMBT5551,215       | 933821840215 | PMBT5551           |
| 74HCT541DB,118     | 935187540118 | 74HCT541DB         |
| PZU6.2B2L,315      | 934061670315 | PZU6.2B2L          |
| BZX84-A39,215      | 934045850215 | BZX84-A39          |
| MMBZ27VAL,215      | 934061801215 | MMBZ27VAL          |
| BUK7Y38-100EX      | 934067444115 | BUK7Y38-100E       |
| PDZ18BF            | 934054865135 | PDZ18B             |
| PMV40UN2R          | 934068493215 | PMV40UN2           |
| PMEG4005EGWJ       | 934070368118 | PMEG4005EGW        |
| BZX384-C75,115     | 934057661115 | BZX384-C75         |
| 1N4730A,113        | 933931560113 | 1N4730A            |
| BZV55-C4V7,115     | 933699440115 | BZV55-C4V7         |
| 74HCT02D,652       | 933714160652 | 74HCT02D           |
| BZX384-C3V6,115    | 934057629115 | BZX384-C3V6        |
| BAS70H,115         | 934059279115 | BAS70H             |
| PESD3V3U1UL,315    | 934062949315 | PESD3V3U1UL        |
| PESD5V0F1BRSFYL    | 934067751315 | PESD5V0F1BRSF      |
| PUMB2,115          | 934055443115 | PUMB2              |
| 74AHCT125BQ,115    | 935285543115 | 74AHCT125BQ        |
| PMZ550UNEYL        | 934069328315 | PMZ550UNE          |
| 74CBTLV3257PW-Q10J | 935302229118 | 74CBTLV3257PW-Q100 |
| "74LV74D,112"      | 935063300112 | 74LV74D            |
| PDTC143EM,315      | 934057178315 | PDTC143EM          |
| 74HC367PW,118      | 935188420118 | 74HC367PW          |
| PESD5V0X2UAMBYL    | 934068184315 | PESD5V0X2UAMB      |
| BAS21W,115         | 934063268115 | BAS21W             |
| NX3008NBKV,115     | 934065632115 | NX3008NBKV         |
| PMEG3005ELD,315    | 934065338315 | PMEG3005ELD        |
| 74LVC1T45GM-Q100X  | 935690846115 | 74LVC1T45GM-Q100   |
| PHPT60610NYX       | 934068583115 | PHPT60610NY        |
| HEF4518BT,652      | 933373230652 | HEF4518BT          |
| BZX84-B22,215      | 933770430215 | BZX84-B22          |
| "HEF4060BT,652"    | 933567150652 | HEF4060BT          |
| MMBZ6V2AL,215      | 934063464215 | MMBZ6V2AL          |
| BZT52-C2V7J        | 934071098118 | BZT52-C2V7         |
| PMEG4005EGWX       | 934070368115 | PMEG4005EGW        |
| 74HC85PW,118       | 935189180118 | 74HC85PW           |
| 74VHC08PW-Q100J    | 935303217118 | 74VHC08PW-Q100     |
| PBHV9115Z,115      | 934061412115 | PBHV9115Z          |
| 74HCT273D-Q100J    | 935301458118 | 74HCT273D-Q100     |
| "74LVC00APW,112"   | 935249980112 | 74LVC00APW         |
| 74AHC123APW,118    | 935265564118 | 74AHC123APW        |
| "74HCT14D,652"     | 933714440652 | 74HCT14D           |

|                    |              |                 |
|--------------------|--------------|-----------------|
| PZU5.1BA,115       | 934062779115 | PZU5.1BA        |
| PSMN2R6-40YS,115   | 934063932115 | PSMN2R6-40YS    |
| BZB984-C4V7,115    | 934056720115 | BZB984-C4V7     |
| PH1225AL,115       | 934064141115 | PH1225AL        |
| BZX884-B56,315     | 934057451315 | BZX884-B56      |
| BZT52H-B5V1,115    | 934064786115 | BZT52H-B5V1     |
| 74HC132D,653       | 933714130653 | 74HC132D        |
| PMEG4005AEV,115    | 934057833115 | PMEG4005AEV     |
| 74AHC132D,118      | 935262989118 | 74AHC132D       |
| BZV90-C2V7,115     | 934014620115 | BZV90-C2V7      |
| PZT2222A,135       | 933975330135 | PZT2222A        |
| BCM56DSX           | 934070952115 | BCM56DS         |
| PUMB9,115          | 934057506115 | PUMB9           |
| BZX84-B3V6,215     | 933770310215 | BZX84-B3V6      |
| PBSS4350Z,135      | 934056526135 | PBSS4350Z       |
| 74HCT244BQ,115     | 935273729115 | 74HCT244BQ      |
| PMEG4010EGWJ       | 934070369118 | PMEG4010EGW     |
| 74AUP2GU04GM,115   | 935280001115 | 74AUP2GU04GM    |
| 74HC00D,652        | 933713360652 | 74HC00D         |
| BZX84J-C51,115     | 934061009115 | BZX84J-C51      |
| PMEG2005EGWX       | 934070365115 | PMEG2005EGW     |
| 74LVC162244ADL,118 | 935237670118 | 74LVC162244ADL  |
| "74LVC2GU04GW,125" | 935274026125 | 74LVC2GU04GW    |
| PLVA665A,215       | 934017390215 | PLVA665A        |
| BZX79-C3V9,113     | 933117690113 | BZX79-C3V9      |
| "74HC164D,652"     | 933714070652 | 74HC164D        |
| 2PD602ASL,215      | 934062315215 | 2PD602ASL       |
| PDTC143EU,115      | 934044090115 | PDTC143EU       |
| PMEG45A10EPDAZ     | 934068205139 | PMEG45A10EPD    |
| 74HC40103D,653     | 933714730653 | 74HC40103D      |
| PSMN4R1-60YLX      | 934069893115 | PSMN4R1-60YL    |
| "74HC377PW,112"    | 935188440112 | 74HC377PW       |
| PDTA144ET,235      | 934031080235 | PDTA144ET       |
| PMPB11EN,115       | 934066621115 | PMPB11EN        |
| PRTR5VOU2AX,215    | 934059879215 | PRTR5VOU2AX     |
| "74LVC126APW,112"  | 935241120112 | 74LVC126APW     |
| BCX70G,215         | 933483650215 | BCX70G          |
| 74HC138PW,118      | 935174380118 | 74HC138PW       |
| PMEG3001EEFZ       | 934660269317 | PMEG3001EEF     |
| BZX84J-B75,115     | 934060977115 | BZX84J-B75      |
| 74LVC8T245BQ,118   | 935290138118 | 74LVC8T245BQ    |
| PBSS4360PASX       | 934069625115 | PBSS4360PAS     |
| 74AHC1G02GV/C4H    | 935303156125 | 74AHC1G02GV/C4  |
| BZX79-C4V7,133     | 933117710133 | BZX79-C4V7      |
| 74ALVT16373DGG,118 | 935209640118 | 74ALVT16373DGG  |
| 74HCT595PW-Q100,11 | 935298878118 | 74HCT595PW-Q100 |

|                      |              |                  |
|----------------------|--------------|------------------|
| "74LVC3G07GT,115"    | 935278933115 | 74LVC3G07GT      |
| BCX19,215            | 933209640215 | BCX19            |
| 74HCT4051DB,112      | 935173800112 | 74HCT4051DB      |
| BAS101,215           | 934060848215 | BAS101           |
| 74AVC2T45DC,125      | 935283716125 | 74AVC2T45DC      |
| PDTC123EM,315        | 934058288315 | PDTC123EM        |
| BSS84,215            | 933946360215 | BSS84            |
| 74LVC595ABQ,115      | 935282468115 | 74LVC595ABQ      |
| 74HC4051D-Q100,118   | 935298447118 | 74HC4051D-Q100   |
| BUK7Y98-80EX         | 934067426115 | BUK7Y98-80E      |
| 74HCT273PW-Q100J     | 935301459118 | 74HCT273PW-Q100  |
| "74LVC1G38GV,125"    | 935276662125 | 74LVC1G38GV      |
| HEF4060BT,653        | 933567150653 | HEF4060BT        |
| HEF4528BT,653        | 933373260653 | HEF4528BT        |
| 74AHCT125D,118       | 935262764118 | 74AHCT125D       |
| "74HCT4040D,652"     | 933715260652 | 74HCT4040D       |
| PTVS48VP1UP,115      | 934064185115 | PTVS48VP1UP      |
| BC859BW,115          | 934024310115 | BC859BW          |
| BZV85-C8V2,113       | 933500630113 | BZV85-C8V2       |
| "74HCT11PW,118"      | 935186350118 | 74HCT11PW        |
| 74HC595D,118         | 935009160118 | 74HC595D         |
| BZX84-C18,235        | 933388280235 | BZX84-C18        |
| PMBT3906MB,315       | 934065893315 | PMBT3906MB       |
| 74AHCT273PW,118      | 935263591118 | 74AHCT273PW      |
| BZT52-C18X           | 934071132115 | BZT52-C18        |
| PDTA124ET,215        | 934031070215 | PDTA124ET        |
| 74LVT126D,118        | 935209450118 | 74LVT126D        |
| BAS16J,135           | 934060935135 | BAS16J           |
| PMP4501Y,115         | 934059039115 | PMP4501Y         |
| "HEF4081BT,652"      | 933373090652 | HEF4081BT        |
| PBSS4250X,115        | 934057967115 | PBSS4250X        |
| "74HCT1G02GW-Q100,1" | 935298776125 | 74HCT1G02GW-Q100 |
| PCMF3HDMI2SZ         | 934070094087 | PCMF3HDMI2S      |
| 74LVC138APW,118      | 935260747118 | 74LVC138APW      |
| BUK7E2R6-60E,127     | 934066514127 | BUK7E2R6-60E     |
| 74LVT573PW,118       | 935176360118 | 74LVT573PW       |
| BZX384-B6V8,115      | 934057369115 | BZX384-B6V8      |
| BAT54C,215           | 933976370215 | BAT54C           |
| 74HC594DB,118        | 935190160118 | 74HC594DB        |
| PMEG6045ETPX         | 934067593115 | PMEG6045ETP      |
| BZT52-C24J           | 934071135118 | BZT52-C24        |
| PESD5V0V1BA,115      | 934063244115 | PESD5V0V1BA      |
| "74ALVC00D,112"      | 935269710112 | 74ALVC00D        |
| 74AHCT595BQ,115      | 935289563115 | 74AHCT595BQ      |
| BSP52,115            | 933969470115 | BSP52            |
| PDZ12BGWJ            | 934071049118 | PDZ12BGW         |

|                      |              |                  |
|----------------------|--------------|------------------|
| PMBD6050,235         | 933859220235 | PMBD6050         |
| BUK7608-55A,118      | 934055643118 | BUK7608-55A      |
| 74LVC1G27GM,115      | 935297282115 | 74LVC1G27GM      |
| BZT52H-B5V6,115      | 934064787115 | BZT52H-B5V6      |
| "74LVC16374ADGG,112" | 935235190112 | 74LVC16374ADGG   |
| 74AXP1T57GXX         | 935308434115 | 74AXP1T57GXX     |
| 74AHCT04BQ,115       | 935278824115 | 74AHCT04BQ       |
| PZT2907A,135         | 933982040135 | PZT2907A         |
| 74HC6323AD,118       | 935013710118 | 74HC6323AD       |
| 74HCT107D,653        | 933713930653 | 74HCT107D        |
| 1PS76SB17,115        | 934045400115 | 1PS76SB17        |
| "74AHCT1G04GV,125"   | 935271652125 | 74AHCT1G04GV     |
| 74LVT125BQ,115       | 935275705115 | 74LVT125BQ       |
| PMBT3946YPN,125      | 934061453125 | PMBT3946YPN      |
| 74AXP1G32GXH         | 935304048125 | 74AXP1G32GX      |
| BAT754S,215          | 934055732215 | BAT754S          |
| PMZ600UNEYL          | 934068653315 | PMZ600UNE        |
| 74LVC1G07GM,115      | 935277175115 | 74LVC1G07GM      |
| PMBD7000,235         | 933859210235 | PMBD7000         |
| 74ABT16245BDL,118    | 935184420118 | 74ABT16245BDL    |
| 74LVC3G34GN,115      | 935292257115 | 74LVC3G34GN      |
| PLVA668A,215         | 934017400215 | PLVA668A         |
| PUMH10,115           | 934056189115 | PUMH10           |
| BZT52H-C30,115       | 934059414115 | BZT52H-C30       |
| PESD5V0V1BLD,315     | 934065243315 | PESD5V0V1BLD     |
| BZX79-C8V2,133       | 933117770133 | BZX79-C8V2       |
| HEF4027BT,652        | 933372790652 | HEF4027BT        |
| 74LV05APWJ           | 935330428118 | 74LV05APW        |
| PDZ6.2B,115          | 934054854115 | PDZ6.2B          |
| BC869-16,115         | 934011130115 | BC869-16         |
| 74AHC139PW-Q100J     | 935300677118 | 74AHC139PW-Q100  |
| BAW101S,115          | 934057353115 | BAW101S          |
| PBSS305ND,115        | 934060014115 | PBSS305ND        |
| BCX70H,215           | 933478930215 | BCX70H           |
| 74HCT240PW,118       | 935189570118 | 74HCT240PW       |
| 74ALVC374PW,118      | 935269732118 | 74ALVC374PW      |
| "74LVC1G17GW-Q100,1" | 935298483125 | 74LVC1G17GW-Q100 |
| NZH12B,115           | 934064368115 | NZH12B           |
| 74HC4067BQ,118       | 935284681118 | 74HC4067BQ       |
| BZX79-B18,133        | 933166930133 | BZX79-B18        |
| BAV170VL             | 934032160235 | BAV170           |
| PMEG4005EJF          | 934059003135 | PMEG4005EJ       |
| PESD5Z12,115         | 934061268115 | PESD5Z12         |
| BSP41,115            | 933982010115 | BSP41            |
| BZX79-C15,113        | 933117830113 | BZX79-C15        |
| PMEG4005EPK,315      | 934065383315 | PMEG4005EPK      |

|                    |              |                |
|--------------------|--------------|----------------|
| "74HC4040D,652"    | 933714780652 | 74HC4040D      |
| BF570,215          | 933814420215 | BF570          |
| 74AUP1G57GXZ       | 935307121147 | 74AUP1G57GX    |
| BZX84-C7V5,235     | 933137430235 | BZX84-C7V5     |
| BZV49-C12,115      | 933605980115 | BZV49-C12      |
| PESD5VOL2UM,315    | 934057783315 | PESD5VOL2UM    |
| 74LVC374APW,118    | 935218680118 | 74LVC374APW    |
| PMDT670UPE,115     | 934065734115 | PMDT670UPE     |
| 74LV4051BQ,115     | 935285575115 | 74LV4051BQ     |
| 74LVC1G332GV,125   | 935282687125 | 74LVC1G332GV   |
| 74AUP1T04GXH       | 935690088125 | 74AUP1T04GX    |
| 74LVC240ABQ,115    | 935275101115 | 74LVC240ABQ    |
| "74AHCT1G14GV,125" | 935271664125 | 74AHCT1G14GV   |
| PUMH1,115          | 934054827115 | PUMH1          |
| PESD1USB3B/CX      | 934660293115 | PESD1USB3B/C   |
| "74HC4538D,652"    | 933714910652 | 74HC4538D      |
| BZV55-B30,115      | 933931800115 | BZV55-B30      |
| PMPB12UNEAX        | 934070923115 | PMPB12UNEA     |
| PMEG4015EPK,315    | 934065385315 | PMEG4015EPK    |
| BZX585-B2V7,115    | 934055857115 | BZX585-B2V7    |
| BZX84-A6V8,215     | 934023650215 | BZX84-A6V8     |
| BC850CW,135        | 934022080135 | BC850CW        |
| BZX585-C5V6,115    | 934055845115 | BZX585-C5V6    |
| PMP4201Y,115       | 934059038115 | PMP4201Y       |
| "74HC4053D,652"    | 933714840652 | 74HC4053D      |
| PUMX2,115          | 934059964115 | PUMX2          |
| 74HC164BQ,115      | 935291138115 | 74HC164BQ      |
| BZV90-C12,115      | 934014780115 | BZV90-C12      |
| PMLL4448,115       | 933834760115 | PMLL4448       |
| BZX585-B18,115     | 934057405115 | BZX585-B18     |
| BC849C,215         | 933589670215 | BC849C         |
| PMEG3005AESFYL     | 934068436315 | PMEG3005AESF   |
| 74LVC2G126DP,125   | 935272176125 | 74LVC2G126DP   |
| "74LVC1G06GV,125"  | 935272028125 | 74LVC1G06GV    |
| BCP53-16HX         | 934070288115 | BCP53-16H      |
| 74CBTLV3245PW,118  | 935293823118 | 74CBTLV3245PW  |
| 74HC3G34DC,125     | 935274777125 | 74HC3G34DC     |
| PESD9V0W1BCSFYL    | 934661168315 | PESD9V0W1BCSF  |
| "74LVCH2T45GT,115" | 935284762115 | 74LVCH2T45GT   |
| NZH30C,115         | 934064433115 | NZH30C         |
| PRTR5V0U2F,115     | 934061747115 | PRTR5V0U2F     |
| 74HC04DB-Q100J     | 935301531118 | 74HC04DB-Q100  |
| PSMN018-100PSFQ    | 934068748127 | PSMN018-100PSF |
| PMBT2907AQAZ       | 934660462147 | PMBT2907AQA    |
| BZX384-C20,115     | 934057647115 | BZX384-C20     |
| HEF4040BT,653      | 933372850653 | HEF4040BT      |



|                      |              |                |
|----------------------|--------------|----------------|
| BAT54XY,115          | 934059127115 | BAT54XY        |
| BCW30,215            | 933082741215 | BCW30          |
| PESD5V0U2BM,315      | 934061947315 | PESD5V0U2BM    |
| BCX56,115            | 933272330115 | BCX56          |
| BZX79-C7V5,133       | 933117760133 | BZX79-C7V5     |
| PTVS30VP1UP,115      | 934064178115 | PTVS30VP1UP    |
| "74LVC16373ADGG,112" | 935235170112 | 74LVC16373ADGG |
| 74HC21D,653          | 933756870653 | 74HC21D        |
| HEF4052BT,653        | 933372950653 | HEF4052BT      |
| PMEG045V150EPDZ      | 934067178139 | PMEG045V150EPD |
| 74HC595PW,118        | 935188520118 | 74HC595PW      |
| PDTA143ZU,115        | 934057537115 | PDTA143ZU      |
| PDTC144TU,115        | 934057531115 | PDTC144TU      |
| 74LVT245D,118        | 935155210118 | 74LVT245D      |
| PMEG2005BELD,315     | 934066026315 | PMEG2005BELD   |
| PTVS7V0S1UR,115      | 934061342115 | PTVS7V0S1UR    |
| BZT52-C5V6J          | 934071109118 | BZT52-C5V6     |
| 1N4746A,133          | 933931720133 | 1N4746A        |
| 74HC151D,653         | 933713700653 | 74HC151D       |
| BCP55-16F            | 933917230135 | BCP55-16       |
| PBSS4260PANSX        | 934069678115 | PBSS4260PANS   |
| PBSS5350X,135        | 934055948135 | PBSS5350X      |
| 74VHCT02D,118        | 935289661118 | 74VHCT02D      |
| "74AHC04D,112"       | 935263040112 | 74AHC04D       |
| "74AHC595D,112"      | 935265567112 | 74AHC595D      |
| PDTA144EM,315        | 934057169315 | PDTA144EM      |
| BCP69,115            | 933969380115 | BCP69          |
| PMEG4010ETR,115      | 934066837115 | PMEG4010ETR    |
| BZB84-B68,215        | 934063362215 | BZB84-B68      |
| 74LVC1G123GS,115     | 935295675115 | 74LVC1G123GS   |
| 74AUP1T14GXH         | 935690086125 | 74AUP1T14GX    |
| "74LVC1G38GX,125"    | 935298382125 | 74LVC1G38GX    |
| 74AVC4T245D,118      | 935288131118 | 74AVC4T245D    |
| PSMN3R0-60PS,127     | 934064275127 | PSMN3R0-60PS   |
| BAV70S,135           | 934045740135 | BAV70S         |
| PBSS5630PA,115       | 934063496115 | PBSS5630PA     |
| BAS21H,115           | 934059307115 | BAS21H         |
| BZV85-C30,133        | 933500760133 | BZV85-C30      |
| PRMH11Z              | 934070176147 | PRMH11         |
| BZX585-B4V7,115      | 934055863115 | BZX585-B4V7    |
| BAV103,115           | 933699360115 | BAV103         |
| BCX53-10,115         | 933663060115 | BCX53-10       |
| PMEG4005AEA,115      | 934057752115 | PMEG4005AEA    |
| PSMN016-100YS,115    | 934064533115 | PSMN016-100YS  |
| PESD5V0V1BSF,315     | 934064598315 | PESD5V0V1BSF   |
| PSMN016-100BS,118    | 934066209118 | PSMN016-100BS  |

|                    |              |                 |
|--------------------|--------------|-----------------|
| 74LVC574ABQ,115    | 935273517115 | 74LVC574ABQ     |
| "74LV4053D,112"    | 935175860112 | 74LV4053D       |
| "74AHCT08PW,118"   | 935262677118 | 74AHCT08PW      |
| 74AHCT04APWJ       | 935338676118 | 74AHCT04APW     |
| 74AHCT14APWJ       | 935308206118 | 74AHCT14APW     |
| BZV55-C36,115      | 933699650115 | BZV55-C36       |
| BCV62B,215         | 933792140215 | BCV62B          |
| PBSS5360PASX       | 934069626115 | PBSS5360PAS     |
| "74LVCH1T45GM,132" | 935284755132 | 74LVCH1T45GM    |
| 74LVT16373ADL,118  | 935183110118 | 74LVT16373ADL   |
| BF820W,115         | 934033470115 | BF820W          |
| HEF4051BTT-Q100,11 | 935298521118 | HEF4051BTT-Q100 |
| 1N4749A,113        | 933931750113 | 1N4749A         |
| BZV85-C39,133      | 933500790133 | BZV85-C39       |
| BZX84-A5V6,215     | 934018180215 | BZX84-A5V6      |
| 74HCT4051BQ,115    | 935277423115 | 74HCT4051BQ     |
| 74HC374D,653       | 933713480653 | 74HC374D        |
| BZX84J-B6V8,115    | 934060976115 | BZX84J-B6V8     |
| PZU15B,115         | 934059769115 | PZU15B          |
| BZV55-C47,115      | 933699710115 | BZV55-C47       |
| BZX84J-B10,115     | 934060936115 | BZX84J-B10      |
| PMEG045V100EPDZ    | 934067176146 | PMEG045V100EPD  |
| BC856BMBYL         | 934069543315 | BC856BMB        |
| 74HC02PW/C4J       | 935301818118 | 74HC02PW/C4     |
| BAS16W,115         | 934022380115 | BAS16W          |
| 74HC7014D,118      | 935059840118 | 74HC7014D       |
| 74HCT573D,652      | 933713570652 | 74HCT573D       |
| 74AHCU04PW,118     | 935263043118 | 74AHCU04PW      |
| BCV62B,235         | 933792140235 | BCV62B          |
| 74HCT245D,653      | 933713590653 | 74HCT245D       |
| PDTA144EU,115      | 934044130115 | PDTA144EU       |
| PCMF1USB3B/CZ      | 934660288087 | PCMF1USB3B/C    |
| PUMD4,115          | 934057889115 | PUMD4           |
| PMST2907A,115      | 934044580115 | PMST2907A       |
| 74HCT125D,652      | 933757010652 | 74HCT125D       |
| PESD5V0L1USF,315   | 934065151315 | PESD5V0L1USF    |
| PDZ13B,115         | 934054862115 | PDZ13B          |
| BC847AW,115        | 934021760115 | BC847AW         |
| BZX884-B5V6,315    | 934057193315 | BZX884-B5V6     |
| PSMN011-60MSX      | 934067518115 | PSMN011-60MS    |
| 74HCT193DB,118     | 935189730118 | 74HCT193DB      |
| PUMB10,115         | 934057882115 | PUMB10          |
| 74HCT595PW,118     | 935200990118 | 74HCT595PW      |
| BZX84-C15,215      | 933388260215 | BZX84-C15       |
| BAW56S,115         | 934045730115 | BAW56S          |
| PDZ15B,115         | 934054863115 | PDZ15B          |

|                    |              |                 |
|--------------------|--------------|-----------------|
| BZX84-C27,215      | 933388320215 | BZX84-C27       |
| BST60,115          | 933644280115 | BST60           |
| 74HCT02BQ,115      | 935287821115 | 74HCT02BQ       |
| 74LVC2G32DP,125    | 935273583125 | 74LVC2G32DP     |
| 74HC7014D-Q100J    | 935301183118 | 74HC7014D-Q100  |
| BUK7M17-80EX       | 934070044115 | BUK7M17-80E     |
| PESD5V0U1BB,115    | 934060855115 | PESD5V0U1BB     |
| 74LVT14D,112       | 935209170112 | 74LVT14D        |
| BSS123,215         | 933946340215 | BSS123          |
| 74LVC162244ADGG:11 | 935237680118 | 74LVC162244ADGG |
| BZV55-C12,115      | 933699540115 | BZV55-C12       |
| "74LVC1G99GT,115"  | 935284437115 | 74LVC1G99GT     |
| 74LVT02DB,118      | 935208960118 | 74LVT02DB       |
| CBT3125D,118       | 935270672118 | CBT3125D        |
| BZT52H-B3V6,115    | 934064782115 | BZT52H-B3V6     |
| PMEG4030ER,115     | 934061467115 | PMEG4030ER      |
| 74LV1T00GXH        | 935690115125 | 74LV1T00GX      |
| 1PS79SB30,115      | 934056394115 | 1PS79SB30       |
| PBSS302NZ,135      | 934059043135 | PBSS302NZ       |
| TL431AFDT,215      | 935293275215 | TL431AFDT       |
| TDZ4V3J,115        | 934065707115 | TDZ4V3J         |
| "74HCT4316D,112"   | 933757470112 | 74HCT4316D      |
| PMEG3010ER,115     | 934061458115 | PMEG3010ER      |
| PTVS15VS1UTR,115   | 934065488115 | PTVS15VS1UTR    |
| "74LVC00APW,118"   | 935249980118 | 74LVC00APW      |
| BCP56-10TF         | 934070118135 | BCP56-10T       |
| PDTD113ZT,215      | 934058981215 | PDTD113ZT       |
| "74LVC2G07GW,125"  | 935274165125 | 74LVC2G07GW     |
| "74LVC1G97GW,125"  | 935293191125 | 74LVC1G97GW     |
| PBSS9110T,215      | 934057669215 | PBSS9110T       |
| IP4234CZ6,125      | 934063369125 | IP4234CZ6       |
| PBHV8540T,215      | 934061414215 | PBHV8540T       |
| 74HC4060BQ-Q100,11 | 935298891115 | 74HC4060BQ-Q100 |
| 74HCT86D-Q100,118  | 935298888118 | 74HCT86D-Q100   |
| PESD1CANVL         | 934059097235 | PESD1CAN        |
| "HEF4069UBTT,118"  | 935283025118 | HEF4069UBTT     |
| PMZB290UNE2YL      | 934068612315 | PMZB290UNE2     |
| PMPB43XPEAX        | 934070929115 | PMPB43XPEA      |
| BC847RAPNZ         | 934070162147 | BC847RAPN       |
| PMXB75UPEZ         | 934067153147 | PMXB75UPE       |
| PESD24VS4UD,115    | 934059305115 | PESD24VS4UD     |
| PESD15VS2UAT,215   | 934058065215 | PESD15VS2UAT    |
| BC847BPN,115       | 934042530115 | BC847BPN        |
| BZX884-B8V2,315    | 934057202315 | BZX884-B8V2     |
| 74AUP2G0604GMH     | 935299653125 | 74AUP2G0604GM   |
| PSMN019-100YLX     | 934069905115 | PSMN019-100YL   |

|                     |              |                |
|---------------------|--------------|----------------|
| 74LVC1G17GF,132     | 935282415132 | 74LVC1G17GF    |
| BZX84-A5V1,235      | 934013620235 | BZX84-A5V1     |
| BUK92150-55A,118    | 934056250118 | BUK92150-55A   |
| BST50,115           | 933644250115 | BST50          |
| PMBD914,235         | 933856870235 | PMBD914        |
| BUK9Y25-60E,115     | 934067023115 | BUK9Y25-60E    |
| BSP51,115           | 933986340115 | BSP51          |
| 74HCT175D,652       | 933715060652 | 74HCT175D      |
| PESD5Z2.5,115       | 934061263115 | PESD5Z2.5      |
| BUK7Y21-40EX        | 934067434115 | BUK7Y21-40E    |
| PMEG045T150EPDAZ    | 934068775139 | PMEG045T150EPD |
| 74AHCT125D,112      | 935262764112 | 74AHCT125D     |
| "74AUP2G3404GW,125" | 935297794125 | 74AUP2G3404GW  |
| "74AUP1T57GW,125"   | 935280464125 | 74AUP1T57GW    |
| "74LVC1G34GX,125"   | 935298381125 | 74LVC1G34GX    |
| "74HCT241PW,112"    | 935174600112 | 74HCT241PW     |
| BUK9832-55A/CUX     | 934068285115 | BUK9832-55A/CU |
| 74HC574D,653        | 933715520653 | 74HC574D       |
| PDTC124TT,215       | 934057528215 | PDTC124TT      |
| NZX3V3B,133         | 934062015133 | NZX3V3B        |
| PMEG2002ESF,315     | 934065235315 | PMEG2002ESF    |
| HEF4051BT,653       | 933372940653 | HEF4051BT      |
| BZA456A,135         | 934045760135 | BZA456A        |
| 74LV123D,118        | 935210250118 | 74LV123D       |
| BZX84-B39,215       | 933770480215 | BZX84-B39      |
| BSH105,215          | 934054715215 | BSH105         |
| "74HCT6323AD,112"   | 935013720112 | 74HCT6323AD    |
| 74HCT273DB,118      | 935183580118 | 74HCT273DB     |
| 74HC112PW,118       | 935198300118 | 74HC112PW      |
| BZT52-C2V7X         | 934071098115 | BZT52-C2V7     |
| 74LV04D,118         | 935063130118 | 74LV04D        |
| 74LVC2G14GF,132     | 935282433132 | 74LVC2G14GF    |
| 74HC137D,653        | 933757070653 | 74HC137D       |
| "74AUP1G08GM,132"   | 935279021132 | 74AUP1G08GM    |
| BZV49-C62,115       | 933606150115 | BZV49-C62      |
| BZV55-B5V1,135      | 933827680135 | BZV55-B5V1     |
| PMBT6428,215        | 933813800215 | PMBT6428       |
| PZU2.7B2A,115       | 934062386115 | PZU2.7B2A      |
| BZT52-C13X          | 934071128115 | BZT52-C13      |
| BZX84J-B5V1,115     | 934060969115 | BZX84J-B5V1    |
| BC847,235           | 933589570235 | BC847          |
| BAS40-04W,115       | 934044290115 | BAS40-04W      |
| BZX884-C3V3,315     | 934057211315 | BZX884-C3V3    |
| 74HC123D-Q100,118   | 935299042118 | 74HC123D-Q100  |
| 74HC00PW,118        | 935174110118 | 74HC00PW       |
| BST62,115           | 933644300115 | BST62          |

|                      |              |                   |
|----------------------|--------------|-------------------|
| BC846DS,115          | 934063468115 | BC846DS           |
| BZV85-C12,133        | 933500670133 | BZV85-C12         |
| PBSS4041PX,115       | 934063405115 | PBSS4041PX        |
| BZT52-C7V5J          | 934071113118 | BZT52-C7V5        |
| PUMH9,115            | 934055557115 | PUMH9             |
| PMBT5551,235         | 933821840235 | PMBT5551          |
| PEMD12,115           | 934056859115 | PEMD12            |
| BUK7Y12-55B,115      | 934063307115 | BUK7Y12-55B       |
| PMV55ENEAR           | 934068714215 | PMV55ENEA         |
| BZX100A,115          | 934060843115 | BZX100A           |
| 74HCT2G14GV,125      | 935281017125 | 74HCT2G14GV       |
| PDZ4.3B,115          | 934054850115 | PDZ4.3B           |
| "74LVC1G157GW,125"   | 935278315125 | 74LVC1G157GW      |
| 74LV138DB,118        | 935165960118 | 74LV138DB         |
| "74HCT165D,652"      | 933713790652 | 74HCT165D         |
| BC817-25,235         | 933628630235 | BC817-25          |
| BZX84-A12,215        | 934011770215 | BZX84-A12         |
| "HEF4894BT,112"      | 935194380112 | HEF4894BT         |
| "74HC4520D,112"      | 933714900112 | 74HC4520D         |
| 74LVT14PW,112        | 935209190112 | 74LVT14PW         |
| "74LV132PW,118"      | 935230100118 | 74LV132PW         |
| BZX84-B15,215        | 933770390215 | BZX84-B15         |
| BUK7M3R3-40HX        | 934660781115 | BUK7M3R3-40H      |
| 74LVC574APW,118      | 935219050118 | 74LVC574APW       |
| BCW72,215            | 933149400215 | BCW72             |
| NZH7V5C,115          | 934064363115 | NZH7V5C           |
| BAS101S,215          | 934060849215 | BAS101S           |
| HEF4051BT-Q100,118   | 935298519118 | HEF4051BT-Q100    |
| PSMN6R9-100YSFX      | 934071219115 | PSMN6R9-100YSF    |
| BZV90-C5V1,115       | 934014690115 | BZV90-C5V1        |
| BC857CMB,315         | 934065891315 | BC857CMB          |
| "74AHC1G07GW,125"    | 935267470125 | 74AHC1G07GW       |
| BZX79-C3V3,133       | 933117670133 | BZX79-C3V3        |
| 74HC151D-Q100,118    | 935298755118 | 74HC151D-Q100     |
| BZX84-C36,235        | 933388350235 | BZX84-C36         |
| BZV85-C13,133        | 933500680133 | BZV85-C13         |
| "74LVC1G125GW-Q100," | 935298478125 | 74LVC1G125GW-Q100 |
| BZX84J-C33,115       | 934060997115 | BZX84J-C33        |
| BZX84J-C6V8,115      | 934061017115 | BZX84J-C6V8       |
| BC817-16W,135        | 934021920135 | BC817-16W         |
| 74AHCT244APWJ        | 935308262118 | 74AHCT244APW      |
| BZX384-C11,115       | 934057641115 | BZX384-C11        |
| PSMN3R5-80PS,127     | 934065169127 | PSMN3R5-80PS      |
| 74HC4020D,652        | 933714770652 | 74HC4020D         |
| PSMN012-60YS,115     | 934064401115 | PSMN012-60YS      |
| PSMN2R0-30PL,127     | 934063917127 | PSMN2R0-30PL      |

|                     |              |                  |
|---------------------|--------------|------------------|
| BCV47,215           | 933932320215 | BCV47            |
| "74AHC1G04GV,125"   | 935271653125 | 74AHC1G04GV      |
| PBSS4350X,135       | 934055628135 | PBSS4350X        |
| PEMH1,115           | 934056862115 | PEMH1            |
| 74HCT10D,653        | 933714360653 | 74HCT10D         |
| 74LV1T34GXH         | 935690204125 | 74LV1T34GX       |
| PESD5V0L5UV,125     | 934057797125 | PESD5V0L5UV      |
| 74HCT221D,118       | 933715110118 | 74HCT221D        |
| 74HC2GU04GW-Q100H   | 935304871125 | 74HC2GU04GW-Q100 |
| "74HC573PW,112"     | 935187000112 | 74HC573PW        |
| BC846BW,135         | 934021740135 | BC846BW          |
| 74LVC541APW,118     | 935260903118 | 74LVC541APW      |
| PESD30VF1BLYL       | 934660742315 | PESD30VF1BL      |
| BC55PASX            | 934068127115 | BC55PAS          |
| PEMH4,115           | 934056710115 | PEMH4            |
| PDZ3.6B,115         | 934054848115 | PDZ3.6B          |
| BZX585-B7V5,135     | 934055868135 | BZX585-B7V5      |
| "74AHC74D,112"      | 935263078112 | 74AHC74D         |
| PBSS5130T,215       | 934057988215 | PBSS5130T        |
| BZB984-C4V3,115     | 934057237115 | BZB984-C4V3      |
| PDZ9.1B,115         | 934054858115 | PDZ9.1B          |
| 74AHC08BQ-Q100X     | 935300983115 | 74AHC08BQ-Q100   |
| PBSS4140U,115       | 934056514115 | PBSS4140U        |
| PZU5.1B1A,115       | 934062776115 | PZU5.1B1A        |
| BCX52-10,115        | 933663050115 | BCX52-10         |
| BZV55-C6V8,135      | 933699480135 | BZV55-C6V8       |
| BCV61,215           | 933677220215 | BCV61            |
| 74AHC02D,118        | 935262692118 | 74AHC02D         |
| PMBTA42,235         | 933776090235 | PMBTA42          |
| BC857BW,135         | 934021850135 | BC857BW          |
| BSS84AKS,115        | 934065308115 | BSS84AKS         |
| PMEG3020CPA,115     | 934064347115 | PMEG3020CPA      |
| BC857BM,315         | 934057147315 | BC857BM          |
| "74AUP1G126GW,125"  | 935279056125 | 74AUP1G126GW     |
| BZX384-C9V1,115     | 934057639115 | BZX384-C9V1      |
| PBHV9040Z,115       | 934061409115 | PBHV9040Z        |
| "74LVC1G07GW,125"   | 935266681125 | 74LVC1G07GW      |
| BZV55-B4V7,115      | 933827670115 | BZV55-B4V7       |
| TL431BFDT,215       | 935293276215 | TL431BFDT        |
| 74LVC1GU04GM,115    | 935277185115 | 74LVC1GU04GM     |
| "74AHCT1G125GV,125" | 935271660125 | 74AHCT1G125GV    |
| "74LVC1G08GX,125"   | 935298378125 | 74LVC1G08GX      |
| 74LVC1G175GM,115    | 935277208115 | 74LVC1G175GM     |
| "74LVC126AD,112"    | 935241100112 | 74LVC126AD       |
| BC807-16,235        | 933628560235 | BC807-16         |
| PMN42XPEAX          | 934068548115 | PMN42XPEA        |

|                    |              |                |
|--------------------|--------------|----------------|
| "74AUP1G32GX,125"  | 935298362125 | 74AUP1G32GX    |
| BZT52H-C39,115     | 934059417115 | BZT52H-C39     |
| PMEG3002AEB,115    | 934057098115 | PMEG3002AEB    |
| PESD36VS2UT,215    | 934063585215 | PESD36VS2UT    |
| PBSS306NZ,135      | 934059047135 | PBSS306NZ      |
| 1N4732A,113        | 933931580113 | 1N4732A        |
| "74HC08D,652"      | 933714270652 | 74HC08D        |
| PZU3.9B2A,115      | 934062479115 | PZU3.9B2A      |
| "74AHCT1G86GW,125" | 935263005125 | 74AHCT1G86GW   |
| 74AXP1G58GMH       | 935301599125 | 74AXP1G58GM    |
| 74LVT2245PW,118    | 935211430118 | 74LVT2245PW    |
| PMF370XN,115       | 934057727115 | PMF370XN       |
| BC56PA,115         | 934065745115 | BC56PA         |
| "74AUP1G09GS,132"  | 935292835132 | 74AUP1G09GS    |
| PBSS2515VS,115     | 934056768115 | PBSS2515VS     |
| 74LVC244ADB,118    | 935210410118 | 74LVC244ADB    |
| 74LV4094D,118      | 935088040118 | 74LV4094D      |
| "74HC4094D,652"    | 933714850652 | 74HC4094D      |
| "74AUP1G97GW,125"  | 935279962125 | 74AUP1G97GW    |
| 74LVC138ADB,112    | 935260746112 | 74LVC138ADB    |
| 74HC2G04GV,125     | 935281022125 | 74HC2G04GV     |
| PSMN7R0-100PS,127  | 934064289127 | PSMN7R0-100PS  |
| PBSS5350SS,115     | 934061032115 | PBSS5350SS     |
| "74LVC1G74GT,115"  | 935278917115 | 74LVC1G74GT    |
| BC857,235          | 933589740235 | BC857          |
| PMZ950UPELYL       | 934070428315 | PMZ950UPEL     |
| BC847CW,115        | 934021780115 | BC847CW        |
| "74LVC1G98GW,125"  | 935293197125 | 74LVC1G98GW    |
| "74LVT244AD,112"   | 935167130112 | 74LVT244AD     |
| BC856B/DG/B4R      | 934068364215 | BC856B/DG/B4   |
| BCP53-16,115       | 933917350115 | BCP53-16       |
| PDZ4.7BGWX         | 934071087115 | PDZ4.7BGW      |
| 74HC125D,653       | 933756990653 | 74HC125D       |
| BZX84-C11,215      | 933137470215 | BZX84-C11      |
| BZV85-C5V1,133     | 933500580133 | BZV85-C5V1     |
| BCW69,215          | 933149370215 | BCW69          |
| 74AHC132D-Q100J    | 935302483118 | 74AHC132D-Q100 |
| 74ABT244PW,118     | 935176420118 | 74ABT244PW     |
| 74ALVC16245DL,118  | 935187800118 | 74ALVC16245DL  |
| PBSS4350SPN,115    | 934061033115 | PBSS4350SPN    |
| 74AVCH4T245GU,115  | 935293386115 | 74AVCH4T245GU  |
| BZX84J-C3V9,115    | 934061004115 | BZX84J-C3V9    |
| PESD1USB3SZ        | 934069683087 | PESD1USB3S     |
| BUK7K89-100EX      | 934067945115 | BUK7K89-100E   |
| "74AHCT1G00GW,125" | 935262749125 | 74AHCT1G00GW   |
| PMPB33XN,115       | 934066869115 | PMPB33XN       |

|                     |              |                    |
|---------------------|--------------|--------------------|
| TDZ18J,115          | 934065792115 | TDZ18J             |
| BUK7J1R0-40HX       | 934660371115 | BUK7J1R0-40H       |
| 74AHC377PW,118      | 935267995118 | 74AHC377PW         |
| 74AHC1G4214GW-Q10H  | 935690497125 | 74AHC1G4214GW-Q100 |
| PMXB350UPEZ         | 934067152147 | PMXB350UPE         |
| BAS85,135           | 933876540135 | BAS85              |
| 74CBTLV3861BQ,118   | 935294091118 | 74CBTLV3861BQ      |
| BZX384-C2V4,115     | 934057625115 | BZX384-C2V4        |
| PZU5.6B2,115        | 934059819115 | PZU5.6B2           |
| "74HC123PW,112"     | 935186860112 | 74HC123PW          |
| "74HC32PW-Q100,118" | 935298924118 | 74HC32PW-Q100      |
| PDZ20B,115          | 934054866115 | PDZ20B             |
| 2PB709ART,215       | 934061218215 | 2PB709ART          |
| 74LVC1G123DP,125    | 935295667125 | 74LVC1G123DP       |
| PTVS9V0S1UR,115     | 934061346115 | PTVS9V0S1UR        |
| PESD7V0C1BSFYL      | 934660139315 | PESD7V0C1BSF       |
| PHP191NQ06LT,127    | 934058544127 | PHP191NQ06LT       |
| NZH4V7B,115         | 934064357115 | NZH4V7B            |
| "74HC4066PW,112"    | 935175000112 | 74HC4066PW         |
| "74HCT368D,652"     | 933715180652 | 74HCT368D          |
| 74HC14DB,118        | 935174460118 | 74HC14DB           |
| "74AUP1G332GW,125"  | 935280751125 | 74AUP1G332GW       |
| PESD3V3L5UF,115     | 934061195115 | PESD3V3L5UF        |
| 74VHC595PW,118      | 935289513118 | 74VHC595PW         |
| BZX585-B36,115      | 934057412115 | BZX585-B36         |
| HEF4052BTT-Q100,11  | 935298523118 | HEF4052BTT-Q100    |
| BUK9Y65-100E,115    | 934067039115 | BUK9Y65-100E       |
| PESD2USB3SZ         | 934069684087 | PESD2USB3S         |
| BZX384-B33,115      | 934057385115 | BZX384-B33         |
| PMZB320UPEYL        | 934068607315 | PMZB320UPE         |
| 74LVC138ABQ,115     | 935273334115 | 74LVC138ABQ        |
| PTVS5V0Z1BSCYL      | 934660891315 | PTVS5V0Z1BSC       |
| 1N4736A,133         | 933931620133 | 1N4736A            |
| TDZ20J,115          | 934065793115 | TDZ20J             |
| BAW156VL            | 934032650235 | BAW156             |
| 74HCT4046ADB,118    | 935174940118 | 74HCT4046ADB       |
| 74HC14D-Q100,118    | 935298441118 | 74HC14D-Q100       |
| PMEG3030EP,115      | 934061474115 | PMEG3030EP         |
| BZX79-B33,133       | 933166990133 | BZX79-B33          |
| "74AUP1G125GM,132"  | 935279055132 | 74AUP1G125GM       |
| 74LVC125APW,118     | 935231720118 | 74LVC125APW        |
| 74AUP1G79GM,115     | 935279047115 | 74AUP1G79GM        |
| PDTC115EUF          | 934057289135 | PDTC115EU          |
| 74HCT368D,653       | 933715180653 | 74HCT368D          |
| BAS70-05,215        | 933834100215 | BAS70-05           |
| "74LVC1T45GW,125"   | 935284751125 | 74LVC1T45GW        |



|                    |              |                  |
|--------------------|--------------|------------------|
| PRMD13Z            | 934070173147 | PRMD13           |
| PDZ27B,115         | 934054869115 | PDZ27B           |
| PESD5V0S1USF,315   | 934065149315 | PESD5V0S1USF     |
| 74HC238PW,118      | 935189000118 | 74HC238PW        |
| BCV64B,215         | 933835240215 | BCV64B           |
| 74LVT125DB,118     | 935180980118 | 74LVT125DB       |
| PMEG40T10ERX       | 934070412115 | PMEG40T10ER      |
| BZT52-C15X         | 934071129115 | BZT52-C15        |
| PMCM4401VNEAZ      | 934068854084 | PMCM4401VNE      |
| 74LVC1G11GW-Q100H  | 935299287125 | 74LVC1G11GW-Q100 |
| BZT52H-C75,115     | 934059425115 | BZT52H-C75       |
| PBHV8540Z,115      | 934061408115 | PBHV8540Z        |
| BZA962AVL,115      | 934057298115 | BZA962AVL        |
| BCP55-10,115       | 933917220115 | BCP55-10         |
| 74AUP1G157GM,115   | 935279971115 | 74AUP1G157GM     |
| 74LV1T32GXH        | 935690202125 | 74LV1T32GX       |
| PSMN4R2-60PLQ      | 934067502127 | PSMN4R2-60PL     |
| BAS521,115         | 934057766115 | BAS521           |
| 74AXP2G14GMH       | 935304096125 | 74AXP2G14GM      |
| "74LVC1G66GW,125"  | 935269058125 | 74LVC1G66GW      |
| "74AUP1G126GX,125" | 935298369125 | 74AUP1G126GX     |
| 74HCT08D,653       | 933714350653 | 74HCT08D         |
| PESD12VS2UT,215    | 934057610215 | PESD12VS2UT      |
| BAV70/DG/B4VL      | 934068405235 | BAV70/DG/B4      |
| 74AHCT3G14DC,125   | 935275104125 | 74AHCT3G14DC     |
| PESD24VS2UT,215    | 934057612215 | PESD24VS2UT      |
| "74HC1GU04GW,125"  | 935261178125 | 74HC1GU04GW      |
| BZB84-B3V9,215     | 934061706215 | BZB84-B3V9       |
| BSH205G2R          | 934068496215 | BSH205G2         |
| 74AHCV14APWJ       | 935308207118 | 74AHCV14APW      |
| "74LVC2244APW,112" | 935213570112 | 74LVC2244APW     |
| "74LVC2G74GT,115"  | 935280389115 | 74LVC2G74GT      |
| 74HC04D,653        | 933714260653 | 74HC04D          |
| BC857CW,115        | 934021860115 | BC857CW          |
| PDTC143TT,215      | 934055064215 | PDTC143TT        |
| HEF4073BT,652      | 933373040652 | HEF4073BT        |
| BZX84-C51,215      | 933388390215 | BZX84-C51        |
| PMEG045V100EPDAZ   | 934067176139 | PMEG045V100EPD   |
| PBSS5240T,215      | 934056607215 | PBSS5240T        |
| PZT4401,115        | 934012100115 | PZT4401          |
| 1N4743A,113        | 933931690113 | 1N4743A          |
| BZV55-B4V3,115     | 933827660115 | BZV55-B4V3       |
| PESD15VS5UD,115    | 934058435115 | PESD15VS5UD      |
| 74HC4851PW-Q100,11 | 935298463118 | 74HC4851PW-Q100  |
| 74AXP1G97GXZ       | 935307131147 | 74AXP1G97GX      |
| 74HC125PW,112      | 935174340112 | 74HC125PW        |

|                    |              |                   |
|--------------------|--------------|-------------------|
| BZV90-C3V0,115     | 934014630115 | BZV90-C3V0        |
| PDZ3.9B,115        | 934054849115 | PDZ3.9B           |
| "74HC158D,652"     | 933713760652 | 74HC158D          |
| 74LVT244AD,118     | 935167130118 | 74LVT244AD        |
| 74CB3Q3257PW-Q100J | 935690808118 | 74CB3Q3257PW-Q100 |
| "74HC157PW,112"    | 935186880112 | 74HC157PW         |
| 74AVCH4T245D,118   | 935288132118 | 74AVCH4T245D      |
| BCP53-16TX         | 934070116115 | BCP53-16T         |
| PMBT5550,215       | 933845720215 | PMBT5550          |
| 74HC1G14GV-Q100H   | 935299223125 | 74HC1G14GV-Q100   |
| NZH20C,115         | 934064374115 | NZH20C            |
| 74AHC244PW,118     | 935262002118 | 74AHC244PW        |
| 74LVC245ADB,118    | 935211530118 | 74LVC245ADB       |
| PMBTA92,235        | 933776100235 | PMBTA92           |
| BAS516,315         | 934055217315 | BAS516            |
| BZT52H-B3V3,115    | 934064781115 | BZT52H-B3V3       |
| BCX71J,235         | 933483670235 | BCX71J            |
| BZV85-C11,133      | 933500660133 | BZV85-C11         |
| 74HCT154DB,112     | 935182550112 | 74HCT154DB        |
| BUK7Y22-100EX      | 934067443115 | BUK7Y22-100E      |
| "74HC132PW,112"    | 935185800112 | 74HC132PW         |
| PMEG3005EB,115     | 934060117115 | PMEG3005EB        |
| BZX84-C6V8,215     | 933137420215 | BZX84-C6V8        |
| PUMD6,115          | 934055430115 | PUMD6             |
| "74HC4049D,652"    | 933714800652 | 74HC4049D         |
| PMV50ENEAR         | 934068715215 | PMV50ENEA         |
| "74HC4066D,652"    | 933714420652 | 74HC4066D         |
| PMV37ENEAR         | 934661155215 | PMV37ENEA         |
| BZV55-B22,115      | 933931770115 | BZV55-B22         |
| 74LVT16240ADGG,118 | 935202860118 | 74LVT16240ADGG    |
| 74LVC244ADB,112    | 935210410112 | 74LVC244ADB       |
| 74LV4051DB,118     | 935190980118 | 74LV4051DB        |
| BZV85-C33,133      | 933500770133 | BZV85-C33         |
| 74LV1T125GWH       | 935690104125 | 74LV1T125GW       |
| "74AHCT86PW,118"   | 935263555118 | 74AHCT86PW        |
| 74HC390PW,118      | 935189060118 | 74HC390PW         |
| BSH201,215         | 934054717215 | BSH201            |
| BUK7610-100B,118   | 934057113118 | BUK7610-100B      |
| PMEG3010EH,115     | 934059031115 | PMEG3010EH        |
| "74HC390PW,112"    | 935189060112 | 74HC390PW         |
| "74HC4052PW,112"   | 935187490112 | 74HC4052PW        |
| PESD5V0L5UY,125    | 934057803125 | PESD5V0L5UY       |
| BUK9M9R1-40EX      | 934070082115 | BUK9M9R1-40E      |
| 74HC154DB,112      | 935182570112 | 74HC154DB         |
| PMCM650CUNEZ       | 934070441023 | PMCM650CUNE       |
| 74HC4094D,653      | 933714850653 | 74HC4094D         |

BAS321JX  
PESD2CAN,215  
PBSS5160PAPX  
PMEG3010EGWJ  
74LVC08APW,112

934660321115  
934060118215  
934068941115  
934070452118  
935250040112

BAS321J  
PESD2CAN  
PBSS5160PAPS  
PMEG3010EGW  
74LVC08APW

## Information Notification

New outer box label CIN 202002003I

# Information Notification CIN 202002003I

## New outer box Label

### **Introduction:**

Nexperia will change Nexperia outer box label to achieve:



- Compliancy to ECIA (Electronics Component Industry Association) label standardization
- Quality and operation efficiency improvements
- Environmentally friendly reduce material use and waste

**Effective date: 17<sup>th</sup> Aug 2020**

**Details of current and new label can be found on next slides**

# Nexperia New Outer Box Label

Details current versus new outer box label

| Current outer box label  | New Outer box label   |
|--|---|
|  <p>REF NR. HK5133033</p> <p>CARTON 0001/0001</p> <p>TTL QTY 2500 PC G.W. .95 (KGS)</p> <p>TTL INNER BOX 1 N.T. .17 (KGS)</p> <p>01_10_11_BB1_W</p> <p>SHIP TO (998217)</p> <p>HK513303300010001</p> <p>CONT SIZE 911</p> <p>LABEL SET L1107</p> <p>LP NR. 5133033 SHD 10-MAR-20</p> <p>SHT 998217</p> <p>DEST DXP_HUN 11</p> <p>1 ) 12NC 935690628118</p> <p>TYPE 74HC4852PW/C5</p> <p>P/N 8909003331</p> <p>P/O 55230879/001/58</p> <p>QTY 2500 PC INNER BOX 1</p> <p>DATE CODE 2008 NON STANDARD PROD</p> <p>ORIGIN: 0890 THAILAND</p> <p>HALOGEN FREE</p> <p>EU/CN RoHS COMPLIANT</p> |  <p>Ship From: NEXPERIA<br/>Unit 1103 - 1104<br/>11/F Goodman Interlink<br/>. 39 Tsing Yi Road, Tsing Yi, N.<br/>Hong Kong</p> <p>Ship To: 998217</p> <p>(K)Purchase Order# 55230879/001/58</p> <p>(P)Customer PN: 8909003331 (4K)PO Line#</p> <p>(1P)MPN: 74HC4852PW/C5J</p> <p>HALOGEN FREE</p> <p>EU/CN RoHS COMPLIANT</p> <p>CODENO: 935690628118</p> <p>(Q)Quantity: 2500 (100)Date Code: 2008</p> <p>(1T)Lot: CYC225 (4L)C00: TH</p> <p>(4S)Package ID: HK5133033</p> <p>01_10_11_BB1_W</p> <p>G.W. .95 (KGS)</p> <p>N.T. .787 (KGS)</p> <p>Package Count 0001 / 0001</p> <p>TTL Inner Box 1</p> <p>LP5133033</p> <p>SHD 10-MAR-20 CONT SIZE 911</p> <p>DEST DXP_HUN 11</p> |

# Nexperia New Outer Box Label

## Details of content new outer box label

New item in new label

Change in new label

| Field Name                     | Current outer box label |                   |    | New outer box label |                   |                  |                                |
|--------------------------------|-------------------------|-------------------|----|---------------------|-------------------|------------------|--------------------------------|
|                                | Text                    | 1D                | 2D | Text                | 1D                | 2D               | Remarks                        |
| Batch No.                      | N                       |                   |    | Y                   | 1TCYC225          | 1TCYC225         |                                |
| Container Size Id              | Y                       |                   |    | Y                   |                   |                  |                                |
| Country of Origin              | Y                       |                   |    | Y                   | 4LTH              | 4LTH             |                                |
| Customer Part No.              | Y                       | N8909003331       |    | Y                   | P8909003331       | P8909003331      |                                |
| Customer PO Line No.           | N                       |                   |    | Y                   | 4K                | 4K               |                                |
| Customer PO No.                | Y                       | P55230879/001/58  |    | Y                   | K55230879/001/58  | K55230879/001/58 |                                |
| Datecode                       | Y                       | Q5000D1941        |    | Y                   | 10D2008           | 10D2008          |                                |
| Destination ID                 | Y                       |                   |    | Y                   |                   |                  |                                |
| Environmental symbols          | Y                       |                   |    | Y                   |                   |                  |                                |
| Gross weight (KG)              | Y                       |                   |    | Y                   |                   |                  |                                |
| License Plate no.              | Y                       | 5133033           |    | Y                   | 5133033           |                  |                                |
| Net weight (KG)                | Y                       |                   |    | Y                   |                   |                  |                                |
| Orderable Part No.             | N                       |                   |    | Y                   | 1P74HC4852PW/C5J  | 1P74HC4852PW/C5J |                                |
| Package Count                  | Y                       |                   |    | Y                   |                   |                  |                                |
| Package ID                     | N                       |                   |    | Y                   | 4SHK5133033       | 4SHK5133033      |                                |
| Ship date                      | Y                       |                   |    | Y                   |                   |                  |                                |
| Ship-from address              | N                       |                   |    | Y                   |                   |                  |                                |
| Shipping box number            | Y                       | HK513303300010001 |    | Y                   | HK513303300010001 |                  |                                |
| Shipping Remarks               | Y                       |                   |    | Y                   |                   |                  |                                |
| Ship-to address                | Y                       |                   |    | Y                   |                   |                  |                                |
| Ship-to funloc                 | Y                       |                   |    | Y                   |                   |                  |                                |
| Supplier Name                  | N                       |                   |    | Y                   |                   |                  |                                |
| Total inner box Qty            | Y                       |                   |    | Y                   |                   |                  |                                |
| Total Qty/carton               | Y                       |                   |    | Y                   | Q2500             | Q2500            |                                |
| 12NC                           | Y                       | 1P935690628118    |    | Y                   |                   |                  | Refer to PQ label(s)           |
| Label code                     | Y                       |                   |    | N                   |                   |                  | For Nexperia internal use only |
| No of Inner box (per datecode) | Y                       |                   |    | N                   |                   |                  | Refer to PQ label(s)           |
| Packing list no.               | Y                       |                   |    | N                   |                   |                  | Refer to Shipping box number   |
| Qty (per datecode)             | Y                       | Q2500D2008        |    | N                   |                   |                  | Refer to PQ label(s)           |
| Type No.                       | Y                       |                   |    | N                   |                   |                  | Refer to PQ label(s)           |

EFFICIENCY WINS.